

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

20-Sep-19

ESTIMATE REPAIR BILL FOR TOYOTA PRIUS REGN NO: SHD 1835 K

1 pc	Rear bumper		\$	458.60
2 pcs	Rear bumper n/s & o/s side retainer @ \$94.80	X sue	\$	189.60
2 pcs	Rear bumper n/s stay @ @ \$139.60	X sue	\$	279.20
1 pc	Rear bumper reinforcement	X sue	\$	205.70
1 pc	n/s tail lamp lower bracket	X sue	\$	35.70
1 pc	Rear bumper LH lower lip	X sue	\$	118.10
			\$	1,286.90
		Less 25%	\$	321.73
			\$	965.18

S/NETT

1 set	Rear bumper clips		\$	48.00
1 set	Reverse sensor	X sue	\$	280.00
1 pc	Rear bumper top protector		\$	80.00
	Sundry		\$	50.00 X 4
	Towing Fee		\$	50.00 50
	To check wiring		\$	50.00 X 4
	To dismantle and renew the reverse sensor to the new bumper, reset of the same.		\$	120.00 30
	To dismantle and replace the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc		\$	650.00 20
	To putty and spray painting on the rear bumper, end panel		\$	400.00 180
	To apply rustproofing onto the repaired and replaced panels.		\$	120.00 X 2
			\$	2,813.18

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

18/10/19
Cost of US\$700 / 2 days

Kalin 1/1/19
22/9/19 16.00
2 days
45
After Repair ph