

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

20-Sep-19

ESTIMATE REPAIR BILL FOR TOYOTA PRIUS REGN NO: SHD 1835 K

1 pc	Rear bumper	\$	458.60
2 pcs	Rear bumper n/s & o/s side retainer @ \$94.80	\$	189.60
2 pcs	Rear bumper n/s stay @ @ \$139.60	\$	279.20
1 pc	Rear bumper reinforcement	\$	205.70
1 pc	n/s tail lamp lower bracket	\$	35.70
1 pc	Rear bumper LH lower lip	\$	118.10
			\$ 1,286.90
Less 25%			\$ 321.73
			\$ 965.18

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00
1 pc	Rear bumper top protector	\$	80.00
Sundry			
Towing Fee			
To check wiring			
To dismantle and renew the reverse sensor to the new bumper, reset of the same.			
To dismantle and replace the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc			
To putty and spray painting on the rear bumper, end panel			
To apply rustproofing onto the repaired and replaced panels.			
			\$ 2,813.18

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

L&K Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalvin Kky

22/9/19 16:05
2 days
4/5
After Repair photo