

INSURER

INS. CASE OWNER:

CC 3 / AIG1901 6763, T1 dx. 9/23

LKK:

IDAC:

Surveyor:

MM

DOI:

ASSIGNMENT

2/16/19

Date / Time:

23/9/19

Registered in Merimen:

23/9/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLZ 98229

Name of Insured:

KONG YSAE SHYMAN

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

20/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

3269674886

Policy No.:

80002051-01

Make / Model:

M55AN

Place of Accident:

JANG E KO

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLZ 98229



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

23/12/19 - FILE PAS TO TYPE MANDATE

23/1/2020 - FILE PAS TO HAND TO CLASSE

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

21/1/2020

Confirm with:

Caroline

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost: (w/ GST)

\$5

8548.87

OI travelling straight on "only turn left" lane

Loss of Rental (LOR):

\$5

-

(days)

Loss of Use (LOU):

\$5

360.00

(\$

60

x

6

days)

Loss of Income (LOI):

\$5

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5

2.00

Medical:

\$5

-

Disbursement:

\$5

-

(e.g. Tow/ Independent)

Legal Cost

\$5

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$320

Total:

\$5

8910.87

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

8910.87

Name 1:

Performance Motors Limited

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT
22/01/2020

ISS. REC. BY:

Tampin

REP:

AIG

d

ASSIGNMENT

From:

Date:

7.10.2019

Estimated Cost:

UD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLQ 7474

at Workshop m/s

Performance

of

303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

myo?

Vehicle: IN / OUT

Date:

Person Contacted:

Joseph

Veh No:

SLQ 7474

Yr Regn:

2017 June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 216D

c.c.

1496

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading:

38375

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAZE320705746729

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

7/10/14 R250

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P - \$7989.60 (Red \$1837.60 / 197)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Exp. Format:

Lump Sum / L.P. ()

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week end (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

T/T

Performance Motors Limited

A Gine Darby Motors Company
 Co. Reg. No. 197401509W GST Reg. No. M2-0020081-X
 Toll-Free Number: (1800-2255269)

101, Alexandra Road
 Gine Darby Performance Centre
 Singapore 119941
 Fax: 64747770

189, Karpooling Road
 East Coast Centre
 Singapore 438180
 Fax: 63445773

115, Alexandra Road
 Gine Darby Business Centre
 Singapore 119944
 Fax: 64796601 (ATTN: Sales)
 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

23 SEP 2019

E S T I M A T E

Estimate No. : b1 52826
 Date Estimated : 23/09/2019
 Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
 YEO FWU-JERN ANGI (YANG PUZHEN)
 19 SHELFORD ROAD
 #04-48
 SINGAPORE 288408

- ACCOUNT - 121
 AIG Asia Pacific Insurance Pte. Ltd.
 78 Shenton Way
 #08-16 Chartis Building
 Singapore 079120

REGN. NO.	CHASSIS NO.	RECN. DATE	MODEL	MILEAGE
SLQ747Y	WBA2E320705H46229	28/06/2017	216d G TOURER	0

DESCRIPTION	VALUE
Replacing left front fender, left wing mirror, rework front bumper and left front door	2550 3,825.00
Spray front bumper, left front fender, left front door, left wing mirror	2593 2,882.00
To check steering geometry and conduct wheel alignment according to BMW specification (1X)	451 531.00
To replace tyre and wheel rim including balancing. (1x)	80 94.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights	150 177.00
Sundries <i>NA</i>	80.7 150.00

Total Labour 1: 7,659.00

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 7.5X17 DOUBLE SPK 385	1	798.00	inf 798.00
FRT LH FENDER	1	627.15	inf 627.15
MODEL DESIGNATION LETTERING SIDE (L	1	46.30	inf 46.30
LH OUTSIDE MIRROR COVER CAP PRIMED	1	121.40	crq 121.40
LH LOWER HOUSING SECTION	1	25.05	an 25.05
LH EXTERIOR MIRROR W/O MOUNTING PAR	1	491.25	dis 491.25
LH ADDITIONAL TURN INDICATOR LAMP	1	59.05	nn 59.05

Total Parts : 2,168.20



Final Report

Estimate No. : **b1 52826**
Date Estimated : **23/09/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
YEO PWU-JERN ANGI (YANG PUZHEN)
19 SHELFORD ROAD
#04-48

SINGAPORE 288408

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ747Y	WBA2E320705H4622	28/06/2017	216d G TOURER	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	121 DISC. %	NETT
To replace front front left fender and left wing mirror assembly including to make good front left door and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	2,550.00	0	2,550.00
To respray front bumper, front left fender, front left door and left wing mirror cover	2,593.00	0	2,593.00
To check steering geometry and conduct wheel alignment according to BMW specification.	451.00	0	451.00
To replace front left wheel rim including balancing.	80.00	0	80.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00
Sundries	80.00	0	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# ALLOY RIM 7.5X17 DOUBLE SPK 385	798.00	1.00	0	798.00
FRT LH FENDER	627.15	1.00	0	627.15
MODEL DESIGNATION LETTERING SIDE (L	46.30	1.00	0	46.30
# RIVET	0.50	3.00	0	1.50
LH OUTSIDE MIRROR COVER CAP PRIMED	121.40	1.00	0	121.40
LH EXTERIOR MIRROR W/O MOUNTING PAR	491.25	1.00	0	491.25



Final Report

SUPPLEMENTARY ITEMS

Total Labour :	5,904.00
Total Parts :	2,085.60
Total Labour & Parts :	7,989.60
GST @7%:	559.27
Grand Total :	<u>8,548.87</u>

Tan Sri Kij LKK	11/11/19	6

LOSS OF USE = \$60 X 6 DAYS
GIA SEARCH FEE = \$2.00



Supplementary

Estimate No. : **b1 52826**
Date Estimated : **23/09/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
YEO PWU-JERN ANGI (YANG PUZHEN)
19 SHELFORD ROAD
#04-48

SINGAPORE 288408

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ747Y	WBA2E320705H4622	28/06/2017	216d G TOURER	0

DESCRIPTION	ACCOUNT:	121	
	ORIGINAL PRICE	DISC. %	NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RIVET	0.50	3.00	0	1.50
#				
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	1.50
Total Labour & Parts :	1.50

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

23 SEP 2019

E S T I M A T E

Estimate No. : b1 52826
Date Estimated : 23/09/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
YEO PWU-JERN ANGI (YANG PUZHEN)
19 SHELFORD ROAD
#04-48

SINGAPORE 288408

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ747Y	WBA2E320705H46229	28/06/2017	216d G TOURER	0

DESCRIPTION

Replacing left front fender, left wing mirror, rework front bumper and left front door

Spray front bumper, left front fender, left front door, left wing mirror

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

To replace tyre and wheel rim including balancing. (1x).

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

Sundries

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VALUE

2550 3,825.00

2593 2,882.00

451 531.00

80 94.00

150 177.00

? 150.00

Total Labour 1: 7,659.00

DESCRIPTION

ALLOY RIM 7.5X17 DOUBLE SPK 385
FRT LH FENDER
MODEL DESIGNATION LETTERING SIDE (L)
LH OUTSIDE MIRROR COVER CAP PRIMED
LH LOWER HOUSING SECTION
LH EXTERIOR MIRROR W/O MOUNTING PAR
LH ADDITIONAL TURN INDICATOR LAMP

QTY	PRIC
1	798.00
1	627.15
1	46.30
1	121.40
1	25.05
1	491.25
1	59.05

VALUE

cut 798.00

left 627.15

new 46.30

R x 121.40

new 25.05

dis 491.25

? 59.05

Total Parts : 2,168.20

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64767770280, Kengong Azang Road
East Coast Centre
Singapore 438180
Fax: 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52826
Date Estimated : 23/09/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ747Y	WBA2E320705H46229	28/06/2017	216d G TOURER	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 7/10/11 0350 Excess S\$ _____

Surveyor's Name Tanjun Sign _____

Surveyor's Tel 97495747 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail tanjun@iklauto.com

Working Days Recommend 5 days - 6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	7,659.00
Parts	:	2,168.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	687.90
Grand Total	:	10,515.10

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

View Received Message

This mail is associated with :

***SLQ747Y (3288627488SG)**
[SL29822G]

TP
YEO PWU JERN ANG
Sep 20 2019 12:00PM
[KONG TSAE SHYUAN]
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 21/01/2020 12:18 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8910.87) - SLQ747Y - Claim Handler: Tan, Bennie-WZ

Approved:8910.87:*Subject to Final Repair Bill & GIA Search Bill in order

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Sep 2019 Edit Reg		07 Oct 2019 00:00 Edit Adj Rpt	S\$7,989.60 Edit Estimates	S\$7,989.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KONG TSAE SHYUAN , ID: S8166394G								
Main Claimant:	YEO PWU JERN ANGI , ID: S7426352F								
Vehicle Reg. No.:	SLQ747Y	Date of Loss:	20/09/2019 12:00 - :59 26 Months and 23 Days From LTA Reg Date (Man Yr)						
Claim Type:	TP / 3288627488SG	Policy/Cover Note No.:	1800030511 (Comprehensive) Coverage: 23/03/2019 - 22/03/2020						
Vehicle Reg. No. (Insured):	SL29822G	Policy No. (Claimant):	CN834543						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (21/01/2020): Alert - Adj Mandate Approved (S\$8910.87) - SLQ747Y - Claim Handler: Tan, Bennie-...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ747Y (32886274885G)
[SLZ9822G]
TP
YEO PWU JERN ANGI
Sep 20 2019 12:00PM
[KONG TSAE SHYUAN]
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Video										1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	21/01/20 12:13	TP Video - Accident							Load AVI		
Letters/Correspondences										1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	18/12/19 18:26	Odometer Reading							Load JPG ☒		
2	18/12/19 18:26	Chassis Number							Load JPG ☒		
3	18/12/19 18:26	General View							Load JPG ☒		
4	18/12/19 18:26	General View							Load JPG ☒		
5	18/12/19 18:26	General View							Load JPG ☒		
6	18/12/19 18:26	General View							Load JPG ☒		
7	18/12/19 18:26	General View							Load JPG ☒		
8	18/12/19 18:26	General View							Load JPG ☒		
9	18/12/19 18:26	General View							Load JPG ☒		
10	18/12/19 18:26	General View							Load JPG ☒		
11	18/12/19 18:26	General View							Load JPG ☒		
12	18/12/19 18:26	General View							Load JPG ☒		
13	18/12/19 18:26	General View							Load JPG ☒		
14	18/12/19 18:26	General View							Load JPG ☒		
15	18/12/19 18:26	General View							Load JPG ☒		
16	18/12/19 18:26	General View							Load JPG ☒		
17	18/12/19 18:26	General View							Load JPG ☒		
18	18/12/19 18:26	General View							Load JPG ☒		
19	18/12/19 18:26	General View							Load JPG ☒		
20	18/12/19 18:26	General View							Load JPG ☒		
21	18/12/19 18:26	General View							Load JPG ☒		
22	18/12/19 18:26	General View							Load JPG ☒		
23	18/12/19 18:26	General View							Load JPG ☒		
24	18/12/19 18:27	Replacement Part Photo							Load JPG ☒		
25	18/12/19 18:27	Replacement Part Photo							Load JPG ☒		
26	18/12/19 18:27	Replacement Part Photo							Load JPG ☒		
27	18/12/19 18:27	Replacement Part Photo							Load JPG ☒		
Documentation										1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	23/09/19 17:02	TP ESTIMATE							Load PDF		
2	23/09/19 17:02	TP GIA REPORT							Load PDF		
3	08/10/19 17:17	TP ESTIMATE- MARKED							Load PDF		
4	26/12/19 15:15	LETTER TO OI							Load PDF		
5	15/01/20 12:16	LOD							Load PDF		
6	15/01/20 12:16	GIA SEARCH FEE							Load PDF		
7	15/01/20 12:20	TP_ESTIMATE-MARKED-FINAL							Load PDF		
8	23/01/20 10:40	WORKSHOP INVOICE							Load PDF		

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
9	23/01/20 10:40	AUTHORISATION TO ACT FORM		Load PDF	
10	23/01/20 10:40	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	24/09/19 11:52	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 	^ v
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLZ9822G (Insd veh)	Model:	BMW 216D 1.5 D ACTIVE
	SLQ747Y (TP veh)		TOURER (F45) (A)
Date of Accident:	20/09/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	10,516.71
Final Repair Cost	:	\$	8,548.87
Loss of Use	:	\$	360.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	8,910.87

6.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 8,910.87
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

23 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19016763/T1DA3Q2

Date: 23/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800030511
 Claimant: SLQ747Y Insured Vehicle No: SLZ9822G
 Vehicle No: SLQ747Y
 Date of Loss: 20/09/2019 Nature of Claim: TP Claim No: 3288627488SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ747Y
 Make & Model: BMW 216D, 1.5 D Active Tourer (F45) (A) Engine No: 32069888B37C15A
 Reg. Date: 28/06/2017 (Man. Year: 2017) Chassis No: WBA2E320705H46229
 Colour: White Odometer: 38375 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,319.70	2,165.60	154.10	6.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,509.00	5,824.00	1,685.00	22.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,828.70	7,989.60	1,839.10	18.71
+ GST 7.00/7.00% (S\$)	688.01	559.27	128.74	18.71
Nett Amount (S\$)	10,516.71	8,548.87	1,967.84	18.71
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,910.87		

INSPECTION

Date of Assignment: 07/10/2019

Date Inspected: 07/10/2019 Inspected At:

Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*ALLOY RIM 7.5X17 DOUBLE SPK 385	Cut	798.00 FS	*798.00 FS
3	1		*FRT LH FENDER	Bent	627.15 FS	*627.15 FS
4	1		*MODEL DESIGNATION LETTERING SIDE (L)	Necessary	46.30 FS	*46.30 FS
5	1		*LH OUT SIDE MIRROR COVER CAP PRIMED	Cracked	121.40 FS	*121.40 FS
6	1		*LH LOWER HOUSING SECTION	Not Necessary	25.05 FS	*- FS
7	1		*LH EXTENRIOR MIRROR W/O MOUNTING PAR	Distorted	491.25 FS	*491.25 FS
8	1		*LH ADDITIONAL TURN INDICATION LAMP	Not Necessary	59.05 FS	*- FS
9	3		*RIVET	Necessary	1.50 FS	*1.50 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,319.70** **2,165.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACING LEFT FRONT FENDER ,LEFT WING MIRROR ,REWORK FRONT BUMPER AND LEFT FRONT DOOR	New	3,825.00	2,550.00
2	SPRAY FRONT BUMPER ,LEFT FRONT FENDER ,LEFT FRONT DOOR ,LEFT WING MIRROR	New	2,882.00	2,593.00
3	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
4	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (S\$)			7,509.00	5,824.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >