

INS. CASE OWNER:

Norsiah

CC3/AIG19016776/T/da3

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time : 23/09/2019

Registered in Merimen: 23/09/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SMH 5238C

Claim No. : 9827746437SG

Name of Insured : RAJ KAPOOR S/O SRIKAN PANDAY

Policy No. : 1900011019

Insured Tel No. : HP: +65-93875580

Make / Model : NISSAN SYLPHY-1.6 (A)

Excess See II : S\$ D.O.A : 23/09/2019 09:25

Place of Accident : INSIDE CLEMENTI CAMP

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SJJ 1170P

INSRS:
WSP: Performance
Tel: Motors
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	SJJ1170P - X	SMH 5238C - X	STAGE	DATE / PIC
25-09-19	BOTH PARTIES ARE EQUALLY TO BE BLAMED FOR CAUSING THE COLLISION		Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
20/12/19	FILE PASS TO TYPE MPNDATC		Documentation Check List:	Handler Typist
22/1/20	FILE PASS TO HANU TO CCVLS		Notification ltr (if non-pickup)	☒
			After call ltr to OI:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice:	☒
			LTA / GIA :	☒
			Medical Bill:	☐
			PIR:	☐
			Mandate/Reject Instruction:	☐
			LOD	☒
			Payment Breakdown Form:	☐
			Post-Repair Photos:	☐
			Others:	☐
PRELIMINARY ADVICE Date/Time: Sent By:				
FINALIZATION Date/Time: Confirm with: Confirm by:				
Repair Cost:	S\$	(days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: 21/1/2020 Confirm with: Caroline Email: ☒ Call: ☐				
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	H/LC	
Repair Cost: (w/loss)	S\$ 18543.47			
Loss of Rental (LOR):	S\$ 1500.00	(15 days) X \$100		
Loss of Use (LOU):	S\$ -	(\$ x days)		
Loss of Income (LOI):	S\$ -	(\$ x days)		
LOR only ☒ LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	S\$ 2.00			
Medical:	S\$ -			
Disbursement:	S\$ -	(e.g. Tow/ Independent)		
Legal Cost	S\$ -			
Total:	S\$ 20045.47	Global Sum S\$:		
FINAL PAYMENT Date/Time: Confirm with: Email: ☐ Call: ☐				
Payee 1:	S\$ 20045.47	Name 1:	Performance Motors Limited	
Payee 2: (Strike if N.A.)	S\$	Name 2:		
Payee 3: (Strike if N.A.)	S\$	Name 3:		

COPY SENT

1) Claim status: Normal/Reject/Private Settle
 2) Report Format: ☒
 3) Survey fee: \$320

ASS. REC. BY:

Taylor

REF:

AUG

16776 (1/01)

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$165K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

China

Veh No:

555 1170P

(r Regn:

2019, June

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X1

cc

1499

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp Reading

8389

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA JG120X03677719

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal

6

mm

Rear

R/Bal

6

mm

L/Bal

6

mm

U/Bal

6

mm

D.O.A.

D.O.I

22/11/19

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Plp - \$17330.35 (Red \$4445.75/201)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Rep. Form:

Emp. Sign / U/C:

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Other:

TOTAL

Performance Motors Limited

A Siam Derby Motors Company
Co. Reg. No. 197451339M GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255265)

151, Alexandra Road
Siam Derby Performance Centre
Singapore 159941
Fax: 64747773

230, Rongong Arany Road
Siam Derby Centre
Singapore 418185
Fax: 63449773

115, Alexandra Road
Siam Derby Business Centre
Singapore 159944
Fax: 64796631 (AfterSales)
64796624 (Workshop)



GST REG. NO : M2 - 0020081 - X

23 SEP 2019

E S T I M A T E

Estimate No. : b1 52830
Date Estimated : 23/09/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Tan Kiam Seong Desmond
Blk 1G Cantonment Road
#43-77

Singapore 085701

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJJ1170P	WBAJG120X03G77719	24/06/2019	X1 sDrive18i	0

DESCRIPTION

Replace right rear fender, right rear door, right lower side
skirting include remove attachment etc and repair on
accident damage area

6375 6,800.00

Spray painting right rear side fender, right rear door,
roof frame, tail pan and floor pan

3408 3,787.00

To remove and install boot compartment carpet and garnish
to facilitate repairs

230 271.00

To conduct checks on all doors and bootlid central locking
system for proper function.

150 177.00

To carry out body cavity preservation.
(For cut panel)

451 531.00

To carry out body cavity preservation.
(2 panel)

200 236.00

To remove and install fuel tank to facilitate repairs
including extract fuel and conduct leak tests

451 531.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1X)

451 531.00

To replace tyre and wheel rim including balancing (X)
right rear

80 94.00

To supply and install rear right fender window glass
solar film

425 425.00

To supply and install rear right window glass
solar film

425 425.00

Sundries

150.00

Performance Motors Limited

A Time Parity Motors Company
Co. Reg. No. 191401999M GST Reg. No. M2-0020081-X
Toll Free Number: 1800-2251249

333, Alexandra Road
Time Parity Performance Centre
Singapore 119941
Fax: 64747710

240, Kembangan Avenue Road
East Coast Centre
Singapore 438160
Fax: 63449771

313, Alexandra Road
Time Parity Business Centre
Singapore 119944
Fax: 64796401
64796424
[AfterSales@PerformanceMotors.com.sg]



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 52830
Date Estimated : 23/09/2019
Prepared By : Chua Kee Sin

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJJ1170P	WBAJG120X03G77719	24/06/2019	X1 sDrive18i	0

DESCRIPTION

(DG/SL) GLASS PRIMER 30ML (VP206)
(DG/SL) GLASS PRIMER 30ML (VP206)
(S/L) SEAM SEAL 300ML

QTY	PRIC	VALUE
1	27.85	27.85
1	27.85	27.85
1	33.80	33.80
Total Parts :		7,818.10

UKS Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Page No. _____ Claim No. _____

Date & Time 22/10/19 @ 3:20 Excess \$5

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 97495749 Authorized Yes / No

Authorized Date "WP" Time _____

RESURVEY PARTS PHOTO BY SURVEYOR (Y/N) PM Yes / No

Surveyor's Email tanjiah@ukshant.com

Working Days Recommend 11 - 12 days

Labour 1	:	13,958.00
Parts	:	7,818.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,524.33
Grand Total	:	23,300.43

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



Final Report

Estimate No. : **b1 52830**
Date Estimated : **23/09/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Tan Kiam Seong Desmond
Blk 1G Cantonment Road
#43-77

Singapore 085701

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJJ1170P	WBAJG120X03G77	24/06/2019	X1 sDrive18i	0
DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT	
To replace rear right fender, rear right door, right side skirting and rear right wheel arch trim etc including to remove and install body parts in order to carry out painting job.	6,375.00	0	6,375.00	
To respray rear right fender, rear right door, right side skirting, right roof frame, tail end panel and trunk floor panel etc.	3,408.00	0	3,408.00	
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00	0	230.00	
To conduct checks on all doors and bootlid central locking system for proper function.	150.00	0	150.00	
To carry out body cavity preservation. (For cut panel).	451.00	0	451.00	
To carry out body cavity preservation.	200.00	0	200.00	
To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests.	451.00	0	451.00	
To check steering geometry and conduct wheel alignment according to BMW specification (1X)	451.00	0	451.00	
To replace rear right wheel rim including balancing.	80.00	0	80.00	
Sundries.	150.00	0	150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# BLIND RIVET NUT WITH COLLAR M5	5.55	1	0	5.55
LIGHT ALLOY WHEEL Y SPK 569	1,006.00	1	0	1,006.00
RR RH FENDER	1,725.45	1	0	1,725.45
RR RH DOOR	1,197.80	1	0	1,197.80
REAR RH MOULDING ROCKER PANEL	64.25	1	0	64.25
REAR RH SIDE WINDOW FIXED (ALU)	317.85	1	0	317.85
REAR RH WHEEL ARCH TRIM	151.00	1	0	151.00
RH SIDE SKIRT TRIM (LINES)	257.95	1	0	257.95

Performance Motors Limited

A member of the Sino Darby Group
Co Reg No: 197401559W GST Reg No: M2-0020081-X



Final Report

BLIND RIVET AVIBVLB	0.55	30	0	16.50
(DG/SL) BODY ADHESIVE K5B (195ML)	326.80	1	0	326.80
PUNCH RIVET N4	0.55	20	0	11.00
(DG) BODYWORK ADHESIVE K5A (50ML)	112.70	1	0	112.70
(DG) CLEANER R1 (100ML)	26.15	1	0	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	1	0	131.55
(S/L) SEAM SEAL 300ML	33.80	1	0	33.80

SUPPLEMENTARY ITEMS

Total Labour :	11,946.00
Total Parts :	5,384.35
Total Labour & Parts :	17,330.35
GST @7%:	1,213.12
Grand Total :	18,543.47

DATE	TIME	NAME	PHONE	EMAIL
26/11/19	12	Tanfikh LKK		

CAR RENTAL - \$1530.00 (15 DAYS)
GIA SEARCH FEE - \$2.00



Supplementary

Estimate No. : **b1 52830**
Date Estimated : **23/09/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Tan Kiam Seong Desmond
Blk 1G Cantonment Road
#43-77

Singapore 085701

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJJ1170P	WBAJG120X03G77	24/06/2019	X1 sDrive18i	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
-------------	----------------------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT WITH COLLAR M5	5.55	1	0	5.55

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	5.55
Total Labour & Parts :	5.55

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 052D

Vehicle Details

Vehicle No.: SJJ1170P

Vehicle to be Exported: No

Intended Deregistration
Date: 22 Oct 2019

Vehicle Make: B.M.W.

Vehicle Model: X1 SDRIVE18i LED NAV

Primary Colour: Brown

Manufacturing Year: 2019

Engine No.: 31805599B38B15A

Chassis No.: WBAJG120X03G77719

Maximum Power
Output: 103.0 kW (138 bhp)

Open Market Value: \$36,905.00

Original Registration
Date: 24 Jun 2019

First Registration Date: 24 Jun 2019

Transfer Count: 0

Actual ARF Paid: \$43,667.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 23 Jun 2029

PARF Rebate Amount: \$32,750.00

Intended COE Rebate Details

COE Expiry Date: 23 Jun 2029

COE Category: B - Car above 1600cc or
97kW (130bhp)

COE Period(Years): 10

QP Paid: \$35,906.00

COE Rebate Amount: \$34,719.00

Total Rebate Amount: \$67,469.00

The information contained herein is correct as at 22 Oct 2019

OK

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255266)

301, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438188
Fax: 63449773

311, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

23 SEP 2019

E S T I M A T E

Estimate No. : b1 52830
Date Estimated : 23/09/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Tan Kiam Seong Desmond
Blk 1G Cantonment Road
#43-77

Singapore 085701

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJJ1170P	WBAJG120X03G77719	24/06/2019	X1 sDrive18i	0

DESCRIPTION

VALUE

Replace right rear fender, right rear door, right lower side
skirting include remove attachment etc and repair on
accident damage area

6375 6,800.00

Spray painting right rear side fender, right rear door,
roof frame, tail pan and floor pan

3408 3,787.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

To conduct checks on all doors and bootlid central locking
system for proper function.

150 177.00

To carry out body cavity preservation.
(For cut panel).

451 531.00

To carry out body cavity preservation.
(2 panel).

200 236.00

To remove and install fuel tank to facilitate repairs
including extract fuel and conduct leak tests.

451 531.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1X)

451 531.00

To replace tyre and wheel rim including balancing. (1x).
right rear

80 94.00

To supply and install rear right fender window glass
solar film.

7 425.00

To supply and install rear right window glass
solar film.

7 425.00

Sundries.

150.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 158941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796651 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52830
Date Estimated : 23/09/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJJ1170P	WBAJG120X03G77719	24/06/2019	X1 sDrive18i	0

Total Labour 1: 13,958.00

DESCRIPTION	QTY	PRIC	VALUE
PLASTIC NUT FOR COARSE THREADED PIN	10	0.85	8.50
LIGHT ALLOY WHEEL Y SPK 569	1	1,006.00	1,006.00
HUB CAP WITH CHROME EDGE	1	28.95	28.95
RR RH FENDER	1	1,725.45	1,725.45
RR RH DOOR	1	1,197.80	1,197.80
Positionieru	1	5.75	5.75
REINFORCEMENT PLATE UNIVERSAL	1	52.20	52.20
Reinforcemen	1	53.45	53.45
Reinforcemen	1	53.45	53.45
Reinforcemen	1	65.00	65.00
T WELD BOLT L=5.4MM	10	0.90	9.00
REAR RH MOULDING ROCKER PANEL	1	64.25	64.25
RIVET	20	0.50	10.00
PLASTIC NUT	5	0.85	4.25
Door brake,	1	77.05	77.05
REAR RH DOOR WINDOW GUIDE	1	136.30	136.30
Seal, door t	1	21.80	21.80
Foam pad, do	1	4.50	4.50
RR RH INNER DOOR CHANNEL SEAL	1	67.75	67.75
REAR RH DOOR JOINT SEAL	1	34.80	34.80
RR RH DOOR WINDOW FRAME COVER (ALU)	1	79.30	79.30
RR RH DOOR OUTER CHANNEL COVER (ALU)	1	129.50	129.50
Seal, trim,	1	21.80	21.80
RR RH WINDOW LIFTER W/MOTOR	1	315.10	315.10
REAR RH SIDE WINDOW FIXED (ALU)	1	317.85	317.85
RR RH SIDE DOOR WINDOW FIXED	1	149.70	149.70
Cover for wi	1	94.15	94.15
REAR RH WHEEL HOUSING COVER	1	142.55	142.55
REAR DOOR SEALING TAPE ENTRANCE	1	34.80	34.80
Seal, pillar	1	21.80	21.80
EXPANDING RIVET BLACK	26	1.40	36.40
REAR RH RETAINING STRIP SILL	1	36.90	36.90
REAR RH WHEEL ARCH TRIM	1	151.00	151.00
RH TRIM UNDERRIDE PROTECTION (X LIN	1	223.50	223.50
RH SIDE SKIRT TRIM (LINES)	1	257.95	257.95
DRIVE FOR WINDOW LIFTER	1	255.90	255.90
CAVITY PROTECTION WAX REMOVER 500ML	1	18.45	18.45
BLIND RIVET AVIBVLB	10	0.55	5.50
SCREW (SF PLUS M5X15)	3	0.55	1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	1	326.80	326.80
(DG) BODYWORK ADHESIVE K5A (50ML)	1	112.70	112.70
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	1	131.55	131.55
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	1	131.55	131.55
PUNCH RIVET N4	50	0.55	27.50

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255289)

309, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52830
Date Estimated : 23/09/2019
Prepared By : Chua Kee Sin

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJJ1170P	WBAJG120X03G77719	24/06/2019	X1 sDrive18i	0

DESCRIPTION

(DG/SL) GLASS PRIMER 30ML (VP206)
(DG/SL) GLASS PRIMER 30ML (VP206)
(SL) SEAM SEAL 300ML

QTY	PRIC	VALUE
1	27.85	27.85
1	27.85	27.85
1	33.80	33.80

Total Parts : 7,818.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 22/10/19 @ 320 Excess \$5

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 97495749 Authored Yes / No

Authorised Date 'WP' Time _____

RESURVEY PARTS PHOTO BY SURVEYOR (Yes / No) PML Yes / No

Surveyor's E-mail tanjiah@lkkauto.com

No. of Working Days Recommend 11-12 days

Labour 1	:	13,958.00
Parts	:	7,818.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,524.33
Grand Total	:	23,300.43

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

View Received Message

This mail is associated with :

***SJJ1170P (98277464375G)
[SMH5238C]**

TP
TAN KIAM SEONG DESMOND
Sep 23 2019 9:00AM
[RAJ KAPOOR S/O SRIKAN PANDAY]
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/01/2020 11:20 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$20045.47) - SJJ1170P - Claim Handler: MdNoor, Norsiah

Approved:20045.47.

DOCUMENTS SUMMARY

There are no documents.



Liberty Insurance Pte Ltd

Registration no. 199002711D

51 Club Street

#03-01 Liberty House

Singapore 069428

Tel: (65) 6221 8611 Fax: (65) 6226 3360

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

Certificate No SD19V08035 /VPC2 /R00
Form MX1
Date of Issue 25-JUN-2019
1. Index Mark and Registration No. of Vehicle SJJ1170P
2. Chassis number of Vehicle WBAJG120X03G77719
3. Name of Policyholder TAN KIAM SEONG DESMOND
4. Effective date of Commencement of Insurance for the purposes of the Act 24-JUN-2019 00:00 AM
5. Date of Expiry of Insurance 23-JUN-2021 23:59 PM
6. Persons or Classes of Persons entitled to drive

A) The Policyholder.

B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

7. Limitations as to use:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

8. The Policy does not cover:

A) Use for hire or reward.

B) Use for racing, pace-making, reliability trials or speed-testing.

C) Use for the carriage of goods (other than samples) in connection with any trade or business.

D) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

For and on behalf of
LIBERTY INSURANCE PTE LTD
Approved Insurers


Authorised Signature

For Information only:

COVERAGE
SUM INSURED

EXCESS
FINANCE COMPANY
PRODUCER NAME

Comprehensive, Unladen, Windscreen, NCD Protection
MARKET VALUE AT THE TIME OF LOSS

Section 1 \$5000 Additional Excess For Young & Inexperienced Drivers \$5200 Windscreen Excess \$50
CBS BANK LTD
SD CONTEGO SERVICES

CLXL 20190626

Ver.1.260705

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Sep 2019 Edit Reg		27 Sep 2019 00:00 Edit Adj Rpt	S\$17,330.35 Edit Estimates	S\$17,330.35 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	RAJ KAPOOR S/O SRIKAN PANDAY, ID: S13828211								
Main Claimant:	TAN KIAM SEONG DESMOND, ID: S7236052D								
Vehicle Reg. No.:	SJJ1170P	Date of Loss:	23/09/2019 09:00 - :59 [2 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9827746437SG	Policy/Cover Note No.:	1900011019 (Comprehensive) Coverage: 25/01/2019 - 24/01/2020						
Vehicle Reg. No. (Insured):	SMH5238C	Policy No. (Claimant):	SD19V08035/VPC2/R00MX1						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (20/01/2020): Alert - Adj Mandate Approved (S\$20045.47) - SJJ1170P - Claim Handler: MdNoor, No...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJJ1170P (9827746437SG)
[SMH5238C]
TP
TAN KIAM SEONG DESMOND
Sep 23 2019 9:00AM
[RAJ KAPOOR S/O SRIKAN PANDAY]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Video														1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	15/01/20 12:45	Video - Accident (TP)										1	Load MP4				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print			
1	24/09/19 11:36	OI VIDEO										1	Load MP4				
Letters/Correspondences														1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown										1	Edit				
Photos/Images														3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	18/12/19 18:43	Odometer Reading										1	Load JPG	☒			
2	18/12/19 18:43	Chassis Number										1	Load JPG	☒			
3	18/12/19 18:43	General View										1	Load JPG	☒			
4	18/12/19 18:43	General View										1	Load JPG	☒			
5	18/12/19 18:43	General View										1	Load JPG	☒			
6	18/12/19 18:43	General View										1	Load JPG	☒			
7	18/12/19 18:43	General View										1	Load JPG	☒			
8	18/12/19 18:43	General View										1	Load JPG	☒			
9	18/12/19 18:43	General View										1	Load JPG	☒			
10	18/12/19 18:43	General View										1	Load JPG	☒			
11	18/12/19 18:43	General View										1	Load JPG	☒			
12	18/12/19 18:43	General View										1	Load JPG	☒			
13	18/12/19 18:43	General View										1	Load JPG	☒			
14	18/12/19 18:43	General View										1	Load JPG	☒			
15	18/12/19 18:43	General View										1	Load JPG	☒			
16	18/12/19 18:43	General View										1	Load JPG	☒			
17	18/12/19 18:43	General View										1	Load JPG	☒			
18	18/12/19 18:43	General View										1	Load JPG	☒			
19	18/12/19 18:43	General View										1	Load JPG	☒			
20	18/12/19 18:43	General View										1	Load JPG	☒			
21	18/12/19 18:43	General View										1	Load JPG	☒			
22	18/12/19 18:43	General View										1	Load JPG	☒			
23	18/12/19 18:43	General View										1	Load JPG	☒			
24	18/12/19 18:43	General View										1	Load JPG	☒			
25	18/12/19 18:43	General View										1	Load JPG	☒			
26	18/12/19 18:43	General View										1	Load JPG	☒			
27	18/12/19 18:43	General View										1	Load JPG	☒			
28	18/12/19 18:44	Reinspection Photo										1	Load JPG	☒			
29	18/12/19 18:44	Reinspection Photo										1	Load JPG	☒			
30	18/12/19 18:44	Reinspection Photo										1	Load JPG	☒			
31	18/12/19 18:44	Reinspection Photo										1	Load JPG	☒			
32	18/12/19 18:44	Reinspection Photo										1	Load JPG	☒			
33	18/12/19 18:44	Reinspection Photo										1	Load JPG	☒			
34	18/12/19 18:44	Reinspection Photo										1	Load JPG	☒			
35	18/12/19 18:44	Reinspection Photo										1	Load JPG				

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
36	18/12/19 18:44	Reinspection Photo	 Load JPG	☒
37	18/12/19 18:44	Replacement Part Photo	 Load JPG	☒
38	18/12/19 18:44	Replacement Part Photo	 Load JPG	☒
39	18/12/19 18:44	Replacement Part Photo	 Load JPG	☒
40	18/12/19 18:44	Replacement Part Photo	 Load JPG	☒
41	18/12/19 18:44	Replacement Part Photo	 Load JPG	☒
42	18/12/19 18:44	Replacement Part Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/09/19 18:47	TP ESTIMATE	 Load PDF	
2	23/09/19 18:47	TP GIA REPORT	 Load PDF	
3	23/10/19 11:36	TP ESTIMATE - MARKED	 Load PDF	
4	15/01/20 14:06	LOD	 Load PDF	
5	15/01/20 14:06	RENTAL RECEIPT	 Load PDF	
6	15/01/20 14:06	GIA SEARCH FEE	 Load PDF	
7	30/01/20 12:59	WORKSHOP INVOICE	 Load PDF	
8	30/01/20 12:59	AUTHORISATION TO ACT FORM	 Load PDF	
9	30/01/20 12:59	Release Voucher	 Load PDF	
10	30/01/20 12:59	LETTER TO OI	 Load PDF	
11	30/01/20 13:50	WORKSHOP INVOICE	 Load PDF	
12	30/01/20 13:50	AUTHORISATION TO ACT FORM	 Load PDF	
13	30/01/20 13:50	Release Voucher	 Load PDF	
14	30/01/20 13:50	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/09/19 11:37	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMH5238C (Insd veh)	Model:	BMW X1 SDRIVE18I 1.5 LED
	SJJ1170P (TP veh)		NAV (A)
Date of Accident:	23/09/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	23,318.14
Final Repair Cost	:	\$	18,543.47
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,500.00 15 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	20,045.47

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 20,045.47
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

30 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19016776/T1DA3Q2

Date: 30/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900011019
 Claimant Vehicle No: SJJ1170P Insured Vehicle No: SMH5238C
 Date of Loss: 23/09/2019 Nature of Claim: TP Claim No: 9827746437SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJJ1170P
 Make & Model: BMW X1 SDRIVE18i, 1.5 LED NAV (A) Engine No: 31805599B38B15A
 Reg. Date: 24/06/2019 (Man. Year: 2019) Chassis No: WBAJG120X03G77719
 Colour: Bronze Odometer: 8384 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,834.65	5,534.35	3,300.30	37.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,958.00	11,796.00	1,162.00	8.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,792.65	17,330.35	4,462.30	20.48
+ GST 7.00/7.00% (S\$)	1,525.49	1,213.12	312.37	20.48
Nett Amount (S\$)	23,318.14	18,543.47	4,774.67	20.48
+ Car Rental (15.0 x S\$100.00/day) (S\$)		1,500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		20,045.47		

INSPECTION

Date of Assignment: 27/09/2019

Date Inspected: 27/10/2019 Inspected At:

Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RIGHT FENDER WINDOW GLASS SOLAR FILM	Not Necessary	425.00 FS	*- FS
2	1		*REAR RIGHT WINDOW GLASS SOLAR FILM	Not Necessary	425.00 FS	*- FS
3	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
4	10		*PLASTIC NUT FOR COARSE THREADED PIN	Not Necessary	8.50 FS	*- FS
5	1		*LIGHT ALLOY WHEEL Y SPK 569	Cut	1,006.00 FS	*1,006.00 FS
6	1		*HUB CAP WITH CHROME EDGE	Not Necessary	28.95 FS	*- FS
7	1		*RR RH FENDER	Necessary	1,725.45 FS	*1,725.45 FS
8	1		*RR RH DOOR	Bent	1,197.80 FS	*1,197.80 FS
9	1		*POSITIONIERU	Not Necessary	5.75 FS	*- FS
10	1		*REINFORCEMENT PLATE UNIVERSAL	Not Necessary	52.20 FS	*- FS
11	1		*REINFORCEMENT	Not Necessary	53.45 FS	*- FS
12	1		*REINFORCEMENT	Not Necessary	53.45 FS	*- FS
13	1		*REINFORCEMENT	Not Necessary	65.00 FS	*- FS
14	10		*T WELD BOLT L=5.4MM	Not Necessary	9.00 FS	*- FS
15	1		*REAR RH MOULDING ROCKER PANEL	Cut	64.25 FS	*64.25 FS
16	20		*RIVET	Not Necessary	10.00 FS	*- FS
17	5		*PLASTIC NUT	Not Necessary	4.25 FS	*- FS
18	1		*DOOR BRAKE	Not Necessary	77.05 FS	*- FS
19	1		*REAR RH DOOR WINDOW GUIDE	Not Necessary	136.30 FS	*- FS
20	1		*SEAL DOOR T	Not Necessary	21.80 FS	*- FS
21	1		*FOAM PAD ,DO	Not Necessary	4.50 FS	*- FS
22	1		*RR RH INNER DOOR CHANNEL SEAL	Not Necessary	67.75 FS	*- FS
23	1		*REAR RH DOOR JOINT SEAL	Not Necessary	34.80 FS	*- FS
24	1		*RR RH DOOR WINDOW FRAME COVER (ALU)	Not Necessary	79.30 FS	*- FS
25	1		*RR RH DOOR OUTER CHANNEL COVER (ALU)	Not Necessary	129.50 FS	*- FS
26	1		*SEAL TRIM	Not Necessary	21.80 FS	*- FS
27	1		*RR RH WINDOW LIFTER W/MOTOR	Not Necessary	315.10 FS	*- FS
28	1		*REAR RH SIDE WINDOW FIXED(ALU)	Necessary	317.85 FS	*317.85 FS
29	1		*RR RH SIDE DOOR WINDOW FIXED	Not Necessary	149.70 FS	*- FS
30	1		*COVER FOR WI	Not Necessary	94.15 FS	*- FS
31	1		*REAR RH WHEEL HOUSING COVER	Not Necessary	142.55 FS	*- FS
32	1		*REAR DOOR SEALING TAPE ENTRANCE	Not Necessary	34.80 FS	*- FS
33	1		*SEAL ,PILLAR	Not Necessary	21.80 FS	*- FS
34	1		*EXPANDING RIVET BLACK (26 PCS)	Not Necessary	36.40 FS	*- FS
35	1		*REAR RH RETAINING STRIP SILL	Not Necessary	36.90 FS	*- FS
36	1		*REAR RH WHEEL ARCH TRIM	Cut	151.00 FS	*151.00 FS
37	1		*RH TRIM UNDERRIDE PROTECTION (X LIN)	Not Necessary	223.50 FS	*- FS
38	1		*RH SIDE SKIRT TRIM (LINES)	Cut	257.95 FS	*257.95 FS
39	1		*DRIVE FOR WINDOW LIFTER	Not Necessary	255.90 FS	*- FS
40	1		*CAVITY PROTECTION WAX REMOVER 500ML	Not Necessary	18.45 FS	*- FS
41	1		*BLIND RIVET AVIBVLB (30 PCS)	Necessary	16.50 FS	*16.50 FS
42	3		*SCREW (SF PLUS M5X15)	Not Necessary	1.65 FS	*- FS
43	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	326.80 FS	*326.80 FS
44	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	112.70 FS	*112.70 FS
45	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
46	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
47	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
48	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	131.55 FS	*131.55 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	131.55 FS	*- FS
50	1		*PUNCH RIVET N4 (50 PCS)	Necessary (20 PCS ONLY)	27.50 FS	*11.00 FS
51	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
52	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
53	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
54	1		*BLIND RIVET NUT WITH COLLAR M5	Necessary	5.55 FS	*5.55 FS
Total Parts (\$\$)					8,834.65	5,534.35

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE RIGHT REAR FENDER ,RIGHT REAR DOOR ,RIGHT LOWER SIDE SKIRTING INCLUDE REMOVE ATTACHMENT ETC AND REPAIR ON ACCIDENT DAMAGE AREA	New	6,800.00	6,375.00
2	SPRAY PAINTING RIGHT REAR SIDE FENDER ,RIGHT REAR DOOR ,ROOF FRAME ,TAIL PAN AND FLOOR PAN	New	3,787.00	3,408.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
4	TO CONDUCT CHECKS ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	150.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (2 PANEL)	New	236.00	200.00
7	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING EXTRACT FUEL AND CONDUCT LEAK TESTS	New	531.00	451.00
8	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
9	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING RIGHT REAR	New	94.00	80.00
Gross Labour Cost (S\$)			12,958.00	11,796.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >