

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13156

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1140/2019/NS
Date : 21-Sep-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Gao Kang
Address : 1 Grace Park
: Singapore 557761
Telephone : HP +65 87813910
Type of Claim : Own Damage Claim
Policy No. : 1900152865
Vehicle No : **SMN 7489 A**
Model Code : Audi Q8 3.0 TFSI qu 4MNOX
Model / Year : Aug-19
Engine No : DCB 051783
Chassis No : WAUZZZF10KD010053
Mileage :
Date In :

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMN 7489 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	
2	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 360.00 ✓	
3	To dismantle and renew rear bumper and lhs rear door. To repair lhs rear fender. Re-organise crash management components. Reinstall all parts removed.	600. \$ 3,150.00	1500
4	To respray lhs rear door, door cover, door handle, lhs rear fender, lhs rear door wheel arch trim, both rear wheel arch trims, rear upper bumper and rear lower bumper.	\$ 6,000.00	2700.
5	To carry out diagnostic checks.	S/N \$ 384.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ 10,254.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7489 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER - UPPER	\$ 1,121.00	Ry
2	REAR BUMPER - LOWER	\$ 2,269.00	Ry
3	REAR BUMPER FIXING PARTS	\$ 154.00	?
4	REAR BUMPER GUIDE SECTION - LH	\$ 68.00	?
5	REAR WHEEL HOUSING LINER - LH	\$ 327.00	X
6	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT AND REAR	\$ 66.00	X
7	REAR WHEEL COVER - LH / RH	2 \$ 688.00	LH-mis, RH-?
8	REAR DOOR WHEEL COVER - LH	\$ 179.00	at
9	REAR DOOR - LH	\$ 3,570.00	bt
10	REAR DOOR OUTER SEAL - LH	NEC \$ 157.00	ner
11	BONDING AGENT	NEC \$ 45.00	ner
12	CLEANING SOLUTION	NEC \$ 65.00	ner
13	REAR DOOR ATTACHMENT PARTS	\$ 191.00	?
14	OUTER DOOR SEAL - LH	\$ 234.00	?
15	REAR DOOR CATCH	\$ 96.00	?
16	OUTER DOOR SEAL - LH	\$ 174.00	?
17	SILL PANEL SEAL - LH	\$ 234.00	?
18	REAR DOOR COVER - LH	\$ 464.00	cut
19	EXTERIOR DOOR HANDLE - LH	\$ 320.00	cut
20	DOOR HANDLE CAP - LH	\$ 36.00	?
SUB SPARE PARTS CHARGES		\$ 10,458.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7489 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	DOOR HOUSING	\$ 16.00	?
22	REAR DOOR HANDLE SENSOR - LH	\$ 237.00	?
23	REAR DOOR MOUNTING BAR - LH	\$ 118.00	?
24	ROOF MOLDING - LH	\$ 493.00	X
25	WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER	\$ 191.00	X
26	WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER	\$ 327.00	X
27	SUNDRIES	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 12,340.00
TOTAL LABOUR CHARGES		:	\$ 10,254.00
GRAND TOTAL		:	\$ 22,594.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tan Jia 97495719
Not Authorised
Ex \$4400
23/9/19 @ 4pm
Resurvey before paint
surveillance from
07 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: