

Supervisor:

ASS. REC. BY:

REF: CS/CT19016801/KYf302

Special Instruction:

winwin

Supervisor: Kenneth

ASSIGNMENT (Office)

From (Person): Chong Bon Sen of CT1 Date/Time: 24.9.19 10490.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLE 4567L Insured: _____

at Workshop m/s Lai Hual Tel: 64538110

of 160 sm ming # 04-01

Policy No: DM PCSF3056941702 Claim No: SNM KD204477

Sum Insured: _____ Excess: _____

Make of Vels: _____ D.O.A. 21.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 24.9.19 10.50a.m Person Contacted: Jing H.O.D. Endorsement: _____

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLE 4567L-X</u>
<u>25/9/19</u>	<u>Sent Revert via Merimer</u>
<u>26/9/19</u>	<u>Sent Approval (Excess \$0) by email</u>
<u>11/12</u>	<u>\$ 2738.77 Confirm (Red \$ 151.50, 5%)</u>

Jenny.Lim@Laihuas.com.sg

ASS. REC. BY:

REF:

672/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / STD / Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File post to

RECEIVED 23 DEC 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

F - FMS

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / L.B.I: (\$

P/P \$2738-27

270

220

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Thursday, September 26, 2019 10:23 AM
To: jenny.lim@laihuat.com.sg
Cc: SUR
Subject: OD SLE4567L DOA: 21/09/2019

Dear Sir,Mdm

As instructed by our client, please proceed to repair the insured vehicle SLE4567L (**excess \$0/-**).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SLE4567L (SNM19D204477-SLE4567L-TKL)

OD

Sep 21 2019 10:00AM

[KONG SIOW YING]

Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 19/12/2019 09:38 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2738.27) - SLE4567L - Claim Handler: Chong Boon Sen

Approved:2738.27.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2019 Sendback Est	23 Sep 2019 17:20 S\$2,675.27	24 Sep 2019 10:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	KONG SIOW YING, ID: S7327772H								
Vehicle Reg. No.:	SLE4567L	Date of Loss:	21/09/2019 10:00 - :59 [37 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D204477-SLE4567L-TKL	Policy/Cover Note No.:	DMPCSN3056841902 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/10/2019]								
Driver/Custodian:	SIM CHOON SENG (49 / Male) , NRIC: S7024304, Tel: +6591142468 Email: Edsim4567@gmail.com								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 16 Dec 2019

Preliminary Advice

Vehicle No	: SLE4567L	Accident Date	: 21/09/2019
Make	: TOYOTA SIENTA	Policy No.	: DMPCSN3056841902
Assignment Date	: 24/09/2019	Excess	: S\$0.00
Date of Inspection	: 24/09/2019	Est. Duration of Repair	: 5.00
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages FRONT portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,890.27 (INCLUDING SUPP \$215.00)
Revised Amount	:S\$	2,738.27 (SUPP \$215.00)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,738.27

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	44,736.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,264.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 25 Sep 2019

Preliminary Advice

Vehicle No	: SLE4567L	Accident Date	: 21/09/2019
Make	: TOYOTA SIENTA	Policy No.	: DMPCSN3056841902
Assignment Date	: 24/09/2019	Excess	: S\$0.00
Date of Inspection	: 24/09/2019	Est. Duration of Repair	: 5.00
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages FRONT portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,675.27
Revised Amount	:S\$	2,290.01
Check Items (Estimated)	:S\$	221.00
Total	:S\$	2,511.01

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	44,736.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,264.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/09/2019 14:27
 Date Of Accident 21/09/2019 10:20
 Exact Location Of Accident BEDOK CENTRAL
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLE4567L
Insured/Policyholder
 Name Of Registered Owner KONG SIOW YING
 NRIC No S7327772H
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-91142468
 Alternative Phone No OTHERS-91142468
Vehicle Particulars
 Manufacturer TOYOTA
 Model SIENTA-1.5 G CVT ABS D/AIRBAG 2WD 5DR (A)
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? YES
 If No, Please state action to be taken
 Vehicle Category PRIVATE CAR
Insurance Company
 Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number DMPCSN3056841902
 Cover Note Number
Driver
 Name of Driver SIM CHOON SENG
 NRIC No S7024304J
 Date Of Birth 25/07/1970
 Occupation INDOOR
 Date Of Driving Pass 04/04/1988
 Driving Experience 31 YEARS AND 5 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-91142468
 Fax Number
 Contact Number
 Email Address EDSIM4567@GMAIL.COM



Address	121 TANJONG RHU ROAD #07-18
Postcode	436914
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : SIM YEW SIANG GENDER: : MALE
Passenger 2	NAME: : SIM YEW EN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKK2686U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ADRIAN LIM
NRIC/Passport Number	
Contact Number	94551118
Address	
Postcode	



Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

23 SEP 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

23 SEP 2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Jenny Lim
S8927273H

SKETCH PLAN

Refer to attachment.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car A unable to stop intine hit on to Car B rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.




Policyholder's Signature

Date & Time:

23 SEP 2019

© 201902, 02/09/2019/02/09/2019, v3



Driver's Signature

(if driver is not the policyholder)

Date & Time:

23 SEP 2019



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jenny Lim
S6927273H

Belvoir North Ave 3

ELK 215A
(MSP)

Beckle (curved)



A-SLE 4567 L

B-SKE 2686 U

21/5/19

10.22 am

MOTOR PRIVATE CAR
CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
 Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

DR0555P
Car Type: C
PLM 331708
ORIGINAL

CERTIFICATE No. **DMPCSN3056841902** **Engine No.** **2NR8626645**
Chassis No. **NEP1707036167**

1. **Index Mark and Registration Number of Vehicle** **SLE4567L**

2. **Name of Policy Holder** **KONG SIOW YING**

3. **Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment** **22 July 2019** **Named Drivers Ex Sect. I** **\$5500.00**
Additional Ex Other than Named Drivers:
Ex Sect. I - Age <= 25 **\$13,000.00**
Ex Sect. I - Age >= 26 **\$5500.00**
*** Age as at date of accident**
EX ON WINDSCREEN **\$8100.00**

4. **Date of Expiry of Insurance** **21 July 2020**

5. **Persons or Classes of Persons entitled to drive***

(a) **The Policyholder.**

(b) **Any other person who is driving on the Policyholder's order or with his permission.**

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use for social, domestic and pleasure purposes and for the Policyholder's business.
The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.

One time Waiver of Excess for the first \$5500 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised Workshops for each Policy Year.

HIKE PURCHASE CO. MAYBANK AS IF OWNER

** Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.*

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

Issued By:

Authorised Officer

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Authorised Signatory

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	772H
Vehicle Details	
Vehicle No.:	SLE4567L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5G CVT ABS D/AIRBAG 2WD SDR
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	2NR8626645
Chassis No.:	N5P1707036167
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$20,571.00
Original Registration Date:	22 Jul 2016
First Registration Date:	22 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$10,800.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jul 2026
PARF Rebate Amount:	\$8,100.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,694.00
COE Rebate Amount:	\$36,636.00
Total Rebate Amount:	\$44,736.00

The information contained herein is correct as at 24 Sep 2019

OK

MV = \$62k
Kenneth
29/9/19

Google's Smart Speaker

Shop Google's smallest smart speaker. Learn more about Google Home 1

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

High Loan & Trade In Management Unit! Almost New!



5 years Warranty! As Good As New!
Scented

* Free YICOM evaluation
* Free grooming and 6 months maintenance
* In-house workshop ensures quality service
* Member of SVTA and hire purchase association
* 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

« Back (1 2 3 4 5) Next »

Sort by Date Posted 20 results/page

82 vehicles

Toyota Sienta

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Sienta	Any	Any	2016	Any	Any	Any	All



Toyota Sienta 1.5A Elegance

\$70,800

\$8,660 /yr

20-Oct-2016

1,496 cc

65,047 km

MPV

Available

1 Owner, Borneo Motors 5yrs Warranty. Full Service By Agent. Very Well Kept, Superb Condition, Seeing To Believe, Easy In House Loan/Bank Loan/Trade In Available. Please Call!

Mayfair Motoring

Posted: 24-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A G

\$59,800

\$7,900 /yr

18-Aug-2016

1,496 cc

36,500 km

MPV

Available

Cheapest In The Market! Low Mileage Done! Very Well Kept Condition! No Repairs Needed! Trade In Welcome! Call Us Now For Viewing And Test Drive Before It's Gone!

Posted: 24-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A X

\$63,800

\$8,890 /yr

31-May-2016

1,496 cc

46,472 km

MPV

Available

Most Popular 1.5L MPV, Reliable And Fuel Efficient, Made And Assemble In Japan! Low Fuel Consumption, Low Monthly Repayment Available! Trade In Welcome! Flexible Bank/In House Financing Available. Hurry Call Now To Find Out More!

Benefit Auto Enterprise Pte Ltd

Posted: 24-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A G

\$62,898

\$8,570 /yr

20-Apr-2016

1,496 cc

19,999 km

MPV

Available

Reliance Anniversary Promo. Get A Free 10h Diamond Coating, In Car Camera, 3A Car Mat, 1 Year Comprehensive Warranty From MBM And Servicing Package. Bank/In House Loan With Interest From 2.48%. All Trade In Are Welcomed. Call Us Now.

Posted: 23-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Complete Bodykit Suitable For Toyota Harrier

Complete wide body

More info about this product



Toyota Sienta 1.5A G

\$62,200

\$8,480 /yr

19-Feb-2016

1,496 cc

40,000 km

MPV

Available

1 Careful Owner! Cheapest Depreciation In The Car Market! Showroom Condition! Original Toyota Paint! 100% Loan Approval! Loan Up To 95% Of Car Price! Bank/In-House Loan Available! 120 Points Check Done! STA Welcome! 6 Months Comprehensive Warranty!

Posted: 23-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A X

\$66,800

\$9,530 /yr

07-Apr-2016

1,496 cc

38,000 km

MPV

Available

Reliable And Fuel Efficient Japanese MPV! Made And Assemble In Japan! Tip Top Condition With Original Paint Work! Low Maintenance Low Fuel Consumption, Low Monthly. Trade In Welcome! Flexible Bank/In House Financing Available With Fast And Easy Loan App...

For & Credit Pte Ltd

Posted: 23-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta Hybrid 1.5A G

-

N.A

22-Mar-2016

1,496 cc

-

MPV

SOLD

Fuel Type: Petrol-Electric

Owner Consignment. Viewing By Appointment Basis Only. Come With Bidded 3 Digit Number Plate. Flexible And High Loan Available.

Shuang Hup Credit

Posted: 22-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A X

\$63,900

\$8,710 /yr

20-Jul-2016

1,496 cc

49,800 km

MPV

Available

Elegant Silver MPV, With Reverse Camera And Power Sliding Doors, Low Fuel Consumption, Low Maintenance Cost, One Owner Only, Low Mileage Done, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 21-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A X

\$63,800

\$8,690 /yr

04-Aug-2016

1,496 cc

-

MPV

Available

Hurry Before It's Sold, Depreciation Only \$8k Plus MPV, Purchase From An Award Winning Dealership! Accident-Free Quality Pre Owned With Low Mileage Done For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing. View Today!

88 Motor Trading

Posted: 21-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A X

\$63,800

\$8,690 /yr

04-Aug-2016

1,496 cc

-

MPV

Available

Full Loan Available At \$1000 Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including...

88 Motor Trading

Posted: 21-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



BlackVue DR750S Car Camera

Equipped with Sony Starvis CMOS Sensor, this blackvue full HD cloud camera gives you best image quality under any light condition. Find the list of the best cameras available, each with product information and user reviews.

Find out more!



Toyota Sienta 1.5A X

\$64,800

\$8,770 /yr

20-May-2016

1,496 cc

45,000 km

MPV

Available

Only 1 Owner, High ARF At \$12833, Original Paint From Day 1, Very Well Kept Unit, Powerful Yet Low Fuel Consumption, Make In Japan, Bank/In House Available.

Posted: 21-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A G

\$66,800

\$8,990 /yr

19-Aug-2016

1,496 cc

58,469 km

MPV

Available

Reliable And Fuel Efficient Japanese MPV! 1 Owner Unit, Low Mileage Done, Made And Assemble In Japan! Tip Top Condition, Low Maintenance Cost, Low Fuel Consumption, Low Monthly Repayment Available! Trade In Welcome! Flexible Bank/In House Financing Avail...

Posted: 21-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A G

\$65,800

\$8,990 /yr

11-Jul-2016

1,496 cc

62,076 km

MPV

Available

1 Owner Only! Well Maintained, Unit In Excellent Condition! Don't Miss This Unit! Bank Or In House Loan Available. Call For More Enquiries!

Posted: 21-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A X

\$64,800

\$8,710 /yr

02-Sep-2016

1,496 cc

-

MPV

Available

1 Owner Only. Extremely Excellent Condition. Non Private Hire Vehicle. Car Fully Done Up To Showroom Condition. Bank And In House Full Loan Available. Trade In Welcome. Kindly Contact Our Sales Advisor For Viewing.

Imperium Car Motor Pte Ltd

Posted: 21-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A G

\$67,800

\$8,810 /yr

21-Oct-2016

1,496 cc

55,139 km

MPV

Available

Special Offer Till 30 September Only. Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan And Balloon Scheme Available, No Gimmicks! 7 Seater, Keyless Entry/Start, Reverse Camera, Auto LED's Headlights, 2 x Electric Power Door, Leather Seats, L...

Posted: 20-Sep-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



1 Owner, High Loan Applicable Here Must Call For Discussions, Most Popular 1.5L MPV 7 Seaters, Low Mileage Done, Trade In Welcome. Very Well Taken Care Whole Car Conditions, Buy With A Peace Of Mind From A Good Accredited Company. Hurry Call For Availa...

Benefit Auto Enterprise Pte Ltd

Posted: 20-Sep-2019 Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A X **\$66,800** **\$9,080 /yr** **25-Aug-2016** **1,496 cc** **70,858 km** **MPV** **Available**

Special Offer Till 30 September Only. Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan And Balloon Scheme Available. No Gimmicks! 7 Seater MPV, Keyless Entry/Start, Reverse Camera, Electric Power Door, Leather Seats, Low Fuel Consumption,...

Posted: 19-Sep-2019 Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A G **-** **N/A** **18-Jul-2016** **1,496 cc** **-** **MPV** **SOLD**

Consignment Code: A387 Flexible And Attractive Loan Available. Trade In Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

Consignment

Posted: 18-Sep-2019 Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A X **\$65,800** **\$8,980 /yr** **04-Aug-2016** **1,496 cc** **70,000 km** **MPV** **Available**

1 Owner! Tip Top Condition. Maintained And Serviced Regularly. Will Be Changing To Leather Seats. Easy And Flexible In House Loan.

Viking Motor Pte Ltd

Posted: 18-Sep-2019 Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A X **\$65,800** **\$8,930 /yr** **25-Aug-2016** **1,496 cc** **43,512 km** **MPV** **Available**

100% Loan Easily Can Be Arrange, Blue Color, Reliable And Fuel Efficient Japanese MPV! Made And Assemble In Japan! Low Fuel Consumption, Low Monthly Repayment Available! Trade In Welcome! Flexible Bank/In-House Financing Available With Fast And Easy Lo...

Premium

Benefit Auto Enterprise Pte Ltd

Posted: 17-Sep-2019 Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

« Back (1 2 3 4 5) Next »

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Sienta, Toyota Sienta Singapore, used Toyota Sienta Singapore, used Toyota Sienta, used vehicles Singapore or even buy used Toyota Sienta Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

Compare

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMPCSN3056841902

Repairer Reference: 70885

Date calculated: 23/09/2019 5:08 PM

Summary Information

Full Report

Registration: SLE 4567L

Printed: 23/09/2019 5:08 PM

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMPCSN3056841902	Date of Incident:	21/09/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: TOYOTA
 Model: SIENTA
 Sub Model: G
 Model Sheet Number: 70 T2 05
 Registration: SLE 4567L
 VIN number:
 Odometer: 89532

Model Specs

FROM 07/2016 AIR CONDITIONING FOG LAMPS 1.5 LTR 79 KW
 CVT AUTOMATIC TWO COAT METALLIC PREPARE OFF VEHICLE



Not Authentic
Rehany Bypoint
5 days

Fax: 62564315

Labour

Code	Description	Time Base 10 WU/h	Price = 48.00 SGD/h	
			WU	Price SGD
B040	ADJUST HEADLAMPS		2.0	9.60/
B100	R + R LEFT FRONT WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R		4.0	19.20
B100	R + R RIGHT FRONT WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R		4.0	19.20
NO NUMBER	R + R R/AIR CHANNEL		1.0	4.80/
B010	R + R FRONT BUMPER		5.0	24.00/
B020)	RENEW FRONT BUMPER (REMOVED) INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		4.0	19.20/
B010)	R + R FRONT BUMPER REINFORCEMENT		3.0	14.40/
B040)	R + R LEFT HEADLAMP		1.0	4.80
B040)	R + R RIGHT HEADLAMP		1.0	4.80/
B040)	RENEW HEADLAMP		1.0	4.80/
530051	RENEW BONNET INCLUDES: ASS ATTACHED PARTS AND IF NECE		3.0	14.40

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMPCSN3056841902

Repairer Reference: 70885

Date calculated: 23/09/2019 5:08 PM

Code Description

B080 RENEW
 B125 RENEW BONNET HINGE/S
 B085 RENEW FRONT LOCK CARRIER
 0742 R + R AIR GRILLE
 0993 R/F WING REPAIR
 0994 L/UPP RADIATOR BRKT REPAIR
 0994 R/UPP RADIATOR BRKT REPAIR

Full Report
 Registration: SLE 4567L
 Printed: 23/09/2019 5:08 PM

WU Price SGD

2 9.60
 2 1.0 4.80
 5.0 24.00/
 2.0 9.60
 5 10.0* 48.00 29/
 5 10.0* 48.00 29/
 10 15.0* 72.00

Labour Cost

Panel / Mechanical Labour

Hrs WU Price SGD
 7.20 72.0 345.60

Total of Labour

345.60

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	12.0	
	FRT LOCK CARRIER SURFACE PAINT	4.0	
	R/F WING REPAIR PAINTING <50%	10.0	
	L/F WING SURFACE PAINT	5.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	28.90/ 2.49/ 10.66/ 8.22/
1017	FRT LOCK CARRIER SURFACE PAINT	
0742	R/F WING REPAIR PAINTING <50%	
0741	L/F WING SURFACE PAINT	

Labour Cost - Paint

Factor

Time Paint

Preparation Main Work Metal

Total

Hrs	WU	Price SGD
48.00 SGD/h	31.0	
2.50	25.0	120.00/
10 WU/h	5.60	268.80/

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date:

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMPCSN3056841902

Repairer Reference: 70885

Date calculated: 23/09/2019 5:08 PM

Full Report

Registration: SLE 4567L

Printed: 23/09/2019 5:08 PM

Material Cost - Paint

New Part Painting

Repair Painting

Surface-/Blend Paint

Material-constant Metal Preparation

Total

Price SGD

28.90 /

10.66 /

10.71 /

28.60 /

78.87 /

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Supplier	Price SGD	
0257	FRONT NUMBER PLATE	KNPL3		Reported 0.00	X
0281	FRONT BUMPER	52119 5A956		130.00	—
0341	FRT CTR UPP BRACKET	52521 52050		45.00	✓
0410	GRILLE	53101 52460		240.00	—
0471	BONNET	53301 52390		240.00	—
0474	FRONT BONNET SEAL	53395 52080		18.00	—
0475	L/BONNET HINGE	53420 52431		28.00	X
0476	R/BONNET HINGE	53410 52421		28.00	X
0562	RIGHT HEADLAMP ASSY	81130 52K20		1,000.00	✓
1017	FRT LOCK CARRIER	53205 52190		100.00	✓
1192	R/F AIR DUCT	53285 52500		18.00	✓
				Savings	0.00
				Subtotal	2006 1,847.00
				Fixed Sundry Parts Price	100.00
				Total	1,947.00

f: OEM Parts

n: Non-OEM Parts

u: Used parts

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE SN	35.00*
Total Extras		35.00

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMPCSN3056841902

Repairer Reference: 70885

Date calculated: 23/09/2019 5:08 PM

Full Report

Registration: SLE 4567L

Printed: 23/09/2019 5:08 PM

Final Calculation

	SGD	SGD
Parts	1,847.00	
Fixed Sundry Parts Price	100.00	
Total Parts		1,947.00
Labour Time Base 10 WU/h		
Total 72.0 WU X 48.00 SGD/h	249.60 ✓ 345.60	
Total of Labour		345.60
Total Of Extras		35.00
Paint Work Time Base 10 WU/h		
Labour Cost 56.0 WU X 48.00 SGD/h	268.80 ✓	
Material Cost	278.87 ✓	
Total Paint Including Material		347.67
Repair Cost Excludes GST		2,675.27
GST (+7.0%)		187.27
Repair Cost Included GST		2,862.54

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: 19/4477/OD
Repaier Reference: 70885
Date calculated: 25/09/2019 10:09 AM
Summary Information

Full Report
Registration: SLE 4567L
Printed: 25/09/2019 10:10 AM

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	19/4477/OD	Date of Incident:	21/09/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	SIENTA
Sub Model:	G
Model Sheet Number:	70 T2 05
Registration:	SLE 4567L
VIN number:	
Odometer:	89532

Model Specs

FROM 07/2016	AIR CONDITIONING	FOG LAMPS	1.5 LTR 79 KW
CVT AUTOMATIC	TWO COAT METALLIC	PREPARE OFF VEHICLE	


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: 19/4477/OD
 Repairer Reference: 70885
 Date calculated: 25/09/2019 10:09 AM

Full Report
 Registration: SLE 4567L
 Printed: 25/09/2019 10:10 AM

Labour

Code	Description	Time Base 10 WU/h	Price = 48.00 SGD/h	
			WU	Price SGD
B040	ADJUST HEADLAMPS		2.0	9.60
NO NUMBER	R + R R/AIR CHANNEL		1.0	4.80
B010	R + R FRONT BUMPER		5.0	24.00
B020)	RENEW FRONT BUMPER (REMOVED)		4.0	19.20
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT			
B010)	R + R FRONT BUMPER REINFORCEMENT		3.0	14.40
B040)	R + R RIGHT HEADLAMP		1.0	4.80
B040)	RENEW HEADLAMP		1.0	4.80
530051	RENEW BONNET		3.0	14.40
	INCLUDES: ASS ATTACHED PARTS AND IF NECE RENEW			
B125	RENEW FRONT LOCK CARRIER		5.0	24.00
0341	FRT CTR UPP BRACKET CHECK			
0475	L/BONNET HINGE CHECK			
0476	R/BONNET HINGE CHECK			
0993	L/UPP RADIATOR BRKT CHECK			
0994	R/UPP RADIATOR BRKT CHECK			
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		2.50	25.0	120.00
Total of Labour				120.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	BONNET NEW PART PAINTING		12.0	
	FRT LOCK CARRIER SURFACE PAINT		4.0	
	L/F WING SURFACE PAINT		5.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	28.90
1017	FRT LOCK CARRIER SURFACE PAINT	2.49
0741	L/F WING SURFACE PAINT	8.22

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: 19/4477/OD
 Repairer Reference: 70885
 Date calculated: 25/09/2019 10:09 AM

Full Report
 Registration: SLE 4567L
 Printed: 25/09/2019 10:10 AM

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	48.00 SGD/h			
Time Paint			21.0	
Preparation Main Work Metal		2.50	25.0	120.00
Total	10 WU/h	4.60	46.0	220.80

Material Cost - Paint		Price SGD
New Part Painting		28.90
Surface-/Blend Paint		10.71
Material-constant Metal Preparation		28.60
Total		68.21

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0281	FRONT BUMPER	52119 5A956		130.00
0410	GRILLE	53101 52460		240.00
0471	BONNET	53301 52390		240.00
0474	FRONT BONNET SEAL	53395 52080		18.00
0562	RIGHT HEADLAMP ASSY	81130 52K20		1,000.00
1017	FRT LOCK CARRIER	53205 52190		100.00
1192	R/F AIR DUCT	53285 52500		18.00
f: OEM Parts				
n: Non-OEM Parts				
u: Used parts				
Savings				0.00
Subtotal				1,746.00
Fixed Sundry Parts Price				100.00
Total				1,846.00

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE SN	35.00*
Total Extras		35.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: 19/4477/OD
Repairer Reference: 70885
Date calculated: 25/09/2019 10:09 AM

Full Report
Registration: SLE 4567L
Printed: 25/09/2019 10:10 AM

Final Calculation

	SGD	SGD
Parts	1,746.00	
Fixed Sundry Parts Price	100.00	
Total Parts		1,846.00
Labour Time Base 10 WU/h		
Total 25.0 WU X 48.00 SGD/h	120.00	
Total of Labour		120.00
Total Of Extras		35.00
Paint Work Time Base 10 WU/h		
Labour Cost 46.0 WU X 48.00 SGD/h	220.80	
Material Cost	68.21	
Total Paint Including Material		289.01
Repair Cost Excludes GST		2,290.01
GST (+7.0%)		160.30
Repair Cost Included GST		2,450.31

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: DMPCSN3056841902
Repairer Reference: 70885
Date calculated: 16/12/2019 4:47 PM

Full Report
Registration: SLE 4567L
Printed: 16/12/2019 4:50 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	DMPCSN3056841902	Date of Incident:	21/09/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	SIENTA
Sub Model:	G
Model Sheet Number:	70 T2 05
Registration:	SLE 4567L
VIN number:	
Odometer:	89532

Model Specs

FROM 07/2016	AIR CONDITIONING	FOG LAMPS	1.5 LTR 79 KW
CVT AUTOMATIC	TWO COAT METALLIC	PREPARE OFF VEHICLE	


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 48.00 SGD/h	
			WU	Price SGD
B040	ADJUST HEADLAMPS		2.0	9.60
NO NUMBER	R + R R/AIR CHANNEL		1.0	4.80
NO NUMBER	R + R BONNET LOCK BRKT		2.0	9.60
B010	R + R FRONT BUMPER		5.0	24.00
B020)	RENEW FRONT BUMPER (REMOVED)		4.0	19.20
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT			
B010)	R + R FRONT BUMPER REINFORCEMENT		3.0	14.40
B040)	R + R RIGHT HEADLAMP		1.0	4.80
B040)	RENEW HEADLAMP		1.0	4.80
NO NUMBER	R + R RADIATOR SHROUD		1.0	4.80
530051	RENEW BONNET		3.0	14.40
	INCLUDES: ASS ATTACHED PARTS AND IF NECE RENEW			
B125	RENEW FRONT LOCK CARRIER		5.0	24.00
0475	L/BONNET HINGE REPAIR		2.0*	9.60
0476	R/BONNET HINGE REPAIR		2.0*	9.60
0742	R/F WING REPAIR		5.0*	24.00
0993	L/UPP RADIATOR BRKT REPAIR		5.0*	24.00
0994	R/UPP RADIATOR BRKT REPAIR		10.0*	48.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		5.20	52.0	249.60
Total of Labour				249.60

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	BONNET NEW PART PAINTING		12.0	
	FRT LOCK CARRIER SURFACE PAINT		4.0	
	R/F WING REPAIR PAINTING <50%		10.0	
	L/F WING SURFACE PAINT		5.0	

Paint Material Per Part

Code	Description	Price SGD		
0471	BONNET NEW PART PAINTING			28.90
1017	FRT LOCK CARRIER SURFACE PAINT			2.49
0742	R/F WING REPAIR PAINTING <50%			10.66
0741	L/F WING SURFACE PAINT			8.22
Labour Cost - Paint		Hrs	WU	Price SGD
Factor				48.00 SGD/h
Time Paint			31.0	
Preparation Main Work Metal		2.50	25.0	120.00
Total		5.60	56.0	268.80

Material Cost - Paint

New Part Painting	28.90
Repair Painting	10.66
Surface-/Blend Paint	10.71
Material-constant Metal Preparation	28.60
Total	78.87

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	KNPL3		0.00
0281	FRONT BUMPER	52119 5A956		130.00
0341	FRT CTR UPP BRACKET	52521 52050		45.00
0410	GRILLE	53101 52460		240.00
0471	BONNET	53301 52390		240.00
0474	FRONT BONNET SEAL	53395 52080		18.00
0493	BONNET LOCK	53510 0D640		55.00
0494	BONNET LOCK BRACKET	53208 52904		45.00
0562	RIGHT HEADLAMP ASSY	81130 52K20		1,000.00
1015	UPP RADIATOR COVER	53289 52100		60.00
1017	FRT LOCK CARRIER	53205 52190		100.00
1192	R/F AIR DUCT	53285 52500		18.00
4448	CONDENSER FIX FRAME	88891 0D370		55.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,006.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			2,106.00

Extras

Code	Description	Price SGD
1001	FRONT NUMBER PLATE	35.00*
	Total Extras	35.00

Final Calculation

	SGD	SGD
Parts	2,006.00	
Fixed Sundry Parts Price	100.00	
Total Parts		2,106.00
Labour Time Base 10 WU/h		
Total 52.0 WU X 48.00 SGD/h	249.60	
Total of Labour		249.60
Total Of Extras		35.00
Paint Work Time Base 10 WU/h		
Labour Cost 56.0 WU X 48.00 SGD/h	268.80	
Material Cost	78.87	
Total Paint Including Material		347.67
Repair Cost Excludes GST		2,738.27
GST (+7.0%)		191.68
Repair Cost Included GST		2,929.95

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	70886
Policy No:	DMPCSN3056841902	Date of Loss:	21/09/2019
Vehicle Reg. No.:	SLE4567L	Driveable?	
Driver Age/Info:	49 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KONG SIOW YING		
Driver:	SIM CHOON SENG		
Make/Model:	TOYOTA SIENTA, 1.5 G CVT ABS D/AIRBAG 2WD 5DR (A)	Vehicle Reg. Date:	22/07/2016
Vehicle Colour:	SILVER		
Engine No:	2NR8626645	Chassis No:	NSP1707036167
Odometer:	89532 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	215.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	215.00
+ GST 7.00% (S\$)	15.05
Nett Amount (S\$)	230.05
+ Previous Estimates (S\$)	2,862.54
Claim Total (S\$)	3,092.59

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2019)

Parts: M1-MPV TOYOTA SIENTA 1.5 G CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SLE4567L/29/11/2019 17:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CONDENSER FIX FRAME	0.00	0.00	<i>Nil</i> *55.00 F -
2	1		*UPP RADIATOR COVER	0.00	0.00	<i>Nil</i> *60.00 F -
3	1		*BONNET LOCK	0.00	0.00	<i>Nil</i> *55.00 F -
4	1		*BONNET LOCK BRACKET	0.00	0.00	<i>Nil</i> *45.00 F -

F=Franchise part.

Total Parts (S\$)

215.00

Lai Huat (Meng Kee) Motor Pte Ltd/SLE4567L/29/11/2019 17:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lai Huat (Meng Kee) Motor Pte Ltd/SLE4567L/29/11/2019 17:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMPCSN3056841902
Repairer Reference: 70885
Date calculated: 29/11/2019 5:24 PM

Full Report
Registration: SLE 4567L
Printed: 29/11/2019 5:24 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMPCSN3056841902	Date of Incident:	21/09/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	SIENTA		
Sub Model:	G		
Model Sheet Number:	70 T2 05		
Registration:	SLE 4567L		
VIN number:			
Odometer:	89532		
Model Specs			
FROM 07/2016	AIR CONDITIONING	FOG LAMPS	1.5 LTR 79 KW
CVT AUTOMATIC	TWO COAT METALLIC	PREPARE OFF VEHICLE	

Labour

Code	Description	Time Base 10 WU/h	Price = 48.00 SGD/h	
			WU	Price SGD
B040	ADJUST HEADLAMPS		2.0	9.60
NO NUMBER	R + R R/AIR CHANNEL		1.0	4.80
NO NUMBER	R + R BONNET LOCK BRKT		2.0	9.60
B010	R + R FRONT BUMPER		5.0	24.00
B020)	RENEW FRONT BUMPER (REMOVED)		4.0	19.20
	INCLUDES: REQUIRED ATTACHED PARTS			
	REMOVE AND REFIT			
B010)	R + R FRONT BUMPER REINFORCEMENT		3.0	14.40
B040)	R + R RIGHT HEADLAMP		1.0	4.80
B040)	RENEW HEADLAMP		1.0	4.80
NO NUMBER	R + R RADIATOR SHROUD		1.0	4.80
530051	RENEW BONNET		3.0	14.40
	INCLUDES: ASS ATTACHED PARTS AND IF NECE			
	RENEW			
B125	RENEW FRONT LOCK CARRIER		5.0	24.00
0475	L/BONNET HINGE REPAIR		2.0*	9.60
0476	R/BONNET HINGE REPAIR		2.0*	9.60
0742	R/F WING REPAIR		5.0*	24.00
0993	L/UPP RADIATOR BRKT REPAIR		5.0*	24.00

Code	Description	WU	Price SGD
0994	R/UPP RADIATOR BRKT REPAIR	10.0*	48.00
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	5.20	52.0
	Total of Labour		249.60

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	12.0	
	FRT LOCK CARRIER SURFACE PAINT	4.0	
	R/F WING REPAIR PAINTING <50%	10.0	
	L/F WING SURFACE PAINT	5.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	28.90
1017	FRT LOCK CARRIER SURFACE PAINT	2.49
0742	R/F WING REPAIR PAINTING <50%	10.66
0741	L/F WING SURFACE PAINT	8.22

Labour Cost - Paint

	Factor	48.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			31.0	
	Preparation Main Work Metal		2.50	25.0	120.00
Total		10 WU/h	5.60	56.0	268.80

Material Cost - Paint

	Price SGD
New Part Painting	28.90
Repair Painting	10.66
Surface-/Blend Paint	10.71
Material-constant Metal Preparation	28.60
Total	78.87

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0257	FRONT NUMBER PLATE	KNPL3			0.00
0281	FRONT BUMPER	52119 5A956			130.00
0341	FRT CTR UPP BRACKET	52521 52050			45.00
0410	GRILLE	53101 52460			240.00
0471	BONNET	53301 52390			240.00
0474	FRONT BONNET SEAL	53395 52080			18.00
0493	BONNET LOCK	53510 0D640			55.00
0494	BONNET LOCK BRACKET	53208 52904			45.00
0562	RIGHT HEADLAMP ASSY	81130 52K20			1,000.00

Code	Description	Part Number	Supplier	Price SGD
1015	UPP RADIATOR COVER	53289 52100		60.00
1017	FRT LOCK CARRIER	53205 52190		100.00
1192	R/F AIR DUCT	53285 52500		18.00
4448	CONDENSER FIX FRAME	88891 0D370		55.00

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	2,006.00
u: Used parts	Fixed Sundry Parts Price	100.00
	Total	2,106.00

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE SN	35.00*
	Total Extras	35.00

Final Calculation

	SGD	SGD
Parts	2,006.00	
Fixed Sundry Parts Price	100.00	
Total Parts		2,106.00
Labour Time Base 10 WU/h		
Total 52.0 WU X 48.00 SGD/h	249.60	
Total of Labour		249.60
Total Of Extras		35.00
Paint Work Time Base 10 WU/h		
Labour Cost 56.0 WU X 48.00 SGD/h	268.80	
Material Cost	78.87	
Total Paint Including Material		347.67
Repair Cost Excludes GST		2,738.27
GST (+7.0%)		191.68
Repair Cost Included GST		2,929.95

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347483
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949632
Fax: 62982158, 62942354, 62935021
Email: ftrprnet@mbx3.singnet.com.sg
RCB Reg No.: 188301435F

ICE TO: LAI HUAT (MENG KEE) MOTOR PTE LTD
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426689 62949632 67479292
67426678 62985333 67455824

MAZDA
TEL: 62954551
67495954

HONDA/HYUNDAI DIV
TEL: 62970688 64542288
67493588

MAZDA/FORD DIV
TEL: 62935722
67420366

AIRCON/W/S GLASS
TEL: 62952336
67495997

AUTHORISED STOCKISTS:

NISSAN **TOYOTA** **OPEL**
Genuine Parts GENUINE PARTS GENUINE PARTS

MAZDA **FORD** **HYUNDAI**
Genuine Parts GENUINE PARTS GENUINE PARTS

TAX INVOICE
TAX INVOICE NO.: CL404657
INVOICE DATE : 24/09/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 1

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
T53301-52390		1 PCS	240.000	✓	240.00 ✓
T53420-52430		1	20.000		20.00
T53410-52420		1	20.000		20.00
T53205-52190		1 PCS	100.000	✓	100.00 ✓
T81130-52K30		1 PCS	1000.000	✓	1000.00 ✓
T52119-5A951		1	130.000	✓	130.00 ✓
T53101-52460		1	240.000	✓	240.00 ✓
T53395-52080		1	18.000	✓	18.00 ✓
T52521-52050		1	45.000	✓	45.00 ✓
T53285-52500		1	18.000	✓	18.00 ✓

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

RISED SIGNATURE

10/05

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347483
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949632
Fax: 62982158, 62942354, 62935021
Email: ftrprnet@mbx3.singnet.com.sg
RCB Reg No.: 188301435F

ICE TO: LAI HUAT (MENG KEE) MOTOR PTE LTD
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426689 62949632 67479292
67426678 62985333 67455824

MAZDA
TEL: 62954551
67495954

HONDA/HYUNDAI DIV
TEL: 62970688 64542288
67493588

MAZDA/FORD DIV
TEL: 62935722
67420366

AIRCON/W/S GLASS
TEL: 62952336
67495997

AUTHORISED STOCKISTS:

NISSAN **TOYOTA** **OPEL**
Genuine Parts GENUINE PARTS GENUINE PARTS

MAZDA **FORD** **HYUNDAI**
Genuine Parts GENUINE PARTS GENUINE PARTS

TAX INVOICE
TAX INVOICE NO.: CL404657
INVOICE DATE : 24/09/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 2

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
SLE4567L (NSP170) VICTOR					
			GST Excl Amount :		1847.00
			Special Discount :		
			GST @ 7 % :		129.29

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

1976.29

PRINT BY :
YKN 24/09/2019 09:04:50

豐達汽車私人有限公司 FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62905021
Email: ftrpnet@ntbox3.singnet.com.sg
RCB Reg No.: 196301433R

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426689 62949832 67479292
67426678 62985333 67455824

MAZDA/FORD DIV
TEL: 62935722
67420368

HYUNDAI DIV
TEL: 62970688 64542268
67493588

MAZDA/FORD DIV
TEL: 62935722
67420368

AIRCON/W/S GLASS
TEL: 62952336
67490997

TAX INVOICE

TAX INVOICE NO.: CL404694
INVOICE DATE : 24/09/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 1



ICE TO LAI HUAT (MENG KEE) MOTOR PTE LTD
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
T53208-52904		1	45.000	45.000	45.00 ✓
T88891-52110		1	55.000	55.000	55.00 ✓
T53289-52100		1	60.000	60.000	60.00 ✓
T00467-07316		4	1.000	4.000	4.00
T52161-16010		6	1.500	9.000	9.00
T53510-52620		1 PCS	55.000	55.000	55.00 ✓

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

RISED SIGNATURE

SIGNATURE

2:10

豐達汽車私人有限公司 FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62905021
Email: ftrpnet@ntbox3.singnet.com.sg
RCB Reg No.: 196301433R

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426689 62949832 67479292
67426678 62985333 67455824

MAZDA/FORD DIV
TEL: 62935722
67420368

HYUNDAI DIV
TEL: 62970688 64542268
67493588

MAZDA/FORD DIV
TEL: 62935722
67420368

AIRCON/W/S GLASS
TEL: 62952336
67490997

TAX INVOICE

TAX INVOICE NO.: CL404694
INVOICE DATE : 24/09/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 2



ICE TO LAI HUAT (MENG KEE) MOTOR PTE LTD
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
SLE4567L (NSP170) VICTOR					
			GST Excl Amount :		228.00
			Special Discount :		
			GST @ 7 % :		15.96

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

243.96

PRINT BY :
YKN 24/09/2019 13:48:34

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2019 Sendback Est	23 Sep 2019 17:20 \$52,675.27	24 Sep 2019 10:49 Edit Adj Rpt	\$52,738.27 Edit Estimates	\$52,738.27 View Rpt		Pending for Survey Report Cancel Case
	29 Nov 2019 17:25	29 Nov 2019 17:25 \$5215.00	29 Nov 2019 17:25			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	KONG SIOW YING, ID: S7327772H		
Vehicle Reg. No.:	SLE4567L	Date of Loss:	21/09/2019 10:00 - :59 {37 Months and 30 Days From LTA Reg Date (Man Yr)}
Claim Type:	OD / SNM19D204477-SLE4567L-TKL	Policy/Cover Note No.:	DMPCSN3056841902 (Comprehensive)
		Excess:	\$0.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/10/2019]		
Driver/Custodian:	SIM CHOON SENG (49 / Male), NRIC: S7024304J, Tel: +6591142468 Email: Edsim4567@gmail.com		

ASSOCIATED MAIL RECEIVED

View All | Compose Case Mail

- CHINA_TAIPING (19/12/2019): Alert - Adj Mandate Approved (\$2738.27) - SLE4567L - Claim Handler: Chong Boon ...
- CHINA_TAIPING (26/09/2019): Alert - Adj Mandate Approved (\$2511.01) - SLE4567L - Claim Handler: Chong Boon ...

ALL ASSOCIATED TASKS

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLE4567L (SNM19D204477-SLE4567L-TKL)

OD

Sep 21 2019 10:00AM

[KONG SIOW YING]

Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	23/09/19 17:20	Repairer Estimates	1	Load HTM	
2	29/11/19 17:25	Repairer Estimates Suppl. #1	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/09/19 15:12	Adjuster Immediate Advice	1	Load HTM	
2	16/12/19 17:27	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	23/09/19 16:05	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
2	23/09/19 16:05	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
3	23/09/19 16:05	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
4	23/09/19 16:05	Chassis Number [Linked Accident Report Documents]	1	Load JPG	☒
5	23/09/19 16:05	TP Damaged Photo [Linked Accident Report Documents]	1	Load JPG	☒
6	23/09/19 16:05	TP Damaged Photo [Linked Accident Report Documents]	1	Load JPG	☒
7	23/09/19 16:05	TP Damaged Photo [Linked Accident Report Documents]	1	Load JPG	☒
8	23/09/19 16:05	TP Damaged Photo [Linked Accident Report Documents]	1	Load JPG	☒
9	23/09/19 16:05	TP Damaged Photo [Linked Accident Report Documents]	1	Load JPG	☒
10	23/09/19 17:18	Front View	1	Load JPG	☒
11	23/09/19 17:18	Front View Right	1	Load JPG	☒
12	23/09/19 17:18	Front View Left	1	Load JPG	☒
13	23/09/19 17:18	Chassis Number	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/09/19 12:05	General View	1	Load JPG	☒
2	25/09/19 12:05	General View	1	Load JPG	☒
3	25/09/19 12:05	General View	1	Load JPG	☒
4	25/09/19 12:05	General View	1	Load JPG	☒
5	25/09/19 12:05	General View	1	Load JPG	☒
6	25/09/19 12:05	General View	1	Load JPG	☒
7	25/09/19 12:05	General View	1	Load JPG	☒
8	25/09/19 12:05	General View	1	Load JPG	☒
9	25/09/19 12:05	General View	1	Load JPG	☒
10	25/09/19 12:05	General View	1	Load JPG	☒
11	25/09/19 12:05	General View	1	Load JPG	☒
12	25/09/19 12:05	General View	1	Load JPG	☒
13	25/09/19 12:05	General View	1	Load JPG	☒
14	25/09/19 12:05	General View	1	Load JPG	☒
15	25/09/19 12:05	General View	1	Load JPG	☒
16	25/09/19 12:05	General View	1	Load JPG	☒
17	25/09/19 12:05	General View	1	Load JPG	☒
18	25/09/19 12:05	General View	1	Load JPG	☒
19	25/09/19 12:05	General View	1	Load JPG	☒
20	16/12/19 17:49	Reinspection Photo	1	Load PDF	
21	16/12/19 17:52	Reinspection Photo	1	Load PDF	

Assessment Reports				1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
Documentation				1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	23/09/19 16:03	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	23/09/19 16:04	Sketch [Linked Accident Report Documents]		Load TIF	
3	23/09/19 16:04	Owner's NRIC; Driver's NRIC & Driving Licence [Linked Accident Report Documents]		Load TIF	
4	23/09/19 16:04	Certificate of Insurance [Linked Accident Report Documents]		Load TIF	
5	23/09/19 17:18	E-filed GIA report		Load PDF	
6	23/09/19 17:18	Driver's NRIC & Driving Licence		Load PDF	
7	23/09/19 17:18	Certificate of Insurance		Load PDF	
8	23/09/19 17:18	Enquire PARF / COE Rebate for Registered Vehicle		Load PDF	
9	24/09/19 09:27	Audatex Report		Load PDF	
10	29/11/19 17:34	Supplier's Bill		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/09/19 10:16	audatex adjustment		Load PDF	
2	25/09/19 11:48	ESTIMATE MARKING		Load PDF	
3	25/09/19 11:48	ADJUST SLE4567L		Load PDF	
4	16/12/19 17:04	SUPP		Load PDF	
5	16/12/19 17:05	AUTOTEX		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	06/12/19 18:53	Accident Statement		Load HTM	
2	06/12/19 18:53	Accident Statement		Load HTM	
3	06/12/19 18:56	Accident Statement		Load HTM	
4	06/12/19 18:56	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	23/09/19 16:05	Accident Photo		Load JPG	☒
2	23/09/19 16:05	Accident Photo		Load JPG	☒
3	23/09/19 16:05	Accident Photo		Load JPG	☒
4	23/09/19 16:05	Chassis Number		Load JPG	☒
5	23/09/19 16:05	TP Damaged Photo		Load JPG	☒
6	23/09/19 16:05	TP Damaged Photo		Load JPG	☒
7	23/09/19 16:05	TP Damaged Photo		Load JPG	☒
8	23/09/19 16:05	TP Damaged Photo		Load JPG	☒
9	23/09/19 16:05	TP Damaged Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	23/09/19 16:03	Sketch Plan		Load TIF	
2	23/09/19 16:04	Sketch		Load TIF	
3	23/09/19 16:04	Owner's NRIC; Driver's NRIC & Driving Licence		Load TIF	
4	23/09/19 16:04	Certificate of Insurance		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119016801/KYF3E2

Date: 09/01/2020

REFERENCE

Insured/Claimant: KONG SIOW YING Policy No: DMPCSN3056841902

Date of Loss: 21/09/2019

Nature of Claim: OD

Claim No: SNM19D204477-SLE4567L-TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE4567L		
Make & Model:	TOYOTA SIENTA, 1.5 G CVT ABS D/AIRBAG 2WD 5DR (A)	Engine No:	2NR8626645
Reg. Date:	22/07/2016 (Man. Year: 2016)	Chassis No:	NSP1707036167
Colour:	Metallic Silver	Odometer:	89538 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$62,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50Z R16	Rear Tyre Size:	205/50Z R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 3 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,062.00	2,006.00	56.00	2.72
Miscellaneous Items	135.00	135.00	0.00	0.00
Labour	345.60	249.60	96.00	27.78
Paintwork Labour	347.67	347.67	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,890.27	2,738.27	152.00	5.26
+ GST 7.00/7.00% (S\$)	202.32	191.68	10.64	5.26
Nett Amount (S\$)	3,092.59	2,929.95	162.64	5.26

INSPECTION

Date of Assignment:	24/09/2019 Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	24/09/2019 Inspected At:	160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2020)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 G CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE4567L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		1,847.00 F	*1,791.00 F
Supplementary #1						
2	1		*CONDENSER FIX FRAME	Distorted	55.00 F	*55.00 F
3	1		*UPP RADIATOR COVER	Dented	60.00 F	*60.00 F
4	1		*BONNET LOCK	Distorted	55.00 F	*55.00 F
5	1		*BONNET LOCK BRACKET	Bent	45.00 F	*45.00 F
F=Franchise part.						
Total Parts (S\$)					2,062.00	2,006.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Front number plate (BENT)	35.00	35.00
2	1	Sundry Parts (NECESSARY)	100.00	100.00
Sub Total (S\$)			135.00	135.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Including Material	New	347.67	347.67
Labour Items				
2	Total of Labour	New	345.60	249.60
Gross Labour Cost (S\$)			693.27	597.27

Report was unsubmitted during this print-out.

< END OF ESTIMATES >