

ASS. REC. BY:

REF: CS/CT19016607/Avf307

Special Instruction:

Survivor: Adrian

ASSIGNMENT (Office)

From (Person): Elaine cheng of CTC Date/Time: 22.9.19 17.24p.m

Estimated Cost: Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: GBT1 629G Insured:

at Workshop m/s Stk Auto (S) Pte Ltd Tel: 81517426 | 6386 0669

of 8 Kaki Bukit Ave 4 #03-21

Policy No: DMCRV6 1826881901 Claim No: SNM19D 20442601

Sum Insured: Excess: \$350.00

Make of Veh: D.O.A. 18.9.19

(Client's Record)

CA / REV REP. / REV 24 HRS

Date/Time: 24.9.19 11.00a.m Person Contacted: Ah Hua Vehicle: IN/OUT

H.O.D. Endorsement:

Date/Time Action/Instruction (✓) Estimate

GBT1 629G - CS3/CT19016607/Act5 D on 18/09/2019

25/9/19 @ 1023am Linda agree LS \$30000p

25/9/19 Revert via merimen

25/9/19 Recd approved \$30,000 from Alfred by merimen

25/9/19 Informed Linda Guo Hua c/A on LS repair ex \$350 by email

30/9/19 @ 4pm Spoken to Alfred repaired, request IB1, he said ok need B4

paint

30/9/19 @ 401pm spoken to Linda IB1, to arrange B4 paint

16/10/19 @ 1234pm Spoken to Linda repair limit still at \$30000p

12/11/19 LS \$30,000 confirmed by email (Ref T1, 848.55, 70b)

RECEIVED 12 NOV 2019

GBH6629G.

2018 August

Nissan NV350
white

2488

JN1MC2E26Z0030469.

195RISC

195RISC

SS ☒ EXNOVA / GY / FS / LCA / MIC / CATSUI / RIR / SUM
TOYO / YOKO

Front

Rear

RER

RER

LBR

LBR

D/C

D/C

Surveys needed

STK.

Car is Damaged ☒ Front ☒ Rear ☒ N/S / W / Roof /

Tire / W / Chassis frame / Body Structure affected yes or no

China.

MV 551K
PV 24.3K
Nett 30.7K

12/11 - typist

21

2

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2019		23 Sep 2019 17:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	M/S GOODWILL ENTERTAINMENT HOLDING PTE LTD, Co. Reg. No.: -								
Vehicle Reg. No.:	GBH6629G	Date of Loss:	18/09/2019 19:00 - :59						
Claim Type:	OD / SNM19D204426C01	Policy/Cover Note No.:	DMCVSN1826881901 (Comprehensive)						
		Excess:	S\$350.00						
Repairer:	Stk Auto (s) Pte Ltd (HQ) 8 kaki bukit ave4, #03-21, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/10/2019]								
Driver/Custodian:	GAO FUZE (36 / Male), NRIC: G3211540W, Tel: +6582929699 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***GBH6629G (SNM19D204426C01)**

OD

Sep 18 2019 7:00PM

[M/S GOODWILL ENTERTAINMENT HOLDING PTE LTD]

Stk Auto (s) Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 18/10/2019 11:36 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$30000.00) - GBH6629G - Claim Handler: Elaine Cheong

Approved:30000.00;Proceed to authorize repairs NO MORE THAN \$30,000.00 before EXCESS of \$350.00, RE-INSPECTION of vehicle required.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Elaine Cheong

Date: 16 Oct 2019

Preliminary Advice

Vehicle No	: GBH6629G	Accident Date	: 18/09/2019
Make	: NISSAN NV350	Policy No.	: DMCVSN1826881901
Assignment Date	: 23/09/2019	Excess	: S\$350.00
Date of Inspection	: 24/9/2019	Est. Duration of Repair	: 21
Inspection At	: STK AUTO (S) PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	101,848.55 (incl.supplementary \$5540)
Revised Amount	:S\$	36,253.25
Check Items (Estimated)	:S\$	15,165.75
Total	:S\$	51,419.00 (incl.supplementary \$5540)

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	24,311.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,689.00

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments :Repair limit at \$30,000/-. Kindly approved on the supplementary.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 25 September 2019 1:45 PM
To: STK STK; SUR
Subject: RE: GBH6629H -DOA: 18/9/2019 (CHINA TAIPING OD)

Dear Linda/Guo Hua,

As instructed by our client , please proceed to repair the **insured vehicle GBH 6629G, not exceeding Lump Sum Repair S30,000/- (Excess S350/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: STK STK <stkautosg@gmail.com>
Sent: Tuesday, 24 September 2019 2:13 PM
To: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: GBH6629H -ESTIMATE

Dear

please refer to attachment.

Yours sincerely

Tan Guohua

Chief Executive Officer



STK AUTO (S) PTE LTD | www.stkauto.com.sg

Mobile: (65) 9123 7949 | Tel: (65) 63860669

8 Kaki Bukit Ave 4 #03-21 Singapore 415875 @PREMIER





View Received Message

This mail is associated with :

***GBH6629G (SNM19D204426C01)**
OD
Sep 18 2019 7:00PM
[M/S GOODWILL ENTERTAINMENT HOLDING PTE LTD]
Stk Auto (s) Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 25/09/2019 11:48 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$30000.00) - GBH6629G - Claim Handler: Elaine Cheong

Approved:30000.00:Proceed to authorize repairs NO MORE THAN \$30,000.00 before EXCESS of \$350.00, RE-INSPECTION of vehicle required.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com,assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 25 Sep 2019

Preliminary Advice

Vehicle No	: GBH6629G	Accident Date	: 18/09/2019
Make	: NISSAN NV350	Policy No.	: DMCVSN1826881901
Assignment Date	: 23/09/2019	Excess	: S\$350.00
Date of Inspection	: 24/9/2019	Est. Duration of Repair	: 21
Inspection At	: STK AUTO (S) PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	96,308.55
Revised Amount	:S\$	23,672.75
Check Items (Estimated)	:S\$	30,480.55
Total	:S\$	54,153.30

Lump Sum Repair	:S\$	43,300.00
-----------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	24,311.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,689.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer agree Lump Sum repair not exceeding \$30,000/-

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

838K

Vehicle Details

Vehicle No:

GBH6629G

Vehicle to be Exported:

Yes

Intended Deregistration Date:

20 Sep 2019

Vehicle Make:

NISSAN

Vehicle Model:

NV350 PANEL VAN SDR 2.5 SAT

Primary Colour:

White

Manufacturing Year:

2018

Engine No:

YD250322088

Chassis No:

JN1MC2E26Z0030469

Maximum Power Output:

-

Open Market Value:

\$26,466.00

Original Registration Date:

28 Aug 2018

First Registration Date:

28 Aug 2018

Transfer Count:

0

Actual ARF Paid:

\$1,324.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

27 Aug 2028

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$30,389.00

COE Rebate Amount:

\$24,311.00

Total Rebate Amount:

\$24,311.00

The information contained herein is correct as at 20 Sep 2019

OK

AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

6 vehicles Search nv350 Advanced Search Search View All

Make Model Price Depreciation **Reg Date** Eng Cap Mileage Veh Type Status

Search Selection	nv350	Any	Any	2018	Any	Any	Any	Available
------------------	-------	-----	-----	------	-----	-----	-----	-----------

 **Nissan NV350 2.5A** \$58,800 \$6,400 /yr 28-Nov-2018 2,488 cc 5,800 km Van Available
Fuel Type: Diesel
 Cost Saving Of Almost \$14k Compare To Brand New.And Even If You Go For Brand New, You Might Not Even Had This Superbly Nice 18 Number Plate.Low Mileage & Still Under Warranty As Well,Don't Wait, Make An Appointment With Any Of Hong Wei Sales, Now!
 ☆ Priced: 21-Aug-2019 Tag: 2018 Nissan NV350, 2018 Nissan NV350, Nissan NV350, Nissan NV350, Nissan NV350, NV350, 1800

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/09/2019 15:01
Date Of Accident	18/09/2019 19:45
Exact Location Of Accident	ECP MARINE PARADE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH6629G
Insured/Policyholder	
Name Of Registered Owner	M/S GOODWILL ENTERTAINMENT HOLDING PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-82929699

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1826881901
Cover Note Number	-

Driver

Name of Driver	GAO FUZE
NRIC No	G3211540W
Date Of Birth	22/10/1982
Occupation	INDOOR
Date Of Driving Pass	08/05/2018
Driving Experience	1 YEAR AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82929699
Fax Number	
Contact Number	
Email Address	NOEMAIL

Postcode 455919

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 3

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station.

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMK72E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver KE ZHENJIE

NRIC/Passport Number S8636147G

Contact Number 93381652

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMJ3947S



Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquires by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)


Reporting Centre Personnel's Signature
Name:

Accident Sketch Plan




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

while I was driving along ECP moving parallel

On 18/09/19 at about 1900hrs, the front vehicle came to a stop I followed suit. I can't stop in time and hit onto the vehicle B rear portion. Vehicle B hit onto vehicle C's rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date : 20/9/19

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : GOODWILL ENTERTAINMENT HOLDING PTE LTD

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMCVSN1826881901

Accident Date :

18/9/19

Vehicle Number : GBH6629G

Make & Model : NISSAN NV350 PANEL VAN

ESTIMATED REPAIR COST DETAILS

S/N	DESCRIPTION	QTY	REPAIR AMOUNT	SURVEYOR APP
1	BONNET <i>Distorted</i>	1	\$ 700.00	✓
2	BONNET LOCK	1	\$ 125.00	+
3	BONNET LOCK CATCH	1	\$ 100.00	+
4	BONNET STANDER	1	\$ 65.00	+
5	BONNET HINGE RH	1	\$ 65.00	+
6	BONNET HINGE LH	1	\$ 65.00	+
7	FRONT FIRE PANEL <i>Repair</i>	1	\$ 1,500.00	+
8	FRONT WIPER PANEL <i>Repair</i>	1	\$ 450.00	+
9	FRONT WIPER PANEL GARNISH ?	1	\$ 200.00	+
10	FRONT WIPER LINK RH	1	\$ 250.00	+
11	FRONT WIPER LINK LH	1	\$ 250.00	+
12	FRONT WIPER LINK MOTOR	1	\$ 550.00	+
13	FRONT SUPPORT PANEL CENTER	1	\$ 680.00	+
14	FRONT SUPPORT PANEL BOTTOM	1	\$ 650.00	+
15	FRONT SUPPORT PANEL RH	1	\$ 135.00	+
16	FRONT SUPPORT PANEL LH	1	\$ 135.00	+
17	FRONT SUPPORT PANEL AIR GUIDE RH	1	\$ 85.00	+
18	FRONT SUPPORT PANEL AIR GUIDE LH	1	\$ 85.00	+
19	FRONT WINDSCREEN GLASS <i>shattered</i>	1	\$ 850.00	✓
20	FRONT WINDSCREEN GLASS MOULDING <i>He</i>	1	\$ 180.00	✓
21	FRONT WINDSCREEN PILLAR RH <i>Repair</i>	1	\$ 950.00	✓
22	FRONT WINDSCREEN PILLAR LH <i>Buckled</i>	1	\$ 950.00	✓
23	RH HEADLAMP <i>ld</i>	1	\$ 380.00	✓
24	LH HEADLAMP <i>smashed</i>	1	\$ 380.00	✓
25	RH HEADLAMP BRACKET RH <i>new</i>	1	\$ 65.00	+
26	LH HEADLAMP BRACKET LH <i>new</i>	1	\$ 65.00	+

27	RH HEADLAMP PANEL <i>new</i>	1	\$	350.00	+
28	LH HEADLAMP PANEL	1	\$	350.00	+
29	FRONT FENDER RH <i>new</i>	1	\$	550.00	+
30	FRONT FENDER LH <i>Dischd</i> <i>new</i>	1	\$	550.00	+
31	FRONT FENDER INNER SHIELD RH <i>new</i>	1	\$	165.00	+
32	FRONT FENDER INNER SHIELD LH <i>new</i>	1	\$	165.00	+
33	CROSS MEMBER <i>new</i>	1	\$	1,800.00	+
34	ENGINE LOWER GARNISH ?	1	\$	370.00	?
35	FRONT CHASSIS RH <i>new</i>	1	\$	550.00	+
36	FRONT CHASSIS LH <i>new</i>	1	\$	550.00	+
37	FRONT GRILLE <i>missing</i>	1	\$	550.00	✓
38	FRONT GRILLE BRACKET RH <i>new</i> <i>new</i>	1	\$	55.00	+
39	FRONT GRILLE BRACKET LH <i>new</i> <i>new</i>	1	\$	55.00	+
40	FRONT GRILLE LOGO <i>new</i>	1	\$	65.00	✓
41	FRONT BUMPER <i>Dischd</i>	1	\$	450.00	✓
42	FRONT BUMPPER FOG LAMP COVER RH <i>new</i>	1	\$	90.00	+
43	FRONT BUMPER FOG LAMP COVER LH <i>Dischd</i>	1	\$	90.00	✓
44	FRONT BUMPER RETAINER RH <i>new</i>	1	\$	135.00	✓
45	FRONT BUMPER RETAINER LH <i>new</i>	1	\$	135.00	✓
46	FRONT BUMPER BRACKET RH <i>new</i>	1	\$	65.00	+
47	FRONT BUMPER BRACKET LH <i>new</i>	1	\$	65.00	✓
48	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$	550.00	✓
49	FRONT BUMPER GRILLE CENTRE <i>new</i>	1	\$	500.00	✓
50	AIR DUCT <i>Dischd</i>	1	\$	150.00	✓
51	AIR CLEANER BOX ASSY ?	1	\$	650.00	?
52	AIR CLEANER HOSE ?	1	\$	150.00	?
53	AIR CLEANER HOSE TOP ?	1	\$	250.00	?
54	AIR CLEANER HOUSING ?	1	\$	350.00	?
55	AIR CLEANER INTAKE DUCT ?	1	\$	550.00	?
56	AIR CLEANER INTAKE HOSE ?	1	\$	280.00	?
57	AIR CLEANER OUTET HOSE ?	1	\$	280.00	?
58	AIR CLEANER OUTER HOUSIG ?	1	\$	650.00	?
59	AIR CLANER PIPE ?	1	\$	390.00	?
60	AIR CON BLOWER ?	1	\$	2,100.00	?
61	AIR CON BLOWER MOTOR ?	1	\$	3,500.00	?
62	AIR CON COIL ?	1	\$	650.00	?
63	AIR RESONATOR ?	1	\$	120.00	?
64	TURBER ?	1	\$	3,500.00	?
65	TURBER PIPE ?	1	\$	250.00	?
66	INTER COOLER ?	1	\$	2,800.00	?
67	INTER COOLER PIPE <i>new</i>	1	\$	450.00	+
68	OIL COOLTER <i>new</i>	1	\$	650.00	✓
69	OIL COOLER PIPER <i>new</i>	1	\$	165.00	✓
70	WIPER TANK ?	1	\$	210.00	?
71	WIPER TANK MOTOR ?	1	\$	560.00	?
72	WIPER TANK COVER ?	1	\$	87.00	?
73	TIME BELT <i>new</i>	1	\$	290.00	+
74	TIME TENSIONER <i>new</i>	1	\$	186.00	+
75	TIME BEARING	1	\$	75.00	+
76	ECU <i>new</i>	1	\$	3,500.00	+
77	EUC BRACKET <i>new</i>	1	\$	150.00	+
78	ECU MODUEL	1	\$	850.00	+

79	ECU MODUEL COVER <i>new</i>	1	\$	150.00	+
80	ENGINE MOUNTING FRONT ?	1	\$	185.00	?
81	ENGINE MOUNTING REAR ?	1	\$	165.00	?
82	ENGINE MOUNTING RH ?	1	\$	165.00	?
83	ENGINE MOUNTING LH ?	1	\$	140.00	?
84	DRAF SHAFT <i>new</i>	1	\$	1,500.00	+
85	HORN LOWER ?	1	\$	120.00	?
86	HORN HIGH ?	1	\$	120.00	?
87	FRONT WIPER HARNESS <i>new</i>	1	\$	3,500.00	+
88	LH FRONT CONER PANEL <i>Dented</i>	1	\$	350.00	✓
89	RH FRONT CONER PANEL <i>Repair</i>	1	\$	350.00	+
90	AIR CON CONDERSOR ?	1	\$	500.00	?
91	AIR CON CONDENSOR DRY HOSE <i>Bent</i>	1	\$	180.00	✓
92	AIR CON DISCHARGE HOSE <i>3, Bent</i>	1	\$	350.00	✓
93	AIR CON RECIVE HOSE	1	\$	270.00	✓
94	RECEIVED DRIVER <i>Dented</i>	1	\$	180.00	✓
95	RADIATOR ?	1	\$	600.00	?
96	RADIATOR FAN COWLING ?	1	\$	350.00	?
97	RADIATOR FAN BLADE ?	1	\$	320.00	?
98	RADIATOR FAN MOTOR ?	1	\$	450.00	?
99	RADIATOR SPARE TANK ?	1	\$	95.00	?
100	RADIATOR BRACKET RH ?	1	\$	65.00	?
101	RADIATOR BRACKET LH ?	1	\$	65.00	?
102	RADIATOR BOTTOM HOSE ?	1	\$	150.00	?
103	RADIATOR MOUNTING TOP ?	1	\$	150.00	?
104	DASHBOARD ?	1	\$	860.00	?
105	DASHBOARD COVER ?	1	\$	650.00	?
106	DASHBOARD REINFORCEMENT ?	1	\$	750.00	?
107	DASHBOARD METER <i>new</i>	1	\$	850.00	+
108	PASSENGER DASHBOARD GARNISH ?	1	\$	250.00	?
109	PASSENGER DASHBOARD TOOL BOX ?	1	\$	350.00	?
110	STEERING LOWER GARNISH <i>new</i>	1	\$	20.00	+
111	STEERING RCK PINION ?	1	\$	2,100.00	+
112	DRIVER'S STEERING <i>new</i>	1	\$	1,500.00	+
113	GEAR LEVER GARNISH	1	\$	650.00	+
114	LH FRONT SHOCK ABSORBER	1	\$	180.00	+
115	LH FRONT LOWER ARM	1	\$	200.00	+
116	LH FRONT KNOCKE ARM	1	\$	250.00	+
117	LH FRONT KNOCKE ARM BEARING	1	\$	165.00	+
118	LH FRONT DOOR <i>Dented</i>	1	\$	850.00	✓
119	LH FRONT DOOR HINGE UPPER ? <i>Bent</i>	1	\$	75.00	✓
120	LH FRONT DOOR HINGE LOWER	1	\$	75.00	✓
121	LH FRONT DOOR CHECKER <i>Bent</i>	1	\$	55.00	✓
122	LH FRONT DOOR HANDLE OUTER ? <i>new</i>	1	\$	100.00	+
123	LH FRONT DOOR HANDLE INNER	1	\$	120.00	+
124	LH FRONT DOOR GLASS <i>Shattered</i>	1	\$	500.00	✓
125	LH FRONT DOOR GLASS REGULATOR MOT <i>new</i>	1	\$	350.00	+
126	LH FRONT DOOR GLASS REGULATOR SWI <i>new</i>	1	\$	150.00	✓
127	LH FRONT DOOR GLASS SWITCH COVER <i>new</i>	1	\$	150.00	+
128	LH FRONT DOOR SPEAKER <i>new</i>	1	\$	360.00	+
129	LH FRONT DOOR WEATHERSTRIP <i>new</i>	1	\$	200.00	✓
130	LH FRONT DOOR LOCK <i>new</i>	1	\$	250.00	✓

131	LH FRONT DOOR INNER PILLAR	1	\$	2,000.00	*
132	LH FRONT DOOR OUTER PILLAR	1	\$	2,000.00	*
133	LH FRONT DOOR STEP PANEL	1	\$	200.00	✓
134	LH FRONT DOOR STEP PANEL GARNISH	1	\$	130.00	✓
135	LH FRONT DOOR INNER TRIMBOARD	1	\$	500.00	✓
136	LH FRONT DOOR CENTRE PILLAR	1	\$	2,000.00	*
137	RH FRONT DOOR	1	\$	850.00	+
138	RH FRONT DOOR HINGE UPPER	1	\$	75.00	+
139	RH FRONT DOOR HINGE LOWER	1	\$	75.00	+
140	RH FRONT DOOR CHECKER	1	\$	55.00	+
141	RH FRONT DOOR PILLAR	1	\$	1,500.00	+
142	RH SLIDING DOOR	1	\$	1,200.00	✓
143	RH REAR FENDER	1	\$	1,200.00	+
144	DRIVER SEAT	1	\$	950.00	+
145	PASSENGER SEAT	1	\$	950.00	+
146	DRIVER SEAT BUCKLE RH	1	\$	450.00	+
147	LH FRONT SEAT BELT	1	\$	900.00	+
148	RH FRONT SEAT BELT	1	\$	900.00	+
149	PASSENGER SEA BUCKLE LH	1	\$	550.00	+
150	FUSE BOX	1	\$	1,500.00	?
151	FUSE BOX COVER	1	\$	250.00	?
Sub Total			\$	82,623.00	
Make up 15% on Parts			\$	12,393.45	
Total			\$	95,016.45	

Special Nett Item

1	FRONT NUMBER PLATE	1	\$	65.00	30
2	TOWING FEE	1	\$	300.00	60
3	FRONT FENDER INNER SHIELD CLIPS	10	\$	65.00	+
4	FRONT DOOR SEALANT RH	1	\$	65.00	+
5	FRONT DOOR SEALANT LH	1	\$	65.00	+
6	FRONT CAMERA	1	\$	365.00	+
7	FRONT BUMPER TOWING COVER RH & LH	2	\$	100.00	20
8	IU BRACKET	1	\$	65.00	30
9	COOLANT	1	\$	65.00	50
10	BONNET STOPPER	10	\$	100.00	+
11	IU BRACKET	1	\$	65.00	+
12	AIR FILTER	1	\$	35.00	+
13	ENGINE OIL	1	\$	100.00	+
14	OIL FILTER	1	\$	45.00	+
15	FRONT GRILLE CLIPS	10	\$	65.00	20
16	FRONT WIPER BALDE RH	1	\$	65.00	+
17	FRONT WIPER BLADE LH	1	\$	65.00	+
18	FRONT FENDER INNER SHIELD CLIPS	10	\$	65.00	+
19	FRONT BUMPER CLIPS	10	\$	65.00	30
20	HEADSET MONITOR	1	\$	350.00	+
21	RH FRONT DOOR STICKER	1	\$	25.00	✓
22	LH FRONT DOOR STICKER	1	\$	25.00	✓
23	FRONT WINDSCREEN SEALANT	1	\$	50.00	✓
Sub Total			\$	2,275.00	

ESTIMATED REPAIR COST DETAILS

Labour & Misc

1	LABOUR TO FACILITATE REPAIR	\$	4,500.00	2400
2	R & R ENGINE COMPARTMENT	\$	250.00	?
3	RUST PROOF ON AFFECTED AREAS	\$	50.00	✓
4	R & R FRONT WINDSCREEN	\$	150.00	120
5	TO VACCUM AIR CON SYSTEM & REFILL GAS	\$	120.00	✓
6	TO CHECK LIGHTING AND FOCUS HEADLAMP	\$	150.00	30
7	TO REMOVE AND REFIT DASHBOARD TO ASSIST WORK	\$	250.00	220
8	TO RE-ALIGN EXHAUST CATALYST CONVERTER	\$	25.00	x
9	TO CHECK ELECTRICAL WIRING FOR FRONT LIGHT	\$	130.00	30
10	TO RESET AND PROGRAM ECU AND FAULT CODE	\$	250.00	x
11	TO DISMANTLE SEATS & REPLACE NEW PARTS	\$	350.00	x
12	TO CONDUCT CHASSIS ALIGNMENT	\$	350.00	250
13	TO TRANSFER RH FRONT DOOR AND REFIT NEW DOOR	\$	150.00	80 x
14	TO REMOVE AND REFIT LH FRONT DOOR	\$	150.00	80
15	TO SPRAY PAINT LH FRONT DOOR	\$	250.00	200 x
16	TO SPRAY PAINT LH FRONT FENDER	\$	250.00	x
17	TO SPRAY PAINT RH FRONT FENDER	\$	250.00	+
18	TO SPRAY PAINT RH SLIDING DOOR	\$	250.00	200
19	TO SPRAY PAINT LH SLIDING DOOR	\$	250.00	200
20	TO SPRAY PAINT ON LH REAR FENDER	\$	250.00	✓
21	TO SPRAY PAINT TAILGATE	\$	250.00	✓
22	TO SPRAY PAINT REAR BUMPER	\$	250.00	200
23	TO SPRAY PAINT RH FRONT DOOR	\$	150.00	✓
24	TO SPRAY PAINT FRONT BUMPER	\$	250.00	200
25	TO SPRAY PAINT FRONT SUPPORT PANEL	\$	250.00	x
26	TO SPRAY PAINT BONNET	\$	250.00	200
27	TO SPRAY PAINT FRONT BUMPER REINFORCEMENT	\$	250.00	+
	Sub Total	\$	10,025.00	
	Grand Total	\$	107,316.45	

Adrian King
 2/5 24/05/19
 21 Days

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date : 20/9/19

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : GOODWILL ENTERTAINMENT HOLDING PTE LTD

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMCVSN1826881901

Accident Date :

18/9/19

Vehicle Number : GBH6629G

Make & Model : NISSAN NV350 PANEL VAN

ESTIMATED REPAIR COST DETAILS

S/N	DESCRIPTION	QTY	REPAIR AMOUNT	SURVEYOR APP.
1	BONNET Dist	1	\$ 580.00	✓
2	FRONT FIRE PANEL Dented	1	\$ 1,500.00	✓
3	FRONT WIPER PANEL Dented	1	\$ 450.00	✓
4	FRONT WIPER PANEL GARNISH Deformed	1	\$ 200.00	✓
5	FRONT WIIPER LINK RH Bent	1	\$ 250.00	✓
6	FRONT WIPER LINK LH } NN	1	\$ 250.00	X
7	FRONT WIPER LINK MOTOR } NN	1	\$ 550.00	X
8	FRONT WINDSCREEN GLASS shattered	1	\$ 850.00	✓
9	FRONT WINDSCREEN GLASS MOULDING nec	1	\$ 180.00	✓
10	FRONT WINDSCREEN PILLAR RH R	1	\$ 950.00	X
11	FRONT WINDSCREEN PILLAR LH Buc	1	\$ 950.00	✓
12	RH HEADLAMP Cut	1	\$ 350.00	✓
13	LH HEADLAMP Smashed	1	\$ 350.00	✓
14	RH HEADLAMP BRACKET RH } NN	1	\$ 65.00	X
15	LH HEADLAMP BRACKET LH } NN	1	\$ 65.00	X
16	RH HEADLAMP PANEL } NN	1	\$ 350.00	X
17	LH HEADLAMP PANEL } NN	1	\$ 350.00	X
18	FRONT WHEEL ARCH RH R	1	\$ 650.00	X
19	FRONT WHEEL ARCH LH Distorted	1	\$ 650.00	✓
20	FRONT WHELL ARCH GARNISH RH RH new	1	\$ 165.00	✓
21	FRONT WHEEL ARCH GARNISH LH LH new	1	\$ 165.00	✓
22	CROSS MENBER NN	1	\$ 1,800.00	X
23	ENGINE LOWER GARNISH Rte new	1	\$ 370.00	X
24	FRONT CHASSIS RH } R	1	\$ 550.00	X
25	FRONT CHASSIS LH } R	1	\$ 550.00	X
26	FRONT GRILLE missing	1	\$ 550.00	✓

27	FRONT GRILLE BRACKET RH	} NN	1	\$	55.00	X
28	FRONT GRILLE BRACKET LH	} NN	1	\$	55.00	X
29	FRONT GRILLE LOGO	nrc	1	\$	65.00	✓
30	FRONT BUMPER	Dist	1	\$	450.00	✓
31	FRONT BUMPPER FOG LAMP COVER RH	NN	1	\$	135.00	X
32	FRONT BUMPER FOG LAMP COVER LH	Dist	1	\$	135.00	✓
33	FRONT BUMPER RETAINER RH	} nrc	1	\$	90.00	✓
34	FRONT BUMPER RETAINER LH	} nrc	1	\$	90.00	✓
35	FRONT BUMPER BRACKET RH	NN	1	\$	65.00	X
36	FRONT BUMPER BRACKET LH	Bent	1	\$	65.00	✓
37	FRONT BUMPER REINFORCEMENT	Bent	1	\$	550.00	✓
38	FRONT BUMPER GRILLE CENTRE	crq	1	\$	400.00	✓
39	AIR DUCT	Def	1	\$	150.00	✓
40	AIR CLEANER BOX ASSY	? Crq	1	\$	650.00	✓
41	AIR CLEANER HOSE	? crq	1	\$	150.00	✓
42	AIR CLEANER HOSE TOP	2 new	1	\$	250.00	+
43	AIR CLEANER HOUSING	2 new	1	\$	350.00	+
44	AIR CLEANER INTAKE DUCT	2 new	1	\$	550.00	✓
45	AIR CLEANER INTAKE HOSE	2 new	1	\$	280.00	✓
46	AIR CLEANER OUTET HOSE	2 new	1	\$	280.00	+
47	AIR CLEANER OUTER HOUSIG	2 new	1	\$	650.00	+
48	AIR CLANER PIPE	2 new	1	\$	390.00	+
49	AIR CON BLOWER	2 new	1	\$	2,100.00	✓
50	AIR CON BLOWER MOTOR	2 new	1	\$	3,500.00	X
51	AIR CON COIL	2 new	1	\$	650.00	✓
52	AIR RESONATOR	2 new	1	\$	120.00	X
53	TURBER	2 new	1	\$	3,500.00	+
54	TURBER PIPE	Bent	1	\$	250.00	✓
55	INTER COOLER	2 new	1	\$	2,800.00	X
56	INTER COOLER PIPE	NN	1	\$	450.00	X
57	OIL COOLTER	Bent	1	\$	1,500.00	✓
58	OIL COOLER PIPER	Bent	1	\$	165.00	✓
59	WIPER TANK	? Dist	1	\$	210.00	✓
60	WIPER TANK MOTOR	? DM	1	\$	560.00	✓
61	WIPER TANK COVER	? NN	1	\$	87.00	X
62	DRAF SHAFT	NN	1	\$	1,500.00	X
63	HORN LOWER	Missing	1	\$	120.00	✓
64	HORN HIGH	2 new	1	\$	120.00	+
65	FRONT WIPER HARNESS	NN	1	\$	3,500.00	X
66	LH FRONT CONER PANEL	Dented	1	\$	350.00	✓
67	RH FRONT CONER PANEL	R	1	\$	350.00	X
68	AIR CON CONDERSOR	2 new	1	\$	500.00	+
69	AIR CON CONDENSOR DRY HOSE	Bent	1	\$	180.00	✓
70	AIR CON DISCHARGE HOSE	} Bent	1	\$	350.00	✓
71	AIR CON RECIVE HOSE	} Bent	1	\$	270.00	✓
72	RECEIVED DRIVER	Dented	1	\$	180.00	✓
73	RADIATOR	?	1	\$	550.00	+
74	RADIATOR FAN COWLING	? 2	1	\$	350.00	+
75	RADIATOR FAN BLADE	?	1	\$	320.00	+
76	RADIATOR FAN MOTOR	?	1	\$	450.00	+
77	RADIATOR SPARE TANK	?	1	\$	95.00	+
78	RADIATOR BRACKET RH	?	1	\$	65.00	+

79	RADIATOR BRACKET LH	? <i>from</i>	1	\$	65.00	X
80	RADIATOR BOTTOM HOSE	? <i>from</i>	1	\$	150.00	X
81	RADIATOR MOUNTING TOP	? <i>from</i>	1	\$	150.00	X
82	DASHBOARD	? <i>NN</i>	1	\$	860.00	X
83	DASHBOARD COVER	? <i>NN</i>	1	\$	650.00	X
84	DASHBOARD REINFORCEMENT	? <i>Bent</i>	1	\$	750.00	✓
85	DASHBOARD METER	<i>NN</i>	1	\$	850.00	X
86	PASSENGER DASHBOARD GARNISH	? <i>crq</i>	1	\$	250.00	✓
87	PASSENGER DASHBOARD TOOL BOX	? <i>crq</i>	1	\$	350.00	✓
88	STEERING LOWER GARNISH	<i>NN</i>	1	\$	20.00	X
89	STEERING RCK PINION	} <i>NN</i>	1	\$	2,100.00	X
90	DRIVER'S STEERING		1	\$	1,500.00	X
91	GEAR LEVER GARNISH		1	\$	650.00	X
92	LH FRONT SHOCK ABSORBER	} <i>NN</i>	1	\$	180.00	X
93	LH FRONT LOWER ARM		1	\$	200.00	X
94	LH FRONT KNOCKE ARM		1	\$	250.00	X
95	LH FRONT KNOCKE ARM BEARING	} <i>NN</i>	1	\$	165.00	X
96	LH FRONT DOOR		1	\$	850.00	✓
97	LH FRONT DOOR HINGE UPPER		1	\$	75.00	✓
98	LH FRONT DOOR HINGE LOWER	? <i>Bent</i>	1	\$	75.00	✓
99	LH FRONT DOOR CHECKER	<i>Bent</i>	1	\$	55.00	✓
100	LH FRONT DOOR HANDLE OUTER	<i>NN</i>	1	\$	100.00	X
101	LH FRONT DOOR HANDLE INNER	<i>crq</i>	1	\$	120.00	X ✓
102	LH FRONT DOOR GLASS	<i>shattered</i>	1	\$	500.00	✓
103	LH FRONT DOOR GLASS REGULATOR MOT	<i>dm</i>	1	\$	350.00	✓
104	LH FRONT DOOR GLASS REGULATOR SWIT	<i>dm</i>	1	\$	150.00	✓
105	LH FRONT DOOR GLASS SWITCH COVER	<i>NN</i>	1	\$	150.00	X
106	LH FRONT DOOR SPEAKER	<i>crq</i>	1	\$	360.00	✓
107	LH FRONT DOOR WEATHERSTRIP	<i>cut</i>	1	\$	200.00	✓
108	LH FRONT DOOR LOCK	<i>dm</i>	1	\$	250.00	✓
109	LH FRONT DOOR INNER PILLAR	<i>R</i>	1	\$	1,500.00	X
110	LH FRONT DOOR OUTER PILLAR	<i>Dist</i>	1	\$	1,500.00	✓
111	LH FRONT DOOR STEP PANEL	<i>Bent</i>	1	\$	200.00	✓
112	LH FRONT DOOR STEP PANEL GARNISH	<i>Dented</i>	1	\$	130.00	✓
113	LH FRONT DOOR INNER TRIMBOARD	<i>crq</i>	1	\$	500.00	✓
114	LH FRONT DOOR CENTRE PILLAR	<i>Dented</i>	1	\$	1,500.00	✓
115	RH FRONT DOOR	<i>R</i>	1	\$	850.00	X
116	RH FRONT DOOR HINGE UPPER	} <i>NN</i>	1	\$	75.00	X
117	RH FRONT DOOR HINGE LOWER		1	\$	75.00	X
118	RH FRONT DOOR CHECKER		1	\$	55.00	X
119	RH FRONT DOOR PILLAR	<i>R</i>	1	\$	1,500.00	X
120	RH SLIDING DOOR	<i>Dented</i>	1	\$	1,200.00	✓
121	RH REAR FENDER	<i>R</i>	1	\$	1,200.00	X
122	DRIVER SEAT	} <i>NN</i>	1	\$	950.00	X
123	PASSENGER SEAT		1	\$	950.00	X
124	DRIVER SEAT BUCKLE RH		1	\$	450.00	X
125	LH FRONT SEAT BELT	} <i>NN</i>	1	\$	900.00	X
126	RH FRONT SEAT BELT		1	\$	900.00	X
127	PASSENGER SEA BUCKLE LH		1	\$	550.00	X
128	FUSE BOX	? <i>Not in</i>	1	\$	1,500.00	X
129	FUSE BOX COVER	? <i>Not in</i>	1	\$	250.00	X
130	RH TAILLAMP	<i>cut</i>	1	\$	180.00	✓

Sub Total	\$ 73,977.00
Make up 15% on Parts	\$ 11,096.55
Total	\$ 85,073.55

Special Nett Item

1	FRONT NUMBER PLATE Bent	1	\$ 65.00	30
2	TOWING FEE	1	\$ 300.00	60
4	FRONT DOOR SEALANT RH	1	\$ 65.00	X
5	FRONT DOOR SEALANT LH	1	\$ 65.00	X
6	FRONT CAMERA	1	\$ 365.00	X
7	FRONT BUMPER TOWING COVER RH & LH nrc	2	\$ 100.00	20
8	IU BRACKET nrc	1	\$ 65.00	30
9	COOLANT nrc	1	\$ 65.00	50
10	BONNET STOPPER NN	10	\$ 100.00	X
11	IU BRACKET R	1	\$ 65.00	X
12	AIR FILTER ? NRC	1	\$ 35.00	
13	ENGINE OIL } NN	1	\$ 100.00	X
14	OIL FILTER } NN	1	\$ 45.00	X
15	FRONT GRILLE CLIPS nrc	10	\$ 65.00	20
16	FRONT WIPER BALDE RH	1	\$ 65.00	X
17	FRONT WIPER BLADE LH	1	\$ 65.00	X
18	FRONT FENDER INNER SHIELD CLIPS	10	\$ 65.00	X
19	FRONT BUMPER CLIPS nrc	10	\$ 65.00	30
20	HEADSET MONITOR NN	1	\$ 350.00	X
21	RH FRONT DOOR STICKER	1	\$ 25.00	✓
22	LH FRONT DOOR STICKER	1	\$ 25.00	✓
23	FRONT WINDSCREEN SEALANT	1	\$ 50.00	✓
	Sub Total		\$ 2,210.00	

ESTIMATED REPAIR COST DETAILS

Labour & Misc

1	LABOUR TO FACILIATE REPAIR	\$ 4,500.00	2400
2	R & R ENGINE COMPARTMENT	\$ 250.00	2 X
3	RUST PROOF ON AFFECTED AREAS	\$ 50.00	✓
4	R & R FRONT WINDSCREEN	\$ 150.00	120
5	TO VACCUM AIR CON SYSTEM & REFILL GAS	\$ 120.00	✓
6	TO CHECK LIGHTING AND FOCUS HEADLAMP	\$ 150.00	30
7	TO REMOVE AND REFITX DASHBOARD TO ASSIST WORK	\$ 250.00	220
8	TO RE-ALIGN EXHAUST CATALYST CONVERTER	\$ 25.00	X
9	TO CHECK ELECTORICAL WIRING FOR FORNT LIG	\$ 130.00	30
10	TO RESET AND PROGRAM ECU AND FAULT CODE	\$ 250.00	X
11	TO DISMANTLE SEATS & REPLACE NEW PARTS	\$ 350.00	X
12	TO CONDUCT CHASSIS LIGNMENT	\$ 350.00	250
13	TO TRANSFER RH FRONT DOOR AND REFIT NEW DOOR	\$ 150.00	X
14	TO REMOVE AND REFIT LH FRONT DOOR	\$ 150.00	80
15	TO SPRAY PAINT RH SLIDING DOOR	\$ 250.00	200
16	TO SPRAAY PAINT LH SLIDING DOOR	\$ 250.00	200
17	TO SPRAY PAINT ON LH REAR FENDER	\$ 250.00	✓
18	TO SPRAY PAINT TAILGATE	\$ 250.00	✓
19	TO SPRAY PAINT REAR BUMPER	\$ 250.00	200

20	TO SPRAY PAINT RH FRONT DOOR	\$	150.00	✓
21	TO SPRAY PAINT FRONT BUMPER	\$	250.00	200
22	TO SPRAY PAINT BONNET	\$	250.00	200
23	TO SPRAY PAINT FRONT BUMPER REINFORCEMENT	\$	250.00	X
	Sub Total	\$	9,025.00	
	Grand Total	\$	96,308.55	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

102,489.55

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date : 20/9/19

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : GOODWILL ENTERTAINMENT HOLDING PTE LTD
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMCVSN1826881901 Accident Date : 18/9/19

Vehicle Number : GBH6629G

Make & Model : NISSAN NV350 PANEL VAN

ESTIMATED REPAIR COST DETAILS

S/N	DESCRIPTION	QTY	REPAIR AMOUNT	SURVEYOR APP.
1	BONNET <i>Distorted</i>	1	\$ 700.00	
2	BONNET LOCK	1	\$ 125.00	*
3	BONNET LOCK CATCH	1	\$ 100.00	*
4	BONNET STANDER	1	\$ 65.00	+
5	BONNET HINGE RH	1	\$ 65.00	+
6	BONNET HINGE LH	1	\$ 65.00	+
7	FRONT FIRE PANEL <i>Distorted</i>	1	\$ 1,500.00	+
8	FRONT WIPER PANEL <i>Distorted</i>	1	\$ 450.00	+
9	FRONT WIPER PANEL GARNISH ?	1	\$ 200.00	?
10	FRONT WIPER LINK RH	1	\$ 250.00	+
11	FRONT WIPER LINK LH	1	\$ 250.00	+
12	FRONT WIPER LINK MOTOR	1	\$ 550.00	+
13	FRONT SUPPORT PANEL CENTER	1	\$ 680.00	+
14	FRONT SUPPORT PANEL BOTTOM	1	\$ 650.00	+
15	FRONT SUPPORT PANEL RH	1	\$ 135.00	+
16	FRONT SUPPORT PANEL LH	1	\$ 135.00	+
17	FRONT SUPPORT PANEL AIR GUIDE RH	1	\$ 85.00	+
18	FRONT SUPPORT PANEL AIR GUIDE LH	1	\$ 85.00	+
19	FRONT WINDSCREEN GLASS <i>shattered</i>	1	\$ 850.00	+
20	FRONT WINDSCREEN GLASS MOULDING	1	\$ 180.00	+
21	FRONT WINDSCREEN PILLAR RH	1	\$ 950.00	+
22	FRONT WINDSCREEN PILLAR LH	1	\$ 950.00	+
23	RH HEADLAMP <i>led</i>	1	\$ 380.00	+
24	LH HEADLAMP <i>smashed</i>	1	\$ 380.00	+
25	RH HEADLAMP BRACKET RH	1	\$ 65.00	+
26	LH HEADLAMP BRACKET LH	1	\$ 65.00	+

28	LH HEADLAMP PANEL		\$	350.00	
29	FRONT FENDER RH	Wing Arch garnish	\$	550.00	
30	FRONT FENDER LH	Wing Arch garnish	\$	550.00	
31	FRONT FENDER INNER SHIELD RH		\$	165.00	
32	FRONT FENDER INNER SHIELD LH	new	\$	165.00	
33	CROSS MEMBER	new	\$	1,800.00	
34	ENGINE LOWER GARNISH	new	\$	370.00	
35	FRONT CHASSIS RH	new	\$	550.00	
36	FRONT CHASSIS LH	new	\$	550.00	
37	FRONT GRILLE	missing	\$	550.00	
38	FRONT GRILLE BRACKET RH	new	\$	55.00	
39	FRONT GRILLE BRACKET LH	new	\$	55.00	
40	FRONT GRILLE LOGO	new	\$	65.00	
41	FRONT BUMPER	Dischd	\$	450.00	
42	FRONT BUMPPER FOG LAMP COVER RH	new	\$	90.00	
43	FRONT BUMPER FOG LAMP COVER LH	Dischd	\$	90.00	
44	FRONT BUMPER RETAINER RH	new	\$	135.00	
45	FRONT BUMPER RETAINER LH	new	\$	135.00	
46	FRONT BUMPER BRACKET RH	new	\$	65.00	
47	FRONT BUMPER BRACKET LH	new	\$	65.00	
48	FRONT BUMPER REINFORCEMENT	new	\$	550.00	
49	FRONT BUMPER GRILLE CENTRE	new	\$	500.00	
50	AIR DUCT	Dischd	\$	150.00	
51	AIR CLEANER BOX ASSY	new	\$	650.00	
52	AIR CLEANER HOSE	new	\$	150.00	
53	AIR CLEANER HOSE TOP		\$	250.00	
54	AIR CLEANER HOUSING		\$	350.00	
55	AIR CLEANER INTAKE DUCT	new	\$	550.00	
56	AIR CLEANER INTAKE HOSE	new	\$	280.00	
57	AIR CLEANER OUTET HOSE		\$	280.00	
58	AIR CLEANER OUTER HOUSIG		\$	650.00	
59	AIR CLANER PIPE		\$	390.00	
60	AIR CON BLOWER	new	\$	2,100.00	
61	AIR CON BLOWER MOTOR	new	\$	3,500.00	
62	AIR CON COIL		\$	650.00	
63	AIR RESONATOR		\$	120.00	
64	TURBER	new	\$	3,500.00	
65	TURBER PIPE	new	\$	250.00	
66	INTER COOLER	new	\$	2,800.00	
67	INTER COOLER PIPE	new	\$	450.00	
68	OIL COOLTER	new	\$	650.00	
69	OIL COOLER PIPER	new	\$	165.00	
70	WIPER TANK	Dischd	\$	210.00	
71	WIPER TANK MOTOR	new	\$	560.00	
72	WIPER TANK COVER	new	\$	87.00	
73	TIME BELT		\$	290.00	
74	TIME TENSIONER	new	\$	186.00	
75	TIME BEARING		\$	75.00	
76	ECU		\$	3,500.00	
77	EUC BRACKET	new	\$	150.00	
78	ECU MODUEL		\$	850.00	

80	ENGINE MOUNTING FRONT ?	1	\$	150.00	✓
81	ENGINE MOUNTING REAR ?	1	\$	185.00	✓
82	ENGINE MOUNTING RH ?	1	\$	165.00	✓
83	ENGINE MOUNTING LH ?	1	\$	165.00	✓
84	DRAF SHAFT <i>new</i>	1	\$	140.00	✓
85	HORN LOWER ?	1	\$	1,500.00	✓
86	HORN HIGH <i>missing</i>	1	\$	120.00	✓
87	FRONT WIPER HARNESS <i>new</i>	1	\$	120.00	✓
88	LH FRONT CONER PANEL <i>Sealed</i>	1	\$	3,500.00	✓
89	RH FRONT CONER PANEL <i>Payor</i>	1	\$	350.00	✓
90	AIR CON CONDENSOR ?	1	\$	350.00	✓
91	AIR CON CONDENSOR DRY HOSE <i>Seal</i>	1	\$	500.00	✓
92	AIR CON DISCHARGE HOSE <i>3 Seal</i>	1	\$	180.00	✓
93	AIR CON RECIVE HOSE	1	\$	350.00	✓
94	RECEIVED DRIVER <i>Sealed</i>	1	\$	270.00	✓
95	RADIATOR ?	1	\$	180.00	✓
96	RADIATOR FAN COWLING ?	1	\$	600.00	✓
97	RADIATOR FAN BLADE ?	1	\$	350.00	✓
98	RADIATOR FAN MOTOR ?	1	\$	320.00	✓
99	RADIATOR SPARE TANK ?	1	\$	450.00	✓
100	RADIATOR BRACKET RH ?	1	\$	95.00	✓
101	RADIATOR BRACKET LH ?	1	\$	65.00	✓
102	RADIATOR BOTTOM HOSE ?	1	\$	65.00	✓
103	RADIATOR MOUNTING TOP ?	1	\$	150.00	✓
104	DASHBOARD <i>new</i>	1	\$	150.00	✓
105	DASHBOARD COVER <i>Sealed new</i>	1	\$	860.00	✓
106	DASHBOARD REINFORCEMENT <i>Seal</i>	1	\$	650.00	✓
107	DASHBOARD METER <i>new</i>	1	\$	750.00	✓
108	PASSENGER DASHBOARD GARNISH <i>Sealed</i>	1	\$	850.00	✓
109	PASSENGER DASHBOARD TOOL BOX <i>new</i>	1	\$	250.00	✓
110	STEERING LOWER GARNISH <i>new</i>	1	\$	350.00	✓
111	STEERING RCK PINION ?	1	\$	20.00	✓
112	DRIVER'S STEERING <i>new</i>	1	\$	2,100.00	✓
113	GEAR LEVER GARNISH	1	\$	1,500.00	✓
114	LH FRONT SHOCK ABSORBER	1	\$	650.00	✓
115	LH FRONT LOWER ARM	1	\$	180.00	✓
116	LH FRONT KNOCKE ARM	1	\$	200.00	✓
117	LH FRONT KNOCKE ARM BEARING	1	\$	250.00	✓
118	LH FRONT DOOR <i>Distal</i>	1	\$	165.00	✓
119	LH FRONT DOOR HINGE UPPER ?	1	\$	850.00	✓
120	LH FRONT DOOR HINGE LOWER ?	1	\$	75.00	✓
121	LH FRONT DOOR CHECKER <i>Seal</i>	1	\$	75.00	✓
122	LH FRONT DOOR HANDLE OUTER ?	1	\$	55.00	✓
123	LH FRONT DOOR HANDLE INNER ?	1	\$	100.00	✓
124	LH FRONT DOOR GLASS <i>Shattered</i>	1	\$	120.00	✓
125	LH FRONT DOOR GLASS REGULATOR MOT <i>Sealed</i>	1	\$	500.00	✓
126	LH FRONT DOOR GLASS REGULATOR SWI <i>Seal</i>	1	\$	350.00	✓
127	LH FRONT DOOR GLASS SWITCH COVER <i>new</i>	1	\$	150.00	✓
128	LH FRONT DOOR SPEAKER <i>new sealed</i>	1	\$	150.00	✓
129	LH FRONT DOOR WEATHERSTRIP <i>new</i>	1	\$	360.00	✓
130	LH FRONT DOOR LOCK <i>Seal</i>	1	\$	200.00	✓
			\$	250.00	✓

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date : 20/9/19

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : GOODWILL ENTERTAINMENT HOLDING PTE LTD
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMCVSN1826881901 Accident Date : 18/9/19

Vehicle Number : GBH6629G

Make & Model : NISSAN NV350 PANEL VAN

ESTIMATED REPAIR COST DETAILS

S/N	DESCRIPTION	QTY	REPAIR AMOUNT	SURVEYOR APP.
1	BONNET <i>Dented</i>	1	\$ 700.00	✓
2	BONNET LOCK	1	\$ 125.00	✓
3	BONNET LOCK CATCH	1	\$ 100.00	✓
4	BONNET STANDER	1	\$ 65.00	✓
5	BONNET HINGE RH	1	\$ 65.00	✓
6	BONNET HINGE LH	1	\$ 65.00	✓
7	FRONT FIRE PANEL <i>Dented</i>	1	\$ 1,500.00	✓
8	FRONT WIPER PANEL <i>Dented</i>	1	\$ 450.00	✓
9	FRONT WIPER PANEL GARNISH <i>Dented</i>	1	\$ 200.00	✓
10	FRONT WIPER LINK RH	1	\$ 250.00	✓
11	FRONT WIPER LINK LH	1	\$ 250.00	✓
12	FRONT WIPER LINK MOTOR	1	\$ 550.00	✓
13	FRONT SUPPORT PANEL CENTER <i>Bent</i>	1	\$ 680.00	✓
14	FRONT SUPPORT PANEL BOTTOM <i>Broken</i>	1	\$ 650.00	✓
15	FRONT SUPPORT PANEL RH	1	\$ 135.00	✓
16	FRONT SUPPORT PANEL LH	1	\$ 135.00	✓
17	FRONT SUPPORT PANEL AIR GUIDE RH <i>Broken</i>	1	\$ 85.00	✓
18	FRONT SUPPORT PANEL AIR GUIDE LH	1	\$ 85.00	✓
19	FRONT WINDSCREEN GLASS <i>Shattered</i>	1	\$ 850.00	✓
20	FRONT WINDSCREEN GLASS MOULDING <i>Ne</i>	1	\$ 180.00	✓
21	FRONT WINDSCREEN PILLAR RH <i>Broken</i>	1	\$ 950.00	✓
22	FRONT WINDSCREEN PILLAR LH <i>Broken</i>	1	\$ 950.00	✓
23	RH HEADLAMP <i>Broken</i>	1	\$ 380.00	✓
24	LH HEADLAMP <i>Shattered</i>	1	\$ 380.00	✓
25	RH HEADLAMP BRACKET RH <i>Broken</i>	1	\$ 65.00	✓
26	LH HEADLAMP BRACKET LH <i>Broken</i>	1	\$ 65.00	✓

RH				
28	LH HEADLAMP PANEL		\$	350.00
29	FRONT FENDER RH <i>Repl wheel Arch garnish</i>	1	\$	550.00
30	FRONT FENDER LH <i>Repl wheel Arch garnish</i>	1	\$	550.00
31	FRONT FENDER INNER SHIELD RH <i>Repl wheel Arch garnish</i>	1	\$	165.00
32	FRONT FENDER INNER SHIELD LH <i>Repl wheel Arch garnish</i>	1	\$	165.00
33	CROSS MEMBER <i>new</i>	1	\$	1,800.00
34	ENGINE LOWER GARNISH <i>new</i>	1	\$	370.00
35	FRONT CHASSIS RH <i>Repl</i>	1	\$	550.00
36	FRONT CHASSIS LH <i>Repl</i>	1	\$	550.00
37	FRONT GRILLE <i>missing</i>	1	\$	550.00
38	FRONT GRILLE BRACKET RH <i>new green</i>	1	\$	55.00
39	FRONT GRILLE BRACKET LH <i>new green</i>	1	\$	55.00
40	FRONT GRILLE LOGO <i>new</i>	1	\$	65.00
41	FRONT BUMPER <i>Dischd</i>	1	\$	450.00
42	FRONT BUMPER FOG LAMP COVER RH <i>new</i>	1	\$	90.00
43	FRONT BUMPER FOG LAMP COVER LH <i>Dischd</i>	1	\$	90.00
44	FRONT BUMPER RETAINER RH <i>new</i>	1	\$	135.00
45	FRONT BUMPER RETAINER LH <i>new</i>	1	\$	135.00
46	FRONT BUMPER BRACKET RH <i>new</i>	1	\$	65.00
47	FRONT BUMPER BRACKET LH <i>new</i>	1	\$	65.00
48	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$	550.00
49	FRONT BUMPER GRILLE CENTRE <i>new</i>	1	\$	500.00
50	AIR DUCT <i>Dischd</i>	1	\$	150.00
51	AIR CLEANER BOX ASSY <i>new</i>	1	\$	650.00
52	AIR CLEANER HOSE <i>new</i>	1	\$	150.00
53	AIR CLEANER HOSE TOP ?	1	\$	250.00
54	AIR CLEANER HOUSING ?	1	\$	350.00
55	AIR CLEANER INTAKE DUCT <i>Dischd</i>	1	\$	550.00
56	AIR CLEANER INTAKE HOSE <i>new</i>	1	\$	280.00
57	AIR CLEANER OUTLET HOSE ?	1	\$	280.00
58	AIR CLEANER OUTER HOUSING ?	1	\$	650.00
59	AIR CLEANER PIPE ?	1	\$	390.00
60	AIR CON BLOWER <i>new</i>	1	\$	2,100.00
61	AIR CON BLOWER MOTOR <i>new</i>	1	\$	3,500.00
62	AIR CON COIL ?	1	\$	650.00
63	AIR RESONATOR ?	1	\$	120.00
64	TURBO <i>new</i>	1	\$	3,500.00
65	TURBO PIPE <i>new</i>	1	\$	250.00
66	INTER COOLER <i>new</i>	1	\$	2,800.00
67	INTER COOLER PIPE <i>new</i>	1	\$	450.00
68	OIL COOLER <i>new</i>	1	\$	650.00
69	OIL COOLER PIPE <i>new</i>	1	\$	165.00
70	WIPER TANK <i>Dischd</i>	1	\$	210.00
71	WIPER TANK MOTOR <i>new</i>	1	\$	560.00
72	WIPER TANK COVER <i>new</i>	1	\$	87.00
73	TIME BELT <i>new</i>	1	\$	290.00
74	TIME TENSIONER <i>new</i>	1	\$	188.00
75	TIME BEARING <i>new</i>	1	\$	75.00
76	ECU <i>new</i>	1	\$	3,500.00
77	ECU BRACKET <i>new</i>	1	\$	150.00
78	ECU MODULE	1	\$	850.00

80	ENGINE MOUNTING FRONT ?	1	\$	150.00	✓
81	ENGINE MOUNTING REAR ?	1	\$	185.00	✓
82	ENGINE MOUNTING RH ?	1	\$	165.00	✓
83	ENGINE MOUNTING LH ?	1	\$	165.00	✓
84	DRAF SHAFT <i>new</i>	1	\$	140.00	✓
85	HORN LOWER ?	1	\$	1,500.00	✓
86	HORN HIGH <i>missing</i>	1	\$	120.00	✓
87	FRONT WIPER HARNESS <i>new</i>	1	\$	120.00	✓
88	LH FRONT CONER PANEL <i>Dented</i>	1	\$	3,500.00	✓
89	RH FRONT CONER PANEL <i>Dented</i>	1	\$	350.00	✓
90	AIR CON CONDERSOR ?	1	\$	350.00	✓
91	AIR CON CONDENSOR DRY HOSE <i>Bent</i>	1	\$	500.00	✓
92	AIR CON DISCHARGE HOSE <i>3 Bent</i>	1	\$	180.00	✓
93	AIR CON RECIVE HOSE	1	\$	350.00	✓
94	RECEIVED DRIVER <i>Dented</i>	1	\$	270.00	✓
95	RADIATOR ?	1	\$	180.00	✓
96	RADIATOR FAN COWLING ?	1	\$	600.00	✓
97	RADIATOR FAN BLADE ?	1	\$	350.00	✓
98	RADIATOR FAN MOTOR ?	1	\$	320.00	✓
99	RADIATOR SPARE TANK ?	1	\$	450.00	✓
100	RADIATOR BRACKET RH ?	1	\$	95.00	✓
101	RADIATOR BRACKET LH ?	1	\$	65.00	✓
102	RADIATOR BOTTOM HOSE ?	1	\$	65.00	✓
103	RADIATOR MOUNTING TOP ?	1	\$	150.00	✓
104	DASHBOARD <i>new</i>	1	\$	150.00	✓
105	DASHBOARD COVER <i>cracked New</i>	1	\$	860.00	✓
106	DASHBOARD REINFORCEMENT <i>Bent</i>	1	\$	650.00	✓
107	DASHBOARD METER <i>new</i>	1	\$	750.00	✓
108	PASSENGER DASHBOARD GARNISH <i>cracked</i>	1	\$	850.00	✓
109	PASSENGER DASHBOARD TOOL BOX <i>new cracked</i>	1	\$	250.00	✓
110	STEERING LOWER GARNISH <i>new</i>	1	\$	350.00	✓
111	STEERING RCK PINION ? <i>new</i>	1	\$	20.00	✓
112	DRIVER'S STEERING	1	\$	2,100.00	✓
113	GEAR LEVER GARNISH	1	\$	1,500.00	✓
114	LH FRONT SHOCK ABSORBER	1	\$	650.00	✓
115	LH FRONT LOWER ARM	1	\$	180.00	✓
116	LH FRONT KNOCKE ARM	1	\$	200.00	✓
117	LH FRONT KNOCKE ARM BEARING	1	\$	250.00	✓
118	LH FRONT DOOR <i>Distorted</i>	1	\$	165.00	✓
119	LH FRONT DOOR HINGE UPPER ? <i>Bent</i>	1	\$	850.00	✓
120	LH FRONT DOOR HINGE LOWER	1	\$	75.00	✓
121	LH FRONT DOOR CHECKER <i>Bent</i>	1	\$	75.00	✓
122	LH FRONT DOOR HANDLE OUTER ? <i>new</i>	1	\$	55.00	✓
123	LH FRONT DOOR HANDLE INNER <i>new</i>	1	\$	100.00	✓
124	LH FRONT DOOR GLASS <i>Shattered</i>	1	\$	120.00	✓
125	LH FRONT DOOR GLASS REGULATOR MOT <i>new</i>	1	\$	500.00	✓
126	LH FRONT DOOR GLASS REGULATOR SWI <i>new</i>	1	\$	350.00	✓
127	LH FRONT DOOR GLASS SWITCH COVER <i>new</i>	1	\$	150.00	✓
128	LH FRONT DOOR SPEAKER <i>new</i>	1	\$	150.00	✓
129	LH FRONT DOOR WEATHERSTRIP <i>new</i>	1	\$	360.00	✓
130	LH FRONT DOOR LOCK <i>new</i>	1	\$	200.00	✓
		1	\$	250.00	✓

132 LH FRONT DOOR OUTER PILLAR	Dented	1	\$	2,000.00	
133 LH FRONT DOOR STEP PANEL	Set	1	\$	200.00	✓
134 LH FRONT DOOR STEP PANEL GARNISH	Dented	1	\$	130.00	✓
135 LH FRONT DOOR INNER TRIMBOARD	Painted	1	\$	500.00	✓
136 LH FRONT DOOR CENTRE PILLAR	Dented	1	\$	2,000.00	✓
137 RH FRONT DOOR	Regr	1	\$	850.00	x
138 RH FRONT DOOR HINGE UPPER	2	1	\$	75.00	+
139 RH FRONT DOOR HINGE LOWER	2	1	\$	75.00	+
140 RH FRONT DOOR CHECKER		1	\$	55.00	+
141 RH FRONT DOOR PILLAR	Regr	1	\$	1,500.00	+
142 RH SLIDING DOOR	Dented	1	\$	1,200.00	✓
143 RH REAR FENDER	Regr	1	\$	1,200.00	+
144 DRIVER SEAT	2 new	1	\$	950.00	+
145 PASSENGER SEAT	2 new	1	\$	950.00	+
146 DRIVER SEAT BUCKLE RH	new	1	\$	450.00	+
147 LH FRONT SEAT BELT	2 new	1	\$	900.00	+
148 RH FRONT SEAT BELT	2 new	1	\$	900.00	+
149 PASSENGER SEA BUCKLE LH		1	\$	550.00	+
150 FUSE BOX	new	1	\$	1,500.00	x
151 FUSE BOX COVER	new	1	\$	250.00	x
Sub Total			\$	82,623.00	
Make up 15% on Parts			\$	12,393.45	
Total			\$	95,016.45	

✓ M. Thompson ut ✓

Special Nett Item

1 FRONT NUMBER PLATE	Best	1	\$	65.00	30
2 TOWING FEE	new	1	\$	300.00	60
3 FRONT FENDER INNER SHIELD CLIPS	new	10	\$	65.00	+
4 FRONT DOOR SEALANT RH	2	1	\$	65.00	+
5 FRONT DOOR SEALANT LH	2 new	1	\$	65.00	+
6 FRONT CAMERA	new	1	\$	385.00	+
7 FRONT BUMPER TOWING COVER RH & LH	new	2	\$	100.00	20
8 IU BRACKET	new	1	\$	65.00	30
9 COOLANT	Na	1	\$	65.00	50
10 BONNET STOPPER	new	10	\$	100.00	+
11 IU BRACKET	Regr	1	\$	65.00	+
12 AIR FILTER	?	1	\$	35.00	+
13 ENGINE OIL	2 new	1	\$	100.00	+
14 OIL FILTER		1	\$	45.00	+
15 FRONT GRILLE CLIPS	new	10	\$	65.00	20
16 FRONT WIPER BALDE RH	2 new	1	\$	65.00	+
17 FRONT WIPER BLADE LH	2 new	1	\$	65.00	+
18 FRONT FENDER INNER SHIELD CLIPS	new	10	\$	65.00	+
19 FRONT BUMPER CLIPS	new	10	\$	65.00	30
20 HEADSET MONITOR	new	1	\$	350.00	+
21 RH FRONT DOOR STICKER	2 new	1	\$	25.00	✓
22 LH FRONT DOOR STICKER	2 new	1	\$	25.00	✓
23 FRONT WINDSCREEN SEALANT	new	1	\$	50.00	✓
Sub Total			\$	2,275.00	

Labour & Misc

1	LABOUR TO FACILITATE REPAIR	\$	4,500.00	2400
2	R & R ENGINE COMPARTMENT	\$	250.00	✓
3	RUST PROOF ON AFFECTED AREAS	\$	50.00	✓
4	R & R FRONT WINDSCREEN	\$	180.00	120
5	TO VACCUM AIR CON SYSTEM & REFILL GAS	\$	120.00	✓
6	TO CHECK LIGHTING AND FOCUS HEADLAMP	\$	150.00	20
7	TO REMOVE AND REFIT DASHBOARD TO ASSIST WORK	\$	250.00	220
8	TO RE-ALIGN EXHAUST CATALYST CONVERTER	\$	25.00	✓
9	TO CHECK ELECTRICAL WIRING FOR FRONT LIG	\$	130.00	20
10	TO RESET AND PROGRAM ECU AND FAULT CODE	\$	250.00	✓
11	TO DISMANTLE SEATS & REPLACE NEW PARTS	\$	350.00	✓
12	TO CONDUCT CHASSIS ALIGNMENT	\$	350.00	250
13	TO TRANSFER RH FRONT DOOR AND REFIT NEW DOOR	\$	150.00	80 X
14	TO REMOVE AND REFIT LH FRONT DOOR	\$	150.00	80
15	TO SPRAY PAINT LH FRONT DOOR	\$	250.00	200
16	TO SPRAY PAINT LH FRONT FENDER <i>RH Rear Fender</i>	\$	250.00	✓
17	TO SPRAY PAINT RH FRONT FENDER	\$	250.00	✓
18	TO SPRAY PAINT RH SLIDING DOOR	\$	250.00	200
19	TO SPRAY PAINT LH SLIDING DOOR	\$	250.00	200
20	TO SPRAY PAINT ON LH REAR FENDER	\$	250.00	✓
21	TO SPRAY PAINT TAILGATE	\$	250.00	✓
22	TO SPRAY PAINT REAR BUMPER	\$	250.00	200
23	TO SPRAY PAINT RH FRONT DOOR	\$	150.00	✓
24	TO SPRAY PAINT FRONT BUMPER	\$	250.00	200
25	TO SPRAY PAINT FRONT SUPPORT PANEL	\$	250.00	✓
26	TO SPRAY PAINT BONNET	\$	250.00	200
27	TO SPRAY PAINT FRONT BUMPER REINFORCEMENT	\$	250.00	✓
	Sub Total	\$	10,025.00	
	 Grand Total	\$	 107,316.45	

Adrian King
2/2 24/05/19
21 Days.

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

SUPPLEMENTARY

Date : 14/10/2019

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : GOODWILL ENTERTAINMENT HOLDING PTE LTD

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMCVSN1826881901

Accident Date : 18/09/2019

Vehicle Number : GBH6629G

Make & Model : NISSAN NV350

ESTIMATED REPAIR COST DETAILS

S/N	DESCRIPTION	QTY	REPAIR AMOUNT	SURVEYOR APP.
1	GEAR BOX <i>Plan</i>	1	\$ 2,500.00	<i>JS</i>
2	FRONT PANEL LOWER LH <i>Assembled</i>	1	\$ 250.00	<i>JS</i>
3	BRACKET PEDAL UPPER <i>Assembled</i>	1	\$ 180.00	<i>JS</i>
4	FRT KICKING PLATE LH <i>Assembled</i>	1	\$ 200.00	<i>JS</i>
5	FRONT BUMPER BAR <i>Best</i>	1	\$ 165.00	<i>JS</i>
6	OIL COOLANT BRACKET <i>Assembled</i>	1	\$ 165.00	<i>JS</i>
7	RH TAIL LAMP <i>Assembled</i>	1	\$ 280.00	<i>JS</i>
	Sub Total		\$ 3,740.00	
	TOTAL		\$ 3,740.00	
Special Note:				
1	REPLACE GEAR BOX OIL	1	\$ 150.00	<i>JS</i>
2	REPLACE GEAR BOX VALVE SEAL 1 SET	1	\$ 150.00	<i>JS</i>
3	LABOUR CHARGE FOR REMOVE AND REFIT GEAR BOX FLUSHING GEAR BOX		\$ 1,500.00	<i>JS</i>
	Sub Total		\$ 1,800.00	
	Grand Total		\$ 5,540.00	

Admin
15/10/19.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 12 November 2019 3:27 PM
To: 'STK STK'; Chong Boon Sen; SUR
Subject: RE: FW: GBH6629H -DOA: 18/9/2019 (CHINA TAIPING OD)
Attachments: SATISFACTION NOTE WITH SIGN (1).jpeg; Invoice 2018-3840 COST OF REPAIR (1).pdf

Dear Linda,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: STK STK <stkautosg@gmail.com>
Sent: Tuesday, 12 November 2019 3:14 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: FW: GBH6629H -DOA: 18/9/2019 (CHINA TAIPING OD)

Dear Veron

Please refer to attached document for your proceed the payment.

Yours sincerely

Tan Guohua

Chief Executive Officer

STK AUTO (S) PTE LTD | www.stkauto.com.sg

Mobile: (65) 9123 7949 | Tel: (65) 63860669

8 Kaki Bukit Ave 4 #03-21 Singapore 415875 @PREMIER



Veron Chen (LKKAUTO) <veronchen@lkkauto.com> 于2019年11月12日周二 上午9:58写道 :

Dear Linda,

Offer Lump Sum \$30,000/- before excess \$350 @ 21 days.

If confirm, please forward invoice and discharge voucher.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)

Sent: Thursday, 26 September 2019 7:45 AM

To: STK STK <stkaautosg@gmail.com>; SUR <sur@lkkauto.com>

Subject: RE: GBH6629H -DOA: 18/9/2019 (CHINA TAIPING OD)

Dear Linda/Guo Hua,

Attach DV.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)

Sent: Wednesday, 25 September 2019 1:45 PM

To: STK STK <stkaautosg@gmail.com<<mailto:stkaautosg@gmail.com>>>; SUR

<sur@lkkauto.com<<mailto:sur@lkkauto.com>>>

Subject: RE: GBH6629H -DOA: 18/9/2019 (CHINA TAIPING OD)

Dear Linda/Guo Hua,

As instructed by our client , please proceed to repair the insured vehicle GBH 6629G, not exceeding Lump Sum Repair \$30,000/- (Excess \$350/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before

completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: STK STK <stkautosg@gmail.com<<mailto:stkautosg@gmail.com>>>
Sent: Tuesday, 24 September 2019 2:13 PM
To: assignments <assignments@lkkauto.com<<mailto:assignments@lkkauto.com>>>; SUR
<sur@lkkauto.com<<mailto:sur@lkkauto.com>>>
Subject: RE: GBH6629H -ESTIMATE

Dear

please refer to attachment.

Yours sincerely

Tan Guohua

Chief Executive Officer

STK AUTO (S) PTE LTD | www.stkauto.com.sg<<http://www.stkauto.com.sg/>>

Mobile: (65) 9123 7949 | Tel: (65) 63860669

8 Kaki Bukit Ave 4 #03-21 Singapore 415875 @PREMIER

[<https://docs.google.com/uc?export=download&id=0B5QCnAUqS3C2UzI1ZGFrVG55V1U&revid=0B5QCnAUqS3C2T29iY1dKTFFIMTBzdDVUcWI2UFg3UFVDMUZFPQ>]

SATISFACTION VOUCHER

Name & Address of Insured:

Goodwill Entertainment Holding Pte Ltd

33 UBI AVE 3
05-16
Venter 542886

STK AUTO

www.stkauto.com.sg

Name & Address of Repairers:

8 Kaki Bukit Ave 4 #03-21 Singapore 415871

Tel: 63860069 Fax: 63860069 Hotline(24hrs): 81227949

Date & Place of Accident:

Policy No:

DMCVSN/182688/901

Claim No:

Vehicle No:

GBH 6629G

Cost of Repairs:

31725.50

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., settling the repair costs stated above with the said repairers I/We hereby release and discharge the said Insurers from all further obligations and liabilities under the aforesaid policy in respect of an accident involving my/our said motor vehicle on the above-mentioned date and place.

I/We agree that by virtue of such payment the said Insurers are subrogated to all my/our rights and remedies in respect of the damage to the said Motor Vehicle in accordance with the laws governing the Contract of Insurance.

I/We hereby grant the said Insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefor. I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their part they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:-



Company's Chop & Signature

INSURED:-



Company's Chop & Signature

WITNESS:-

Linda 林秀林

Name & Signature

8 Kaki Bukit Ave 4 #03-21

Premier @ Kaki Bukit Singapore 415871

Address

25/10/2019

Date

WITNESS:-

XIE YUNFENG

Name & Signature

BLK 706 TAMARIS STREET 71 #1-76

Address

25/10/2019

Date



TAX INVOICE

GBH6629G
Attention: MOTOR CLAIM DEPT
CHINA TAIPING INSURANCE (SINGAPORE) PTE
LTD
3 Anson Rd, #16-00 Springleaf Tower, 079909
6389 6111

Invoice Date
12 Nov 2019
Invoice Number
2018-3840
UEN/GST Reg. No.
201539883N

STK AUTO (S) PTE LTD
8 Kaki Bukit Ave 4
#03-21 Premier@Kaki Bukit
Singapore 415875
HP:91237949
Tel:63860669

Description	Quantity	Unit Price	Amount SGD
COST OF REPAIR DOA :18/09/2019	1.00	30,000.00	30,000.00
LESS EXCESS	1.00	(350.00)	(350.00)
		Subtotal	29,650.00
		INCLUDES SALES GST 7%	2,075.50
		TOTAL SGD	31,725.50

Due Date: 12 Nov 2019

- ** Received In Good Order & Condition. Goods Sold Are Not Refundable/Return.
- ** Interest rate of 5% per month, calculated on a daily basis, is levied on payment for overdue amount/account owing to STK AUTO (S) PTE LTD after seven (7) days from date of invoice.
- ** Cheque should be crossed and make payable to "STK AUTO (S) PTE LTD".
- ** Transfer to OCBC current account: 6951-58626-001

Customer's Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2019		23 Sep 2019 17:29 Edit Adj Rpt	S\$30,000.00 Edit Estimates	S\$30,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	M/S GOODWILL ENTERTAINMENT HOLDING PTE LTD, Co. Reg. No.: -								
Vehicle Reg. No.:	GBH6629G	Date of Loss:	18/09/2019 19:00 - :59 [12 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D204426C01	Policy/Cover Note No.:	DMCVSN1826881901 (Comprehensive)						
		Excess:	S\$350.00						
Repairer:	Stk Auto (s) Pte Ltd (HQ) 8 kaki bukit ave4, #03-21, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/10/2019]								
Driver/Custodian:	GAO FUZE (36 / Male) , NRIC: G3211540W, Tel: +6582929699 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (18/10/2019): Alert - Adj Mandate Approved (S\$30000.00) - GBH6629G - Claim Handler: Elaine Che... - CHINA_TAIPING (25/09/2019): Alert - Adj Mandate Approved (S\$30000.00) - GBH6629G - Claim Handler: Elaine Che...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH6629G (SNM19D204426C01)

OD

Sep 18 2019 7:00PM

[M/S GOODWILL ENTERTAINMENT HOLDING PTE LTD]

Stk Auto (s) Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	19/09/19 15:13	Accident Statement	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/09/19 11:09	Adjuster Immediate Advice	1	Load HTM	
2	16/10/19 14:59	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
2	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
3	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
4	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
5	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
6	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
7	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
8	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
9	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
10	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
11	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
12	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
13	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
14	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
15	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
16	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
17	19/09/19 15:10	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/09/19 09:36	General View	1	Load PDF	
2	16/10/19 12:07	Reinspection Photo (1)	1	Load PDF	
3	16/10/19 12:07	Reinspection Photo (2)	1	Load PDF	
Documentation				1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	23/09/19 17:44	OD - GBH6629G	1	Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	19/09/19 15:11	Accident Sketch Plan [Linked Accident Report Documents]	1	Load JPG	☒
2	19/09/19 15:11	Accident Sketch Plan [Linked Accident Report Documents]	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/09/19 09:36	MARK ESTIMATE	1	Load PDF	
2	16/10/19 12:52	SUPPLEMENTARY	1	Load PDF	
3	12/11/19 15:30	WORKSHOP INVOICE	1	Load PDF	
4	12/11/19 15:30	DISCHARGE VOUCHER	1	Load JPG	☒

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
1	19/09/19 15:13	Accident Statement	 Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
1	19/09/19 15:10	Accident Photo	 Load JPG	☒
2	19/09/19 15:10	Accident Photo	 Load JPG	☒
3	19/09/19 15:10	Accident Photo	 Load JPG	☒
4	19/09/19 15:10	Accident Photo	 Load JPG	☒
5	19/09/19 15:10	Accident Photo	 Load JPG	☒
6	19/09/19 15:10	Accident Photo	 Load JPG	☒
7	19/09/19 15:10	Accident Photo	 Load JPG	☒
8	19/09/19 15:10	Accident Photo	 Load JPG	☒
9	19/09/19 15:10	Accident Photo	 Load JPG	☒
10	19/09/19 15:10	Accident Photo	 Load JPG	☒
11	19/09/19 15:10	Accident Photo	 Load JPG	☒
12	19/09/19 15:10	Accident Photo	 Load JPG	☒
13	19/09/19 15:10	Accident Photo	 Load JPG	☒
14	19/09/19 15:10	Accident Photo	 Load JPG	☒
15	19/09/19 15:10	Accident Photo	 Load JPG	☒
16	19/09/19 15:10	Accident Photo	 Load JPG	☒
17	19/09/19 15:10	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
1	19/09/19 15:11	Accident Sketch Plan	 Load JPG	☒
2	19/09/19 15:11	Accident Sketch Plan	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
^ v Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19016807/AVF3E2

Date: 25/11/2019

REFERENCE

Insured/Claimant: M/S GOODWILL ENTERTAINMENT HOLDING PTE LTD

Policy No: DMCVSN1826881901

Date of Loss: 18/09/2019

Nature of Claim: OD

Claim No: SNM19D204426C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH6629G

Make & Model: NISSAN NV350, 2.5 D Panel Van (M)

Engine No: YD25032208B

Reg. Date: 28/08/2018 (Man. Year: 2018)

Chassis No: JN1MC2E26Z0030469

Colour: White

Odometer: 0 km

Engine Capacity: 2488 cc

Market Value/New Car Price: S\$55,000.00

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	91,284.55	32,848.00	58,436.55	64.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,125.00	5,090.00	6,035.00	54.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	102,409.55	37,938.00	64,471.55	62.95
Approved Total (Overridden) (S\$)		30,000.00		
- Excess (S\$)	350.00	350.00	0.00	0.00
(S\$)	102,059.55	29,650.00	72,409.55	70.95
+ GST 7.00/7.00% (S\$)	7,144.17	2,075.50	5,068.67	70.95
Nett Amount (S\$)	109,203.72	31,725.50	77,478.22	70.95

INSPECTION

Date of Assignment: 23/09/2019

Date Inspected: 24/09/2019 Inspected At:

Stk Auto (s) Pte Ltd (HQ)
8 kaki bukit ave4, #03-21
Singapore 415875

Estimated Period of Repair: 21.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 25 Nov 2019)
Parts:	N/A	NISSAN NV350 2.5 D Panel Van (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBH6629G)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FIRE PANEL (WCP)	Dented	1,500.00 F	*1,500.00 F
2	1		*FRONT WIPER PANEL (WCP)	Dented	450.00 F	*450.00 F
3	1		*FRONT WIPER PANEL GARNISH (WCP)	Deformed	200.00 F	*200.00 F
4	1		*FRONT WIPER LINK RH (WCP)	Bent	250.00 F	*250.00 F
5	1		*FRONT WIPER LINK LH (WCP)	Not Necessary	250.00 F	*- F
6	1		*FRONT WIPER LINK MOTOR (WCP)	Not Necessary	550.00 F	*- F
7	1		*FRONT WINDSCREEN GLASS (WCP)	Shattered	850.00 F	*850.00 F
8	1		*FRONT WINDSCREEN GLASS MOULDING (WCP)	Necessary	180.00 F	*180.00 F
9	1		*FRONT WINDSCREEN PILLAR RH (WCP)	Repair	950.00 F	*- F
10	1		*FRONT WINDSCREEN PILLAR LH (WCP)	Buckled	950.00 F	*950.00 F
11	1		*RH HEADLAMP (WCP)	Cut	350.00 F	*350.00 F
12	1		*LH HEADLAMP (WCP)	Smashed	350.00 F	*350.00 F
13	1		*RH HEADLAMP BRACKET RH (WCP)	Not Necessary	65.00 F	*- F
14	1		*LH HEADLAMP BRACKET LH (WCP)	Not Necessary	65.00 F	*- F
15	1		*RH HEADLAMP PANEL (WCP)	Not Necessary	350.00 F	*- F
16	1		*LH HEADLAMP PANEL (WCP)	Not Necessary	350.00 F	*- F
17	1		*FRONT WHEEL ARCH RH (WCP)	Repair	650.00 F	*- F
18	1		*FRONT WHEEL ARCH LH (WCP)	Distorted	650.00 F	*650.00 F
19	1		*FRONT WHEEL ARCH GARNISH RH (WCP)	Not Necessary	165.00 F	*- F
20	1		*FRONT WHEEL ARCH GARNISH LH (WCP)	Deformed	165.00 F	*165.00 F
21	1		*CROSS MEMBER (WCP)	Not Necessary	1,800.00 F	*- F
22	1		*ENGINE LOWER GARNISH (WCP)	Not Necessary	370.00 F	*- F
23	1		*FRONT CHASSIS RH (WCP)	Repair	550.00 F	*- F
24	1		*FRONT CHASSIS LH (WCP)	Repair	550.00 F	*- F
25	1		*FRONT GRILLE (WCP)	Missing	550.00 F	*550.00 F
26	1		*FRONT GRILLE BRACKET RH (WCP)	Not Necessary	55.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*FRONT GRILLE BRACKET LH (WCP)	Not Necessary	55.00 F	*- F
28	1		*FRONT GRILLE LOGO (WCP)	Necessary	65.00 F	*65.00 F
29	1		*FRONT BUMPER (WCP)	Distorted	450.00 F	*450.00 F
30	1		*FRONT BUMPER FOG LAMP COVER RH (WCP)	Not Necessary	135.00 F	*- F
31	1		*FRONT BUMPER FOG LAMP COVER LH (WCP)	Distorted	135.00 F	*135.00 F
32	1		*FRONT BUMPER RETAINER RH (WCP)	Necessary	90.00 F	*90.00 F
33	1		*FRONT BUMPER RETAINER LH (WCP)	Necessary	90.00 F	*90.00 F
34	1		*FRONT BUMPER BRACKET RH (WCP)	Not Necessary	65.00 F	*- F
35	1		*FRONT BUMPER BRACKET LH (WCP)	Bent	65.00 F	*65.00 F
36	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	550.00 F	*550.00 F
37	1		*FRONT BUMPER GRILLE CENTRE (WCP)	Cracked	400.00 F	*400.00 F
38	1		*AIR DUCT (WCP)	Deformed	150.00 F	*150.00 F
39	1		*AIR CLEANER BOX ASSY (WCP)	Cracked	650.00 F	*650.00 F
40	1		*AIR CLEANER HOSE (WCP)	Cracked	150.00 F	*150.00 F
41	1		*AIR CLEANER HOSE TOP (WCP)	Not Necessary	250.00 F	*- F
42	1		*AIR CLEANER HOUSING (WCP)	Not Necessary	350.00 F	*- F
43	1		*AIR CLEANER INTAKE DUCT (WCP)	Distorted	550.00 F	*550.00 F
44	1		*AIR CLEANER INTAKE HOSE (WCP)	Distorted	280.00 F	*280.00 F
45	1		*AIR CLEANER OUTLET HOSE (WCP)	Not Necessary	280.00 F	*- F
46	1		*AIR CLEANER OUTER HOUSING (WCP)	Not Necessary	650.00 F	*- F
47	1		*AIR CLEANER PIPE (WCP)	Not Necessary	390.00 F	*- F
48	1		*AIR CON BLOWER (WCP)	Cracked	2,100.00 F	*2,100.00 F
49	1		*AIR CON BLOWER MOTOR (WCP)	Not Necessary	3,500.00 F	*- F
50	1		*AIR CON COIL (WCP)	Cracked	650.00 F	*650.00 F
51	1		*AIR RESONATOR (WCP)	Not Necessary	120.00 F	*- F
52	1		*TURBO (WCP)	Not Necessary	3,500.00 F	*- F
53	1		*TURBO PIPE (WCP)	Bent	250.00 F	*250.00 F
54	1		*INTER COOLER (WCP)	Not Necessary	2,800.00 F	*- F
55	1		*INTER COOLER PIPE (WCP)	Not Necessary	450.00 F	*- F
56	1		*OIL COOLER (WCP)	Bent	1,500.00 F	*1,500.00 F
57	1		*OIL COOLER PIPER (WCP)	Bent	165.00 F	*165.00 F
58	1		*WIPER TANK (WCP)	Distorted	210.00 F	*210.00 F
59	1		*WIPER TANK MOTOR (WCP)	Damaged	560.00 F	*560.00 F
60	1		*WIPER TANK COVER (WCP)	Not Necessary	87.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
61	1		*DRAF SHAFT (WCP)	Not Necessary	1,500.00 F	*- F
62	1		*HORN LOWER (WCP)	Missing	120.00 F	*120.00 F
63	1		*HORN HIGH (WCP)	Not Necessary	120.00 F	*- F
64	1		*FRONT WIPER HARNESS (WCP)	Not Necessary	3,500.00 F	*- F
65	1		*LH FRONT CONER PANEL (WCP)	Dented	350.00 F	*350.00 F
66	1		*RH FRONT CONER PANEL (WCP)	Repair	350.00 F	*- F
67	1		*AIR CON CONDERSOR (WCP)	Not Necessary	500.00 F	*- F
68	1		*AIR CON CONDENSOR DRY HOSE (WCP)	Bent	180.00 F	*180.00 F
69	1		*AIR CON DISCHARGE HOSE (WCP)	Bent	350.00 F	*350.00 F
70	1		*AIR CON RECIVE HOSE (WCP)	Bent	270.00 F	*270.00 F
71	1		*RECEIVED DRIVER (WCP)	Dented	180.00 F	*180.00 F
72	1		*RADIATOR (WCP)	Not Necessary	550.00 F	*- F
73	1		*RADIATOR FAN COWLING (WCP)	Not Necessary	350.00 F	*- F
74	1		*RADIATOR FAN BLADE (WCP)	Not Necessary	320.00 F	*- F
75	1		*RADIATOR FAN MOTOR (WCP)	Not Necessary	450.00 F	*- F
76	1		*RADIATOR SPARE TANK (WCP)	Not Necessary	95.00 F	*- F
77	1		*RADIATOR BRACKET RH (WCP)	Not Necessary	65.00 F	*- F
78	1		*RADIATOR BRACKET LH (WCP)	Not Necessary	65.00 F	*- F
79	1		*RADIATOR BOTTOM HOSE (WCP)	Not Necessary	150.00 F	*- F
80	1		*RADIATOR MOUNTING TOP (WCP)	Not Necessary	150.00 F	*- F
81	1		*DASH BOARD (WCP)	Not Necessary	860.00 F	*- F
82	1		*DASHBOARD COVER (WCP)	Not Necessary	650.00 F	*- F
83	1		*DASHBOARD REINFORCEMENT (WCP)	Bent	750.00 F	*750.00 F
84	1		*DASHBOARD METER (WCP)	Not Necessary	850.00 F	*- F
85	1		*PASSENGER DASHBOARD GARNISH (WCP)	Cracked	250.00 F	*250.00 F
86	1		*PASSENGER DASHBOARD TOOL BOX (WCP)	Cracked	350.00 F	*350.00 F
87	1		*STEERING LOWER GARNISH (WCP)	Not Necessary	20.00 F	*- F
88	1		*STEERING RCK PINION (WCP)	Not Necessary	2,100.00 F	*- F
89	1		*DRIVERS STEERING (WCP)	Not Necessary	1,500.00 F	*- F
90	1		*GEAR LEVER GARNISH (WCP)	Not Necessary	650.00 F	*- F
91	1		*LH FRONT SHOCK ABSORBER (WCP)	Not Necessary	180.00 F	*- F
92	1		*LH FRONT LOWER ARM (WCP)	Not Necessary	200.00 F	*- F
93	1		*LH FRONT KNOCKE ARM (WCP)	Not Necessary	250.00 F	*- F
94	1		*LH FRONT KNOCKE ARM BEARING (WCP)	Not Necessary	165.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
95	1		*LH FRONT DOOR (WCP)	Distorted	850.00 F	*850.00 F
96	1		*LH FRONT DOOR HINGE UPPER (WCP)	Bent	75.00 F	*75.00 F
97	1		*LH FRONT DOOR HINGE LOWER (WCP)	Bent	75.00 F	*75.00 F
98	1		*LH FRONT DOOR CHECKER (WCP)	Bent	55.00 F	*55.00 F
99	1		*LH FRONT DOOR HANDLE OUTER (WCP)	Not Necessary	100.00 F	*- F
100	1		*LH FRONT DOOR HANDLE INNER (WCP)	Cracked	120.00 F	*120.00 F
101	1		*LH FRONT DOOR GLASS (WCP)	Shattered	500.00 F	*500.00 F
102	1		*LH FRONT DOOR GLASS REGULATOR MOT (WCP)	Damaged	350.00 F	*350.00 F
103	1		*LH FRONT DOOR GLASS REGULATOR SWIT (WCP)	Damaged	150.00 F	*150.00 F
104	1		*LH FRONT DOOR GLASS SWITCH COVER (WCP)	Not Necessary	150.00 F	*- F
105	1		*LH FRONT DOOR SPEAKER (WCP)	Cracked	360.00 F	*360.00 F
106	1		*LH FRONT DOOR WEATHERSTRIP (WCP)	Cut	200.00 F	*200.00 F
107	1		*LH FRONT DOOR LOCK (WCP)	Damaged	250.00 F	*250.00 F
108	1		*LH FRONT DOOR INNER PILLAR (WCP)	Repair	1,500.00 F	*- F
109	1		*LH FRONT DOOR OUTER PILLAR (WCP)	Distorted	1,500.00 F	*1,500.00 F
110	1		*LH FRONT DOOR STEP PANEL (WCP)	Bent	200.00 F	*200.00 F
111	1		*LH FRONT DOOR STEP PANEL GARNISH (WCP)	Dented	130.00 F	*130.00 F
112	1		*LH FRONT DOOR INNER TRIMBOARD (WCP)	Cracked	500.00 F	*500.00 F
113	1		*LH FRONT DOOR CENTRE PILLAR (WCP)	Dented	1,500.00 F	*1,500.00 F
114	1		*RH FRONT DOOR (WCP)	Repair	850.00 F	*- F
115	1		*RH FRONT DOOR HINGE UPPER (WCP)	Not Necessary	75.00 F	*- F
116	1		*RH FRONT DOOR HINGE LOWER (WCP)	Not Necessary	75.00 F	*- F
117	1		*RH FRONT DOOR CHECKER (WCP)	Not Necessary	55.00 F	*- F
118	1		*RH FRONT DOOR PILLAR (WCP)	Repair	1,500.00 F	*- F
119	1		*RH SLIDING DOOR (WCP)	Dented	1,200.00 F	*1,200.00 F
120	1		*RH REAR FENDER (WCP)	Repair	1,200.00 F	*- F
121	1		*DRIVER SEAT (WCP)	Not Necessary	950.00 F	*- F
122	1		*PASSENGER SEAT (WCP)	Not Necessary	950.00 F	*- F
123	1		*DRIVER SEAT BUCKLE RH (WCP)	Not Necessary	450.00 F	*- F
124	1		*LH FRONT SEAT BELT (WCP)	Not Necessary	900.00 F	*- F
125	1		*RH FRONT SEAT BELT (WCP)	Not Necessary	900.00 F	*- F
126	1		*PASSENGER SEA BUCKLE LH (WCP)	Not Necessary	550.00 F	*- F
127	1		*FUSE BOX (WCP)	Not Necessary	1,500.00 F	*- F
128	1		*FUSE BOX COVER (WCP)	Not Necessary	250.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
129	1		*RH TAILLAMP (WCP)	Cut	180.00 F	*180.00 F
130	1		*FRONT NUMBER PLATE	Bent	65.00 FS	*30.00 FS
131	1		*FRONT DOOR SEALANT RH	Not Necessary	65.00 FS	*- FS
132	1		*FRONT DOOR SEALANT LH	Not Necessary	65.00 FS	*- FS
133	1		*FRONT CAMERA	Not Necessary	365.00 FS	*- FS
134	2		*FRONT BUMPER TOWING COVER RH & LH	Necessary	100.00 FS	*20.00 FS
135	1		*IU BRACKET	Necessary	65.00 FS	*30.00 FS
136	1		*COOLANT	Necessary	65.00 FS	*50.00 FS
137	10		*BONNET STOPPER	Not Necessary	100.00 FS	*- FS
138	1		*IU BRACKET	Repair	65.00 FS	*- FS
139	1		*AIR FILTER	Not Necessary	35.00 FS	*- FS
140	1		*ENGINE OIL	Not Necessary	100.00 FS	*- FS
141	1		*OIL FILTER	Not Necessary	45.00 FS	*- FS
142	10		*FRONT GRILLE CLIPS	Necessary	65.00 FS	*20.00 FS
143	1		*FRONT WIPER BLADE RH	Not Necessary	65.00 FS	*- FS
144	1		*FRONT WIPER BLADE LH	Not Necessary	65.00 FS	*- FS
145	10		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	65.00 FS	*- FS
146	10		*FRONT BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
147	1		*HEADSET MONITOR	Not Necessary	350.00 FS	*- FS
148	1		*RH FRONT DOOR STICKER	Necessary	25.00 FS	*25.00 FS
149	1		*LH FRONT DOOR STICKER	Necessary	25.00 FS	*25.00 FS
150	1		*FRONT WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
151	1		*GEAR BOX (WCP)	Not Necessary	2,500.00 F	*- F
152	1		*FRONT PANEL LOWER LH (WCP)	Distorted	250.00 F	*250.00 F
153	1		*BRACKET PEDAL UPPER (WCP)	Distorted	180.00 F	*180.00 F
154	1		*FRT KICKING PLATE LH (WCP)	Cracked	200.00 F	*200.00 F
155	1		*FRONT BUMPER BAR (WCP)	Bent	165.00 F	*165.00 F
156	1		*OIL COOLANT BRACKET (WCP)	Damaged	165.00 F	*165.00 F
157	1		*RH TAILLAMP (WCP)	Cut	280.00 F	*280.00 F
158	1		*BONNET (WCP)	Distorted	580.00 F	*580.00 F
F=Franchise part, S=SpcNett.						
Sub Total (\$\$)					79,627.00	28,600.00
+ Margin on L,N Items 15.00/15.00% (\$\$)					11,657.55	4,248.00
Total Parts (\$\$)					91,284.55	32,848.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	300.00	60.00
2	LABOUR TO FACILITATE REPAIR	New	4,500.00	2,400.00
3	R & R ENGINE COMPARTMENT	New	250.00	0.00
4	RUST PROOF ON AFFECTED AREAS	New	50.00	50.00
5	R & R FRONT WINDSCREEN	New	150.00	120.00
6	TO VACUUM AIR CON SYSTEM & REFILL GAS	New	120.00	120.00
7	TO CHECK LIGHTING AND FOCUS HEADLAMP	New	150.00	30.00
8	TO REMOVE AND REFITX DASHBOARD TO ASSIST WORK	New	250.00	220.00
9	TO RE-ALIGN EXHAUST CATALYST CONVERTER	New	25.00	0.00
10	TO CHECK ELECTORICAL WIRING FOR FORNT LIG	New	130.00	30.00
11	TO RESET AND PROGRAM ECU AND FAULT CODE	New	250.00	0.00
12	TO DISMANTLE SEATS & REPLACE NEW PARTS	New	350.00	0.00
13	TO CONDUCT CHASSIS LIGNMENT	New	350.00	250.00
14	TO TRANSFER RH FRONT DOOR AND REFIT NEW DOOR	New	150.00	0.00
15	TO REMOVE AND REFIT LH FRONT DOOR	New	150.00	80.00
16	TO SPRAY PAINT RH SLIDING DOOR	New	250.00	200.00
17	TO SPRAY PAINT LH SLIDING DOOR	New	250.00	200.00
18	TO SPRAY PAINT ON LH REAR FENDER	New	250.00	250.00
19	TO SPRAY PAINT TAILGATE	New	250.00	250.00
20	TO SPRAY PAINT REAR BUMPER	New	250.00	200.00
21	TO SPRAY PAINT RH FRONT DOOR	New	150.00	150.00
22	TO SPRAY PAINT FRONT BUMPER	New	250.00	200.00
23	TO SPRAY PAINT BONNET	New	250.00	200.00
24	TO SPRAY PAINT FRONT BUMPER REINFORCEMENT	New	250.00	0.00
25	REPLACE GEAR BOX OIL	New	150.00	80.00
26	REPLACE GEAR BOX VALVE SEAL 1 SET	New	150.00	0.00
27	LABOUR CHARGE FOR REMOVE AND REFIT GEAR BOX FLUSHING GEAR BOX	New	1,500.00	0.00
Gross Labour Cost (S\$)			11,125.00	5,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >