

# TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188  
Customer Detail

Jo : 196700086Z  
g No : MR-8500000-9

## ESTIMATE

load "My Toyota SG" app on Playstore or Appstore to access your Toyota account & more!


Account Detail	Account No	Mr Tan Guan Cheng 60 Lakeside Drive #06-39 Singapore 648320 Mobile: 97545348
SIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	
	Document No	
	0	
	Document Date	
	23/09/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
	JETHEHT E4	ASV51R	27/10/2015	SKW3569E	0	48877	.50D/SKW3569E/21091
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

053DK5100103645	6ARPO53114	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00
-----------------	------------	----	------------------	------------	------	------------	------

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
2	BP-SUNDRY SUNDRIES POLICY NO.: A29098945 ACC DATE: 21.09.19 TOW IN : 22.09.19 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
L	BP-LPO SUPPLY REGN PLATE (PO# ) (frit with casing)				61 68.00
Z	BP-SLANT SUPPLY SEALANT (NETT) (2 SETS)				200.00
B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP.				180.00
B	BP-LAB2 DRILL HOLE TO INSTALL FRT BUMPER SENSOR.				180.00
B	BP-MECH2 RESET AND REPROGRAMME ECU.				180.00
B	BP-MECH2 REMOVE AIR CON COMPONENTS TO REGAS AND ASSIST REPAIR.				360.00
B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, BONNET, FRT SUPPORT PANEL, BOTH FRT FENDER AND AFFECTED PORTION OF CAR.				2880 3600.00

Rasul  
Hp 90010068  
8 days  
24/09/19 @ 1150  
EXCESS: TBA  
Rear  
Repair before paint

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

4044302

4044302

SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE  
TIME 23/09/2019  
17:03

VEHICLE NO

SKW3569E

STOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



# TOYOTA

No : 196700086Z  
No : MR-8500000-9

## ESTIMATE

Had "My Toyota SG" app on Playstore or Appstore to access your Toyota account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

Account Detail

Account No

S1000004 / ICCU1

Document No

0

Document Date

23/09/2019

Customer Detail


Mr Tan Guan Cheng  
60 Lakeside Drive  
#06-39  
Singapore 648320  
Mobile: 97545348

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
5	JETHEHT E4	ASV51R	27/10/2015	SKW3569E	0	48877	50D/SKW3569E/21091
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

R053DKS100103645	6ARPO53114	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00
------------------	------------	----	------------------	------------	------	------------	------

L	Ca	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				2360 3540.00
10	1	S52119-0X914 COVER, FR BUMPER L/C de	1.00	596.90	15.00	507.36
11	2	S52611-06420 ABSORBER, FR BUMPER ca	1.00	102.50	15.00	87.12
12	3	S52021-06101 REINFORCEMENT, FR ?	1.00	399.50	15.00	339.57
13	4	S53102-06120 GRILLE SUB-ASSY, RAD ca	1.00	733.30	15.00	623.30
14	5	S52114-06360 BRACKET, FR BUMPER E ne	1.00	80.70	15.00	68.59
15	6	S52536-06160 RETAINER, FR BUMPER L ne	1.00	100.40	15.00	85.34
16	7	S52535-06170 RETAINER, FR BUMPER R ne	1.00	100.40	15.00	85.34
17	8	T90467-05090 B1 CLIP ne	2.00	3.90	15.00	6.62
18	9	S52129-06410 COVER, FR BUMPER, LW at	1.00	40.70	15.00	34.59
19	0	S53101-06860 GRILLE SUB-ASSY, RAD ca	1.00	600.50	15.00	510.42
20	1	S53301-06290 HOOD SUB-ASSY bt	1.00	1477.30	15.00	1255.70
21	2	S53805-06160 SHIELD SUB-ASSY, FEN de	1.00	203.10	15.00	172.63
22	3	S53811-06180 FENDER SUB-ASSY, RH bt	1.00	860.90	15.00	731.76
23	4	T90467-07166 CLIP ne	8.00	2.80	15.00	19.04
24	5	S53381-06140 SELA, HOOD ne	1.00	88.50	15.00	75.22
25	6	S53510-06241 LOCK ASSY, HOOD bt	1.00	135.00	15.00	114.75
26	7	S53201-06262 SUPPORT SUB-ASSY bt	1.00	640.50	15.00	544.42
27	8	S53208-06121 SUPPORT SUB-ASSY, HO ?	1.00	93.20	15.00	79.22

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4044303

SECURITY GUARD

4044303

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 23/09/2019  
TIME 17:03

VEHICLE NO

SKW3569E

SIGNATURE



Borneo Motors



# TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

## ESTIMATE

196700086Z  
MR-8500000-9

and "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

### Account Detail

Account No

S1000004 / ICCUAI

Document No

0

Document Date

23/09/2019

### Customer Detail


Mr Tan Guan Cheng  
60 Lakeside Drive  
#06-39  
Singapore 648320  
Mobile: 97545348

MSIG Insurance (Singapore) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807  
Attn: Motor Claims Dept

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
5	JETHEE	E4	ASV51R	27/10/2015	SKW3569E	0	48877 50D/SKW3569E/21091
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
RO53DK5100103645	6ARP053114	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
28	9	T90467-07217 CLIP <i>rel</i>	10.00	2.50	15.00	21.20
29	0	S53294-06420 DEFLECTOR, RADIATOR <i>de</i>	1.00	129.10	15.00	109.73
30	1	S53293-06420 DEFLECTOR, RADIATOR	1.00	129.10	15.00	109.73
31	2	S81150-06D50 HEADLAMP ASSY, LH <i>ca</i>	1.00	2821.10	15.00	2397.93
32	3	S81110-06D50 HEADLAMP ASSY, RH <i>ca</i>	1.00	2821.10	15.00	2397.93
33	4	S08889-80102 COOLANT, SLLC&& <i>rel</i>	2.00	79.50	15.00	135.14
34	5	S75443-06A80 PLATE, LUGGAGE COMPT <i>rel</i>	2.00	45.60	15.00	77.52
35	6	S75771-06080 MOULDING, HOOD, FR <i>ca</i>	1.00	209.60	15.00	178.16
36	7	S51441-06260 COVER, ENGINE UNDER, <i>de</i>	1.00	145.20	15.00	123.42
37	8	S51442-06250 COVER, ENGINE UNDER, <i>de</i>	1.00	185.80	15.00	157.93
38	9	T90467-07214 CLIP <i>rel</i>	6.00	2.60	15.00	13.26
39	0	S53851-06110 PAD, FR WHEEL OPENIN <i>mis</i>	1.00	53.60	15.00	45.56
40	1	T81210-0D042 R/FRT FOG LAMP ASSY, ?	1.00	310.40	15.00	263.84

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 5 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	
	Please acknowledge receipt of vehicle	Parts	19,780.34	
		Labour	11,372.34	
		Materials	8,340.00	
		Lubrication/Fluid	68.00	
		Others	0.00	
			0.00	
			0.00	
			GST 7.00%	1,384.62
			Less	0.00
			Amount Due	21,164.96

4044304

PLEASE TEAR ALONG PERFORATED LINE

4044304

SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 23/09/2019  
TIME 17:03

VEHICLE NO

SKW3569E

SIGNATURE



Borneo Motors

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**