



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Attn: Rasul
8 days Final Bill
TAX INVOICE

Page 2 of 2
Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tan Guan Cheng 60 Lakeside Drive #06-39 Singapore 648320 Mobile: 97545348
	Document No 38042652	
	Document Date 17/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	JETHEHT E4	ASV51R	27/10/2015	SKW3569E	119768	48877	50D/SKW3569E/21091!
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR053DK5100103645	6ARP053114	60	Francis Cher T S	16/10/2019 16.39	16/10/2019 16.39		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:A29098945 ACC DATE:21.09.19 TOW IN : 22.09.19 EXCESS:\$700 DATE-IN: DATE SURVEY:24.09.19 NO OF REPAIR DAYS:8 days BY:RASUL (LKK) AUTHORISED ON:	*			50.00
2	L	BP-LPO SUPPLY REGN PLATE (PO# 24085) (fitted with casing) E33				68.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT) (2 SETS)	*			200.00
4	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP.	*			180.00
5	B	BP-LAB2 DRILL HOLE TO INSTALL FRT BUMPER SENSOR.	*			180.00
6	B	BP-MECH2 RESET AND REPROGRAMME ECU.	18			180.00
7	B	BP-MECH2 REMOVE AIR CON COMPONENTS TO REGAS AND ASSIST REPAIR.	18			360.00
8	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, BONNET, FRT SUPPORT PANEL, BOTH FRT FENDER AND AFFECTED PORTION OF CAR.	*			2880.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128162 6333
PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SKW3569E

CUSTOMER

DATE 17/10/2019
TIME 07:34

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Moto

411633



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

TAX INVOICE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tan Guan Cheng 60 Lakeside Drive #06-39 Singapore 648320
	Document No 38042652	Mobile: 97545348
	Document Date 17/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	JETHEHT E4	ASV51R	27/10/2015	SKW3569E	119768	48877	50D/SKW3569E/21091
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR053DK5100103645	6ARP053114	60	Francis Cher T S	16/10/2019 16.39	16/10/2019 16.39		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED * PORTION OF CAR.				2360.00
10	V	EXC Excess element of insurance repair to be 88 paidby the insured party				-700.00
11	1	S52119-0X914 COVER, FR BUMPER L/C	1.00	596.90	15.00	507.36
12	2	S52611-06420 ABSORBER, FR BUMPER	1.00	102.50	15.00	87.12
13	3	S53102-06120 GRILLE SUB-ASSY, RAD	1.00	733.30	15.00	623.30
14	4	S52114-06360 BRACKET, FR BUMPER	1.00	80.70	15.00	68.59
15	5	S52129-06410 COVER, FR BUMPER, LW	1.00	40.70	15.00	34.59
16	6	S53101-06860 GRILLE SUB-ASSY, RAD	1.00	600.50	15.00	510.42
17	7	S53301-06290 HOOD SUB-ASSY	1.00	1477.30	15.00	1255.70
18	8	S53805-06160 SHIELD SUB-ASSY, FEN	1.00	203.10	15.00	172.63
19	9	S53811-06180 FENDER SUB-ASSY, RH	1.00	860.90	15.00	731.76
20	0	S53381-06140 SELA, HOOD	1.00	88.50	15.00	75.22
21	1	S53510-06241 LOCK ASSY, HOOD	1.00	135.00	15.00	114.75
22	2	S53201-06262 SUPPORT SUB-ASSY	1.00	640.50	15.00	544.42
23	3	T90467-07217 CLIP	10.00	2.50	15.00	21.20
24	4	S53294-06420 DEFLECTOR, RADIATOR	1.00	129.10	15.00	109.73
25	5	S81150-06D50 HEADLAMP ASSY, LH	1.00	2821.10	15.00	2397.93
26	6	S81110-06D50 HEADLAMP ASSY, RH	1.00	2821.10	15.00	2397.93

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128162. PLEASE TEAR ALONG PERFORATED LINE.

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SKW3569E

CUSTOMER

DATE 17/10/2019
TIME 07:34

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Moto

411633



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

TAX INVOICE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Page 2 of 3
Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tan Guan Cheng 60 Lakeside Drive #06-39 Singapore 648320 Mobile: 97545348
	Document No 38042652	
	Document Date 17/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	JETHT	E4	27/10/2015	SKW3569E	119768	48877	50D/SKW3569E/21091
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR053DK5100103645	6ARP053114	60	Francis Cher T S	16/10/2019 16.39	16/10/2019 16.39		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
27	7	S08889-80102 COOLANT, SLIC&&&	2.00	79.50	15.00	135.14
28	8	S75443-06A80 PLATE, LUGGAGE COMPT	2.00	45.60	15.00	77.52
29	9	S75771-06080 MOULDING, HOOD, FR	1.00	209.60	15.00	178.16
30	0	S51441-06260 COVER, ENGINE UNDER,	1.00	145.20	15.00	123.42
31	1	S51442-06250 COVER, ENGINE UNDER,	1.00	185.80	15.00	157.93
32	2	T90467-07214 CLIP	6.00	2.60	15.00	13.26
33	3	S88460-06270 CONDENSER ASSY	1.00	1949.80	15.00	1657.33
34	4	S52335-06170 RETAINER, FR BUMPER R	1.00	100.40	15.00	85.34
35	5	S53208-06121 SUPPORT SUB-ASSY, HO	1.00	93.20	15.00	79.22
36	6	S53882-06140 SEAL, FR FENDER, RE	1.00	75.30	15.00	64.00
37	7	T90541-09128 CUSHION	1.00	5.50	15.00	4.67

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 12,228.64 Labour 6,390.00 Materials 68.00 Lubrication/Fluid 0.00 Others 0.00	17,986.64
			GST 7.00% 1,259.06
			Less 0.00
			Amount Due 19,245.70

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 1281626334
PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/10/2019
TIME 07:34

4116334

VEHICLE NO SKW3569E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors