

ASS. REC. BY:

REF: CS/FCI 19016810/USF3N2

Special Instruction:

Survivor: MarcusASSIGNMENT (Office)From (Person): Murina Chia San San of FCI Date/Time: 24.9.19 12.45p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 5073B Insured: SHC 7005Eat Workshop m/s LEE Brothers Tel: 65095521of 11001 Bukit Ave L #102-47 AutobayPolicy No: _____ Claim No: D19006107MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21-09-2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 24.9.19 1.34p.m Person Contacted: Adeline Seng H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	PC 5073B-X
	SHC 7005E - CS/INCO8032144/Kcet b.o.A - 29/11/2019
25/09/19 @ 17:02 pm	revised PA to Merina v.i.a email.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In / Out / Jammed / Leaked / Burnt or

Brake: In / Out / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/9/19

4/5 @ 6500 confirmed with AH hai
(\$ 11,403.23 Red - 64%)

RECEIVED 30 SEP 2019

Date/Time, File Pass to?

30/09/19

1)

Typ: 4

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

8x15=120

170+120

50

50+50

127

567

Report Format:

Lump Sum / I.B.I: (\$ 6,500/- 45)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006107MFSH

Date: 25 September 2019

Our Ref: CS/FCI19016810/Usf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. PC 5073B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/09/2019 at the premises of M/s Lee Brothers Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 18,203.23 .
Revised Estimate Amount	: S\$ 6,749.20 .
"Check" Items Amount	: S\$ 2,001.65 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the o/s front portion & o/s body.
The undercarriage affected due to collision.



Comments/ Present Status:

Damages Consistent.

Repair days: 7 days

Yours faithfully

Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	23-09-2019	Our Ref No. D19006107MFSH
Accident Date	21-09-2019	Claim Type. Third Party
Insured Vehicle	SHC7005E	Third Party Vehicle. PC5073B
Survey Location	1 KAKI BUKIT AVE 6 #02-47 AUTOBAY	
Contact Person.	ADELINE SENG	
Contact No.	65095521/ 0	Fax No. 65095523
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LEE BROTHERS AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Re: SURVEY ASSESSMENT - D19006107MFSH/1

Shirley Hiew (LKK Auto)

Wed 25/9/2019 5:02 PM

To: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

 1 attachments (81 KB)

PRELI ADVISE - PC 5073B.pdf;

Dear Merina,

Enclosed preliminary revised of vehicle PC 5073B.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>**Sent:** Tuesday, 24 September 2019 1:35 PM**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>;
SUR <sur@lkkauto.com>**Cc:** 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>**Subject:** RE: SURVEY ASSESSMENT - D19006107MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin**LKK Auto Consultants Pte Ltd**Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>**Sent:** Tuesday, 24 September, 2019 12:45 PM**To:** ASSIGNMENTS@LKKAUTO.COM**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia
<MerinaChia@msfirstcapital.com.sg>**Subject:** PRI: SURVEY ASSESSMENT - D19006107MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.



All-in-one Cloud POS & Restaurant Management Solution. Trusted worldwide. [FIND OUT MORE](#)

Up to **70%** PSG Support

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

2016 Mini Cooper 1.5a Twin Power Turbo At \$92,988!



Immaculate Condition, Single Owner, 100% Accident Free. Trade In Welcome! StarAd



Think One Automobile

NEW & USED COMMERCIAL VEHICLES



Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

Toyota Hiace commuter

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Hiace commuter		Any	Any	2016	Any	Any	Any	Available
	Toyota	Hiace Commuter 3.0A GL	\$66,800	\$9,780 /yr	22-Jul-2016	2,982 cc	-	Bus	Available
Fuel Type: Diesel Please Call To Arrange For Viewing, Thanks. Posted: 23-Sep-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace Commuter 3.0A GL	\$63,800	\$9,760 /yr	07-Apr-2016	2,982 cc	118,100 km	Bus	Available
Fuel Type: Diesel Think One Automobile & Trading Posted: 15-Sep-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace Commuter 3.0A GL	\$78,000	\$10,920 /yr	14-Nov-2016	2,982 cc	128,645 km	Bus	Available
Fuel Type: Diesel Single Owner Used Fuel Stations Diesel, (Non Industrial), Accident Free, Regular Service At 10,000 Km Or Every 2 Months. Posted: 17-Aug-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace Commuter 3.0A GL	\$61,800	\$9,540 /yr	16-Mar-2016	2,982 cc	-	Bus	Available
Fuel Type: Diesel Think One Automobile & Trading Posted: 16-Aug-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Hanip Automobiles Pte Ltd - Specialist for Toyota Car repair, servicing & maintenance Hanip Automobiles is one of the few workshops in Singapore which is owned, run and operated by a former diagnostic specialist and master technician. More info about this shop								
	Toyota	Hiace Commuter 3.0A GL	\$60,000	\$9,540 /yr	06-Jan-2016	2,982 cc	-	Bus	Available
Fuel Type: Diesel 1 Owner Only. Well Maintained Bus. Good Condition. Posted: 12-Aug-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									

Save this search criteria, to get email alerts whenever a match is found.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 057N

Vehicle Details

Vehicle No.: PC5073B

Vehicle to be Exported: No

Intended Deregistration Date: 24 Sep 2019

Vehicle Make: TOYOTA

Vehicle Model: HIACE COMMUTER 3.0 GL AUTO

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 1KD2593969

Chassis No.: KDH2230027145

Maximum Power Output: -

Open Market Value: \$42,729.00

Original Registration Date: 15 Sep 2016

First Registration Date: 15 Sep 2016

Transfer Count: 0

Actual ARF Paid: \$2,137.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 14 Sep 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$47,889.00

COE Rebate Amount: \$33,399.00

Total Rebate Amount: \$33,399.00

The information contained herein is correct as at 24 Sep 2019

OK

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

SHC7005E

ESTIMATE

DATE : 23.09.2019

VEHICLE NO : PC5073B

MAKE/MODEL : TOYOTA HIACE

ACC DATE : 21.09.2019

not Allent
hlan
2/5 \$6500
24/9/19
the cheater

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	SS	SS
1	1 FRONT STEP GARNISH RH	258.40	258.40
2	1 FRONT WHEEL HUB CAP RH	201.35	201.35
3	1 FRONT SHOCK ABSORBER RH	190.80	190.80
4	1 FRONT TOP ARM RH	654.10	654.10
5	1 FRONT LOWER ARM RH	453.50	453.50
6	1 FRONT LOWER ARM BQL JOINT RH	210.40	210.40
7	1 FRONT STABILIZER BAR LINK RH	110.43	110.43
8	1 FRONT STAY ARM RH	165.80	165.80
9	1 FRONT KNUCKLE ARM RH	503.60	503.60
10	1 FRONT KNUCKLE BEARING RH	210.49	210.49
11	1 STEERING RACK ASSY	3,481.40	3,481.40
12	1 STEERING CROSSMEMBER	2,013.10	2,013.10
13	1 DOOR CENTRE PILLAR RH	855.90	855.90
14	1 SIDE BODY PANEL RH (FRONT)	1,601.10	1,601.10
15	1 SIDE BODY PANEL RH (CENTRE)	950.40	950.40
16	1 SIDE BODY PANEL RH (REAR)	1,822.40	1,822.40
17	1 REAR WHEEL HUB CAP RH	201.35	201.35
18	1 REAR SHOCK ABSORBER RH	169.75	169.75
19	1 REAR AXLE HOUSING	3,453.10	3,453.10
20	1 REAR AXLE HOUSING WHEEL HALF SHAFT RH	335.20	335.20
21	1 REAR AXLE HOUSING WHEEL HALF SHAFT BEARING RH	210.60	210.60
22	1 REAR BUMPER	517.10	517.10
23	2 REAR BUMPER SIDE RETAINER RH/LH	110.35	220.70
			18,790.97
		LESS 25%	4,697.74
			14,093.23

71,44.04
5358.03

SPECIAL NETT ITEMS

1	1 FRONT WHEEL RIM RH	150.00	150.00
2	1 FRONT TYRE RH	280.00	280.00
3	1 (SET) SIDE BODY PANEL WINDSCREEN SPONGE TAPE RH	40.00	40.00
4	1 (SET) SIDE BODY PANEL WINDSCREEN SEALANT RH	150.00	150.00
5	1 SIDE BODY PANEL STICKER *EXCURSION BUS RH	20.00	20.00
6	1 REAR WHEEL RIM RH	150.00	150.00
7	1 REAR TYRE RH	280.00	280.00
			1,070.00

456

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
LABOUR CHARGES :			
1	TO KNOCK OUT DENT, CUT/WELD SIDE BODY PANEL AND REPLACE ACCIDENT PARTS	900	1,000.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	750	800.00
3	TO REMOVE, REPLACE FRONT UNDERCARRIAGE	150	450.00
4	TO REMOVE, REFIX SIDE BODY WINDSCREEN	180	200.00
5	TO REMOVE, REFIX CUSHION, CARPET AND INNER TRIM	100	150.00
6	TO REMOVE, REPLACE REAR UNDERCARRIAGE	180	280.00
7	4 WHEEL ALIGNMENT	80	100.00
8	TO TUFF KOTE		60.00
			3,040.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 18,203.23

LEE Auto Consultants hence notify
any Insurer of the following:

- * To Insure deformation spray painting
- * To Insure damaged part(s) during resurvey
- * Repairs are subject to confirmation
- * This estimate is on a "Without Prejudice" basis
- * No other modification(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p-5358-03
s.w 456.00
L - 2320.00

8134.03
6507



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19016810/Usf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7005E	Veh. Inspected	PC 5073B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006107MFSH	Excess (\$)	0.00	
Assign From	CHIA SAN SAN	Assign Date	24/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE COMMUTER GL (A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KDH2230027145	Colour	WHITE	
Odometer	260619	Steering	AFFECTED	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2019	Inspection Date	24/09/2019	
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 5073B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT STEP GARNISH RH	CUT	258.40	258.40
1	FRONT WHEEL HUB CAP RH	DISTORTED	201.35	201.35
1	FRONT SHOCK ABSORBER RH	TWISTED	190.80	190.80
1	FRONT TOP ARM RH	BENT	654.10	654.10
1	FRONT LOWER ARM RH	BENT	453.50	453.50
1	FRONT LOWER ARM BALL JOINT RH	TWISTED	210.40	210.40
1	FRONT STABILIZER BAR LINK RH	SERVICEABLE	110.43	-
1	FRONT STAY ARM RH	BENT	165.80	165.80
1	FRONT KNUCKLE ARM RH	BENT	503.60	503.60
1	FRONT KNUCKLE BEARING RH	NECESSARY	210.49	210.49
1	STEERING RACK ASSY	SERVICEABLE	3,481.40	-
1	STEERING CROSSMEMBER	NOT NECESSARY	2,013.10	-
1	DOOR CENTRE PILLAR RH	BADLY DENTED	855.90	855.90
1	SIDE BODY PANEL RH (FRONT)	BADLY DENTED	1,601.10	1,601.10
1	SIDE BODY PANEL RH (CENTRE)	BADLY DENTED	950.40	950.40
1	SIDE BODY PANEL RH (REAR)	TO REPAIR SEE LABOUR	1,822.40	-
1	REAR WHEEL HUB CAP RH	MISSING	201.35	201.35
1	REAR SHOCK ABSORBER RH	TWISTED	169.75	169.75
1	REAR AXLE HOUSING	NOT NECESSARY	3,453.10	-
1	REAR AXLE HOUSING WHEEL HALF SHAFT RH	NOT NECESSARY	335.20	-
1	REAR AXLE HOUSING WHEEL HALF SHAFT BEARING RH	NOT NECESSARY	210.60	-
1	REAR BUMPER	CUT	517.10	517.10
2	REAR BUMPER SIDE RETAINER RH/LH @\$110.35	NOT NECESSARY	220.70	-
	LESS 25% DISCOUNT		-4,697.74	-1,786.01
			14,093.23	5,358.03
SPECIAL NETT ITEMS				
1	FRONT WHEEL RIM RH (SN)	BENT	150.00	50.00
1	FRONT TYRE RH (LOCAL PURCHASE)(\$180.00)(60%)(SN)	PUNCTURE	280.00	108.00
1	SET SIDE BODY PANEL WINDSCREEN SPONGE TAPE RH (SN)	NECESSARY	40.00	40.00

Report Ref No. CS/FCI19016810/Usf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET SIDE BODY PANEL WINDSCREEN SEALANT RH (SN)	NECESSARY	150.00	80.00
1	SIDE BODY PANEL STICKER *EXCURSION BUS RH (SN)	NECESSARY	20.00	20.00
1	REAR WHEEL RIM RH (SN)	BENT	150.00	50.00
1	REAR TYRE RH (LOCAL PURCHASE)(\$180.00)(60%)(SN)	GRAZED	280.00	108.00
			1,070.00	456.00
	LABOUR			
	TO KNOCK OUT DENT,CUT/WELD SIDE BODY PANEL AND REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF SIDE BODY PANEL RH (REAR).		1,000.00	900.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		800.00	750.00
	TO REMOVE,REPLACE FRONT UNDERCARRIAGE.		450.00	150.00
	TO REMOVE,REFIX SIDE BODY WINDSCREEN.		200.00	180.00
	TO REMOVE,REFIX CUSHION,CARPET AND INNER TRIM.		150.00	100.00
	TO REMOVE,REPLACE REAR UNDERCARRIAGE.		280.00	100.00
	4 WHEEL ALIGNMENT.		100.00	80.00
	TO TUFF KOTE.		60.00	60.00
			3,040.00	2,320.00
GRAND TOTAL			18,203.23	8,134.03
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,500.00

Report Ref No. CS/FCI19016810/Usf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.