

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52834**
Date Estimated : **24/09/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -

Damian Ong Wen Kai
188 Depot Road
#11-15 The Interlace

Singapore 109688

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9681M	WBAJG120X05N02	30/04/2019	X1 sDrive18i	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			
To replace rear bumper bottom trim panel including to remove and install body parts in order to carry out repair job/	850.00		0	850.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		0	150.00
Sundries.	40.00		0	40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM PANEL BOTTOM (BASI	191.80	1	0	191.80

Total Labour :	1,040.00
Total Parts :	191.80
Total Labour & Parts :	1,231.80
GST @7%:	86.23
Grand Total :	1,318.03

	OD	3RD PARTY	DATE	WORKING DAYS
FAX TO FAX NO		Taufik LKK	28/10/19	3
FAX TO FAX NO				
FAX TO FAX NO				
CONFIRMED DATE				

CAR RENTAL - \$200.00 (2 DAYS)
GIA SEARCH FEE - \$2.00