

INSURER

INS. CASE OWNER

KORSAH

CC³ /AIG1901 6818, T1 6818

LJCK

IDAC

Surveyor:

TAUMIKH

DOI:

ASSIGNMENT

07/10/19

Date / Time:

24/09/19

Registered in Merimen:

24/09/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMP 1377T

Claim No.:

42943684984

Name of Insured:

UNDA V80 WAM PING

Policy No.:

190061218

Insured Tel No.:

HP:

Make / Model:

FCA

Excess Sec II :S\$

D.O.A.:

23/09/19

Place of Accident:

ORIENTAL RD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SMP 9681M



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
		Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	30/09/19 - VIC
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☒
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☒
		Others:	☒

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: P/L	S\$ 1,231.80	(3 days) Reduction: 50 %
FINAL SETTLEMENT	Date/Time: 11/12/19	Confirm with: CAROLINE
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 27
Repair Cost: (w/sgd)	S\$ 1,318.03	
Loss of Rental (LOR):	S\$ 200.00	(2 days) X \$100.00
Loss of Use (LOU):	S\$ -	(S x days)
Loss of Income (LOI):	S\$ -	(S x days)
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]
GIA/LTA Search	S\$ 2.00	
Medical:	S\$ -	
Disbursement:	S\$ -	(e.g. Tow/ Independent)
Legal Cost:	S\$ -	
Total:	S\$ 1,520.03	Global Sum S\$: -
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	S\$ 1,520.03	Name 1: PERFORMANCE MOTORS LIMITED
Payee 2: (Strike if N.A.)	S\$ -	Name 2: -
Payee 3: (Strike if N.A.)	S\$ -	Name 3: -

GOAL

Performance Motors Limited

A Lion Garry Motors Company
Co Reg. No. 19741119W GST Reg. No. M2-0020081-X
Toll-Free Number 1800-2215555

111, Alexandra Road
Lion Garry Performance Centre
Singapore 119941
Tel: 64747770

290, Kembangan Road
West Coast Centre
Singapore 119185
Tel: 64747771

215, Alexandra Road
Lion Garry Business Centre
Singapore 119944
Tel: 64794421 (AfterSales)
64794424 (Insurance)



Change to 4/10 Send in
Due 5/10
7/10/2019
Garry engine
nothing

GST REG. NO : M2 - 0020081 - X

24 SEP 2019

ESTIMATE

Estimate No. : b1 52834	Page No. : 1 of 4
Date Estimated : 24/09/2019	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Damian Ong Wen Kai 188 Depot Road #11-15 The Interlace Singapore 109688	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO. : SMK9681M	CHASSIS NO. : WBAJG120X05N02887	REGN. DATE : 30/04/2019	MODEL : X1 sDrive18i	MILEAGE : 0
----------------------	---------------------------------	-------------------------	----------------------	-------------

DESCRIPTION	VALUE
Replace rear bumper lower trim panel include remove attachment etc and repair on damage are a	850 1,275.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries. Nil	✓ 40.00
Total Labour 1:	1,492.00

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER TRIM PANEL BOTTOM (BASI	1	191.80	191.80
REAR BUMPER MIDDLE TRIM PANEL (PDC)	1	265.65	265.65
REAR BUMPER TOWING EYE COVER	1	36.60	36.60
ULTRASONIC SENSOR BLACK	2	248.70	497.40
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
Total Parts :			1,011.65

Claims ID / 3rd Party / Uninsured losses / Direct Settlement

Rego No. : *7101180* Claim No. : *7101180*

Insured Name : *Tan Kah* Excess \$5 : *Nil*

Surveyor's Name : *Tan Kah* Sign : *[Signature]*

Surveyor's No. : *7101180* Authorized : *[Signature]*

Authorized Date : *24/09/2019* Time : *3:00pm*

RESURVEY PARTS PHOTO BY SURVEYOR : *[Signature]* No. : *7101180* PML Fee / No

Surveyor's E-mail : *tan.kah@liongarry.com.sg*

or 3 Working Days Repayment : *3 days*

LKK Auto Consultants hence notify the Repairer of the following:

• To survey before/after spray painting

• To survey damaged parts using surveyor

• **Labour** is subject to confirmation

• **Part** survey is on a "Without Prejudice" basis

• **Labour** is allowed

• **Excess** item(s) must be surveyed and

is subject to final approval from Insurance Company

Total GST @ 7%

Authorized by Repairer

Grand Total

1,492.00

1,011.65

0.00

0.00

175.26

2,678.91

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

2,503.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401558W, GST Reg. No. M2-0020081-4



Final Report

Estimate No. : **b1 52834**
Date Estimated : **24/09/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -

Damian Ong Wen Kai
188 Depot Road
#11-15 The Interlace

Singapore 109688

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9681M	WBAJG120X05N02i	30/04/2019	X1 sDrive18i	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			
To replace rear bumper bottom trim panel including to remove and install body parts in order to carry out repair job/	850.00	0	0	850.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	0	150.00
Sundries.	40.00	0	0	40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM PANEL BOTTOM (BASI	191.80	1	0	191.80

Total Labour :	1,040.00
Total Parts :	191.80
Total Labour & Parts :	1,231.80
GST @7%:	86.23
Grand Total :	1,318.03

	(C)	APPROVED	DATE	
TAX TO PAY NO		Tau Fikih	28/10/19	3
TAX TO PAY NO		LKC		

CAR RENTAL - \$200.00 (2 DAYS)
GIA SEARCH FEE - \$2.00

Vic (LKKAuto)

From: Sharon Heng L K <sharon.heng.leekun@sime-darby.com.sg>
Sent: Monday, 28 October, 2019 4:42 PM
To: Taufikh (LKKAuto)
Cc: Vic (LKKAuto)
Subject: DIRECT SETTLEMENT FINAL REPORT - SMK9681M
Attachments: SKM_C45819102814292.pdf

Dear Taufikh

For your perusal :

Labor	\$1040.00
Part	\$ 191.80
Total	\$1231.80

Owner is claiming CAR RENTAL - \$200.00 (2 DAYS).
 GIA SEARCH FEE - \$2.00

Note : 3 working days.

Please reply me directly.

Best Regards

Sharon Heng
Performance Motors Ltd
Body & Paint
DID : 63190123
Fax : 64743229

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

-----Original Message-----

From: service.pml@sime-darby.com.sg [mailto:service.pml@sime-darby.com.sg]
Sent: Monday, 28 October, 2019 2:30 PM
To: Sharon Heng L K
Subject: Message from KM_C458

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Rempang Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

24 SEP 2019

ESTIMATE

Estimate No. : b1 52834
Date Estimated : 24/09/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Damian Ong Wen Kai
188 Depot Road
#11-15 The Interlace

Singapore 109688

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9681M	WBAJG120X05N02887	30/04/2019	X1 sDrive18i	0

DESCRIPTION

Replace rear bumper lower trim panel include remove attachment etc and repair on damage are a

VALUE

1850 / 2,275.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 / 177.00

Sundries.

✓ 40.00

Total Labour 1: 1,492.00

DESCRIPTION

REAR BUMPER TRIM PANEL BOTTOM (BASI)
REAR BUMPER MIDDLE TRIM PANEL (PDC)
REAR BUMPER TOWING EYE COVER
ULTRASONIC SENSOR BLACK
DECOUPLING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	191.80	191.80
1	265.65	265.65
1	36.60	36.60
2	248.70	497.40
4	5.05	20.20

Total Parts : 1,011.65

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 7/10/19 3pm Excess \$0

Surveyor's Name Tanjit Sign

Surveyor's Tel 9740155944 Authorised Yes / No

Authorised Date 7/10/19 Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PM Yes / No

Surveyor's E-mail tanjit@chuan.com.sg

No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting

- To display damaged part(s) during resurvey

- Labour 1 subject to confirmation

- Parts survey is on a "Without Prejudice" basis

- Labour 2 location(s) is allowed :

- Excess any item(s) must be resurveyed and

- is subject to final approval from Insurance Company

Total GST @ 7% 175.26

Acknowledged by Repairer

Grand Total : 2,678.91

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7888 Fax: (65) 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

MOTOR INSURANCE COVER NOTE

Cover Note No. **60600220**

The Insured named in the Schedule below having proposed for insurance in respect of the Motor Vehicle described in the Schedule below the risk is hereby HELD COVERED in the terms of the Company's usual form of Policy applicable thereto for the period as stated below unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

Agent No. : 156474
Name of Insured : Damian Ong Wen Kai
Make and Description of Vehicle : BMW X1 sDrive18i RL
Vehicle Registration No. : SMK9681M
Year of Manufacture : 2019
Engine No. : 34485637B38B15A
Chassis No. : WBAJG120X05N02887
Capacity : 1,499 Cubic Capacity
Cover Type : Comprehensive
Sum Insured (SGD) : Market Value
Period of Insurance : 12/07/2019 to 29/10/2020
Excess (SGD) : 500
Finance Company : UNITED OVERSEAS BANK LIMITED



I/We hereby certify that this Cover Note is issued in accordance with the Provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Cap. 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Not valid unless countersigned by the
Company's Authorised Representative



MSIG Insurance (Singapore) Pte. Ltd.
Authorised Insurers

Amy Ler
Senior Vice President, Agencies

Date of Issue : 11/07/2019

This Cover Note is valid for 30 days from the date of issue.

Print Received Message

This mail is associated with :

***SMK9681M (4894368498SG)**
[SMP1377T]
TP
DAMIAN ONG WEN KAI
Sep 23 2019 6:35PM
[LINDA VOO WAN PING]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 11/12/2019 10:39 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1520.03) - SMK9681M - Claim Handler: MdNoor, Norsiah

Approved:1520.03.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Sep 2019 Edit Reg		07 Oct 2019 00:00 Edit Adj Rpt	S\$1,231.80 Edit Estimates	S\$1,231.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LINDA VOO WAN PING, ID: S7140288F								
Main Claimant:	DAMIAN ONG WEN KAI, ID: S8028410A								
Vehicle Reg. No.:	SMK9681M	Date of Loss:	23/09/2019 18:00 - :59 [4 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4894368498SG	Policy/Cover Note No.:	1900161318 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMP1377T	Policy No. (Claimant):	60600220						
	Excess:								
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 03/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (11/12/2019): Alert - Adj Mandate Approved (S\$1520.03) - SMK9681M - Claim Handler: MdNoor, Nor...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMK9681M (4894368498SG)
[SMP1377T]
TP
DAMIAN ONG WEN KAI
Sep 23 2019 6:35PM
[LINDA VOO WAN PING]
Performance Motors Limited

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Video

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/10/19 13:48	Video - Accident TP VIDEO FOOTAGE	1 Load MP4	

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1 Edit	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/11/19 08:54	Adjuster Immediate Advice	1 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/10/19 15:26	Odometer Reading	1 Load JPG	
2	29/10/19 15:26	Chassis Number	1 Load JPG	
3	29/10/19 15:26	General View	1 Load JPG	
4	29/10/19 15:26	General View	1 Load JPG	
5	29/10/19 15:26	General View	1 Load JPG	
6	29/10/19 15:26	General View	1 Load JPG	
7	29/10/19 15:26	General View	1 Load JPG	
8	29/10/19 15:26	General View	1 Load JPG	
9	29/10/19 15:26	General View	1 Load JPG	
10	29/10/19 15:26	General View	1 Load JPG	
11	29/10/19 15:26	General View	1 Load JPG	
12	29/10/19 15:26	General View	1 Load JPG	
13	29/10/19 15:26	General View	1 Load JPG	
14	29/10/19 15:26	General View	1 Load JPG	
15	29/10/19 15:26	General View	1 Load JPG	
16	29/10/19 15:26	General View	1 Load JPG	
17	29/10/19 15:26	General View	1 Load JPG	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/09/19 14:33	TP ESTIMATE.	1 Load PDF	
2	24/09/19 14:33	TP GIA REPORT	1 Load PDF	
3	30/09/19 14:47	EMAIL TO OI	1 Load PDF	
4	30/09/19 14:47	LETTER TO OI	1 Load PDF	
5	08/10/19 17:16	TP ESTIMATE- MARKED	1 Load PDF	
6	29/10/19 15:36	TP ESTIMATE - FINALIZED	1 Load PDF	
7	06/11/19 08:44	TP LOD	1 Load PDF	
8	17/12/19 15:01	WORKSHOP INVOICE	1 Load PDF	
9	17/12/19 15:01	AUTHORISATION TO ACT FORM	1 Load PDF	
10	17/12/19 15:01	Release Voucher	1 Load PDF	
11	17/12/19 15:01	RENTAL RECEIPT	1 Load PDF	
12	17/12/19 15:01	LOD	1 Load PDF	
13	17/12/19 15:01	GIA SEARCH	1 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/09/19 14:47	OI GIA REPORT	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

TEAM _____

Vehicle No:	SMP1377T (Insd veh)	Model:	BMW X1 1.5 SDRIVE 18i (A)
	SMK9681M (TP veh)		
Date of Accident:	23/09/2019		

Global Sum Settlement	:	[]	Yes	[X]	No
Repair Estimate	:	\$		2,678.91	
Final Repair Cost	:	\$		1,318.03	
Loss of Use	:	\$			days at \$0.00 per day
Rental (if any)	:	\$		200.00	2 days
LTA / GIA Search Fee	:	\$		2.00	
Others:	:	\$		0.00	
	:	\$			
Final Settlement Sum	:	\$		1,520.03	
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)					
A) For <u>Non GIA Registered Workshop</u>:		Agreed Liability _____(%)			
B) For <u>GIA Registered Workshop</u>:		BOLA Applicable: Yes/ No BOLA Scenario No: <u>27</u>			
BOLA Liability: _____100_____(%)		Assessed Liability (*): _____(%)			
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply</i>					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	1,520.03
2)		: \$	
3)		: \$	

17 Dec
2019

Date _____

https://singapore.merimen.com/claims/index.cfm?fusebox=SVCdoc&fuseaction=dsp_... 17/12/2019

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19016818/T1HB3Q2

Date: 17/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900161318
 Claimant Vehicle No: SMK9681M Insured Vehicle No: SMP1377T
 Date of Loss: 23/09/2019 Nature of Claim: TP Claim No: 4894368498SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK9681M
 Make & Model: BMW X1, 1.5 SDRIVE 18I (A) Engine No: 34485637B38B15A
 Reg. Date: 30/04/2019 (Man. Year: 2019) Chassis No: WBAJG120X05N02887
 Colour: White Odometer: 4928 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,051.65	231.80	819.85	77.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,452.00	1,000.00	452.00	31.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,503.65	1,231.80	1,271.85	50.80
+ GST 7.00/7.00% (S\$)	175.26	86.23	89.03	50.80
Nett Amount (S\$)	2,678.91	1,318.03	1,360.88	50.80
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,520.03		

INSPECTION

Date of Assignment: 07/10/2019
 Date Inspected: 07/10/2019 Inspected At: Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*40.00 FS
2	1		*REAR BUMPER TRIM PANEL BOTTOM (BASl)	Deformed	191.80 FS	*191.80 FS
3	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Not Necessary	265.65 FS	*- FS
4	1		*REAR BUMPER TOWING EYE COVER	Not Necessary	38.60 FS	*- FS
5	2		*ULTRASONIC SENSOR BLACK	Not Necessary	497.40 FS	*- FS
6	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
Total Parts (S\$)					1,051.65	231.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE REAR BUMPER LOWER TRIM PANEL INCLUDE REMOVE ATTACHMENT ETC AND REPAIR ON DAMAGE AREA	New	1,275.00	850.00
2	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			1,452.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >