

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

India International Insurance Pte Ltd

64 , Cecil Street # 04 - 05

IOB Building

Singapore 049711

Tel : 6347 - 6100

Fax : 6224 - 4174

Quotation

DATE : 24.09.2019

VEH NO : SLE8565R

MODEL : Toyota Wish

D O A : 21.09.2019

YR REF : SHC8813H

Xiao Tony

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLE8565R (TOYOTA WISH)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Delam d</i>	1	481.90 ✓
2	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - LH & RH <i>new</i>	2	97.00 ✓
4	Front Bumper Sponge <i>cracked</i>	1	123.60 ✓
5	Front Bumper Reinforcement <i>Bent</i>	1	289.00 ✓
6	Front Bumper Fog Lamp - LH & RH <i>new</i>	2	532.00 +
7	Front Bumper Lower Grille <i>new</i>	1	132.60 +
8	Front Grille <i>cracked</i>	1	186.50 ✓
9	Front Brace Panel <i>Bent</i>	1	110.60 ✓
10	Headlamp - LH & RH <i>cracked</i>	2	1,711.80 ✓
11	Front Support Panel <i>Repair</i>	1	870.30 X
12	Bonnet <i>Dented</i>	1	733.80 ✓
13	Bonnet Lock <i>new</i>	1	112.50 ✓
14	Bonnet Chrome Moulding <i>cut</i>	1	287.70 ✓
15	Air Con Condenser <i>Bent</i>	1	1,429.00 ✓
16	Radiator <i>new</i>	1	1,632.00 X
17	Rear Bumper <i>Distorted</i>	1	485.00 ✓
18	Rear Bumper Clips <i>new</i>	1	30.00 ✓
19	Rear Bumper Reflector - LH & RH <i>new</i>	2	166.20 +
20	Rear Bumper Impact Bracket - LH & RH <i>Dented</i>	2	136.80 ✓
21	Rear End Panel <i>Dislodged</i>	1	581.10 ✓
22	Rear End Panel Top Garnish <i>Delam d</i>	1	326.20 ✓
23	Tail Lamp - LH & RH <i>new</i>	2	835.80 +
24	Tail Lamp Lower Bracket - LH & RH <i>new</i>	2	85.00 X
25	Tailgate <i>Distorted</i>	1	1,272.90 ✓
26	Tailgate Lock <i>new</i>	1	497.00 ✓
27	Tailgate Weatherstripe <i>cut</i>	1	276.10 ✓
28	Tailgate Outer Chrome Moulding <i>cracked</i>	1	383.80 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SLE8565R (TOYOTA WISH)

29	Tailgate Inner Trim Board <i>could</i>	1	485.50 ✓
30	Tailgate Inner Trim Board Clips <i>new</i>	1	30.00 ✓
31	Tailgate Glass Moulding <i>new</i>	1	140.60 ✓
32	Toyota Logo <i>new</i>	1	74.10 ✓
33	Rear Fender - LH <i>Repis</i>	1	979.50 +
34	Rear Fender Glass Moulding - LH <i>new</i>	1	112.10 +
35	Rear Fender Inner Trim Board - LH & RH <i>new</i>	2	1,384.80 +
36	Rear Fender Inner Trim Board Clips <i>new</i>	1	60.00 ✓
37	Floor Panel Top Board <i>new</i>	1	535.70 X
38	Rear Exhaust Pipe <i>Repis</i>	1	971.10 X
39	Rear Exhaust Mounting <i>new</i>	1	28.50 +
40	Rear Exhaust Heat Shield <i>new</i>	1	215.10 X
41	Spare Tyre Lock Regulator <i>new</i>	1	388.90 ✓
			19,242.10
			(4,810.53)
			\$ 14,431.58

10761.4
8071.05

Less 25%

S/NET ITEMS

1	Front Number Plate <i>could</i>	1	30.00 ✓
2	Front Number Plate Holder <i>could</i>	1	30.00 ✓
3	Rear Number Plate <i>could</i>	1	30.00 ✓
4	Rear Number Plate Holder <i>could</i>	1	30.00 ✓
5	Reverse Sensor <i>new</i>	1	280.00 200
6	Rear End Panel Sealant <i>new</i>	1	60.00 ✓
7	Tailgate Glass Sealant <i>new</i>	1	60.00 ✓
8	Rear Fender Glass Sealant - LH <i>new</i>	1	60.00 +
			580.00

Total Parts

\$ 15,011.58

LABOUR CHARGE

1	To knocking & pull out front & rear portion & renew above parts	\$	2,400.00 1600
2	To putty & spray up paint works	\$	2,200.00 1500
3	To check wiring	\$	100.00 60
4	To underseal	\$	200.00 60
5	To remove reverse sensor	\$	100.00 50
6	To remove tailgate glass	\$	180.00 120

RE : ESTIMATE FOR ACCIDENT REPAIR SLE8565R (TOYOTA WISH)

7	To transfer tailgate fittings	\$	150.00 80
8	To remove exhaust pipe	\$	150.00 80
9	To remove upholstery	\$	150.00 80
10	To remove rear fender glass	\$	120.00 X
11	To remove condenser, radiator & to re-gas	\$	180.00 120
Total Labour		\$	5,930.00
Grand Total		\$	20,941.58

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 12261.05
L/S: T-1K (Nett Value)
13 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: