



Vehicle Repair Estimate

Date : 20-Sep-2019

Vehicle Num : SGZ6991E

Make/Model : Golf Mk7 1.4TSI

Chassis No : WVVZZZAUZDW105852

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear Bumper	1	\$ <i>de</i> 910.00	\$ 910.00
2	Impact beam	1	\$? 390.00	\$ 390.00
3	Attachment strip bumper	1	\$ <i>nei</i> 70.00	\$ 70.00
4	Tail light (Right)	1	\$ <i>cut</i> 205.00	\$ 205.00
5	Rear lock mechanism with micro switch	1	\$? 535.00	\$ 535.00
6	Trunk Lid	1	\$ <i>bt</i> 1,330.00	\$ 1,330.00
7	Golf lettering	1	\$ <i>nei</i> 60.00	\$ 60.00
8	TSI bluemotion		<i>nei</i>	
9				
10				
11				
12	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary charges must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____			
13				
14				
15				
16				
17				
	TOTAL PARTS			\$ 3,500.00
	TOTAL AMOUNT			\$ 3,500.00
	MISCELLANEOUS ITEM			
	Sundries		\$ <i>20 nei</i> 80.00	\$ 80.00
	Number plate with casing		\$ <i>bt</i> 35.00	\$ 35.00
	LABOUR			
1	For the removal, transfer and installation of various associated components from rear bumper, trunk lid, windscreen, parking aid, harness, wiring, lock mechanism		\$ <i>400.</i> 650.00	\$ 650.00
1	Surface preparation and paint for trunk lid and bumper		\$ <i>450.</i> 800.00	\$ 800.00
3	To perform complete diagnosis of the vehicle		\$ <i>✓</i> 90.00	\$ 90.00
	<i>Tanphu 97495729</i> <i>WP' 25/9/19 P445</i> <i>4-5 days</i> <i>Tanphu e Uthantam</i> <i>Lumpsum</i> <i>Resurvey before paint</i>			
	TOTAL			\$ 5,155.00
	GST 7%			\$ 360.85
	GRAND TOTAL			\$ 5,515.85