



Vehicle Repair Estimate

Date : 20-Sep-2019

Vehicle Num : SGZ6991E

Make/Model : Golf Mk7 1.4TSI

Chassis No : WVVZZZAUZDW105852

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear Bumper	1	\$ 910.00	\$ 910.00
2	Impact beam	1	\$ 390.00	\$ 390.00
3	Attachment strip bumper	1	\$ 70.00	\$ 70.00
4	Tail light (Right)	1	\$ 205.00	\$ 205.00
5	Rear lock mechanism with micro switch	1	\$ 535.00	\$ 535.00
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
	TOTAL PARTS			\$ 2,110.00
	TOTAL AMOUNT			\$ 2,110.00
	MISCELLANEOUS ITEM			
	Sundries		\$ 80.00	
	Number plate with casing		\$ 35.00	
	LABOUR			
1	For the removal, transfer and installation of various associated components from rear bumper, trunk lid, windscreen, parking aid, harness, wiring, lock mechanism		\$ 650.00	\$ 650.00
1	Surface preparation and paint for trunk lid and bumper		\$ 800.00	\$ 800.00
3	To perform complete diagnosis of the vehicle		\$ 90.00	\$ 90.00
	TOTAL			\$ 3,650.00