

辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

19/09/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR KIA CERATO - SMG9566J

1pc	front RH headlamp	\$ 1,855.00	?
1pc	front RH headlamp lower bracket	\$ 65.00	X
1pc	front centre grille	\$ 390.00	X
1pc	front centre grille top garnish	\$ 185.00	X
1pc	front centre grille lower garnish	\$ 180.00	X
1pc	front bumper	\$ 925.00	?
1pc	front bumper RH side retainer	\$ 65.00	X
1pc	front bumper grille	\$ 195.00	X
1pc	front bumper garnish lower garnish	\$ 365.00	✓
1pc	front bumper RH side lamp	\$ 320.00	✓
1pc	front bumper RH side lamp garnish	\$ 155.00	?
1pc	front bumper sponge	\$ 185.00	X
1pc	front bumper reinforcement	\$ 395.00	?
1pc	front bumper "KIA" logo	\$ 45.00	✓
10pcs	front bumper clip @\$5.00	\$ 50.00	?

\$ 5,375.00

less 10%

\$ 537.50

\$ 4,837.50

wiring

\$ 120.00

spray painting

\$ 600.00

Labour Charge

\$ 600.00

Total

\$ 6,157.50



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not in (LKK) 23/09/19 Monday

Not within 11 Rm 87 Penny After Paint 2 days

Not A

13/ 22cl 20cl