

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5523P****AAD1909-164***Not Authored*  
*61 Smg & 160cl*

Vehicle No.:

Chassis No.:

Vehicle Make:

23 SEP 2019

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHC 5523P**

VF1ABL15AUC278863

RENAULT

LATITUDE

18.9.19

AIG-

15/8/2014

PART		LIST	
1	DOOR PANEL REAR RH	\$	758.70 ✓
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL OUTER RH	\$	1,184.99
1	ROCKER PANEL CENTER RH	\$	990.25
1	FENDER PANEL REAR RH	\$	1,933.20
1	FENDER PANEL INNER TRIM REAR RH	\$	671.45
1	WHEELARCH REAR RH	\$	275.40
1	BUMPER COVER REAR	\$	561.70
1	BUMPER LOWER REAR	\$	411.90
1	BUMPER BRACKET CTR REAR	\$	98.10
1	BUMPER BRACKET SIDE RH REAR	\$	82.10
1	BUMPER RETAINER RH REAR	\$	59.80
1	BUMPER REFLECTOR RH	\$	16.60
1	BUMPER BEAM REAR	\$	547.80
1	BUMPER BEAM BRACKET RH REAR	\$	100.90
1	TAILLAMP RH	\$	313.10
<b>TOTAL</b>		<b>\$</b>	<b>9,497.29</b>
<b>10%</b>		<b>\$</b>	<b>949.73</b>
		<b>\$</b>	<b>8,547.56</b>

**Special Nett**

1	REAR DOOR STICKER '6555-3333'	\$	80.00 <i>base</i>
1	FENDER INNER TRIM CLIP RH	\$	28.00 X
1	TAILLAMP CLIP RH	\$	5.00 X
1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00 X
2	REAR WINDSCREEN SEALANT	\$	80.00 X

**Trans-cab Auto Services Pte Ltd**

AAD1909-164

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5523P

1	WINDSCREEN MOULDING	\$	nn	100.00	} X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
1	REAR RIGHT TYRE	\$	SL	300.00	
1	REAR RIGHT TYRE RIM	\$	SL	380.00	
1SET	PARKING AID	\$	SL	700.00	
1SET	REAR BUMPER CLIP	\$	nn	66.00	
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	
1SET	BUMPER RETAINER CLIP RH RR	\$	nn	20.00	
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	
<b>TOTAL</b>		<b>\$</b>		<b>2,025.00</b>	

<b>TOTAL PARTS</b>	<b>\$</b>	<b>10,572.56</b>
--------------------	-----------	------------------

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,500.00	6401 3001
----	----------	-----------

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$	nn	380.00 X
----	----	----------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	nn	380.00 X
----	----	----------

To check steering geometry and computer wheel alignment

\$	nn	220.00 X
----	----	----------

To transfer of rear windscreen glass to facilitate bodywork repair.

\$	nn	170.00 X
----	----	----------

To rust-proofing of the affected areas.

\$		170.00 301
----	--	------------

To transfer of Rear fender fittings, attachment and perform water seepage test.

\$	nn	380.00 X
----	----	----------

**Trans-cab Auto Services Pte Ltd**

AAD1909-164

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5523P**

To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	<i>601</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>151</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>X</i>
Putty and spray painting of the affected portion.	\$	4,500.00	<i>6601</i>
<b>TOTAL</b>	<b>\$</b>	<b>11,970.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>22,542.56</b>	

**LUMP SUM (REPAIR DAY)**~~15~~ DAYS*3 days*