

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Sep-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6915 K

1 pc	Rear bumper		\$	696.00
1 pc	Rear bumper lower cover		\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00		\$	58.00
1 pc	Rear bumper inner sponge		\$	114.00
1 pc	Rear bumper reinforcement		\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00		\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00		\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00		\$	36.00
				\$ 1,861.00
				Less 10%
				\$ 186.10
				\$ 1,674.90

S/NETT

1 set	Rear bumper clips		\$	48.00
1 set	Reverse sensor		\$	280.00 200
1 pc	Rear bumper top protector		\$	80.00
				Sundry
				\$ 50.00 X 1
				To dismantle / replace reverse sensor to new bumper and reset to the same
				\$ 120.00 30
				To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.
				\$ 180.00 X 1
				To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.
				\$ 650.00 200
				To putty and spray painting on rear bumper, end panel, bootlid lower garnish
				\$ 400.00 180
				To apply rustproofing on the repaired and replaced panels.
				\$ 120.00 X 1
				\$ 3,602.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

18/10/19
Total 45 \$ 1150 / 200
//

Kalmanay
23/9/19 1720
200
45
After Repair