

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

23-Sep-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6915 K

1 pc	Rear bumper ✓	\$ 696.00
1 pc	Rear bumper lower cover ✓	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ✕	\$ 58.00
1 pc	Rear bumper inner sponge ✕	\$ 114.00
1 pc	Rear bumper reinforcement ✕	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ✕	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ✕	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ✕	\$ 36.00
		<hr/>
		\$ 1,861.00
		Less 10%
		<hr/>
		\$ 1,674.90

### S/NETT

1 set	Rear bumper clips ✓	\$ 48.00
1 set	Reverse sensor ✓	\$ <del>280.00</del> 200
1 pc	Rear bumper top protector ✕	\$ 80.00
Sundry		\$ <del>50.00</del> ✕
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ <del>120.00</del> 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ <del>180.00</del> ✕
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.		\$ <del>650.00</del> 200
To putty and spray painting on rear bumper, end panel, bootlid lower garnish ✕		\$ <del>400.00</del> 180
To apply rustproofing on the repaired and replaced panels.		\$ <del>120.00</del> ✕
		<hr/>
		\$ 3,602.90

( ALL THE REPAIR COSTS ARE SUBJECT TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Acknowledged by Repairer  
Signature: *Kalman*

*23/9/19 1720h*  
*2 days*  
*45*  
*After Repairs*