

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1909-100

DATE : 20-Sep-2019

POLICY NO. : DIRECTASIA MT/00513876/01

VEHICLE REG. NO. : SKW9960T

VEHICLE MAKE : TOYOTA ESTIMA 2.4 (A)

TO Motor Claim Department

India International Insurance Pte Ltd

64 Cecil Street, #04-#05 IOB Building, Singapore 049711

Tel: 6347 6100

Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 680.00	\$ 680.00
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer LH	1	\$ 60.00	\$ 60.00
4	Rear Bumper Bracket LH	1	\$ 60.00	\$ 60.00
5	Rear Bumper Reflector LH	1	\$ 60.00	\$ 60.00
6	Rear Bumper Tow Eye Cover	1	\$ 30.00	\$ 30.00
7	Rear Tailgate	1	\$ 1,580.00	\$ 1,580.00
8	Rear Tailgate Rubber Seal	1	\$ 380.00	\$ 380.00
9	Rear Tailgate Lock Assy	1	\$ 480.00	\$ 480.00
10	Rear Tailgate Lock Cover	1	\$ 50.00	\$ 50.00
11	Rear Tailgate Lock Latch	1	\$ 40.00	\$ 40.00
12	Rear Tailgate Estima Emblem	1	\$ 50.00	\$ 50.00
13	Rear Tailgate Toyota Emblem	1	\$ 80.00	\$ 80.00
14	Rear Tailgate X Emblem	1	\$ 50.00	\$ 50.00
15	Rear Floor Panel	1	\$ 780.00	\$ 780.00
16	Rear End Panel	1	\$ 680.00	\$ 680.00
17	Rear End Panel Garnish Upper	1	\$ 280.00	\$ 280.00
18	Rear End Panel Garnish Lower	1	\$ 180.00	\$ 180.00
19	Rear Windscreen Moulding	1	\$ 100.00	\$ 100.00
			Total Spare Parts	\$ 5,670.00
	<u>SPECIAL NETT</u>			
20	Reverse Sensor	1	\$ 200.00	\$ 200.00
			Total Special Nett	\$ 200.00
	<u>LABOUR</u>			
21	Spray Painting Rear Bumper, Tailgate and Inner Panel	1	\$ 800.00	\$ 800.00
22	Remove, Replace and Repair Accident Affected Area	1	\$ 800.00	\$ 800.00
23	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 100.00	\$ 100.00
24	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00
25	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00
26	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
27	Check and Rectify Electrical wiring	1	\$ 30.00	\$ 30.00
			Total Labour	\$ 2,030.00
			Amount Before Excess	\$ 7,900.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1909-100

DATE : 20-Sep-2019

POLICY NO. : DIRECTASIA MT/00513876/01

VEHICLE REG. NO. : **SKW9960T**

VEHICLE MAKE : TOYOTA ESTIMA 2.4 (A)

TO Motor Claim Department**India International Insurance Pte Ltd**

64 Cecil Street, #04-#05 IOB Building, Singapore 049711

Tel: 6347 6100

Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.			Add GST @ 7%	553.00
			Total Amount Payable	\$ 8,453.00