



**Main Office :** No. 22, Jalan Kilang, Singapore 159419  
Tel: 6476 3333 Fax: 6271 5891

**Service Centre :** Block 100B, Bukit Merah Lane 3,  
#01-04/06/08/115, Singapore 159722  
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0088864-2

**Mova Spray Centre**  
2K Oven Spray Painting System

**Power-M Automotive Pte Ltd**  
Specialise In Car Air-con Services,  
Car Audio & Hi-Fi System.

**Hilton Car Rental Centre**  
**Hilton Auto Trading**  
Dealing In New/Used Cars, Hire Purchase & Insurance.



**TP INSURER:** India International Insurance Pte Ltd (HQ)

0

Singapore

**Claimant Insurer:** NTUC Income Insurance Co-operative Ltd

*Alan 9669276*

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/09/2019
Vehicle Reg. No.:	SGS3971U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ONG TEIK HONG		
Make/Model:	TOYOTA WISH, 1.8 X (A)	Vehicle Reg. Date:	13/03/2007
Vehicle Colour:	SILVER	Chassis No:	ZNE100349690
Engine No:	1ZZ2815171		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %	Nett Item Discount:	10.00 %
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS	Amount
Parts	5,737.50
Miscellaneous Items	11.00
Labour	2,450.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>8,198.50</b>
<b>+ GST 7.00% (S\$)</b>	<b>573.90</b>
<b>Nett Amount (S\$)</b>	<b>8,772.40</b>

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Sep 2019)**Parts:** M1-MPV TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SGS3971U)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>de</i>	25.00	0.00	*595.00 FL
2	2 <i>1pc (LH)</i>		*REAR BUMPER SIDE RETAINER <i>ne</i>	25.00	0.00	*160.00 FL
3	1		*REAR BUMPER ABSORBER BRACKET LH <i>?</i>	25.00	0.00	*140.00 FL
4	10		*REAR BUMPER CLIPS <i>ne</i>	25.00	0.00	*30.00 FL
5	1		*TAILGATE <i>bt</i>	25.00	0.00	*1,680.00 FL
6	1		*TAILGATE GARNISH <i>cn</i>	25.00	0.00	*290.00 FL
7	1		*TAILGATE LOGO <i>ne</i>	25.00	0.00	*50.00 FL
8	1		*TAILGATE LOCK <i>bt</i>	25.00	0.00	*330.00 FL
9	1		*TAILGATE GLASS <i>bro</i>	25.00	0.00	*1,680.00 FL
10	1		*TAILGATE GLASS MOULDING <i>ne</i>	25.00	0.00	*140.00 FL
11	1		*TAILGATE WIPER BLADE <i>ne</i>	25.00	0.00	*70.00 FL
12	1		*TAILGATE WIPER ARM <i>Spa</i>	25.00	0.00	*140.00 FL
13	1		*TAILGATE INNER TRIM	25.00	0.00	*495.00 FL
14	1		*TAIL LAMP LH <i>bro</i>	25.00	0.00	*630.00 FL
15	1		*END PANEL GARNISH	25.00	0.00	*190.00 FL
16	1		*END PANEL ASSY <i>require bt (photo)</i>	25.00	0.00	*680.00 FL
17	1		*TAILGATE RUBBER <i>ne</i>	25.00	0.00	*290.00 FL
18	1		*REAR NUMBER PLATE <i>bt</i>	0	0.00	<i>35</i> *45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,635.00
- List Item Discount on L Items (\$\$)	1,897.50

Total Parts (\$\$)	5,737.50
--------------------	----------

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00 ✓
Sub Total (\$\$)			11.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST	New	40.00 ✓
2	TO REMOVE & INSTALL REAR WINDSCREEN	New	120.00 ✓
3	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE	New	<del>100.00</del> 60 ✓
4	TO REMOVE & INSTALL FUEL TANK IN ORDER TO STRAIGHTEN LH REAR FENDER	New	80.00 X
5	TO REMOVE & INSTALL REAR GARNISHES, CARPET & ETC IN ORDER TO CUT OFF END PANEL	New	<del>200.00</del> 80 ✓
6	TO CUT OFF END PANEL, STRAIGHTEN LH REAR FENDER AND RENEW DAMAGED PARTS	New	<del>950.00</del> 800 ✓
7	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	30.00 ✓
8	TO APPLY RUST PROOF ON REPLACED, REPAIRED AREAS	New	30.00 ✓
9	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	<del>900.00</del> 800 ✓
Gross Labour Cost (\$\$)			2,450.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Pass  
Hp 90010068  
7 days  
4/5  
24/09/19 @ 1420  
Resny after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: