

Balance brought forward.

4,981.20

1 set
1 tube

reverse sensor
windscreen glass sealant

s.nett
s.nett

Repair

220.00 x

65.00 x

To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.

600 1,400.00

To remove and refit tailgate accessories.

60.00 ✓

To remove and refit reverse sensor.

50 80.00

To remove rear windscreen glass.

120 140.00

To apply waterproof sealant on jointed panels.

30 150.00

To check wiring system.

20 40.00

To spray painting on affected areas.

600 900.00

To apply rust proofing.

60 150.00

Total

8,186.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

Ng Weng Heng

c/o 46 Lenton Plain
Singapore 786548

Not Authorized
11 Sep @ 3900hr
Painting After Paint
5 days

Date: 24/09/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA HIACE / JMX 3838		
1 pc	rear bumper	<i>B₁</i> 728.80 <i>L</i>
2 pcs	rear bumper side retainer	@ 49.20 <i>dl</i> <i>cm</i> 98.40 <i>L</i>
4 pcs	rear bumper lower bracket	@ 29.30 <i>dl</i> 117.20 <i>te</i>
1 pc	rear end panel	<i>B₁</i> 562.20 <i>✓</i>
1 pc	rear end panel top trim	<i>S₂</i> 283.10 <i>x</i>
1 pc	rear tail lamp assy	<i>cm</i> 582.10 <i>✓</i>
1 pc	tail lamp apron panel	<i>π</i> 268.70 <i>x</i>
1 pc	rear tail door	<i>B₁</i> 1,554.80 <i>L</i>
1 pc	rear tail door lock	<i>ny</i> 257.00 <i>L</i>
1 pc	rear tail door lock catch	<i>re</i> 68.00 <i>x</i>
1 pc	rear tail door weaterstrip	<i>S₂</i> 379.00 <i>x</i>
1 pcs	rear tail door damper	@ 356.20 <i>S₂</i> 712.40 <i>x</i>
1 pc	rear tail door central lock actuator	<i>S₂</i> 297.60 <i>x</i>
1 pc	rear tail door outer garnish	<i>S₂</i> 284.50 <i>x</i>
1 pc	emblem "LOGO"	<i>re</i> 67.80 <i>-</i>
Sub-total		6,261.60
Less 25%		1,565.40
Sub-total		4,696.20
et	reverse sensor	<i>nd</i> <i>240sn</i> 220.00
be	windscreen glass sealant	<i>re</i> <i>40sn</i> 65.00
Sub-total		4,981.20

^{Kol} AUTOWORX HOUSE

C/O.176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64520715 FAX: 64529250

ESTIMATE

WENG HENG
46 Lenton Plain
Singapore 786548

Date: 30/9/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: SUPPLEMENTARY FOR TOYOTA HIACE / JMX 3838	
	rear end corner panel r/h 281.60	R1 364.70 ✓
	sub-total	364.70
	less 25%	91.18
	total	273.53