

AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

Ng Weng Heng

c/o 46 Lenton Plain
Singapore 786548

Not Authorized
11 Sep @ 7
Passing After Paint
5 days

Date: 24/09/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA HIACE / JMX 3838		
1 pc	rear bumper	<i>B₁</i> 728.80 <i>L</i>
2 pcs	rear bumper side retainer	@ 49.20 <i>dis cm</i> 98.40 <i>L</i>
4 pcs	rear bumper lower bracket	@ 29.30 117.20 <i>L</i>
1 pc	rear end panel	<i>B₁</i> 562.20 <i>L</i>
1 pc	rear end panel top trim	<i>S₂</i> 283.10 <i>X</i>
1 pc	rear tail lamp assy	<i>cm</i> 582.10 <i>L</i>
1 pc	tail lamp apron panel	<i>?</i> 268.70 <i>L</i>
1 pc	rear tail door	<i>B₁</i> 1,554.80 <i>L</i>
1 pc	rear tail door lock	<i>ny</i> 257.00 <i>L</i>
1 pc	rear tail door lock catch	<i>re</i> 68.00 <i>X</i>
1 pc	rear tail door weaterstrip	<i>S₂</i> 379.00 <i>X</i>
2 pcs	rear tail door damper	@ 356.20 <i>S₂</i> 712.40 <i>X</i>
1 pc	rear tail door central lock actuator	297.60 <i>?</i>
1 pc	rear tail door outer garnish	<i>S₂</i> 284.50 <i>X</i>
1 pc	emblem "LOGO"	<i>re</i> 67.80 <i>L</i>
Sub-total		6,261.60
Less 25%		1,565.40
Sub-total		4,696.20
1 set	reverse sensor	<i>nd</i> <i>200sn</i> 220.00
1 tube	windscreen glass sealant	<i>re</i> <i>40sn</i> 65.00
Sub-total		4,981.20
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		

	Balance brought forward.			4,981.20	
1 set	reverse sensor	s.nett	<i>Reversen</i>	220.00	X
1 tube	windscreen glass sealant	s.nett	"	65.00	X
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		<i>600l</i>	1,400.00	
	To remove and refit tailgate accessories.			60.00	✓
	To remove and refit reverse sensor.		<i>50l</i>	80.00	
	To remove rear windscreen glass.		<i>120l</i>	140.00	
	To apply waterproof sealant on jointed panels.		<i>30l</i>	150.00	
	To check wiring system.		<i>20l</i>	40.00	
	To spray painting on affected areas.		<i>600l</i>	900.00	
	To apply rust proofing.		<i>60l</i>	150.00	
		Total		8,186.20	