



MBM WHEELPOWER PTE LTD

Your Ref: SHA1363X

Our Ref: SME7305U

To: India Insurance International Pte Ltd

CC

Email

Fax

Date: 23/9/2019

From: Eryx Tan

Fax: 6452 5333

Contact: 8318 7188

Make / Model: HONDA FREED 1.5G (A)

Chassis No.: GB71074392

Engine No.: LEB5609339

Year of Make: 2018

Accident Date: 23/9/2019

Not Authorized
Re survey B & paint
6-7 days

ESTIMATE FOR VEHICLE NO. : SME7305U

DESCRIPTION	QTY	List Price
TAILGATE	1	\$ 1,550.00 L
TAILGATE WEATHERSTRIP	1	\$ 165.00 ?
REAR WINDSCREEN MOULDING	1	\$ 115.00 L
TAILGATE LAMP RH	1	\$ 650.00 ?
TAILGATE LAMP LH	1	\$ 650.00 ?
TAILGATE "H" LOGO	1	\$ 95.00 L
TAILGATE CHROME MOULDING	1	\$ 410.00 X
TAILGATE "FREED" EMBLEM	1	\$ 95.00 -
TAILGATE "HYBRID" EMBLEM	1	\$ 105.00 -
TAILGATE INNER TRIM	1	\$ 460.00 ?
TAILGATE INNER TRIM CLIPS	10	\$ 100.00 ?
TAILGATE LOCK	1	\$ 295.00 L
TAILGATE LOCK COVER	1	\$ 180.00 ?
TAILGATE LOCK CATCH	1	\$ 150.00 ?
TAIL LAMP LH	1	\$ 750.00 X
TAIL LAMP RH	1	\$ 750.00 X
REAR BUMPER	1	\$ 1,150.00 L
REAR BUMPER RETAINER LH	1	\$ 65.00 X
REAR BUMPER RETAINER RH	1	\$ 65.00 X
REAR BUMPER CLIP	8	\$ 32.00 L
REAR BUMPER REFLECTOR RH	1	\$ 75.00 X
REAR BUMPER REFLECTOR LH	1	\$ 75.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

END PANEL	1	\$	<i>12</i> 515.00 ✓
END PANEL TOP GARNISH	1	\$	95.00 ?
END PANEL TOP GARNISH CLIPS	6	\$	60.00 ?
HYBRID BATTERY	1	\$	12,000.00 ?

TOTAL:	\$	20,652.00
LESS 20%:	\$	(4,130.40)
PARTS TOTAL:	\$	16,521.60

SPECIAL NETT

ANTIRUST COATING	1	\$	<i>601</i> 150.00
REAR BUMPER REVERSE SENSOR	1	\$	<i>1000</i> 400.00
REVERSE CAMERA	1	\$	<i>500</i> 600.00 X
REAR WINDSCREEN SEALANT	1	\$	<i>400</i> 80.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS	\$	<i>800</i> 1,500.00
TO REMOVE & REPLACE REAR WINDSCREEN	\$	<i>1200</i> 150.00
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	<i>600</i> 100.00
TO REMOVE & REFIT TAILGATE INNER COMPONENTS TO FACILITATE REPAIR	\$	<i>600</i> 120.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	<i>?</i> 150.00
TO REMOVE & REPLACE BUMPER SENSORS	\$	<i>500</i> 80.00
TO CHECK & RECONNECT ALL WIRING	\$	<i>200</i> 100.00
TO RESET ECU AFTER REPLACE HYBRID BATTERY	\$	<i>?</i> 180.00
TO SPRAY PAINT ON THE AFFECTED AREA	\$	<i>800</i> 1,000.00

Total:	\$	21,131.60
7% GST:	\$	1,479.21
Grand Total:	\$	22,610.81