

MBM WHEELPOWER PTE LTD

Your Ref: SHA1363X

Our Ref: SME7305U



To: India Insurance International Pte Ltd

CC

Email

Fax

*Not Authorized
Returning B & paint*

*6 days
10*

~~MBM WHEELPOWER PTE LTD~~

Date: 23/9/2019
From: Eryx Tan
Fax: 6452 5333
Contact: 8318 7188
Make / Model: HONDA FREED 1.5G (A)
Chassis No.: GB71074392
Engne No.: LEB5609339
Year of Make: 2018
Accident Date: 23/9/2019

ESTIMATE FOR VEHICLE NO. : SME7305U

DESCRIPTION	QTY	List Price
TAILGATE <i>1320</i>	1	\$ <i>By</i> 1,550.00 <i>L</i>
TAILGATE WEATHERSTRIP <i>143</i>	1	\$ <i>Cr</i> 165.00 <i>2</i>
REAR WINDSCREEN MOULDING	1	\$ <i>Re</i> 115.00 <i>L</i>
TAILGATE LAMP RH <i>368</i>	1	\$ <i>mgcm</i> 650.00 <i>2</i>
TAILGATE LAMP LH <i>368</i>	1	\$ <i>mgcm</i> 650.00 <i>2</i>
TAILGATE "H" LOGO	1	\$ <i>Re</i> 95.00 <i>L</i>
----> TAILGATE CHROME MOULDING	1	\$ <i>Cra</i> <i>Re</i> 410.00 <i>X</i>
TAILGATE "FREED" EMBLEM <i>68.20</i>	1	\$ <i>Re</i> 95.00 <i>-</i>
TAILGATE "HYBRID" EMBLEM <i>68.20</i>	1	\$ <i>Re</i> 105.00 <i>-</i>
TAILGATE INNER TRIM <i>391.70</i>	1	\$ <i>mgcm</i> 460.00 <i>2</i>
TAILGATE INNER TRIM CLIPS <i>09.20</i>	10	\$ <i>50</i> <i>Re</i> 100.00 <i>250</i>
TAILGATE LOCK <i>186.20</i>	1	\$ <i>Re</i> 295.00 <i>L</i>
TAILGATE LOCK COVER	1	\$ <i>Re</i> 180.00 <i>X</i>
TAILGATE LOCK CATCH <i>45</i>	1	\$ <i>Re</i> 150.00 <i>X</i>
TAIL LAMP LH	1	\$ <i>Re</i> 750.00 <i>X</i>
TAIL LAMP RH	1	\$ <i>Re</i> 750.00 <i>X</i>
REAR BUMPER <i>1150</i>	1	\$ <i>By</i> 1,150.00 <i>L</i>
REAR BUMPER RETAINER LH	1	\$ <i>Re</i> 65.00 <i>X</i>
REAR BUMPER RETAINER RH	1	\$ <i>Re</i> 65.00 <i>X</i>
REAR BUMPER CLIP	8	\$ <i>Re</i> 32.00 <i>L</i>
REAR BUMPER REFLECTOR RH	1	\$ <i>Re</i> 75.00 <i>X</i>
REAR BUMPER REFLECTOR LH	1	\$ <i>Re</i> 75.00 <i>X</i>

END PANEL

END PANEL TOP GARNISH

END PANEL TOP GARNISH CLIPS

HYBRID BATTERY

1	\$	12	515.00	✓
1	\$	21	95.00	✓
6	\$	12	60.00	✓
1	\$	12	12,000.00	X

TOTAL:	\$	20,652.00
LESS 20%:	\$	(4,130.40)
PARTS TOTAL:	\$	16,521.60

SPECIAL NETT

ANTIRUST COATING

REAR BUMPER REVERSE SENSOR

REVERSE CAMERA

REAR WINDSCREEN SEALANT

1	\$	601	150.00	✓
1	\$	2000	400.00	
1	\$	12	600.00	X
1	\$	4012	80.00	

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS

TO REMOVE & REPLACE REAR WINDSCREEN

TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR

TO REMOVE & REFIT TAILGATE INNER COMPONENTS TO FACILITATE REPAIR

TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS

TO REMOVE & REPLACE BUMPER SENSORS

TO CHECK & RECONNECT ALL WIRING

TO RESET ECU AFTER REPLACE HYBRID BATTERY

TO SPRAY PAINT ON THE AFFECTED AREA

\$	12001	1,500.00
\$	1201	150.00
\$	601	100.00
\$	601	120.00
\$	?	150.00 1201
\$	501	80.00
\$	201	100.00
\$	?	180.00 1201
\$	8001	1,000.00
Total:	\$	21,131.60
7% GST:	\$	1,479.21
Grand Total:	\$	22,610.81


9696 12663

Mbm wheelpower pte ltd
160 SIN MING DRIVE #06-02
SIN MING AUTOCITY
t 66262 8888 f 6452 5333

MBM WHEELPOWER PTE LTD

Your Ref: SHA1363X

Our Ref: SME7305U



To: India Insurance International Pte Ltd

CC LKK Auto Consultants - Kenneth

Email

Fax

Date: 27/9/2019
 From: Eryx Tan
 Fax: 6452 5333
 Contact: 8318 7188
 Make / Model: HONDA FREED 1.5G (A)
 Chassis No.: GB71074392
 Engine No.: LEB5609339
 Year of Make: 2018
 Accident Date: 23/9/2019

SUPPLEMENTARY ESTIMATE FOR VEHICLE NO. : SME7305U

DESCRIPTION	QTY	List Price
1 REAR END FLOOR PANEL 1150	1	\$ 1,150.00 ✓
2 REAR END BOTTOM PANEL 300.70	1	\$ 350.00 ✓
3 FLOOR MAT 950.80	1	\$ 1,650.00 ✓
4 TAILGATE INNER HANDLE COVER	1	\$ 28.00 ✓
5 REAR FENDER INNER TRIM 295.80	1	\$ 320.00 ✓
TOTAL: \$		3,498.00
LESS 20%: \$		(699.60)
PARTS TOTAL: \$		2,798.40

SPECIAL NETT

~~TO REMOVE REPAIR COSTS FROM THE ESTIMATE TOTAL~~

\$	3,018.40
7% GST: \$	211.29
Grand Total: \$	3,229.69

Mbm wheelpower pte ltd
 160 SIN MING DRIVE #06-02
 SIN MING AUTOCITY
 t 66262 8888 f 6452 5333