

Hk Cecilia choy

Not Authorized
Date
26/9/19
L/S \$3200

Hdy.



Revolution Automotive Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201907652D

JMYSLCyl

Vehic SJM6851J

Mode Mitsubishi Lancer 1.5 Mivec GLS 4A/T

Chass 4A910121191

Year c 2008

NO.	DESCRIPTION	QTY	U/P	AMT
#	List Items			
1	Front bumper retainer (LH)	1	Buf	36.00 ✓
2	Front bumper retainer (RH)	1	11	36.00 X
3	Front number plate garnish	1	To.n	69.00 ✓
4	Front fender (LH) 596.00	1	Buf	610.00 ✓
5	Front fender inner shield (LH)	1	To.n	130.00 ✓
6	Head lamp (LH) 912.00	1	holder	1100.00 ✓
				1981.00

Special Nett Items

7	Front bumper sport (fibre) 1400	1	To.n	1850.00 ✓
8	Front bumper clip set	1	na	50.00 ✓
9	Front fender inner shield clip set (LH)	1	11	50.00 X
10	Front number plate & casing	1	scr	45.00 40
				1995.00

Labour Items

11	To check wiring & lighting system	1		80.00 20
12	To supply under-coating & anti rust treatment on affected areas	1		80.00 30
13	To conduct head lamp focus	1	Repair	100.00 X
14	To repair, replace & realign damaged areas	1		800.00 400
15	To spray painting on affected areas	1		800.00 500
16	Sundries	1	11	50.00 X
				1910.00

List Items Subtotal 1981.00

Special Nett Items Subtotal 1995.00

Labour Items Subtotal 1910.00

Total 5886.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1743.00
102
P-156870
S.W 1490.00
L- 950.00
4008.70