



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SLB 654KMake & Model : HONDA VEZELYear of Manufacture : 2015

Chassis No. : _____

Ins Company : CHINA TAIPING

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 13/09/2019Time of Accident : 13.45Suggested Days of Repair : 5In-house Vehicle Assessor**Repair Estimates**

Case Owner : _____

Signature : _____

Contact No 6848 5725

Parts (a) Cost / List Price Items \$ 5,381.85Plus/Less 20% \$ 1,076.37Total of Cost / List \$ 4,305.48(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 4,305.48Labour (Appendix B) \$ 2,000.00Total Repair Cost \$ 6,305.48

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Adrian LingCompany : CCCSurvey conducted on : 25/09/19 at _____Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature] Date: 25/09/19

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SLB654K Case Owner : JOHARI
Make & Model : HONDA VEZEL Year Manufacture : 2015
Chassis No : RU111408557 Engine No : _____
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : _____

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	FRONT BONNET <i>Repr</i>	1		\$ 1,162.20	*		
2	FRONT HEAD LAMP RH <i>cracked</i>	1		\$ 2,366.00	✓	1820	
3	FRONT FENDER RH <i>Dented</i>	1		\$ 755.00	✓		
4	FRONT FENDER WHEEL ARCH RH <i>Repld</i>	1		\$ 199.00	✓		
5	FRONT BUMPER <i>Repr</i>	1		\$ 598.00	*		
6	FRONT BUMPER SIDE RETAINER RH <i>Repr</i>	1		\$ 27.00	+		
7	FRONT BUMPER CLIPS <i>new</i>	15		\$ 68.25	+		
8	FRONT FENDER COWLING RH <i>torn</i>	1		\$ 170.00	✓		
9	FRONT FENDER COWLING CLIP'S <i>new</i>	8		\$ 36.40	✓		
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Vehicle No.	: <u>SLB654K</u>	Case Owner	: <u>JO</u>
Make & Model	: <u>HONDA VEZEL</u>	Year of Manufacture	: <u>2015</u>

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.