

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

23-Sep-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8535 R

1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	106.00
1 pc	Rear bumper n/s reflector	\$	46.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
			\$ 1,905.00
Less 10%			\$ 190.50
			\$ 1,714.50


### S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00
	Rear Bumper Rubber Mat - new \$50 -	\$	200
	Sundry	\$	50.00
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.	\$	200
	To putty and spray painting on rear bumper, end panel	\$	800.00
	To apply rustproofing on the repaired and replaced panels.	\$	180
		\$	400.00
		\$	80.00
		\$	3,672.50

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

24/10/19  
at 45 \$1200 / 2 hrs  
//



Kahin 11/10/19  
23/9/19 17:56  
2 hrs  
45  
After Repair ph