

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

23-Sep-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8535 R


1 pc	Rear bumper	✓	\$	696.00
1 pc	Rear bumper lower cover	✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	✗	\$	58.00
1 pc	Rear bumper inner sponge	✗	\$	114.00
1 pc	Rear bumper reinforcement	✗	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	✗	\$	106.00
1 pc	Rear bumper n/s reflector	✗	\$	46.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	✗	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	✗	\$	36.00
				<hr/>
				\$ 1,905.00
Less 10%				\$ 190.50
				<hr/>
				\$ 1,714.50

S/NETT

1 set	Rear bumper clips	✓	\$	48.00
1 set	Reverse sensor		\$	280.00
	<i>Rear Bumper Rubber Mat - \$50 -</i>			200
	Sundry		\$	50.00 ✗
	To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 ✗
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.		\$	200 800.00
	To putty and spray painting on rear bumper, end panel		\$	180 400.00
	To apply rustproofing on the repaired and replaced panels.		\$	80.00 ✗
				<hr/>
				\$ 3,672.50

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.



Koh 11/11/19
23/9/19 17:06
2075
4/5
After Repair photo