



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 7380A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE & INSTALL FRONT RH ALLOY RIM FOR REPAINT & WHEEL BALANCING.		25.00	25.00
	TO ALIGN & REPAIR RH PORTION & AFFECTED AREAS.		300.00	150.00
	TO SPRAY FRONT BUMPER, FRONT FENDER RH, DRIVER'S DOOR, REAR FENDER RH, REAR BUMPER, SIDE MIRROR COVER RH & FRONT WHEEL RH.		1,200.00	800.00
			1,605.00	975.00
GRAND TOTAL			1,605.00	975.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				975.00

Report Ref No. CS/FCI19016840/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.