



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19016840/Ktf3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-05-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7142S	Veh. Inspected	SKE 7380A
Policy No.		Coverage (\$)	0.00
Claim No.	D19005806MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	24/09/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180 (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WDD2043492F839001	Colour	METALLIC PEARL WHITE
Odometer	153290	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	PIRELLI	7 mm
L/H Front Tyre	225/55 R17	PIRELLI	7 mm
R/H Rear Tyre	225/55 R17	PIRELLI	7 mm
L/H Rear Tyre	225/55 R17	PIRELLI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/09/2019	Inspection Date	07/10/2019
Survey held at	AH LIM MOTOR COMPANY 176 SIN MING DRIVE #05-12 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS.
B)DAMAGES CONSISTENT TO ACCIDENT REPORT.
C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**