

Kd



OPTIMA WERKZ PTE LTD

Co. Reg. No. 201212455W

www.ow.sg

f /OptimaWerkz

● /OptimaWerkz

Date: 01.10.2019
 Vehicle No: SKK2828C
 Model: MERCEDES BENZ GLC250 AMG COUPE
 Chassis: WDC2533462F183959 - 2016
 Reg.Year: 2017

Third Party Insurer: AIG
 Third Party Veh No: SKF4013A
 Date of Accident: 23.09.2019

Not with bank

Running B4 parting 4 days
 85189.53

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>2303-25</i>	1		<i>RT</i> \$2,303.25
2	REAR TAILGATE "AMG" EMBLEM	1		<i>RT</i> \$208.65
3	REAR BUMPER	1		<i>RT</i> \$1,111.50
4	REAR BUMPER CLIPS	12	\$5.80	<i>RT</i> \$69.60
5	REAR BUMPER LOWER COVER	1	<i>RT</i> \$633.70	
6	REAR WINDSCREEN STOPPER	2	\$15.00	<i>RT</i> \$30.00
7	REAR TAILGATE INNER TRIM CLIPS	10	\$6.50	<i>RT</i> \$65.00
SUB TOTAL				\$4,421.70
LESS 10%				-\$442.17
PARTS TOTAL				\$3,979.53

P - \$3979.53
 S/N - \$40.00
 L - \$1170.00
 (4 days)
 Part by Part
 \$5189.53 ✓ etc

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>RT</i> \$60.00
S/N TOTAL				\$60.00

LABOUR CHARGES:

LABOUR CHARGES TO REPAIR, REPLACE, REMOVE & READJUST REAR ACCIDENT AREAS & ETC

400
\$500.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN RUBBER & ETC

1201
\$150.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC

5001
\$700.00

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR, REAR REVERSE CAMERA & ETC. BACK TO ORIGINAL OPERATIONS

601
\$120.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 Fax: (+65) 6452 9223



Date: 01.10.2019
 Vehicle No: SKK2828C
 Model: MERCEDES BENZ GLC250 AMG COUPE
 Chassis: WDC2533462F183959 - 2016
 Reg.Year: 2017

Third Party Insurer: AIG
 Third Party Veh No: SKF4013A
 Date of Accident: 23.09.2019

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL CONDITIONS	\$150.00	601
TO TUFF KOTE & UNDERSEAL MATERIALS	\$100.00	301
TO DIAGNOSIS FAULTY CODE & RESET MEMORY	\$120.00	XX
LABOUR TOTAL	\$1,840.00	

ONG	TOTAL	\$5,879.53
-----	-------	------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: