

ASS. REC. BY: Adrian

REF: ^{CG} / A2G 19016852 / Aaf312

ASSIGNMENT

Minimum

From: _____ Date: **24.9.2019**

Estimated Cost: _____

☒ OD / ☐ P / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: **SFE 26D**

at Workshop n/s: **Premium**

of **55 Wbi road 1**

Insured: _____

Policy No: **1800156747**

Claims No: **383035116756**

Sum Insured: _____ Excess: **800 26/4/19**
800 09/3/20

(Client's Record)

Make of Veh: **10.00a.m ownr waiting**

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **160K**

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: **04 hrs** days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / ☒ REV / ☐ REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Veh No: **SFE26D** Yr Regn: **2018 / Dec**

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or

Make: **Audi A5 SB** C.G: **1984**

Colour: **Black** A/C: **Insured / Std / NI / NA**

Sp. Reading: **8982** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **WAU22ZF50KA006377**

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ STD A/Rim or

Tyre Size: F: **255/35R19**
R: **255/35R19**

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 06 mm	R/Bal. 06 mm
L/Bal. 06 mm	L/Bal. 06 mm
D.O.A. _____	D.O.L. 24/09/19

Survey held at: **Premium**

Des. of Damages: Frt / Rear / ☒ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	00A16g
	SFE 26D - CVT / VAL 14001713 / R4
15/9/19 @ 10.53am	Report to Victor via Messenger.
16/9/19 @ 9.59am	Victor informed CA via Messenger.
16/9/19 @ 11.4am	Informed Tony CIA & Ex: \$800 by email.
24/09/20 @ 9.40am	Confirmed with Caroline final fig @ 3845.68, 4 days. (Red @ 3864.52, 50%)

RECEIVED 10 MAR 2020

Date/Time, File Pass to? ☐ : Prel. Report

10/3 finish ☐ : Final Report

Date/Time, File Return to? _____

Days Of Repair: **4**

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee: _____

Transportation: **200**

S + RS: **11**

Photos: _____

Notes: _____

Rep. Form: **MEP-00**

Lum. Sum: **3845.68**

TOTAL: **211**

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 25 Sep 2019

Preliminary Advice

Vehicle No	: SFE26D	Accident Date	: 19/09/2019
Make	: AUDI A5	Policy No.	: 1800156747
Assignment Date	: 25/09/2019	Excess	: S\$0.00
Date of Inspection	: 24/09/2019	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,813.00
Revised Amount	:S\$	3,516.00
Check Items (Estimated)	:S\$	769.00
Total	:S\$	4,285.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	160,000.00
COE / PARF Rebate	:S\$	63,849.00
Salvage Value	:S\$	
Margin for Repair	:S\$	96,151.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING FOR TYRE RIM PRICES.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 26 September 2019 11:14 AM
To: Claims Dept
Cc: 'Carrine Leong'; SUR
Subject: RE: OD CLAIM FOR SFE 26 D ON 19/9/2019

Dear Tony,

Please take note the message from insurance officer: "LABOUR 1 NEED TO TAKE OUT AS NOT NECESSARY SINCE NOT REPLACING BUMPER". (OR YOUR NEED TO DISCUSS WITH ADRIAN)

As instructed by our client, please proceed to repair the insured vehicle **SFE 26D (Excess \$ 800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Wednesday, 25 September 2019 10:40 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: FW: OD CLAIM FOR SFE 26 D ON 19/9/2019

Dear Shiau Chan,

Refer this email on yesterday.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Singapore 408699

p. +65 6366 2323, d. +65 67689911

e.<mailto:claims@premiumauto.com.sg> w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shiau Chan (LKKAUTO)

From: Gan, Hun Chung <Hunchung.Gan@aig.com>
Sent: Monday, 9 March 2020 5:06 PM
To: Shiau Chan (LKKAUTO)
Cc: Lim, Sheng Yang; Parthiban, Theerthan; Mohd Rizal, Nur Mariah Huibrechts
Subject: RE: AIG-OD / 3830351167SG / SFE 26D

Hi Shiau Chan,

System auto changed the excess to \$0.00.

31	27 Sep 2019 11:30	Clin Registration Modified	Excess: 800.00 -> 0.00.
	27 Sep 2019	The Claim Linked to	

The correct excess amount should be \$ 800.00.

Thank You

Best Regards.

Gan Hun Chung
AIG
Claim Examiner I.
Singapore- Auto Express
E: Hunchung.Gan@aig.com

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Monday, March 9, 2020 4:59 PM
To: Gan, Hun Chung <Hunchung.Gan@aig.com>
Subject: [EXTERNAL] AIG-OD / 3830351167SG / SFE 26D

This message is from an external sender; be cautious with links and attachments.

Dear Hun Chung,

Kindly confirm the excess is \$800.00 (half waiver) or \$0.00 (full waiver). (original excess \$1,600.00)

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 24 February 2020 9:40 AM
To: Carrine Leong; SUR
Cc: 'Boo seng yak'; 'Chang Chee Sing'; jlayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SFE26D - OD AIG - SURVEYED 24 NOV 19

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$3,845.68 before excess \$0.00 & GST and 4 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Thursday, 20 February 2020 6:08 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Chang Chee Sing' <claims@premiumauto.com.sg>; jlayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SFE26D - OD AIG - SURVEYED 24 NOV 19

Dear Shiau Chan,

Original rim price is \$963.50.

Please find attachment file for your attention.

Thanks & Best Regard

Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd [Reg No 199902271W]

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 21 February 2020 9:03 AM
To: 'Koh, Victor-CK'
Cc: 'Fong, Andy-SY'
Subject: RE: PENDING FOR MANDATE AND RE-MANDATE APPROVAL
Attachments: SFE26 ORIGINAL RIM INVOICE.pdf

Dear Victor,

According to the repairer, the original rim prices of SFE 26D is \$963.50. The document already uploaded in Merimen System.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 19 February 2020 2:50 PM
To: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>
Subject: RE: PENDING FOR MANDATE AND RE-MANDATE APPROVAL

Dear Victor,

Thank you for the email.

We will check and revert to you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Wednesday, 19 February 2020 2:06 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>
Subject: RE: PENDING FOR MANDATE AND RE-MANDATE APPROVAL

Hi Shiau Chan,

SFE26D – Kindly check and let me know what is the original rim price?

Thanks & Regards

Victor Koh
AIG

Shiau Chan (LKKAUTO)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Wednesday, 19 February 2020 2:06 PM
To: Shiau Chan (LKKAUTO)
Cc: Fong, Andy-SY
Subject: RE: PENDING FOR MANDATE AND RE-MANDATE APPROVAL

Hi Shiau Chan,

SFE26D – Kindly check and let me know what is the original rim price?

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, February 18, 2020 4:08 PM
To: Koh, Victor-CK
Cc: Fong, Andy-SY
Subject: [EXTERNAL] RE: PENDING FOR MANDATE AND RE-MANDATE APPROVAL

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

Kindly advise the mandate and re-mandate approval as below.

Especially for GBD 6912J, repairer keep asking for the approval.

Kindly assist.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 18 February 2020 9:11 AM
To: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Subject: PENDING FOR MANDATE AND RE-MANDATE APPROVAL

Dear Victor,

View Received Message

This mail is associated with :

***SFE26D (3830351167SG)**

OD

Sep 19 2019 5:00PM

[LEE CHEOW YEW JULIAN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 27/09/2019 11:30 AM.

To LKK_HQ

Subject SFE26D / OD / 19/09/2019 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$0.00

Thank you

AIG OneClaim Integration User

DOCUMENTS SUMMARY

There are no documents.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	20 Sep 2019 14:25	Cim Veh Model Changed		[] Merimen Administrator
2	20 Sep 2019 14:25	Cim Created	Reg No: SFE26D, Policy No: 1800156747, Acct Date: 2019/09/19, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA119124717	[I] Merimen Administrator
3	23 Sep 2019 09:16	Cim Registration Modified	Acct Time:17:20:00->17:00:00.	[I] Lim, Sheng Yang
4	25 Sep 2019 09:17	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] LEE SU THING
5	25 Sep 2019 09:17	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
6	25 Sep 2019 09:17	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
7	25 Sep 2019 09:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/04	[A] LEE SU THING
8	25 Sep 2019 09:17	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] LEE SU THING
9	25 Sep 2019 09:17	Cim Registration Modified	Rep:1137->200611.	[A] LEE SU THING
10	25 Sep 2019 09:17	Cim Veh Model Changed	(205279) AUDI A5 2.0 SPORTBACK (A).	[A] LEE SU THING
11	25 Sep 2019 09:17	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
12	25 Sep 2019 10:46	Adj Rpt Initiated		[A] SHIAU CHAN
13	25 Sep 2019 10:46	Insured Phone No Updated	[None] -> [+6597209820]	[A] SHIAU CHAN
14	25 Sep 2019 10:46	Cim Dtl Modified	JPJ Reg. Date: -> 2018/12/29.	[A] SHIAU CHAN
15	25 Sep 2019 10:46	Cim Details Notified		[A] SHIAU CHAN
16	25 Sep 2019 10:50	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/10/04	[A] SHIAU CHAN
17	25 Sep 2019 10:53	Adj Mandate Request	Cur.Req:4285.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	25 Sep 2019 14:37	Cim Registration Modified	Init.Est.:->5,000 - 6,000, Excess: -> 800.00, Excess Waived: -> 800.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.	[I] Gan, Hunchung
19	25 Sep 2019 14:37	Label Added	{20226}:Coverage Confirmed.	[A] Merimen Administrator
20	26 Sep 2019 09:59	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/04, Mandate Remarks: Labour 1 to take out not necessary since not replacing bumper.	[I] Koh, Victor-CK
21	26 Sep 2019 09:59	Adj Mandate Set	Approved:3516.00:Labour 1 to take out not necessary since not replacing bumper, Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2291020	25 Sep 2019 10:46:21	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFE26D		11.77

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	20 Sep 2019 14:25	Cim Veh Model Changed			[] Merimen Administrator
2	20 Sep 2019 14:25	Cim Created	Reg No: SFE26D, Policy No: 1800156747, Acct Date: 2019/09/19, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA119124717		[I] Merimen Administrator
3	23 Sep 2019 09:16	Cim Registration Modified	Acct Time:17:20:00->17:00:00.		[I] Lim, Sheng Yang
4	25 Sep 2019 09:17	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.		[] LEE SU THING
5	25 Sep 2019 09:17	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)		[] LEE SU THING
6	25 Sep 2019 09:17	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] LEE SU THING
7	25 Sep 2019 09:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/04		[A] LEE SU THING
8	25 Sep 2019 09:17	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.		[A] LEE SU THING
9	25 Sep 2019 09:17	Cim Registration Modified	Rep:1137->200611.		[A] LEE SU THING
10	25 Sep 2019 09:17	Cim Veh Model Changed	(205279) AUDI A5 2.0 SPORTBACK (A).		[A] LEE SU THING
11	25 Sep 2019 09:17	Adj Adjuster Assigned	[None] -> ADRIAN LING		[A] LEE SU THING
12	25 Sep 2019 10:46	Adj Rpt Initiated			[A] SHIAU CHAN
13	25 Sep 2019 10:46	Insured Phone No Updated	[None] -> [+6597209820]		[A] SHIAU CHAN
14	25 Sep 2019 10:46	Cim Dtl Modified	JPJ Reg. Date: -> 2018/12/29.		[A] SHIAU CHAN
15	25 Sep 2019 10:46	Cim Details Notified			[A] SHIAU CHAN
16	25 Sep 2019 10:50	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/10/04		[A] SHIAU CHAN
17	25 Sep 2019 10:53	Adj Mandate Request	Cur.Reg:4285.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORIS E REPAIR.		[A] SHIAU CHAN
18	25 Sep 2019 14:37	Cim Registration Modified	Init.Est.->5,000 - 6,000. Excess: -> 800.00. Excess Waived: -> 800.00. 2F Remarks: -> Not Ap plicable. GST: -> 7.00.		[I] Gan, Hunchung
19	25 Sep 2019 14:37	Label Added	(20226):Coverage Confirmed.		[A] Merimen Administrator
20	26 Sep 2019 09:59	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/04, Mandate Remarks: Labour 1 to take out not necessary since not replacing bumper.		[I] Koh, Victor-CK
21	26 Sep 2019 09:59	Adj Mandate Set	Approved:3516.00:Labour 1 to take out not necessary since not replacing bumper.Reinsp:Yes.		[I] Koh, Victor-CK
22	27 Sep 2019 11:30	Cim Registration Modified	Excess: 800.00 -> 0.00.		[I] AIG OneClaim Integration User
23	22 Jan 2020 14:45	Adj Mandate Request	Cur.Reg:3845.68:KINDLY APPROVE REPAIR COST OF \$3,845.68.		[A] SHIAU CHAN
24	21 Feb 2020 11:53	Adj Mandate Set	Approved:3845.68.		[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	026A
Vehicle Details	
Vehicle No.:	SFE26D
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	CVK072389
Chassis No.:	WAUZZZF50KA006377
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$39,101.00
Original Registration Date:	29 Dec 2018
First Registration Date:	29 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$46,742.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2028
PARF Rebate Amount:	\$35,056.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,101.00
COE Rebate Amount:	\$28,793.00
Total Rebate Amount:	\$63,849.00

The information contained herein is correct as at 25 Sep 2019

OK

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LEE CHEOW YEW JULIAN
Period of Insurance : 29 Dec 2018 To 28 Dec 2020
Engine No. : CVK 072389
Chassis No. : WAUZZZF50KA006377

Vehicle No. : SFE26D
Policy No. : 1800156747
Endorsement No. :
Issued Date : 11 Jan 2019

ABOUT THE COVER

Make/Model : AUDI A5 Sportback 2.0TFSI S Tronic (Design)
Engine Capacity/Tonnage : 1,984.00 CC **Sum Insured** : Market Value
Driver Restriction : NA **Off Peak Car** : No
First Year of Registration : 2018
Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LEE CHEOW YEW JULIAN - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 95 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125284

PREMIUM LEASING - TGL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Staffery Ltd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13144

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1141/2019/NS
Date	:	21-Sep-19

Vehicle NOT IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Dr Lee Cheow Yew Julian
Address	:	3 Jalan Hajjah #03-05 Singapore 468698
Telephone	:	(HP) +65 97209820
Type of Claim	:	Own Damage Claims
Policy No.	:	1800156747
Vehicle No	:	SFE 26 D
Model Code	:	A5 Sportback 2.0 TFSI
Model / Year	:	29/12/2018
Engine No	:	CVK 072389
Chassis No	:	WAUZZZF50Ka006377
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Sep-19
Place of Accident	:	Junction Of Irrawandy Rd & Balestier Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 26 D

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓ X	
2	To dismantle front bumper rhs front fender. To renew rhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,400.00 1000,	
3	To respray rhs front fender.	\$ 1,200.00 550,	
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,552.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 26 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER - RH <i>Dented</i>	S	968.00 ✓ <i>774.40</i>
2	FRONT FENDER ATTACHMENT PARTS <i>RH NEC</i>	S	48.00 ? X
3	FRONT FENDER CLOSING ELEMENT - RH <i>Not NEC</i>	S	68.00 ? X
4	FRONT FENDER BRACKET - RH <i>NEC</i>	S	32.00 ? X
5	FRONT FENDER REAR BRACKET <i>not NEC</i>	S	53.00 ? X
6	FRONT FENDER CENTRE BRACKET <i>Not NEC</i>	S	32.00 ? X
7	FRONT FENDER BRACE - RH <i>Not NEC</i>	S	107.00 X
8	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH <i>Not NEC</i>	S	45.00 ? X
9	FRONT WHEEL HOUSING LINER - RH <i>NEC</i>	S	256.00 X
10	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>NEC</i>	S	82.00 X
11	WHEEL SPOILER <i>NEC</i>		TBC ✓
12	WHEEL SPOILER END PLATE - RH <i>NEC</i>	S	33.00 X
13	STONE CHIP GUARD - RH <i>Not NEC</i>	S	46.00 ? X
14	FENDER LEDGE COVER - INNER <i>Free</i>	S	32.00 ✓ <i>25.44</i>
15	FENDER LEDGE COVER - OUTER	S	14.00 ✓ <i>11.04</i>
16	FRONT FENDER TRIM <i>NEC</i>	NEC S	145.00 ? <i>115.60</i>
17	SUNDRIES <i>Not NEC</i>	S	300.00 ? X
TOTAL SPARE PARTS		:	\$ 2,261.00
TOTAL LABOUR CHARGES			\$ 4,552.00
GRAND TOTAL			\$ 6,813.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

18, Front RH Tyre Rim *at*
fls

\$ TBC ✓ *897.20*

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 24/09/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13144

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1141/2019/NS
Date : 21-Sep-19

Vehicle NOT IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

4 days - ok - jb - 16 Jan 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Dr Lee Cheow Yew Julian
Address : 3 Jalan Hajjah
#03-05
Singapore 468698
Telephone : (HP) +65 97209820
Type of Claim : Own Damage Claims
Policy No. : 1800156747
Vehicle No : **SFE 26 D**
Model Code : A5 Sportback 2.0 TFSI
Model / Year : 29/12/2018
Engine No : CVK 072389
Chassis No : WAUZZZF50Ka006377
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-Sep-19
Place of Accident : Junction Of Irrawandy Rd & Balestier Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 26 D

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	
2	To dismantle front bumper rhs front fender. To renew rhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,400.00	\$ 1,000.00
3	To respray rhs front fender.	\$ 1,200.00	\$ 550.00
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
5	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,552.00	\$ 2,022.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFE 26 D**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER - RH	\$ 968.00	\$ 774.40
2	FRONT FENDER ATTACHMENT PARTS	\$ 48.00	
3	FRONT FENDER CLOSING ELEMENT - RH	\$ 68.00	
4	FRONT FENDER BRACKET - RH	\$ 32.00	
5	FRONT FENDER REAR BRACKET	\$ 53.00	
6	FRONT FENDER CENTRE BRACKET	\$ 32.00	
7	FRONT FENDER BRACE - RH	\$ 107.00	
8	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	\$ 45.00	
9	FRONT WHEEL HOUSING LINER - RH	\$ 256.00	
10	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 82.00	
11	WHEEL SPOILER	TBC	
12	WHEEL SPOILER END PLATE - RH	\$ 33.00	
13	STONE CHIP GUARD - RH	\$ 46.00	
14	FENDER LEDGE COVER - INNER	\$ 32.00	\$ 25.44
15	FENDER LEDGE COVER - OUTER	\$ 14.00	\$ 11.04
16	FRONT FENDER TRIM	NEC \$ 145.00	\$ 115.60
17	RHS front tyre/rim	\$ 897.20	\$ 897.20
18	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		\$ 3,158.20	\$ 1,823.68
TOTAL LABOUR CHARGES		\$ 4,552.00	\$ 2,022.00
GRAND TOTAL		\$ 7,710.20	\$ 3,845.68

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Customer Signature



Audi

ETKA - Order Form

Order Form:

SFE26D-RIM

17:56

20.02.2020

SFE26D

Editor:

Item Description	Remark	Model	Qty	SGD	D
8W0 601 025 BH VIN: WAUEZZF50KA006377 Aluminium rim Colour code: Location : 2C03-C Stock : 0	8,5JX18H2 ET29 5/112 LD8	PR-CV8	1	963,50	
			+ 7.0% VAT	----- 963,50 67,45 1030,95 -----	SGD

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SFE 26 D

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1141/2019/NH

4th March 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SFE 26 D, Audi A5 SB 2.0 TFSI S-TRONIC.

With reference to the above-mentioned vehicle, no. **SFE 26 D**, claimant, **Mr. Lee Cheow Yew Julian**, please find the related document per attached.

1. A copy of the Original invoice no. 85014942 – S\$ 3,258.88.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SFE 26 D

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:25

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014942 Date : 03/03/2020 Order : SFE0026D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SFE0026D (V 40301) Regn Date: 29/12/2018 Mileage: 12434 WIP No.: 13144

Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF50KA006377 Engine: CVK 072389 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER AND RHS REAR FENDER. TO RENEW RHS FRONT FENDER.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY RHS FRONT FENDER	550.00	1.00	550.00
S	BODYWORK	M: TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
Q	OTHERS	M: TO SUPPLY RHS FRONT RIM (BY OWNEN)	897.20	1.00	897.20
X	A8W6821106B	FENDER(LAST)	Less 020%	1.00	968.00
X	A8W6820582E	COVER	Less 020%	1.00	31.80
X	A8W6823746	COVER	Less 020%	1.00	13.80
X	A8W6853602A PUZ	TRIM	Less 020%	1.00	144.50

Parts 926.48
Labour 897.20
Sublet 2,022.00
Menus 0.00
Lubricant 0.00



Sub-Total 3,045.68

7% GST 213.20

Grand Total 3,258.88

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SFE26D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1141/2019/TF
16 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A5 SPORTBACK 2.0 TFSI S tronic
Vehicle Chassis No. : WAUZZZF50KA006377
Vehicle Regn No. : SFE26D
Vehicle Mileage : 9430KM
Vehicle Owner : Mr. Lee Cheow Yew Julian
Certificate No : 1800156747
Own Damage Excess : \$856.00 (Inclusive GST)
Accident Date : 19/09/2019
Place : Junction Of Irrawandy Rd and Balestier Rd
Repair Cost : \$ 3258.88
WIP No. : 13144
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 1130am
Date : 21 Oct 2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2019		25 Sep 2019 09:17 Edit Adj Rpt	S\$3,845.68 Edit Estimates	S\$3,845.68 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	LEE CHEOW YEW JULIAN, ID: S1811026A, Tel: +6597209820			
Vehicle Reg. No.:	SFE26D	Date of Loss:	19/09/2019 17:00 - :59 [8 Months and 21 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 3830351167SG	Policy/Cover Note No.:	1800156747 (Comprehensive)	
		Excess:	S\$800.00	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/10/2019]			
Driver/Custodian:	VIVIAN TEO EE LING (52 / Female) , NRIC: S1795287J, Tel: +6594680600 Email: VIVTEO@SINGNET.COM.SG			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (09/03/2020): SFE26D / OD / 19/09/2019 / Coverage & Excess update
- AIG_SG (21/02/2020): Alert - Adj Mandate Approved (S\$3845.68) - SFE26D - Claim Handler: Gan, Hunchung
- AIG_SG (27/09/2019): SFE26D / OD / 19/09/2019 / Coverage & Excess update
- AIG_SG (26/09/2019): Alert - Adj Mandate Approved (S\$3516.00) - SFE26D - Claim Handler: Gan, Hunchung
- AIG_SG (25/09/2019): SFE26D / OD / 19/09/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFE26D (3830351167SG)**
OD
Sep 19 2019 5:00PM
[LEE CHEOW YEW JULIAN]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/09/19 14:24	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/19 10:50	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/19 10:52	General View	Load JPG	☒
2	25/09/19 10:52	Chassis Number	Load JPG	☒
3	25/09/19 10:52	General View	Load JPG	☒
4	25/09/19 10:52	General View	Load JPG	☒
5	25/09/19 10:52	General View	Load JPG	☒
6	25/09/19 10:52	General View	Load JPG	☒
7	25/09/19 10:52	General View	Load JPG	☒
8	25/09/19 10:52	General View	Load JPG	☒
9	25/09/19 10:52	General View	Load JPG	☒
10	25/09/19 10:52	General View	Load JPG	☒
11	25/09/19 10:52	General View	Load JPG	☒
12	25/09/19 10:52	General View	Load JPG	☒
13	25/09/19 10:52	General View	Load JPG	☒
14	25/09/19 10:52	General View	Load JPG	☒
15	25/09/19 10:52	General View	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/19 10:51	Singapore Accident Statement	Load PDF	
2	25/09/19 10:51	Certificate of Insurance	Load PDF	
3	25/09/19 10:51	ESTIMATE	Load PDF	
4	25/09/19 10:58	Driver's Driving License	Load PDF	
5	22/01/20 14:43	TYRE RIM TAX INVOICE	Load PDF	
6	22/01/20 14:43	REVISED ESTIMATE	Load PDF	
7	21/02/20 09:00	ORIGINAL RIM INVOICE	Load PDF	
8	10/03/20 15:10	WORKSHOP INVOICE	Load PDF	
9	10/03/20 15:10	DISCHARGE VOUCHER	Load PDF	

Linked Accident Report Documents

			View View in Browser	
Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/09/19 14:24	Video - Accident	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/12/19 18:51	Accident Statement	Load HTM	

Video			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
2	06/12/19 18:51	Accident Statement	 Load HTM	☐
3	06/12/19 18:52	Accident Statement	 Load HTM	☐
4	06/12/19 18:52	Accident Statement	 Load HTM	☐
Photos/Images			3 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/09/19 14:20	Accident Photo	 Load JPG	☒
2	20/09/19 14:20	Accident Photo	 Load JPG	☒
3	20/09/19 14:20	Accident Photo	 Load JPG	☒
4	20/09/19 14:20	Accident Photo	 Load JPG	☒
5	20/09/19 14:20	Accident Photo	 Load JPG	☒
6	20/09/19 14:20	Accident Photo	 Load JPG	☒
7	20/09/19 14:20	Accident Photo	 Load JPG	☒
8	20/09/19 14:20	Accident Photo	 Load JPG	☒
9	20/09/19 14:20	Accident Photo	 Load JPG	☒
10	20/09/19 14:20	Accident Photo	 Load JPG	☒
11	20/09/19 14:20	Accident Photo	 Load JPG	☒
12	20/09/19 14:20	Accident Photo	 Load JPG	☒
13	20/09/19 14:20	Accident Photo	 Load JPG	☒
14	20/09/19 14:20	Accident Photo	 Load JPG	☒
15	20/09/19 14:20	Accident Photo	 Load JPG	☒
16	20/09/19 14:20	Accident Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/09/19 14:22	Sketch Plan	 Load JPG	☒
2	20/09/19 14:22	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19016852/AQF3N2

Date: 10/03/2020

REFERENCE

Insured/Claimant:	LEE CHEOW YEW JULIAN	Policy No:	1800156747	
Date of Loss:	19/09/2019	Nature of Claim:	OD	Claim No: 3830351167SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFE26D	Engine No:	CVK072389
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF50KA006377
Reg. Date:	29/12/2018 (Man, Year: 2018)	Odometer:	8982 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,158.20	1,823.68	1,334.52	42.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,552.00	2,022.00	2,530.00	55.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,710.20	3,845.68	3,864.52	50.12
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	6,910.20	3,045.68	3,864.52	55.92
+ GST 7.00/7.00% (S\$)	483.71	213.20	270.51	55.92
Nett Amount (S\$)	7,393.91	3,258.88	4,135.03	55.92

INSPECTION

Date of Assignment:	25/09/2019		
Date Inspected:	24/09/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - RH	Dented	968.00 FS	*774.40 FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	48.00 FS	*- FS
3	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	68.00 FS	*- FS
4	1		*FRONT FENDER BRACKET - RH	Not Necessary	32.00 FS	*- FS
5	1		*FRONT FENDER REAR BRACKET	Not Necessary	53.00 FS	*- FS
6	1		*FRONT FENDER CENTRE BRACKET	Not Necessary	32.00 FS	*- FS
7	1		*FRONT FENDER BRACE - RH	Not Necessary	107.00 FS	*- FS
8	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	45.00 FS	*- FS
9	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	256.00 FS	*- FS
10	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	82.00 FS	*- FS
11	1		*WHEEL SPOILER (NPA)	Not Necessary	-	-
12	1		*WHEEL SPOILER END PLATE - RH	Not Necessary	33.00 FS	*- FS
13	1		*STONE CHIP GUARD - RH	Not Necessary	46.00 FS	*- FS
14	1		*FENDER LEDGE COVER - INNER	Necessary	32.00 FS	*25.44 FS
15	1		*FENDER LEDGE COVER - OUTER	Necessary	14.00 FS	*11.04 FS
16	1		*FRONT FENDER TRIM	Necessary	145.00 FS	*115.60 FS
17	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
18	1		*FRONT RH TYRE RIM	Cut	897.20 FS	*897.20 FS

F=Franchise part, S=SpcNett.

Total Parts (\$\$)	3,158.20	1,823.68
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	0.00
2	TO DISMANTLE FRONT BUMPER RHS FRONT FENDER. TO RENEW RHS FRONT FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,400.00	1,000.00
3	TO RESPRAY RHS FRONT FENDER.	New	1,200.00	550.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			4,552.00	2,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >