

ASS. REC. BY:

REF: CS/MSG/19016863/21VFS312

Special Instruction:

Author: RASU1

ASSIGNMENT (Office)

Merimen

From (Person): Mund Ashik B. Modi

MS19

Date/Time: 24/01/2019 5:28pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 769E

Insured:

SKA 8959X

at Workshop m/s

Ding Automotive.

Tel:

96891857

of

31 corporation Road

Policy No:

1000925977

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:23am 25/9/19

Person Contacted:

Velan

Vehicle IN/OUT

Date/Time	Action/Instruction
	Polimile ✓
	SHC 769E - CS/PC1/8008137/Kshar BA - 06/04/2018
	SKA 8959X - X
26/9/19	Send preli revised via merimen
3/10/19	Final fig \$ 1540 (Red 9427.51, 869 (No LS) confirmed by email

ASS. REC. BY:

REF: MSIG

8399

ASSIGNMENT

From:

Date:

25/09/2019

Veh No:

SHC 769E

Yr Regn:

2015 / FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Estimated Cost:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHC 769E

at Workshop m/s

Ding Auto

of

31 Corporation Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

10am-12pm

velan@ 96891857

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Make:

Hyundai I40 1.7L

c.c 1685

Colour

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

549958

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHLCB41UMFU066069

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TRIANGLE

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/09/19

D.O.I.

25/09/19

Survey held at

Disk auto

Des. of Damages: Frt / Rear / B / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 04 OCT 2019

3/10/2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

3/10 - typist

Rep. Format:

menmen

Lump Sum / L.B.:

1540/-

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

200

11

211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 26 Sep 2019

Preliminary Advice

Insured Vehicle No	: SKA8959X	Accident Date	: 21/09/2019
TP Vehicle No	: SHC769E	Assignment Date	: 24/09/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 5.00
Date of Inspection	: 25/09/2019		
Inspection At	: DING AUTOMOTIVE PTE LTD (HQ) 31 CORPORATION ROAD SINGAPORE 649825		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,967.51
Revised Amount	:S\$	1,570.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,570.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2019		24 Sep 2019 17:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YANMAR ASIA (S) COPORATION PTE LTD, Co. Reg. No.: 198903008G		
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHC769E	Date of Loss:	21/09/2019 13:00 - :59 [55 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	1000925977 (Comprehensive) Coverage: 12/04/2019 - 11/04/2020
Vehicle Reg. No. (Insured):	SKA8959X	Policy No. (Claimant):	
		Excess:	
Repairer:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/09/2019]		
Driver/Custodian (Insured):	MORISHITA MASA HARU (30 / Male) , NRIC: G3400293U Email:		
Adj Asg. Remarks:	Car in 25/09/19 10am to 12pm. Manual assigned to LKK via email on 24/09/19. (Manual Assign), Car In, Liab: unclear, Agree on SJE. Assign: LKK Auto / AutoProbe. Contact: Vadivelan @ 9689 1857 / 6265 7130.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Tuesday, 24 September 2019 4:50 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned

ACCIDENT INVOLVING SHC769E AND SKA8959X (MSIG) ON 21/09/2019 SURVEYOR ARRANGEMENT

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua

Sent: Tuesday, 24 September, 2019 3:37 PM

To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>

Subject: FW: ACCIDENT INVOLVING SHC769E AND SKA8959X (MSIG) ON 21/09/2019 SURVEYOR ARRANGEMENT

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG



A Member of **MS&AD** INSURANCE GROUP

From: Taxis Customer Service [<mailto:taxiscs@stengg.com>]

Sent: Tuesday, 24 September, 2019 3:29 PM

To: Helene Phua <helene_phua@sg.msig-asia.com>

Cc: Muhd Ashik B Madi <ashik_madi@sg.msig-asia.com>

Subject: RE: ACCIDENT INVOLVING SHC769E AND SKA8959X (MSIG) ON 21/09/2019 SURVEYOR ARRANGEMENT

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Hi,

Please assign LKK Auto Consultants Pte Ltd or AutoProbe Consultants for survey. Appreciate for arrangement.

Best Regards,

VADIVELAN MOHAN

Ding Automotive Pte Ltd

Hp : 96891857 / 62657130

From: Helene Phua <helene_phua@sg.msig-asia.com>

Sent: Tuesday, September 24, 2019 2:21 PM

To: Taxis Customer Service <taxiscs@stengg.com>

Cc: Muhd Ashik B Madi <ashik_madi@sg.msig-asia.com>

Subject: RE: ACCIDENT INVOLVING SHC769E AND SKA8959X (MSIG) ON 21/09/2019 SURVEYOR ARRANGEMENT

WARNING! THIS EMAIL ORIGINATES FROM OUTSIDE ST ENGINEERING.

Hi,

We refer to your email dated 24/09/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Chow Bo Xiong
2) Kenneth Kong	7) E C Looi
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- (a) ***Fast lane settlement is not applicable for cases that liability is in dispute***
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Taxis Customer Service [<mailto:taxiscs@stengg.com>]

Sent: Tuesday, September 24, 2019 11:46 AM

To: Claims <claims@sg.msig-asia.com>

Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg

Subject: ACCIDENT INVOLVING SHC769E AND SKA8959X ON 21/09/2019 SURVEYOR ARRAGEMENT

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Officer ,

Kindly please arrange surveyor on 25/9/2019@10am-12PM. Vehicle still on road and driver will ground vehicle on 25/9/2019 morning. Please refer SAS report for your reference and please feel free call my mobile number if need any clarification.

Thanks

Best Regards,

VADIVELAN MOHAN
Ding Automotive Pte Ltd
Hp : 96891857 / 62657130

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Veron Chen (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 3 October 2019 10:05 AM
To: Veron Chen (LKKAUTO)
Subject: RE: 50112054 / SHC769E - Finalize Amount & After Repair Photo . (DOA:21/09/2019)

Veron,

This case no parts given so it is part by part

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Taxis Customer Service [mailto:taxiscs@stengg.com]
Sent: Wednesday, 2 October, 2019 6:32 PM
To: Rasul (LKKAUTO)
Cc: dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; kelly.ding@dingauto.sg; Asher Sng (LKKAUTO); CS A Team; Admin A; SUR
Subject: 50112054 / SHC769E - Finalize Amount & After Repair Photo . (DOA:21/09/2019)

Dear Rasul,

Please see below for the finalize according to our conversion to finalize for SHC769E

Please refer attachment Estimate & After Paint for SHC769E

Part By Part

Total Repair - 05 Days

Labour = \$1220

S/n = \$320

Parts = \$0

L+S+P = \$1540

Total Finalize amount = \$1540

Thank You

Best Regards ,

Guang

Ding Automotive Pte Ltd

Hp : 93299929 / 62657130

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 3 October 2019 4:06 PM
To: Rasul (LKKAUTO); SUR; Taxis Customer Service
Cc: dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; Asher Sng (LKKAUTO); CS A Team; Admin A
Subject: RE: 50112054 / SHC769E - Finalize Amount & After Repair Photo . (DOA:21/09/2019)

Dear Guang,

WITHOUT PREJUDICE

Confirmed finalize amount \$1540 @ 5 working days.

Kindly send Final invoice and all supporting documents directly to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Taxis Customer Service [<mailto:taxiscs@stengg.com>]
Sent: Wednesday, 2 October, 2019 6:32 PM
To: Rasul (LKKAUTO)
Cc: dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; kelly.ding@dingauto.sg; Asher Sng (LKKAUTO); CS A Team; Admin A; SUR
Subject: 50112054 / SHC769E - Finalize Amount & After Repair Photo . (DOA:21/09/2019)

Dear Rasul,

Please see below for the finalize according to our conversion to finalize for SHC769E

Please refer attachment Estimate & After Paint for SHC769E

Part By Part

Total Repair - 05 Days

Labour = \$1220

S/n = \$320

Parts = \$0

L+S+P = \$1540

Total Finalize amount = \$1540

Thank You

Best Regards ,

Guang
Ding Automotive Pte Ltd
Hp : 93299929 / 62657130

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 839G

Vehicle Details

Vehicle No.: SHC769E

Vehicle to be Exported: No

Intended Deregistration Date: 26 Sep 2019

Vehicle Make: HYUNDAI

Vehicle Model: I40 1.7L CRDI AT ABS AIRBAG 4DR

Primary Colour: Yellow

Manufacturing Year: 2014

Engine No.: D4FDEU483047

Chassis No.: KMHLB41UMFU066069

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$19,807.00

Original Registration Date: 11 Feb 2015

First Registration Date: 11 Feb 2015

Transfer Count: 0

Actual ARF Paid: \$12,307.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 10 Feb 2023

PARF Rebate Amount: \$9,230.00

Intended COE Rebate Details

COE Expiry Date: 10 Feb 2023

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$52,904.00

COE Rebate Amount: \$22,329.00

Total Rebate Amount: \$31,559.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/09/2019 20:23
Date Of Accident	21/09/2019 13:30
Exact Location Of Accident	ALONG THE BIO CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC769E
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40-1.7 D CRDI (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	WONG WENG KONG SIMON
NRIC No	S1153980G
Date Of Birth	24/12/1955
Occupation	OUTDOOR
Date Of Driving Pass	27/01/1995
Driving Experience	24 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88088752
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 18 TAMAN HO SWEE #06-09 SINGAPORE
Postcode	0316
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE NOT SUITABLE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA8959X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: V. Bal.
NRIC/FIN No.:

Accident Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 21/9/19 ABOUT 13:30 HOURS I WAS TRAVELLING WITH MY TAXI (SKC769E) ALONG THE BIO CRESCENT. AT TIME NO PASSENGER ON BOARD. AT POINT WHEN I WERE TURNING, suddenly I VEHICLE (SKA8959X) WHICH ALREADY PARKED IN WRONG DIRECTION AND DRIVE OUT SUDDENLY COLLIDED ON MY VEHICLE RAS BODY. DUE TO ACCIDENT MY VEHICLE BODY ON RAS HAD DAMAGED. I TOOK SOME PHOTOS FOR ACCIDENT REPORTING PURPOSE. NO INJURY WAS INVOLVED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: VAD
NRIC/FIN No.:

GLA/BMC Sketch Plan Form V3

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

25/09/2019 11:39

JOB-NO: 50112054

OWNER'S PARTICULARSNAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILSLICENSE NO: SHC0769E TRANS: AUTO
MAKE / MODEL: HYUNDAI / i40
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 1CHASSIS: KMHLE41UMFU066069
ENGINE: D4FDEU483047**CLAIM DETAILS**

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00	Y		400
2 R&R REAR WINDSCREEN GLASS TO REPLACE REAR RHS FENDER	1.00	180.00	0.00	180.00	Y		X
3 R&R REAR RHS DOOR COMPONENT	1.00	150.00	0.00	150.00	Y		X
4 R&R FRONT RHS DOOR COMPONENT	1.00	150.00	0.00	150.00	Y		X
5 CHECK AND CALIBRATE BOTH FRONT & REAR RHS POWER WINDOW AFTER REPAIR	1.00	120.00	0.00	120.00	Y		X
6 REPSRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		200
7 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		X repaired
8 RESPRAY REAR RHS OUTER & INNER FENDER	1.00	250.00	0.00	250.00	Y		200
9 RESPRAY REAR RHS DOOR (INNER & OUTER)	1.00	250.00	0.00	250.00	Y		200
10 RESPRAY FRONT RHS DOOR (INNER & OUTER)	1.00	250.00	0.00	250.00	Y		200
11 SUNDRIES	1.00	50.00	0.00	50.00	Y		20
12 R&R REAR RHS TAIL LAMP AND REPOSITION BOTH TAIL LAMP AFTER REPAIR	1.00	80.00	0.00	80.00	Y		X
13 R&R REAR PASSENGER SEAT & SEAT BELT & QUARTER GLASS TO REPLACE FENDER	1.00	200.00	0.00	200.00	Y		X
TOTAL:		3,180.00	0.00	3,180.00			

MATERIALS

1 REAR BUMPER repair	1.00	669.50	133.90	535.60	L	Y	
2 REAR BUMPER RETAINER RHS X SUC	1.00	42.84	8.57	34.27	L	Y	
3 REAR FENDER PANEL RHS repair	1.00	2,171.50	434.30	1,737.20	L	Y	
4 REAR FENDER INNER PANEL RHS X SUC	1.00	1,374.80	274.96	1,099.84	L	Y	
5 REAR RHS DOOR ASSY repair	1.00	2,201.00	440.20	1,760.80	L	Y	
6 FRONT RHS DOOR ASSY repair	1.00	2,256.00	451.20	1,804.80	L	Y	
7 REAR BUMPER CLIPS X SUC	1.00	45.00	0.00	45.00 30	S	Y	
8 REAR BUMPER ADS STICKER	1.00	150.00	0.00	150.00 80	S	Y	
9 REAR RHS FENDER ADS STICKER	1.00	150.00	0.00	150.00 80	S	Y	
10 REAR RHS DOOR ADS STICKER	1.00	150.00	0.00	150.00 80	S	Y	
11 FRONT RHS DOOR ADS STICKER	1.00	150.00	0.00	150.00 80	S	Y	
12 REAR RHS DOOR CLIPS X } SUC	1.00	45.00	0.00	45.00	S	Y	
13 FRONT RHS DOOR CLIPS X	1.00	45.00	0.00	45.00	S	Y	
14 SEALANT REAR FENDER RHS X	1.00	80.00	0.00	80.00	S	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
TOTAL:		9,530.64	.743.13	7,787.51			
TOTAL PARTS & LABOUR:		12,710.64	1,743.13	10,967.51			

EXCESS/LOADING:SS 0.00

No. Of Day:

5 daysRE-SURVEY: BEFORE AFTER PAINTINGPART-BY-PART OR LUMP SUM: SSDATE OF SURVEY: 25 / 09 / 19 @ 1200

SURVEYED BY:

Rasul

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

25/09/2019 11:39

JOB-NO: 50112054

OWNER'S PARTICULARSNAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILSLICENSE NO: SHC0769E TRANS: AUTO
MAKE / MODEL: HYUNDAI / i40
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 1CHASSIS: KMHLB41UMFU066069
ENGINE: D4FDEU483047CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00	Y		400
2 R&R REAR WINDSCREEN GLASS TO REPLACE REAR RHS FENDER	1.00	180.00	0.00	180.00	Y		X
3 R&R REAR RHS DOOR COMPONENT	1.00	150.00	0.00	150.00	Y		X
4 R&R FRONT RHS DOOR COMPONENT	1.00	150.00	0.00	150.00	Y		X
5 CHECK AND CALIBRATE BOTH FRONT & REAR RHS POWER WINDOW AFTER REPAIR	1.00	120.00	0.00	120.00	Y		X
6 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		200
7 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		X repair
8 RESPRAY REAR RHS OUTER & INNER FENDER	1.00	250.00	0.00	250.00	Y		200
9 RESPRAY REAR RHS DOOR (INNER & OUTER)	1.00	250.00	0.00	250.00	Y		200
10 RESPRAY FRONT RHS DOOR (INNER & OUTER)	1.00	250.00	0.00	250.00	Y		200
11 SUNDRIES	1.00	50.00	0.00	50.00	Y		20
12 R&R REAR RHS TAIL LAMP AND REPOSITION BOTH TAIL LAMP AFTER REPAIR	1.00	80.00	0.00	80.00	Y		X
13 R&R REAR PASSENGER SEAT & SEAT BELT & QUARTER GLASS TO REPLACE FENDER	1.00	200.00	0.00	200.00	Y		X
TOTAL:		3,180.00	0.00	3,180.00			

MATERIALS

1 REAR BUMPER repair	1.00	669.50	133.90	535.60	L	Y	
2 REAR BUMPER RETAINER RHS X	1.00	42.84	8.57	34.27	L	Y	
3 REAR FENDER PANEL RHS repair	1.00	2,171.50	434.30	1,737.20	L	Y	
4 REAR FENDER INNER PANEL RHS X	1.00	1,374.80	274.96	1,099.84	L	Y	
5 REAR RHS DOOR ASSY repair	1.00	2,201.00	440.20	1,760.80	L	Y	
6 FRONT RHS DOOR ASSY repair	1.00	2,256.00	451.20	1,804.80	L	Y	
7 REAR BUMPER CLIPS repair	1.00	45.00	0.00	45.00 30XS	Y		
8 REAR BUMPER ADS STICKER repair	1.00	150.00	0.00	150.00 80 S	Y		
9 REAR RHS FENDER ADS STICKER repair	1.00	150.00	0.00	150.00 80 S	Y		
10 REAR RHS DOOR ADS STICKER repair	1.00	150.00	0.00	150.00 80 S	Y		
11 FRONT RHS DOOR ADS STICKER repair	1.00	150.00	0.00	150.00 80 S	Y		
12 REAR RHS DOOR CLIPS X	1.00	45.00	0.00	45.00	S	Y	
13 FRONT RHS DOOR CLIPS X	1.00	45.00	0.00	45.00	S	Y	
14 SEALANT REAR FENDER RHS X	1.00	80.00	0.00	80.00	S	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
TOTAL:		9,530.64	,743.13	7,787.51			
TOTAL PARTS & LABOUR:		12,710.64	1,743.13	10,967.51			

EXCESS/LOADING: \$\$ 0.00

No. Of Day: 5 daysRE-SURVEY: BEFORE AFTER PAINTINGPART-BY-PART OR LUMP SUM: \$\$DATE OF SURVEY: 25 / 09 / 19 @ 1200SURVEYED BY: RasulCONTACT NO: 90010068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Part By Part

Labour = \$ 1220

S/M = \$ 320

Parts = \$ 0

L+STP = \$ 1540

Final Amount = \$ 1540

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016863/R1VF3N2

Date: 08/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1000925977
Claimant Vehicle No :	SHC769E	Insured Vehicle No :	SKA8959X
Date of Loss:	21/09/2019	Nature of Claim:	TP
		Claim No:	231478

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC769E	Engine No:	D4FDEU483047
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMFU066069
Reg. Date:	11/02/2015 (Man. Year: 2014)	Odometer:	549958 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,837.51	340.00	7,497.51	95.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,200.00	1,930.00	61.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,967.51	1,540.00	9,427.51	85.96
+ GST 7.00/7.00% (S\$)	767.73	107.80	659.93	85.96
Nett Amount (S\$)	11,735.24	1,647.80	10,087.44	85.96

INSPECTION

Date of Assignment:	24/09/2019	Inspected At:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD Singapore 649825
Date Inspected:	25/09/2019		

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2019)
Parts: 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC769E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	669.50 FL	*-FL
2	1		*REAR BUMPER RETAINER RHS	Serviceable	42.84 FL	*-FL
3	1		*REAR FENDER PANEL RHS	Repair	2,171.50 FL	*-FL
4	1		*REAR FENDER INNER PANEL RHS	Serviceable	1,374.80 FL	*-FL
5	1		*REAR RHS DOOR ASSY	Repair	2,201.00 FL	*-FL
6	1		*FRONT RHS DOOR ASSY	Repair	2,256.00 FL	*-FL
7	1		*REAR BUMPER CLIPS	Serviceable	45.00 FS	*-FS
8	1		*REAR BUMPER ADS STICKER	Necessary	150.00 FS	*80.00 FS
9	1		*REAR RHS FENDER ADS STICKER	Necessary	150.00 FS	*80.00 FS
10	1		*REAR RHS DOOR ADS STICKER	Necessary	150.00 FS	*80.00 FS
11	1		*FRONT RHS DOOR ADS STICKER	Necessary	150.00 FS	*80.00 FS
12	1		*REAR RHS DOOR CLIPS	Serviceable	45.00 FS	*-FS
13	1		*FRONT RHS DOOR CLIPS	Serviceable	45.00 FS	*-FS
14	1		*SEALANT REAR FENDER RHS	Serviceable	80.00 FS	*-FS
15	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,580.64	340.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,743.13	0.00
Total Parts (\$\$)	7,837.51	340.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	1,000.00	400.00
2	R&R REAR WINDSCREEN GLASS TO REPLACE REAR RHS FENDER	New	180.00	0.00
3	R&R REAR RHS DOOR COMPONENT	New	150.00	0.00
4	R&R FRONT RHS DOOR COMPONENT	New	150.00	0.00
5	CHECK AND CALIBRATE BOTH FRONT & REAR RHS POWER WINDOW AFTER REPAIR	New	120.00	0.00
6	RESPRAY REAR BUMPER	New	250.00	200.00
7	RESPRAY REAR BUMPER	New	250.00	0.00
8	RESPRAY REAR RHS OUTER & INNER FENDER	New	250.00	200.00
9	RESPRAY REAR RHS DOOR (INNER & OUTER)	New	250.00	200.00
10	RESPRAY FRONT RHS DOOR (INNER & OUTER)	New	250.00	200.00
11	R&R REAR RHS TAIL LAMP AND REPOSITION BOTH TAIL LAMP AFTER REPAIR	New	80.00	0.00
12	R&R REAR PASSENGER SEAT & SEAT BELT & QUARTER GLASS TO REPLACE FENDER	New	200.00	0.00
Gross Labour Cost (\$\$)			3,130.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >