

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9836E****AAD1909-202**

*Not Authorised*  
*1/1 Sep 8 1100h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

24 SEP 2019

**SHD 9836E**

VF1ABL15AUC277444

RENAULT

LATITUDE

21.9.19

**III**

25/4/2014

| PART |                                 | LIST |             |
|------|---------------------------------|------|-------------|
| 1    | BUMPER COVER FRT                | \$   | Sn 747.20 X |
| 1    | BUMPER RETAINER FRT RH          | \$   | Sn 101.40 X |
| 1    | BUMPER SUPPORT FRT              | \$   | Sn 10.70 X  |
| 1    | HEADLAMP RH                     | \$   | Sn 743.60 X |
| 1    | HEADLAMP PANEL FRT RH           | \$   | Sn 128.30 X |
| 1    | FENDER PANEL FRT RH             | \$   | Sn 437.10 ✓ |
| 1    | WHEELARCH FRT RH                | \$   | Sn 191.40   |
| 1    | FENDER BRACKET LOWER RH         | \$   | Sn 11.80    |
| 1    | FENDER INSULATOR RH             | \$   | Sn 66.30    |
| 1    | RADIATOR GRILLE                 | \$   | Sn 969.90   |
| 1    | RADIATOR GRILLE BADGE 'RENAULT' | \$   | Sn 225.36   |
| 1    | RADIATOR GRILLE FRAME           | \$   | Sn 686.00   |
| 1    | FRAME FULL SUPPORT PANEL        | \$   | Sn 592.70   |
| 1    | FRAME FULL SUPPORT BRACKET      | \$   | Sn 41.60    |
| 1    | BONNET                          | \$   | Sn 1,312.70 |
| 1    | BONNET INSULATOR                | \$   | Sn 294.30   |
| 1    | BONNET STRUT RH                 | \$   | Sn 53.30    |
| 1    | BONNET HINGE RH                 | \$   | Sn 237.40   |
| 1    | BONNET LOCK                     | \$   | Sn 152.80   |
| 1    | BONNET CABLE                    | \$   | Sn 55.20    |
| 1    | BONNET CABLE COVER              | \$   | Sn 80.60    |
| 1    | BONNET SEAL OUTER               | \$   | Sn 83.20    |
| 1    | BONNET SEAL INNER               | \$   | Sn 70.10    |
| 1    | WIPER RESERVOIR MOTOR           | \$   | Sn 82.60    |
| 1    | WIPER RESERVOIR                 | \$   | Sn 179.60   |
| 1    | WIPER RESERVOIR NECK            | \$   | Sn 29.30    |
| 1    | DOOR PANEL FRT RH               | \$   | Sn 2,844.66 |
| 1    | DOOR HINGE UPPER RH             | \$   | Sn 261.28   |

**Trans-cab Auto Services Pte Ltd****AAD1909-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9836E**

|              |                             |           |                    |   |
|--------------|-----------------------------|-----------|--------------------|---|
| 1            | DOOR HINGE LOWER RH         | \$        | <i>R</i> 300.55    | X |
| 1            | DOOR CHECK FRONT RH         | \$        | <i>SL</i> 194.77   | X |
| 1            | DOOR WHEATHESTRIIP FRONT RH | \$        | <i>SL</i> 410.27   | X |
| 1            | DOOR SEAL FRONT RH          | \$        | <i>SL</i> 72.82    | X |
| 1            | DOOR MIRROR ASSY RH         | \$        | <i>SL</i> 1,483.40 | X |
| <b>TOTAL</b> |                             | <b>\$</b> | <b>13,152.21</b>   |   |
| <b>10%</b>   |                             | <b>\$</b> | <b>1,315.22</b>    |   |
|              |                             | <b>\$</b> | <b>11,836.99</b>   |   |

**Special Nett**

|              |                                    |           |                  |               |
|--------------|------------------------------------|-----------|------------------|---------------|
| 1            | BUMPER CLIP FRT                    | \$        | <i>nn</i> 66.00  | } X           |
| 1            | BUMPER BRACKET CLIP FRT RH         | \$        | <i>nn</i> 12.00  |               |
| 1            | BUMPER SUPPORT CLIP FRT RH         | \$        | <i>nn</i> 10.50  |               |
| 1            | BUMPER GRILLE LOWER CLIP           | \$        | <i>nn</i> 69.00  |               |
| 1SET         | FRAME FULL SUPPORT PANEL CLIP      | \$        | <i>nn</i> 70.00  |               |
| 2            | FRAME FULL SUPPORT PANEL NUT       | \$        | <i>nn</i> 20.00  |               |
| 2            | FRAME FULL SUPPORT PANEL STUD      | \$        | <i>nn</i> 30.00  |               |
| 1            | WHEELARCH CLIP FRT RH              | \$        | <i>nn</i> 30.50  |               |
| 1            | FRONT RIGHT TYRE                   | \$        | <i>SL</i> 300.00 |               |
| 1            | FRONT RIGHT TYRE RIM               | \$        | <i>SL</i> 380.00 |               |
| 1SET         | Front licence plate with holder    | \$        | <i>SL</i> 80.00  |               |
| 1SET         | RADIATOR GRILLE SCREW              | \$        | <i>nn</i> 16.00  |               |
| 1SET         | RADIATOR GRILLE FRAME CLIP         | \$        | <i>nn</i> 52.00  |               |
| 1            | WINDSCREEN SEALANT                 | \$        | <i>nn</i> 109.20 |               |
| 1            | FRONT WINDSCREEN MOULDING          | \$        | <i>nn</i> 120.00 |               |
| 1            | FRONT WINDSCREEN INNER SPONGE SEAL | \$        | <i>nn</i> 100.00 |               |
| 6            | BONNET INSULATOR CLIP L70Y         | \$        | <i>nn</i> 7.30   | } <i>601n</i> |
| 2            | BONNET CABLE CLIP L70Y             | \$        | <i>nn</i> 6.31   |               |
| 2            | BONNET CABLE COVER SCREW L70Y      | \$        | <i>nn</i> 10.85  |               |
| 1            | FRONT DOOR STICKER 'Trans-Cab'     | \$        | <i>nn</i> 80.00  |               |
| 1            | FRONT DOOR STICKER 'Classic'       | \$        | <i>nn</i> 80.00  |               |
| 1            | FRONT RH WHEEL HUB CAP             | \$        | <i>nn</i> 35.00  | ✓             |
| <b>TOTAL</b> |                                    | <b>\$</b> | <b>1,684.67</b>  |               |

**TOTAL PARTS \$ 13,521.66****LABOUR**

To transfer of front windscreen glass to facilitate bodywork repair.

\$ *nn* 170.00 X

**Trans-cab Auto Services Pte Ltd****AAD1909-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9836E**

|                                                                                                                           |    |           |      |
|---------------------------------------------------------------------------------------------------------------------------|----|-----------|------|
| Putty and spray painting of the affected portion.                                                                         | \$ | 6,000.00  | 440/ |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 6,000.00  | 300/ |
| To rust-proofing of the affected areas.                                                                                   | \$ | 170.00    | 30/  |
| To transfer of front fender fittings, attachment and perform water seepage test.                                          | \$ | nn 380.00 | X    |
| To transfer of bonnet fittings, attachment and perform water seepage test.                                                | \$ | nn 380.00 | X    |
| To check steering geometry and computer wheel alignment                                                                   | \$ | 220.00    | 80/  |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00    | 15/  |
| To transfer of front bumper fittings, attachment and perform water seepage test.                                          | \$ | nn 380.00 | X    |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | nn 170.00 | X    |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | nn 380.00 | X    |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                                           | \$ | nn 380.00 | X    |
| To transfer of door fittings, attachment and perform water seepage test.                                                  | \$ | nn 380.00 | X    |

**TOTAL \$ 15,180.00****Over All Total \$ 28,701.66****LUMP SUM (REPAIR DAY)****20 DAYS**  
**2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: