

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5876R**

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model: 24 SEP 2019  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration :

AAD1909-123

*Not Authoised*  
*Resung B4paint*

81202.83

**SHD 5876R**

JTDKB3FU803079270

TOYOTA

PRIUS

15.9.19

**AIG**

17/1/2019

		PART
1	1	FRONT BUMPER
2	1	FRONT BUMPER SIDE RETAINER LH
3	1	FRONT LED LAMP (LOWER) LH
4	1	FRONT HEADLAMP LH
5	1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1
6	1	MOTOR, HEADLAMP LEVELING, LH
7	1	FRONT FENDER LH
8	1	LINER, FRONT FENDER, LH
9	1	GRILLE SUB-ASSY, RADIATOR
10	1	GRILLE, RADIATOR, LOWER NO.1
11	1	FRONT BONNET
12	1	HINGE ASSY, HOOD, LH
13	1	MOULDING ASSY, BODY ROCKER PANEL, LH
14	1	REINFORCE SUB-ASSY, ROCKER, OUTER LH

		LIST
\$	Bu	509.10
\$	Sn	112.70
\$	Sn	907.75
\$	Sn	2,909.04
\$	Sn	492.30
\$	Sn	413.10
\$	n	963.80
\$	Sn	200.70
\$	Sn	341.60
\$	Sn	167.90
\$	n	969.00
\$	n	58.00
\$	n	583.30
\$	n	572.10

<b>TOTAL</b>	\$	<b>9,200.39</b>
<b>25%</b>	\$	<b>2,300.10</b>
	\$	<b>6,900.29</b>

		Special Nett
1	1	FRONT WHEEL RIM
2	1	FRONT WHEEL RIM COVER
3	1	FRONT TYRE 195/65/15
4	1	CLIP, FRONT FENDER LINER
5	1	FRONT NUMBER PLATE WITH MOULDING
6	1	BUMPER CLIP FRT
7	1	WINDSCREEN SEALANT
8	1	FRONT WINDSCREEN MOULDING
9	1	FRONT WINDSCREEN INNER SPONGE SEAL

\$	Sn	1,570.55	X
\$	Sn	175.80	X
\$	Sn	350.00	X
\$	nn	22.00	X
\$	Sn	200.00	X
\$	nn	66.00	
\$	nn	253.80	X
\$	nn	120.00	X
\$	nn	100.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD1909-123**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5876R**

**TOTAL \$ 2,858.15**

**TOTAL PARTS \$ 9,758.44**

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	440l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	300l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To transfer of front windscreen glass to facilitate bodywork repair.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	15%
To transfer of Front Bonnet fittings, attachments and perform water seepage test.	\$	nn 170.00	X

**TOTAL \$ 11,170.00**

**Over All Total \$ 20,928.44**

**(PART-BY-PART) Repair Days 15 days  
2 days**

LKK Auto Consultants hence notify the Repairer of the following:  
 \* No resurvey before/after spray painting  
 \* To display damaged part(s) during resurvey  
 \* Parts prices are subject to confirmation  
 \* Third party survey is on a "Without Prejudice" basis  
 \* No illegal modification(s) is allowed  
 \* Supplementary item(s) must be approved  
 \* is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: