

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9990S

AAD1909-192

*Not Authorized
C/Sing \$6550/.*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

24 SEP 2019

SHD 9990S

VF1ABL15AUC278140

RENAULT

LATITUDE

21.9.19

CHINA TAIPING

13/6/2014

PART		LIST	
1	1	BUMPER COVER REAR	\$ <i>R</i> 561.70 ✓
2	1	BUMPER LOWER REAR	\$ <i>RM</i> 411.90 ✓
3	1	BUMPER BRACKET CTR REAR	\$ <i>DIY</i> 98.10 ✓
4	1	BUMPER BRACKET SIDE RH REAR	\$ <i>SM</i> 82.10 X
5	1	BUMPER RETAINER RH REAR	\$ <i>SM</i> 59.80 X
6	1	BUMPER REFLECTOR RH	\$ <i>SM</i> 16.60 X
7	1	BUMPER BRACKET SIDE LH REAR	\$ <i>SM</i> 80.80 X
8	1	BUMPER RETAINER LH REAR	\$ <i>DIY</i> 54.20 ✓
9	1	BUMPER REFLECTOR LH	\$ <i>CM</i> 16.60 ✓
10	1	BUMPER BEAM REAR	\$ <i>R</i> 547.80 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$ <i>R</i> 114.50 ✓
12	1	BUMPER BEAM BRACKET RH REAR	\$ <i>R</i> 100.90 X
13	1	BOOT REAR	\$ <i>R</i> 1,677.20 ✓
14	1	BOOT FINISHER	\$ <i>CM</i> 344.70 ✓
15	1	BOOT WHEATERSTRIP	\$ <i>WT</i> 178.20 <i>50/12 89.1052</i>
16	1	BOOT REFLECTOR LAMP LH	\$ <i>CA</i> 277.70 ✓
17	1	BOOT REFLECTOR LAMP RH	\$ <i>SM</i> 277.70 X
18	1	BOOT BADGE 'RENAULT'	\$ <i>RM</i> 82.40 ✓
19	1	BOOT BADGE	\$ <i>RM</i> 95.80 ✓
20	1	BOOT STRUT LH	\$ <i>SM</i> 145.10
21	1	BOOT STRUT RH	\$ <i>SM</i> 145.10
22	1	BOOT HINGE LH	\$ <i>R</i> 254.20
23	1	BOOT HINGE RH	\$ <i>R</i> 253.80
24	1	BOOT INNER TRIM BOARD	\$ <i>SM</i> 611.00 } X
25	1	BOOT SWITCH	\$ <i>SM</i> 113.00
26	1	BOOT LOCK	\$ <i>R</i> 246.60
27	1	BOOT LOCK CATCH	\$ <i>R</i> 41.70

Trans-cab Auto Services Pte Ltd

AAD1909-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9990S

28	2	LICENCE PLATE LAMP	\$	Sm	26.30	}
29	2	BOOT RUBBER PLUG	\$	Sm	139.30	
30	1	FENDER PANEL INNER TRIM REAR LH	\$	Sm	671.45	
31	1	FENDER PANEL REAR LH	\$	R	1,933.20	
32	1	WHEELARCH REAR LH	\$	Sm	275.40	
33	1	TAILLAMP RH	\$	Sm	313.10	
34	1	TAILLAMP PANEL RH	\$	R	401.40	}
35	1	TAILLAMP LH	\$	CM	401.40	
36	1	TAILLAMP PANEL LH	\$	R	401.40	✓
37	1	OUTER PANEL REAR (End Panel)	\$	R	745.80	✓
38	1	OUTER PANEL REAR (End Panel)TRIM	\$	CM	404.56	✓
39	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	1,229.40	X
40	1	SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
41	1	EXHAUST REAR	\$	R	5,263.60	X
42	1	EXHAUST CAP REAR	\$	R	125.40	X
TOTAL			\$		19,833.12	
10%			\$		1,983.31	
			\$		17,849.81	

Special Nett

1	1SET	PARKING AID	\$	Shot	700.00	400sm
2	1SET	REAR BUMPER CLIP	\$	R	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	R	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	R	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sm	16.00	X
11	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	R	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	R	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sm	385.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9990S**AAD1909-192**

17	1	SPARE TYRE	\$	Sm	330.00	X
18	1	FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19	1	TAILLAMP CLIP RH	\$	nn	5.00	X
20	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	X
21	1	WINDSCREEN MOULDING	\$	nn	100.00	X
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
23	1	TAILLAMP CLIP LH	\$	nn	5.00	✓
24	1	Rear Bumper Protector	\$	nn	100.00	X
25	1	REAR LEFT TYRE	\$	Sm	300.00	X
26	1	REAR LEFT TYRE RIM	\$	Sm	380.00	X
TOTAL			\$		2,940.20	

TOTAL PARTS	\$	20,790.01
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	7001
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

Trans-cab Auto Services Pte Ltd

AAD1909-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9990S

To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>601</i>
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>na</i> 380.00	<i>X</i>

TOTAL \$ 18,820.00

Over All Total \$ 39,610.01

(LUMP SUM) Repair Days

~~25 DAYS~~

3 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: