

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 12558

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1136/2019/NS
Date : 19-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm Neelofur Sarwar
Address : 27C Surin Avenue
Singapore 535607
Telephone : HP +65 92315572
Type of Claim : Own Damage Claims
Policy No. : 1900021956
Vehicle No : **SMJ 3249 Z**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Feb-19
Engine No : CHZ c26275
Chassis No : WAUZZZ8VXK1016783
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Sep-19
Place of Accident : Junction Of Serangoon Ave 5 And Hougang Ave 9

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 3249 Z

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 500 .	
3	To respray front bumper and bonnet.	\$ 2,000.00 1100	
4	To conduct diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>5,352.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3249 Z

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER <i>cracked</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PART <i>new</i>	\$ 170.00	+
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$ 70.00	+
4	FRONT BUMPER GRILLE - CENTRE <i>cracked</i>	\$ 146.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 488.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2 \$ 540.00	+
7	FRONT BUMPER COVER TRIM - LH / RH <i>new</i>	2 \$ 296.00	148 +
8	FRONT BUMPER WHEEL HOUSING LINER ADAPTER - LH / RH <i>new</i>	2 \$ 68.00	+
9	RADIATOR GRILLE <i>cracked</i>	\$ 1,301.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT ?	\$ 174.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>1st cracked</i>	2 \$ 342.00	171
12	FRONT BUMPER SIDE REINFORCEMENT ?	\$ 660.00	?
13	FRONT BUMPER FOAM FILLER PIECE ?	\$ 172.00	?
14	FRONT BUMPER FOAM FILLER PIECE COVER ?	\$ 111.00	?
15	AIRCON STICKER <i>3</i>	NEC \$ 7.00	✓
16	CAUTION SIGN <i>3</i>	NEC \$ 13.00	✓
17	SIGNAL HORN RETAINER - LH HIGH TONE <i>3</i>	\$ 182.00	+
18	SIGNAL HORN RETAINER - RH LOW TONE <i>3</i>	\$ 182.00	+
19	BONNET <i>Regis</i>	\$ 2,898.00	+
20	BONNET ATTACHMENT PARTS <i>new</i>	\$ 149.00	+
SUB TOTAL SPARE PARTS		: \$ 9,799.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3249 Z

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	BONNET EDGE PROTECTION <i>3 new</i>	\$ 25.00	+
22	BONNET STRIKER - LH / RH	2 \$ 200.00	+
23	BONNET CATCH HOOK	\$ 81.00	+
24	BONNET LID LOCK WITH MICROSWITCH <i>2 new</i>	2 \$ 367.00	+
25	BONNET BOWDEN CABLE - CENTRE	\$ 53.00	+
26	LED HEADLIGHT - LH / RH <i>Not new</i>	2 \$ 10,058.00	+
27	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH / RH <i>new</i>	2 \$ 256.00	+
28	WASH WATER RESERVOIR <i>new</i>	\$ 186.00	+
29	RADIATOR AIR GUIDE - LH / RH <i>new</i>	2 \$ 44.00	+
30	RADIATOR AIR GUIDE - UPPER CENTRE <i>Not new</i>	\$ 11.00	+
31	FRONT NO PLATE <i>Best -</i>	S/N \$ 40.00	✓
32	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		: \$ 21,520.00	
TOTAL LABOUR CHARGES		: \$ 5,352.00	
GRAND TOTAL		: \$ 26,872.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 25/09/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 24 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant