

ASS. REG. BY:

Adrian

REF:

AIG CC3/A1G 19016893/Avf3A2

ASSIGNMENT

Merimen

From:

Date:

25/09/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SMJ 3249Z

at Workshop m/s

Premium

of 55 ubi road 1

Insured:

Policy No.

19000 21956

Claims No.

Sum Insured:

Excess:

600

(Client's Record)

Make of Vehl:

10.00000000 Wany

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

100%

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum. Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMJ3249Z Yr Regn: 2019, Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 Sedan

C.C. 999.

Colour:

Blue.

A/C: Insured / Std / NI / NA

Sp. Reading:

11728.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU2228VXK1016783.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16.

R: 225/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

14/9/19

D.O.I.

25/09/19.

Survey held at

Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

00 AIG.

SMJ 3249Z - NA / MSG 19016236/24

h01 - 14/09/2019

25/9/19

Revert via merimen

26/9/19

Rec approved \$5660 from Victor via merimen

26/9/19

Informed Huzaini c/A ex \$600 by email

13/11/19

Final fig \$8004.08 (Real 18,928.92, 70% confirmed by email)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 23/12 - typist

Rep. Form:

Merimen

Estim. Sum / TP / EV

8004.08

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weel end (\$)

Survey Fee:

200

Transportation:

11

S + RS. \$

Photos:

Others:

TOTAL

211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 25 Sep 2019

Preliminary Advice

Vehicle No	: SMJ3249Z	Accident Date	: 14/09/2019
Make	: AUDI A3	Policy No.	: 1900021956
Assignment Date	: 25/09/2019	Excess	: S\$0.00
Date of Inspection	: 25/09/2019	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,872.00
Revised Amount	:S\$	5,660.00
Check Items (Estimated)	:S\$	1,517.00
Total	:S\$	7,177.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	41,989.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,011.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

View Received Message

This mail is associated with :

***SMJ3249Z (4929663050SG)**

OD

Sep 14 2019 3:00PM

[NEELOFUR SARWAR]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 13/11/2019 10:15 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8004.08) - SMJ3249Z - Claim Handler: Gan, Hunchung

Approved:8004.08:

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 September 2019 4:36 PM
To: claims@premiumauto.com.sg; SUR
Cc: (nora.khai@premiumauto.com.sg)
Subject: RE: OD CLAIM FOR SMJ 3249 Z ON 14/9/2019

Dear Ezuwan Huzaini,

As instructed by our client, please proceed to repair the **insured vehicle SMJ 3249Z (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 26 September 2019 3:01 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SMJ 3249 Z ON 14/9/2019

Hi Veron,

I have already sent to you yesterday. Please find attached

Thank you.

Best Regards,
Ezuwan Huzaini
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Sent: Thursday, 26 September 2019 2:11 PM

To: claims@premiumauto.com.sg; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>;

SUR <sur@lkkauto.com>

Subject: RE: OD CLAIM FOR SMJ 3249 Z ON 14/9/2019

Dear Ezuwan Huzaini,

Driving licensed ?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 25 September 2019 3:36 PM

To: claims@premiumauto.com.sg; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>;

SUR <sur@lkkauto.com>

Subject: RE: OD CLAIM FOR SMJ 3249 Z ON 14/9/2019

Dear Ezuwan Huzaini,

Driving licensed ?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Wednesday, 25 September 2019 12:17 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: claims@premiumauto.com.sg

Subject: RE: OD CLAIM FOR SMJ 3249 Z ON 14/9/2019

Dear All,

Vehicle already done survey. Please advise on the repair approval.

Thank you.

Best Regards,
Ezuwan Huzaini
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims <claims@premiumauto.com.sg>

Sent: Thursday, 19 September 2019 3:09 PM

To: 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: RE: OD CLAIM FOR SMJ 3249 Z ON 14/9/2019

Dear all,

Attached is the estimate for your kind reference.

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims <claims@premiumauto.com.sg>

Sent: Tuesday, 17 September 2019 9:54 AM

To: 'Admin-D (LKKAUTO)' <admin-d@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: OD CLAIM FOR SMJ 3249 Z ON 14/9/2019

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Please arrange survey on 24/9/19, 10am. Owner waiting.

Best Regards,

Syafiq

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SMJ3249Z (4929663050SG)**

OD

Sep 14 2019 3:00PM

[NEELOFUR SARWAR]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **26/09/2019 16:15 PM.**

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5660.00) - SMJ3249Z - Claim Handler: Gan, Hunchung

Approved:5660.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Shirley Hiew (LKK Auto)

From: jiayee.yap@premiumauto.com.sg
Sent: Tuesday, 29 October 2019 5:08 pm
To: Adrian Ling (LKKAuto); CS A Team; Admin A; SUR; Veron Chen (LKKAuto)
Cc: 'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'
Subject: FINAL REVISION - SMJ3249Z - OD AIG - SURVEYED 05 SEP 19
Attachments: PA11362019 - SMJ 3249 Z - AUDI A3 SEDAN 1.0 TFSI 8V - FRONT - OD (AIG).xls;
29102019164915-0001.pdf; WhatsApp Image 2019-10-25 at 3.51.01 PM (1).jpeg;
WhatsApp Image 2019-10-25 at 3.51.01 PM (2).jpeg; WhatsApp Image 2019-10-25 at
3.51.01 PM.jpeg; WhatsApp Image 2019-10-08 at 2.40.46 PM (1).jpeg; WhatsApp Image
2019-10-08 at 11.45.17 AM.jpeg; WhatsApp Image 2019-10-08 at 11.45.16 AM (1).jpeg;
WhatsApp Image 2019-10-08 at 11.45.16 AM.jpeg; WhatsApp Image 2019-10-08 at
11.45.11 AM.jpeg; WhatsApp Image 2019-10-08 at 11.45.12 AM.jpeg

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$8004.08 @ 5 days of repairs

Your early closure is well appreciated.

Thanks & Best Regard
JiaYee Yap
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. jiayee.yap@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 13 November 2019 12:46 PM
To: jiajee.yap@premiumauto.com.sg; CS A Team; Admin A; SUR
Cc: 'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SMJ3249Z - OD AIG - SURVEYED 05 SEP 19

Dear Jia Yee,

Confirm repair cost of \$8004.08 before excess \$600 and GST @ 5 days of repairs

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiajee.yap@premiumauto.com.sg <jiajee.yap@premiumauto.com.sg>
Sent: Tuesday, 29 October 2019 5:08 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SMJ3249Z - OD AIG - SURVEYED 05 SEP 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$8004.08 @ 5 days of repairs

Your early closure is well appreciated.

Thanks & Best Regard
JiaYee Yap
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. jiajee.yap@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	357G
Vehicle Details	
Vehicle No.:	SMJ3249Z
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	CHZC26275
Chassis No.:	WAUZZZ8VXK1016783
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$22,102.00
Original Registration Date:	28 Feb 2019
First Registration Date:	28 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$22,943.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2029
PARF Rebate Amount:	\$17,207.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,301.00
COE Rebate Amount:	\$24,782.00
Total Rebate Amount:	\$41,989.00

The information contained herein is correct as at 25 Sep 2019

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 12558

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1136/2019/NS
Date	:	19-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mdm Neelofur Sarwar
Address	:	27C Surin Avenue Singapore 535607
Telephone	:	HP +65 92315572
Type of Claim	:	Own Damage Claims
Policy No.	:	1900021956
Vehicle No	:	SMJ 3249 Z
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Feb-19
Engine No	:	CHZ c26275
Chassis No	:	WAUZZZ8VXK1016783
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	14-Sep-19
Place of Accident	:	Junction Of Serangoon Ave 5 And Hougang Ave 9

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 3249 Z

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 500.00	
3	To respray front bumper and bonnet.	\$ 2,000.00 1100 ✓	✓
4	To conduct diagnostic checks.	S/N \$ 192.00 ✓	✓
	TOTAL LABOUR CHARGES	: \$ 5,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3249 Z

S/N	Parts Description		Damage Parts & Prices		Remarks
			S/NETT		
1	FRONT BUMPER <i>Reh d</i>	\$	1,830.00	✓	1464
2	FRONT BUMPER FIXING PART <i>new</i>	\$	170.00	x	
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$	70.00	x	
4	FRONT BUMPER GRILLE - CENTRE <i>cracked</i>	\$	146.00	✓	116.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	488.00	x	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2 \$	540.00	+	
7	FRONT BUMPER COVER TRIM - LH / RH <i>new</i>	2 \$	296.00	148 x	
8	FRONT BUMPER WHEEL HOUSING LINER ADAPTER - LH / RH <i>new</i>	2 \$	68.00	x	
9	RADIATOR GRILLE <i>cracked</i>	\$	1,301.00	✓	1040.80
10	RADIATOR GRILLE CLOSING ELEMENT <i>cracked</i>	\$	174.00		138.80
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>1st cracked</i>	2 \$	342.00	171	136.40
12	FRONT BUMPER SIDE REINFORCEMENT <i>new</i>	\$	660.00	? x	
13	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$	172.00	? x	
14	FRONT BUMPER FOAM FILLER PIECE COVER <i>new</i>	\$	111.00	? x	
15	AIRCON STICKER <i>3 per</i>	NEC \$	7.00	✓	5.12
16	CAUTION SIGN	NEC \$	13.00	✓	9.76
17	SIGNAL HORN RETAINER - LH HIGH TONE <i>3 new</i>	\$	182.00	+	
18	SIGNAL HORN RETAINER - RH LOW TONE	\$	182.00	+	
19	BONNET <i>Rip Buckled</i>	\$	2,898.00		2318.40
20	BONNET ATTACHMENT PARTS <i>new</i>	\$	149.00	+	
SUB TOTAL SPARE PARTS			\$	9,799.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3249 Z

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	BONNET EDGE PROTECTION <i>3 new</i>	\$ 25.00	+
22	BONNET STRIKER - LH / RH	2 \$ 200.00	+
23	BONNET CATCH HOOK	\$ 81.00	+
24	BONNET LID LOCK WITH MICROSWITCH <i>3 new</i>	2 \$ 367.00	+
25	BONNET BOWDEN CABLE - CENTRE	\$ 53.00	+
26	LED HEADLIGHT - LH / RH <i>Not new</i>	2 \$ 10,058.00	+
27	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH / RH <i>new</i>	2 \$ 256.00	+
28	WASH WATER RESERVOIR <i>new</i>	\$ 186.00	+
29	RADIATOR AIR GUIDE - LH / RH <i>new</i>	2 \$ 44.00	+
30	RADIATOR AIR GUIDE - UPPER CENTRE <i>Not new</i>	\$ 11.00	+
31	FRONT NO PLATE <i>Best -</i>	S/N \$ 40.00	40
32	SUNDRIES <i>See.</i>	\$ 400.00	? <i>34.214</i>
TOTAL SPARE PARTS		: \$ 21,520.00	
TOTAL LABOUR CHARGES		: \$ 5,352.00	
GRAND TOTAL		: \$ 26,872.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

26933

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Ling*
Surveyed Date : *25/09/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 04 Days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3249 Z

OK
27/9

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
1	FRONT BUMPER <i>Rehd</i>	\$	1,830.00	✓
2	FRONT BUMPER FIXING PART <i>new</i>	\$	170.00	+
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$	70.00	+
4	FRONT BUMPER GRILLE - CENTRE <i>cracked</i>	\$	146.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	488.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2 \$	540.00	+
7	FRONT BUMPER COVER TRIM - LH / RH <i>new</i>	2 \$	296.00	148. x.
8	FRONT BUMPER WHEEL HOUSING LINER ADAPTER - LH / RH <i>new</i>	2 \$	68.00	+
9	RADIATOR GRILLE <i>cracked</i>	\$	1,301.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT <i>? new</i>	\$	174.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>1st cracked</i>	2 \$	342.00	171
12	FRONT BUMPER SIDE REINFORCEMENT <i>?</i>	\$	660.00	?
13	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	\$	172.00	?
14	FRONT BUMPER FOAM FILLER PIECE COVER <i>?</i>	\$	111.00	?
15	AIRCON STICKER <i>3 new</i>	NEC \$	7.00	✓
16	CAUTION SIGN <i>3 new</i>	NEC \$	13.00	✓
17	SIGNAL HORN RETAINER - LH HIGH TONE <i>3 new</i>	\$	182.00	+
18	SIGNAL HORN RETAINER - RH LOW TONE <i>3 new</i>	\$	182.00	+
19	BONNET <i>Regr</i>	\$	2,898.00	+
20	BONNET ATTACHMENT PARTS <i>new</i>	\$	149.00	+
SUB TOTAL SPARE PARTS		:	\$ 9,799.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3249 Z

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	BONNET EDGE PROTECTION	\$ 25.00	+
22	BONNET STRIKER - LH / RH	2 \$ 200.00	+
23	BONNET CATCH HOOK	\$ 81.00	+
24	BONNET LID LOCK WITH MICROSWITCH	2 \$ 367.00	+
25	BONNET BOWDEN CABLE - CENTRE	\$ 53.00	+
26	LED HEADLIGHT - LH / RH	2 \$ 10,058.00	+
27	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH / RH	2 \$ 256.00	+
28	WASH WATER RESERVOIR	\$ 186.00	+
29	RADIATOR AIR GUIDE - LH / RH	2 \$ 44.00	+
30	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 11.00	+
31	FRONT NO PLATE	S/N \$ 40.00	+
32	SUNDRIES	\$ 400.00	?
TOTAL SPARE PARTS		: \$ 21,520.00	
TOTAL LABOUR CHARGES		: \$ 5,352.00	
GRAND TOTAL		: \$ 26,872.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1136/2019/NS
Date 8-Oct-19
Service Advisor Glory Tan
Pages 1 of 1
Regn No SMJ 3249 Z
Model No Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description
----------	-------------

Unit Price	Amount
------------	--------

Parts

1	Headlight washer hose
---	-----------------------

\$ 61.00	48.16
----------	-------

TOTAL

\$ 61.00

For Premium Automobiles Pte Ltd

Authorised Signature

[Handwritten Signature]

9/10/19 @ 11.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 12558

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1136/2019/NS
Date : 19-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Adrian,
5 days - ok - Jy - 29 Oct 2019*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm Neelofur Sarwar
Address : 27C Surin Avenue
Singapore 535607
Telephone : HP +65 92315572
Type of Claim : Own Damage Claims
Policy No. : 1900021956
Vehicle No : **SMJ 3249 Z**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Feb-19
Engine No : CHZ c26275
Chassis No : WAUZZZ8VXK1016783
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Sep-19
Place of Accident : Junction Of Serangoon Ave 5 And Hougang Ave 9

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 3249 Z

S/N	Nature of Jobs		Estimated Charges		Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$	360.00
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organise crash management components. Reinstall all parts removed.		\$ 2,800.00	\$	1,000.00
3	To respray front bumper and bonnet.		\$ 2,000.00	\$	1,100.00
4	To conduct diagnostic checks.	S/N	\$ 192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 5,352.00	\$	2,652.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3249 Z

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	Remarks
1	FRONT BUMPER	\$ 1,830.00	\$ 1,464.00
2	FRONT BUMPER FIXING PART	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 70.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 146.00	\$ 116.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 488.00	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$ 540.00	
7	FRONT BUMPER COVER TRIM - LH / RH	2 \$ 296.00	
8	FRONT BUMPER WHEEL HOUSING LINER ADAPTER - LH / RH	2 \$ 68.00	
9	RADIATOR GRILLE	\$ 1,301.00	\$ 1,040.80
10	RADIATOR GRILLE CLOSING ELEMENT	\$ 174.00	\$ 138.80
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 342.00	\$ 136.40
12	FRONT BUMPER SIDE REINFORCEMENT	\$ 660.00	
13	FRONT BUMPER FOAM FILLER PIECE	\$ 172.00	
14	FRONT BUMPER FOAM FILLER PIECE COVER	\$ 111.00	
15	AIRCON STICKER	NEC \$ 7.00	\$ 5.12
16	CAUTION SIGN	NEC \$ 13.00	\$ 9.76
17	SIGNAL HORN RETAINER - LH HIGH TONE	\$ 182.00	
18	SIGNAL HORN RETAINER - RH LOW TONE	\$ 182.00	
19	BONNET	\$ 2,898.00	\$ 2,318.40
20	BONNET ATTACHMENT PARTS	\$ 149.00	
	SUB TOTAL SPARE PARTS	\$ 9,799.00	\$ 5,229.68

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3249 Z

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
			\$ 5,229.68
21	BONNET EDGE PROTECTION	\$ 25.00	
22	BONNET STRIKER - LH / RH	2 \$ 200.00	
23	BONNET CATCH HOOK	\$ 81.00	
24	BONNET LID LOCK WITH MICROSWITCH	2 \$ 367.00	
25	BONNET BOWDEN CABLE - CENTRE	\$ 53.00	
26	LED HEADLIGHT - LH / RH	2 \$ 10,058.00	
27	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH / RH	2 \$ 256.00	
28	WASH WATER RESERVOIR	\$ 186.00	
29	RADIATOR AIR GUIDE - LH / RH	2 \$ 44.00	
30	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 11.00	
31	FRONT NO PLATE	S/N \$ 40.00	\$ 40.00
	SUPPLEMENTARY		\$ 48.16
32	SUNDRIES	\$ 400.00	\$ 34.24
	TOTAL SPARE PARTS	\$ 21,520.00	\$ 5,352.08
	TOTAL LABOUR CHARGES	\$ 5,352.00	\$ 2,652.00
	GRAND TOTAL	\$ 26,872.00	\$ 8,004.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1136/2019/NS 8-Oct-19 Glory Tan 1 of 1 SMJ 3249 Z Audi A3 Sedan 1.0 TFSI 8V	
Quantity	Description	Unit Price	Amount	
<u>Parts</u> 1	Headlight washer hose	\$ 61.00	\$ 48.16	Torn
TOTAL		\$ 61.00	\$48.16	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMJ 3249 Z

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1136/2019/NH

18th Dec 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SMJ 3249 Z, Audi A3 SEDAN 1.0 TFSI.

With reference to the above-mentioned vehicle, no. **SMJ 3249 Z**, claimant, **Mdm. Neelofur Sarwar**, please find the related document per attached.

1. A copy of the Original invoice no. 85014617 – S\$ 7,922.37.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SMJ 3249 Z

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 1183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:23

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014617	Account: A0006 (T 0)
	Date : 17/12/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SMJ3249Z	
	Term : 30	

Regn No: SMJ3249Z (V 41012)	Regn Date: 28/02/2019	Mileage: 12324	WIP No.: 12558
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8VXK1016783	Engine: CHZ C26275	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND BONNET.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V5807065R GRU	COVER Less 020%	1.00	1830.00	1,464.00
X	A8V5807647B 9B9	GRILLE(LAST) Less 020%	1.00	145.50	116.40
X	A8V3853651AA3FZ	GRILLE Less 020%	1.00	1301.00	1,040.80
X	A8V3853949	PLATE(LAST) AP Less 020%	1.00	173.50	138.80
X	A8V5807681AA9B9	GRILL(LAST) Less 020%	1.00	170.50	136.40
X	A8V0010515A	STICKER Less 020%	1.00	6.40	5.12
X	A8K0010520C	STICKER Less 020%	1.00	12.20	9.76
X	A8V5823029A	HOOD(LAST) AP Less 020%	1.00	2898.00	2,318.40
X	A8V0121283K	(SK)AIR DUCT AP Less 020%	1.00	21.40	17.12
X	A8V0121284K	AIR DUCT AP Less 020%	1.00	21.40	17.12
X	A8V3955970P	HOSE AP Less 020%	1.00	60.20	48.16

Parts 5,312.08
Labour 0.00
Sublet 2,692.00
Menus 0.00
Lubricant 0.00

Sub-Total 7,404.08

7% GST 518.29

Grand Total 7,922.37



17/12

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMJ 3249 Z

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1136/2019/EH
12 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 Sedan 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8VXK1016783
Vehicle Regn No. : **SMJ 3249 Z**
Vehicle Mileage : 12324 KM
Vehicle Owner : Mdm Neelofur Sarwar
Certificate No : 1900021956
Own Damage Excess : S\$ 642.00 (Inclusive 7% GST)
Accident Date : 14 September 2019
Place : Junction of Serangoon Ave 5 and Hougang Ave 9
Repair Cost : \$ 7922.33
WIP No. : 12558
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


11.30 am
11/10/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Sep 2019		25 Sep 2019 14:36 Edit Adj Rpt	S\$8,004.08 Edit Estimates	S\$8,004.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: NEELOFUR SARWAR , ID: S2531357G, Tel: +6592315572	
Vehicle Reg. No.: SMJ3249Z	Date of Loss: 14/09/2019 15:00 - :59 [6 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 4929663050SG	Policy/Cover Note No.: 1900021956 (Comprehensive)
	Excess: S\$600.00
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911	
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/10/2019]	
Driver/Custodian: SHAFIA MEHBOOB HASSAN (24 / Female) , NRIC: S9511431H, Tel: +6592315572 Email: SHAFIAMH@GMAIL.COM	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (13/11/2019): Alert - Adj Mandate Approved (S\$8004.08) - SMJ3249Z - Claim Handler: Gan, Hunchu...
- AIG_SG (26/09/2019): Alert - Adj Mandate Approved (S\$5660.00) - SMJ3249Z - Claim Handler: Gan, Hunchu...
- AIG_SG (26/09/2019): SMJ3249Z / OD / 14/09/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMJ3249Z (4929663050SG)

OD

Sep 14 2019 3:00PM

[NEELOFUR SARWAR]

Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/19 16:44	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/19 15:31	General View	 Load JPG	☒
2	25/09/19 15:31	General View	 Load JPG	☒
3	25/09/19 15:31	General View	 Load JPG	☒
4	25/09/19 15:31	General View	 Load JPG	☒
5	25/09/19 15:31	General View	 Load JPG	☒
6	25/09/19 15:31	General View	 Load JPG	☒
7	25/09/19 15:31	General View	 Load JPG	☒
8	25/09/19 15:31	General View	 Load JPG	☒
9	25/09/19 15:31	General View	 Load JPG	☒
10	25/09/19 15:31	General View	 Load JPG	☒
11	25/09/19 15:31	General View	 Load JPG	☒
12	25/09/19 15:31	General View	 Load JPG	☒
13	25/09/19 15:31	General View	 Load JPG	☒
14	25/09/19 15:31	General View	 Load JPG	☒
15	25/09/19 15:31	General View	 Load JPG	☒
16	25/09/19 15:31	General View	 Load JPG	☒
17	25/09/19 15:31	General View	 Load JPG	☒
18	25/09/19 15:31	General View	 Load JPG	☒
19	25/09/19 15:31	General View	 Load JPG	☒
20	25/09/19 15:31	General View	 Load JPG	☒
21	25/09/19 15:31	General View	 Load JPG	☒
22	25/09/19 15:31	General View	 Load JPG	☒
23	25/09/19 15:31	General View	 Load JPG	☒
24	25/09/19 15:31	General View	 Load JPG	☒
25	25/09/19 15:31	General View	 Load JPG	☒
26	25/09/19 15:31	General View	 Load JPG	☒
27	25/09/19 15:31	General View	 Load JPG	☒
28	25/09/19 15:31	General View	 Load JPG	☒
29	25/09/19 15:31	General View	 Load JPG	☒
30	25/09/19 15:31	General View	 Load JPG	☒
31	25/09/19 15:31	General View	 Load JPG	☒
32	25/09/19 15:31	General View	 Load JPG	☒
33	25/09/19 15:31	General View	 Load JPG	☒
34	25/09/19 15:31	General View	 Load JPG	☒
35	25/09/19 15:31	General View	 Load JPG	☒
36	25/09/19 15:31	General View	 Load JPG	☒
37	25/09/19 15:31	General View	 Load JPG	☒
38	31/10/19 18:17	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
39	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
40	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
41	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
42	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
43	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
44	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
45	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
46	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
47	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
48	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
49	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
50	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
51	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
52	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
53	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
54	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
55	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
56	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
57	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
58	31/10/19 18:17	Reinspection Photo	 Load JPG	☒
59	31/10/19 18:18	Reinspection Photo	 Load JPG	☒
60	31/10/19 18:18	Reinspection Photo	 Load JPG	☒
61	31/10/19 18:18	Reinspection Photo	 Load JPG	☒
62	31/10/19 18:18	Reinspection Photo	 Load JPG	☒
63	31/10/19 18:18	Reinspection Photo	 Load JPG	☒
64	31/10/19 18:18	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/19 15:50	Singapore Accident Statement	 Load PDF	
2	25/09/19 15:50	Certificate of Insurance	 Load PDF	
3	25/09/19 15:51	MARK ESTIMATE	 Load PDF	
4	26/09/19 15:14	Driver's Driving License	 Load PDF	
5	01/11/19 09:50	FINAL MARKING	 Load PDF	
6	01/11/19 09:50	SUPPLEMENTARY	 Load PDF	
7	27/12/19 08:28	WORKSHOP INVOICE	 Load PDF	
8	27/12/19 08:28	DISCHARGE VOUCHER	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1 per page	☒
1	06/12/19 18:40	Accident Statement	 Load HTM	
2	06/12/19 18:40	Accident Statement	 Load HTM	
3	06/12/19 18:40	Accident Statement	 Load HTM	
4	06/12/19 18:42	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	17/09/19 09:48	Accident Photo	 Load JPG	☒
2	17/09/19 09:48	Accident Photo	 Load JPG	☒
3	17/09/19 09:48	Accident Photo	 Load JPG	☒
4	17/09/19 09:48	Accident Photo	 Load JPG	☒
5	17/09/19 09:48	Accident Photo	 Load JPG	☒
6	17/09/19 09:48	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
7	17/09/19 09:48	Accident Photo	 Load JPG	✓
8	17/09/19 09:48	Accident Photo	 Load JPG	✓
9	17/09/19 09:48	Accident Photo	 Load JPG	✓
10	17/09/19 09:48	Accident Photo	 Load JPG	✓
11	17/09/19 09:48	Accident Photo	 Load JPG	✓
12	17/09/19 09:48	Accident Photo	 Load JPG	✓
13	17/09/19 09:48	Accident Photo	 Load JPG	✓
14	17/09/19 09:48	Accident Photo	 Load JPG	✓
15	17/09/19 09:48	Accident Photo	 Load JPG	✓
16	17/09/19 09:48	Accident Photo	 Load JPG	✓
17	17/09/19 09:48	Accident Photo	 Load JPG	✓
18	17/09/19 09:48	Accident Photo	 Load JPG	✓
19	17/09/19 09:48	Accident Photo	 Load JPG	✓
20	17/09/19 09:48	Accident Photo	 Load JPG	✓
21	17/09/19 09:48	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	17/09/19 09:16	Sketch Plan	 Load JPG	✓
2	17/09/19 09:16	Sketch Plan #2	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19016893/AVF3N2
Date: 27/12/2019

REFERENCE

Insured/Claimant: NEELOFUR SARWAR Policy No: 1900021956
Date of Loss: 14/09/2019 Nature of Claim: OD Claim No: 4929663050SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ3249Z Engine No: CHZC26275
Make & Model: AUDI A3, 999cc TFSI (A) Chassis No: WAUZZZ8VXK1016783
Reg. Date: 28/02/2019 (Man. Year: 2018) Odometer: 11728 km
Colour: Blue
Engine Capacity: 999 cc
Market Value/New Car Price: S\$100,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,568.16	5,352.08	16,216.08	75.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,352.00	2,652.00	2,700.00	50.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,920.16	8,004.08	18,916.08	70.27
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	26,320.16	7,404.08	18,916.08	71.87
+ GST 7.00/7.00% (S\$)	1,842.41	518.29	1,324.12	71.87
Nett Amount (S\$)	28,162.57	7,922.37	20,240.20	71.87

INSPECTION

Date of Assignment: 25/09/2019
Date Inspected: 25/09/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PART	Not Necessary	170.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTRE	Cracked	146.00 FS	*116.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	488.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT-LH/RH	Not Necessary	540.00 FS	*- FS
7	2		*FRONT BUMPER COVER TRIM-LH/RH	Not Necessary	296.00 FS	*- FS
8	2		*FRONT BUMPER WHEEL HOUSING LINER ADAPTER-LH/RH	Not Necessary	68.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	174.00 FS	*138.80 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	N/s Cracked	342.00 FS	*136.40 FS
12	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	660.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
14	1		*FRONT BUMPER FOAM FILLER PIECE COVER	Not Necessary	111.00 FS	*- FS
15	1		*AIRCON STICKER	Necessary	7.00 FS	*5.12 FS
16	1		*CAUTION SIGN	Necessary	13.00 FS	*9.76 FS
17	1		*SIGNAL HORN RETAINER-LH HIGH TONE	Not Necessary	182.00 FS	*- FS
18	1		*SIGNAL HORN RETAINER-RH LOW TONE	Not Necessary	182.00 FS	*- FS
19	1		*BONNET	Buckled	2,898.00 FS	*2,318.40 FS
20	1		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
21	1		*BONNET EDGE PROTECTION	Not Necessary	25.00 FS	*- FS
22	2		*BONNET STRIKER-LH/RH	Not Necessary	200.00 FS	*- FS
23	1		*BONNET CATCH HOOK	Not Necessary	81.00 FS	*- FS
24	2		*BONNET LID LOCK WITH MICROSWITCH	Not Necessary	367.00 FS	*- FS
25	1		*BONNET BOWDEN CABLE-CENTRE	Not Necessary	53.00 FS	*- FS
26	2		*LED HEADLIGHT-LH/RH	Not Necessary	10,058.00 FS	*- FS
27	2		*HEADLIGHT WASHER SYSTEM LIFT CYLINDER-LH/RH	Not Necessary	256.00 FS	*- FS
28	1		*WASH WATER RESERVOIR	Not Necessary	186.00 FS	*- FS
29	2		*RADIATOR AIR GUIDE-LH/RH	Not Necessary	44.00 FS	*- FS
30	1		*RADIATOR AIR GUIDE-UPPER CENTRE	Not Necessary	11.00 FS	*- FS
31	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
32	1		*SUNDRIES	Necessary	400.00 FS	*34.24 FS
33	1		*HEADLIGHT WASHER HOSE	Torn	48.16 FS	*48.16 FS
Total Parts (\$\$)					21,568.16	5,352.08

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND BOTH HEADLIGHTS.RE-ORGANISE CRASH MANAGEMENT VOMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
4	TO CONDUCT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			5,352.00	2,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >