

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900315
Date: 25 Sep 2019
Veh Reg No: SGB3644D
Make/Model: TOYOTA VIOS 1.5E A
Chasis No: MR053HY4204158826
Reg. Date: 16/12/2005
Your Ref No: SLQ997S

Claim Type: Third Party
Accident Date: 23/09/2019
TP Veh Reg No: SLQ997S

Asher

Estimate Repair Cost to Vehicle No :SGB3644D

Quantity	Description	List Price SS	Amount SS
List Price			
1	1 PC FRT FENDER RH <i>Distorted</i>	530.10	✓
2	1 PC FRT FENDER COWLING RH <i>Deformed</i>	151.90	✓
3	1 PC FRT DOOR RH <i>Distorted</i>	819.20	✓
4	2 PCS FRT DOOR HINGE RH <i>Bent</i>	171.60	✓
5	1 PC FRT DOOR CHECK RH	152.10	✓
6	1 PC FRT DOOR PROTECTOR RH <i>Distorted</i>	160.70	✓
7	1 PC FRT DOOR OUTER HANDLE RH <i>Riv</i>	88.40	+
8	1 PC FRT DOOR KEY LOCK RH <i>Ign</i>	166.70	+
9	1 PC FRT DOOR KEY COVER RH	38.50	+
10	1 PC FRT RH DOOR INNER LOCK <i>Dmgd</i>	424.80	✓
11	1 PC FRT RH DOOR INNER LOCK CHECKER <i>new</i>	24.50	+
12	1 PC FRT RH DOOR OUTER MOULDING <i>new</i>	83.20	+
13	1 PC FRT DOOR GLASS CHANNEL RH <i>new</i>	150.70	+
14	1 PC FRT DOOR REGULATOR ASSEMBLY RH <i>new</i>	738.30	+
15	1 PC FRT DOOR RUBBER RH <i>new</i>	186.90	✓
16	1 PC FRT RH DOOR TRIM <i>new</i>	749.30	+
17	1 PC REAR DOOR RH <i>Distorted</i>	703.60	✓
18	2 PCS REAR DOOR HINGE RH <i>Bent</i>	157.60	✓
19	1 PC REAR DOOR RH CHECK <i>Bent</i>	152.10	✓
20	1 PC REAR DOOR PROTECTOR RH <i>Distorted</i>	78.80	✓
21	1 PC REAR DOOR OUTER HANDLE RH <i>new</i>	65.90	+
22	1 PC REAR DOOR INNER LOCK RH <i>Dmgd</i>	437.30	✓
23	1 PC REAR DOOR RUBBER RH <i>new</i>	158.90	✓
24	1 PC REAR DOOR GLASS CHANNEL RH	150.70	+
25	1 PC REAR DOOR GLASS CHANNEL PILLAR RH	165.50	+
26	1 PC REAR DOOR GLASS REGULATOR ASSY RH <i>new</i>	695.20	+
27	1 PC REAR DOOR TRIM RH	689.50	+
28	1 PC REAR DOOR OUTER MOULDING RH	83.20	+
29	1 PC REAR FENDER RH <i>Distorted</i>	804.80	✓
30	1 PC REAR WINDSCREEN MOULDING <i>new</i>	89.30	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST1900315
Date: 25 Sep 2019
Veh Reg No: SGB3644D
Make/Model: TOYOTA VIOS 1.5E A
Chasis No: MR053HY4204158826
Reg. Date: 16/12/2005
Your Ref No: SLQ997S

Claim Type: Third Party
Accident Date: 23/09/2019
TP Veh Reg No: SLQ997S

Estimate Repair Cost to Vehicle No :SGB3644D

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
31	1 PC TAIL LAMP - RH <i>new</i>	352.70 <i>x</i>	
32	1 PC REAR BUMPER <i>Rw</i>	427.90 <i>+</i>	
33	1 PC REAR BUMPER RETAINER RH <i>2</i>	113.80 <i>x</i>	
34	1 PC FRT SHOCK ABSORBER RH	325.50 <i>x</i>	
35	1 PC FRT LOWER ARM RH	792.30 <i>x</i>	
36	1 PC FRT KNUCKLE ARM RH	542.60 <i>x</i>	
37	1 PC FRT WHEEL HUB RH	190.70 <i>x</i>	
38	1 PC FRT DRIVE SHAFT RH	1,253.80 <i>x</i>	
		13,068.60	
	Less 25%	3,267.15	9,801.57
	Special Net		
39	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	40.00 30	
40	1 PC REAR WINDSCREEN SEAL <i>3 new</i>	60.00 40	
41	1 PC REAR WINDSCREEN SEALANT	60.00 40	
42	1 SET REAR BUMPER CLIPS <i>new</i>	40.00 <i>x</i>	
		200.00	200.00
	Labour		
43	1 TOWING	50.00 <i>✓</i>	
44	1 TO CHECK WIRING	50.00 30	
45	1 TO REMOVE AND REFIX REAR DOOR GLASS <i>fittings</i>	100.00 80	
46	1 TO REMOVE AND REFIX FRT DOOR GLASS <i>fittings</i>	100.00 80	
47	1 TO REMOVE AND REFIT SEAT CUSHION	150.00 <i>x</i>	
48	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 <i>✓</i>	
49	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 50	
50	1 TO REMOVE AND REFIT UNDERCARRIAGE	300.00 <i>x</i>	
51	1 TO CHECK WHEEL ALIGNMENT	120.00 <i>x</i>	
52	1 TO SPRAY UNDERSEAL	150.00 80	
53	1 TO SPRAY PAINTING	1,500.00 1000	
54	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00 1000	

2490

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/09/2019
TP Veh Reg No: SLQ997S

Estimate No: EST1900315
Date: 25 Sep 2019
Veh Reg No: SGB3644D
Make/Model: TOYOTA VIOS 1.5E A
Chasis No: MR053HY4204158826
Reg. Date: 16/12/2005
Your Ref No: SLQ997S

Estimate Repair Cost to Vehicle No :SGB3644D

Quantity	Description	List Price S\$	Amount S\$
		4,220.00	4,220.00
	Total		S\$ 14,221.57
	Add GST @ 7%		995.51
	Total Amount Payable		S\$ 15,217.08

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND TWO HUNDRED SEVENTEEN AND CENTS EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

total: 6484.77

W/S : 3.5K (Net Value)

1 1/2 Days

3.5K

11 days