

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/09/2019
TP Veh Reg No: SLQ997S

Estimate No: EST1900315
Date: 25 Sep 2019
Veh Reg No: SGB3644D
Make/Model: TOYOTA VIOS 1.5E A
Chasis No: MR053HY4204158826
Reg. Date: 16/12/2005
Your Ref No: SLQ997S

Estimate Repair Cost to Vehicle No :SGB3644D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC FRT FENDER RH	530.10	
2	1 PC FRT FENDER COWLING RH	151.90	
3	1 PC FRT DOOR RH	819.20	
4	2 PCS FRT DOOR HINGE RH	171.60	
5	1 PC FRT DOOR CHECK RH	152.10	
6	1 PC FRT DOOR PROTECTOR RH	160.70	
7	1 PC FRT DOOR OUTER HANDLE RH	88.40	
8	1 PC FRT DOOR KEY LOCK RH	166.70	
9	1 PC FRT DOOR KEY COVER RH	38.50	
10	1 PC FRT RH DOOR INNER LOCK	424.80	
11	1 PC FRT RH DOOR INNER LOCK CHECKER	24.50	
12	1 PC FRT RH DOOR OUTER MOULDING	83.20	
13	1 PC FRT DOOR GLASS CHANNEL RH	150.70	
14	1 PC FRT DOOR REGULATOR ASSEMBLY RH	738.30	
15	1 PC FRT DOOR RUBBER RH	186.90	
16	1 PC FRT RH DOOR TRIM	749.30	
17	1 PC REAR DOOR RH	703.60	
18	2 PCS REAR DOOR HINGE RH	157.60	
19	1 PC REAR DOOR RH CHECK	152.10	
20	1 PC REAR DOOR PROTECTOR RH	78.80	
21	1 PC REAR DOOR OUTER HANDLE RH	65.90	
22	1 PC REAR DOOR INNER LOCK RH	437.30	
23	1 PC REAR DOOR RUBBER RH	158.90	
24	1 PC REAR DOOR GLASS CHANNEL RH	150.70	
25	1 PC REAR DOOR GLASS CHANNEL PILLAR RH	165.50	
26	1 PC REAR DOOR GLASS REGULATOR ASSY RH	695.20	
27	1 PC REAR DOOR TRIM RH	689.50	
28	1 PC REAR DOOR OUTER MOULDING RH	83.20	
29	1 PC REAR FENDER RH	804.80	
30	1 PC REAR WINDSCREEN MOULDING	89.30	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/09/2019
TP Veh Reg No: SLQ997S

Estimate No: EST1900315
Date: 25 Sep 2019
Veh Reg No: SGB3644D
Make/Model: TOYOTA VIOS 1.5E A
Chasis No: MR053HY4204158826
Reg. Date: 16/12/2005
Your Ref No: SLQ997S

Estimate Repair Cost to Vehicle No :SGB3644D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
31	1 PC TAIL LAMP - RH	352.70	
32	1 PC REAR BUMPER	427.90	
33	1 PC REAR BUMPER RETAINER RH	113.80	
34	1 PC FRT SHOCK ABSORBER RH	325.50	
35	1 PC FRT LOWER ARM RH	792.30	
36	1 PC FRT KNUCKLE ARM RH	542.60	
37	1 PC FRT WHEEL HUB RH	190.70	
38	1 PC FRT DRIVE SHAFT RH	1,253.80	
		13,068.60	
	Less 25%	3,267.15	9,801.57
	Special Net		
39	1 SET FRT FENDER COWLING CLIPS RH	40.00	
40	1 PC REAR WINDSCREEN SEAL	60.00	
41	1 PC REAR WINDSCREEN SEALANT	60.00	
42	1 SET REAR BUMPER CLIPS	40.00	
		200.00	200.00
	Labour		
43	1 TOWING	50.00	
44	1 TO CHECK WIRING	50.00	
45	1 TO REMOVE AND REFIX REAR DOOR GLASS	100.00	
46	1 TO REMOVE AND REFIX FRT DOOR GLASS	100.00	
47	1 TO REMOVE AND REFIT SEAT CUSHION	150.00	
48	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
49	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
50	1 TO REMOVE AND REFIT UNDERCARRIAGE	300.00	
51	1 TO CHECK WHEEL ALIGNMENT	120.00	
52	1 TO SPRAY UNDERSEAL	150.00	
53	1 TO SPRAY PAINTING	1,500.00	
54	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00	

Kang Car Repairers Pte Ltd

I Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/09/2019
TP Veh Reg No: SLQ997S

Estimate No: EST1900315
Date: 25 Sep 2019
Veh Reg No: SGB3644D
Make/Model: TOYOTA VIOS 1.5E A
Chasis No: MR053HY4204158826
Reg. Date: 16/12/2005
Your Ref No: SLQ997S

Estimate Repair Cost to Vehicle No :SGB3644D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		4,220.00	4,220.00
		Total	S\$ 14,221.57
		Add GST @ 7%	995.51
		Total Amount Payable	<u>S\$ 15,217.08</u>

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND TWO HUNDRED SEVENTEEN AND CENTS EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE