



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

14/12/19

Not Authorized

Repair Estimates

SMC 916 M

Parts	(a) Cost / List Price Items	\$	3,219.30
	Plus/Less 20%	\$	643.86
	Total of Cost / List	\$	2,575.44
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
		\$	4500
	Total Parts Cost	\$	2,620.44
	Labour	\$	1,800.00
	Total	\$	4,420.44

SPECIAL NETT: \$45
LABOUR: \$350

TOTAL: \$395 (P/P) , 2 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 25/11/19 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.
- (b) Recommended Days of Repair : 02 day(s)
- (c) Resurvey : Required / ~~Not Required~~
- (d) Excess : \$ _____
- (e) Signature of surveyor : _____ Date: 25/11/19



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259. 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SMC 916 M
 Make & Model : HONDA SHUTTLE
 Chassis No : GP71211706

Submit By : JENNY
 Year Manufactur : 2018
 Engine No. : _____
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>Pl</i>	1	\$45.00	S.N	<input checked="" type="checkbox"/>
2	Front bumper <i>NN</i>	1	\$1,100.00		<input type="checkbox"/> <input checked="" type="checkbox"/>
3	Front bumper clip <i>NN</i>	10	\$40.00		<input type="checkbox"/> <input checked="" type="checkbox"/>
4	Front bumper reinforcement <i>NN</i>	1	\$470.90		<input type="checkbox"/> <input checked="" type="checkbox"/>
5	Front bumper side retainer LH <i>Pl</i>	1	\$25.40		<input checked="" type="checkbox"/>
6	Front bumper side retainer RH <i>Pl</i>	1	\$25.40		<input checked="" type="checkbox"/>
7	Front bumper bracket LH <i>R</i>	1	\$58.00		<input checked="" type="checkbox"/>
8	Front bumper bracket RH <i>R</i>	1	\$58.00		<input checked="" type="checkbox"/>
9	Front emblem <i>NN</i>	1	\$33.40		<input type="checkbox"/> <input checked="" type="checkbox"/>
10	Front grille <i>NN</i>	1	\$445.00		<input type="checkbox"/> <input checked="" type="checkbox"/>
11	Front grille upper chrome <i>NN</i>	1	\$412.50		<input type="checkbox"/> <input checked="" type="checkbox"/>
12	Front grille lower chrome <i>NN</i>	1	\$270.70		<input type="checkbox"/> <input checked="" type="checkbox"/>
13	Front bumper lower grille <i>Pl</i>	1	\$190.00		<input checked="" type="checkbox"/>
14	Front bumper lower grille LH <i>Pl</i>	1	\$45.00		<input checked="" type="checkbox"/>
15	Front bumper lower grille RH <i>Pl</i>	1	\$45.00		<input checked="" type="checkbox"/>
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

45

