

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Accident Date : 23.09.2019

Not Authorised
11pm @ 4200h
Permy After Paint
5day

Policy No: _____ Third Party

Date: 24.09.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mazda 3" Reg. No. SKR5197H Claiming Against Your Insured Reg. No. SJU7117Y			
1pc	Front Fender RH	5.00	<i>R</i> 439.00 ✓
1pc	Front Fender Shield		<i>D11</i> 135.00 ✓
10pcs	Front Fender Shield Clips		<i>M</i> 50.00 ✓
1pc	Front Door RH		<i>R</i> 1,061.50 ✓
1pc	Front Door Sticker		<i>M</i> 175.00 ✓
1pc	Front Door Top Hinge		<i>R</i> 150.00 X
1pc	Front Door Lower Hinge		<i>D11</i> 145.00 ✓
1pc	Front Wheel Rim		<i>M</i> 1,101.70 ✓
1pc	Front Shock Absorber		<i>R</i> 360.00 ✓
1pc	Front Knuckle Arm		<i>R</i> 402.00 ✓
1pc	Front Knuckle Arm Bearing		<i>M</i> 368.00 ✓
1pc	Front Knuckle Arm Bearing Hub		<i>R</i> 125.00 ✓
1pc	Front Lower Arm		<i>D11</i> 508.00 ✓
	Less 20%		5,020.20 1,004.04 4,016.16
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		150.00 <i>601</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 <i>601</i>
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		200.00 <i>1601</i>
	To Conduct Computerize Wheel Alignment Test		80.00 <i>601</i>
	Labour Charge - Panel Beating, Repairing Of Front Fender Inner Panel, Wheel Housing, Front Door Pillar, Rocker Panel and Parts Replacement		600.00 <i>501</i>
	To Respray Affected Areas		750.00 <i>5501</i>
	Total :		<u>5,896.16</u>

Wheel Alignment