

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not Notch in
Penny Bleeping
3 days*

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 02.07.2018

Accident Date : 21.06.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mazda 3" Reg. No. SKR5197H Claiming Against Your Insured Reg. No. GBD6868D			
1pc	Front Bumper		<i>Bz</i> 997.00 <i>—</i>
12pcs	Front Bumper Clips	3.50	<i>na</i> 42.00 <i>—</i>
1pc	Front Bumper Top Beam		<i>Pr</i> 620.00 <i>2</i>
1pc	Front Bumper Reinforcement		<i>R</i> 485.00 <i>X</i>
1pc	Front Bumper Inner Core (Top)		<i>cm</i> 155.00 <i>2</i>
1pc	Front Bumper Center Core		<i>fu</i> 172.00 <i>X</i>
1pc	Front Bumper Top Cover		<i>Bz</i> <i>fu</i> 112.00 <i>2</i>
2pcs	Front Bumper Top Plastic Holders	45.00	<i>cm</i> 90.00 <i>2</i>
2pcs	Front Bumper Top Plastic Holder Lock Clips (Big)	2.70	<i>na</i> 5.40 <i>2</i>
1pc	Brace Panel		<i>Pr</i> 255.00 <i>2</i>
1pc	Support Panel		<i>R</i> 499.00 <i>X</i>
1pc	Air Con Condenser		<i>fu</i> 1,155.00 <i>X</i>
1pc	Grille		<i>cm</i> 110.60 <i>—</i>
1pc	Grille Emblem		<i>na</i> 46.00 <i>—</i>
2pcs	Grille Chrome Mouldings	192.00	<i>CRASH</i> 384.00 <i>—</i>
2pcs	Headlamp Assy RH	850.00	1,700.00 <i>4</i>
			6,828.00
			1,365.60
	Less 20%		5,462.40
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		30.00 <i>20</i>
	To Remove / Refit Air Con Condenser & Refill Gas		<i>na</i> 120.00 <i>X</i>
	To Remove / Refit, Radiator System, Bleed, Refill Coolant.		<i>na</i> 60.00 <i>X</i>
	Labour Charge - Panel Beating, Repairing Of Headlamp Panel, Support Panel and Parts Replacement.		950.00 <i>400</i>
	To Respray Affected Areas		400.00 <i>22</i>
	Total :		<u>7,022.40</u>

0.15 73cm 215cm X