

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Accident Date : 23.09.2019

*Not Authorized
11 Pm @
Running After Paint
5day*

Policy No: _____

Date: _____

Third Party

24.09.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mazda 3" Reg. No. SKR5197H Claiming Against Your Insured Reg. No. SJU7117Y			
1pc	Front Fender RH	5.00	<i>B1</i> 439.00 ✓
1pc	Front Fender Shield		<i>D11</i> 135.00 ✓
10pcs	Front Fender Shield Clips		<i>m</i> 50.00 ✓
1pc	Front Door RH		<i>B1</i> 1,061.50 ✓
1pc	Front Door Sticker		<i>m</i> 175.00 ✓
1pc	Front Door Top Hinge		<i>R</i> 150.00 x
1pc	Front Door Lower Hinge		145.00 ?
1pc	Front Wheel Rim		<i>Ref</i> 1,101.70 ✓
1pc	Front Shock Absorber		360.00 ?
1pc	Front Knuckle Arm		402.00 ?
1pc	Front Knuckle Arm Bearing		368.00 ?
1pc	Front Knuckle Arm Bearing Hub		125.00 ?
1pc	Front Lower Arm		508.00 ?
			5,020.20
	Less 20%		1,004.04
			4,016.16
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		150.00 <i>60d</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 <i>60d</i>
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		200.00 ?
	To Conduct Computerize Wheel Alignment Test		80.00 <i>60d</i>
	Labour Charge - Panel Beating, Repairing Of Front Fender Inner Panel, Wheel Housing, Front Door Pillar, Rocker Panel and Parts Replacement		600.00 <i>50d</i>
	To Respray Affected Areas		750.00 <i>55d</i>
			5,896.16
Total :			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: