

ASS. REC. BY:

REF: CS/FCI 19016102/AT d3

12
Special Instruction:

Surveyor: Adran

ASSIGNMENT (Office)

CWS

From (Person): Moira Chica

of FCI

Date/Time: 9:34am @ 25/1/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJC 9811H

Insured:

SHB 2097C

at Workshop m/s

Premium

Tel:

69689911

of

55 ubi Rund 1

Policy No:

Claim No:

D19005875MFST

Sum Insured:

Excess:

Make of Veh:

D.O.A. 08/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:33am @ 25/1/17

Person Contacted:

Gzuwan

Vehicle IN / OUT

Date/Time

Action/Instruction

To/From/✓

SJC 9811H - X

SHB 2097C - X83 / FCI 17006356 / R/b52

Date: 23/3/17

27/1/17 @ 2:45pm - Revised via email preli advise

REF: FCI

SS: REC. BY:

ASSIGNMENT

From: _____ Date: 26/09/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJC 9811H

at Workshop m/o: premium
of 55 ubi Road 1

Insured:

Policy No:

Claims No:

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 10 am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJC9811H. Yr Regn: 2016 / Sept

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 Sedan c.c. 1395

Colour: Red. A/C: Insured / Std / NI / NA

Sp. Reading: 49434. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAU22ZF49GA111725

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/35R19.

R: 245/35R19.

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 26/09/19.

Survey held at Premium.

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP / 1st Cap.

RECEIVED 26 MAR 2020

Part by Part \$2,402. 3 days.
(Red: 13095: 85%)

Date/Time, File Pass to?

☐

Preli. Report

1) 26/3 Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week end (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

5x15: 75

170+ 75

50

15

310

Rep. Form:

Enq. Serv. / 2402

TP
2402



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005875MFSH

Date: 27/09/2019

Our Ref: CS/FCI19016902/Atd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJC 9811H

Please be informed that we had conducted the inspection of the abovementioned vehicle
27/09/2019 at the premises of M/s Premium have the following to report: -

Workshop Estimate Amount	: S\$ <u>14,267.00</u>
Revised Estimate Amount	: S\$ <u>1,172.00</u>
"Check" Items Amount	: S\$ <u>300.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
o/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Adrian

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	11-09-2019	Our Ref No. D19005875MFSH
Accident Date	08-09-2019	Claim Type. Third Party
Insured Vehicle	SHB2097C	Third Party Vehicle. SJC9811H
Survey Location	55 UBI ROAD 1	
Contact Person.	SYAFIQ	
Contact No.	63882323/ 0	Fax No. 68411183
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIUM AUTOMOBILES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 26 March 2020 11:37 AM
To: Carrine Leong
Subject: RE: FINAL REVISION - SJC9811H - TP FIRSTCAP - SURVEYED 26 SEP 19

Dear Carrine,

Confirm final figure \$2402.00 @ 3 days.

Please submit all relevant documents to First Capital.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Friday, 6 March 2020 5:32 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: FW: FINAL REVISION - SJC9811H - TP FIRSTCAP - SURVEYED 26 SEP 19

Hi Adrian and all,

Revised estimate and owner's invoice is attached.

Please confirm repair cost of \$2402.00 @ 3 days.

Your early closure is much appreciated.

Thanks & Best Regard

Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 27 September 2019 2:45 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Merina Chia'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005875MFSH/1
Attachments: PRELI ADVISED OF SJC 9811H.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJC 9811H**
Number of days (estimated) : 3 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 25 September 2019 11:37 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005875MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer arrange on 26/09/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 25 September 2019 9:34 AM
To: ASSIGNMENTS@LKKAUTO.COM



東南膠輪公司
South East Tyre Co.

Sales Quotation

Date: 22th Jan 2020

Messrs: AUDI A4 SJC9811H

Invoice No: 81147

<u>Services</u>	<u>Quantity</u>	<u>Price</u>
ATS Racelight Racing Royal Silver 8.5x19 ET38	1	\$850
Paint work to Racing Grey	1	\$100
Air-Freight		\$280
	Total (Including GST)	\$1230

William Tan
South East Tyre Co

No 10 Kaki Bukit Road 1
KB Industrial Building
#01-20
Singapore 416175

Tel: 68442288



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13409

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1152/2019/NS
Date : 24-Sep-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : SHB 2097 C

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Ms Ng Chin Chin
Address : Blk 543 Jurong West St 42
#07-59
Singapore 640543
Telephone : (HP) +65 85227091
Type of Claim : Third party Claims
Policy No. : 10781841
Vehicle No : **SJC 9811 H**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Sep-16
Engine No : CVN 014459
Chassis No : WAUZZZF49GA111725
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Sep-19
Place of Accident : Along Fullerton Square Towards Battery Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJC 9811 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✕	
2	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N \$ 300.00 ✕	
3	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 ✕	
4	To dismantle front bumper, rhs front fender and rhs front door. To renew rhs front fender and rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 ✕	
5	To respray rhs front fender, rhs front door and rhs wing mirror cover.	\$ 2,600.00 700 ✓	
6	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
7	To carry out diagnostic check.	S/N \$192.00 ✕	
TOTAL LABOUR CHARGES		: <u>\$ 6,812.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJC 9811 H

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER - RH <i>Repair</i>	\$ 700.00	X
2	FRONT FENDER ATTACHMENT PARTS <i>3 New</i>	\$ 183.00	+
3	FRONT FENDER CLOSING ELEMENT - RH	\$ 45.00	+
4	FRONT FENDER BRACKET - RH <i>New</i>	\$ 32.00	X
5	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH <i>New</i>	\$ 45.00	X
6	FRONT FENDER BRACKET <i>3 New</i>	\$ 29.00	X
7	FRONT FENDER BRACE	\$ 107.00	X
8	FRONT WHEEL HOUSING LINER - RH	\$ 220.00	+
9	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>3 New</i>	\$ 82.00	+
10	FENDER LEDGE COVER - RH INNER <i>3 New</i>	\$ 28.00	+
11	FENDER LEDGE COVER - RH OUTER	\$ 21.00	+
12	EXTERIOR MIRROR MOUNTING - RH	\$ 824.00	+
13	MIRROR CAP - RH	\$ 220.00	+
14	MIRROR GLASS - RH	\$ 1,553.00	X
15	FRONT DOOR - RH	\$ 2,152.00	+
16	FRONT DOOR OUTER SEAL - RH	NEC \$ 185.00	+
17	BONDING AGENT <i>3 New</i>	NEC \$ 45.00	+
18	CLEANING SOLUTION	NEC \$ 65.00	+
19	FRONT DOOR ATTACHMENT PARTS <i>3 New</i>	\$ 488.00	+
20	FRONT DOOR CATCH	\$ 96.00	+
21	TYRE PRESURE DATA PLATE	\$ 35.00	+
22	FRONT RIM - RH <i>at</i>	TBC	1230
23	SUNDRIES ?	\$ 300.00	? X not nec
TOTAL SPARE PARTS		:	\$ 7,455.00
TOTAL LABOUR CHARGES		:	\$ 6,812.00
GRAND TOTAL		:	\$ 14,267.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

15497



Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 26/09/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13409

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1152/2019/NS
Date : 24-Sep-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : SHB 2097 C

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Hi Adrian

3 days - ok - jb -20 Feb 20

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Ms Ng Chin Chin
Address : Blk 543 Jurong West St 42
#07-59
Singapore 640543
Telephone : (HP) +65 85227091
Type of Claim : Third party Claims
Policy No. : 10781841
Vehicle No : **SJC 9811 H**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Sep-16
Engine No : CVN 014459
Chassis No : WAUZZZF49GA111725
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Sep-19
Place of Accident : Along Fullerton Square Towards Battery Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJC 9811 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	
2	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N \$ 300.00	
3	To remove and transfer rhs front door's multi-lock system and power window devices. lbspect for damages.	S/N \$ 280.00	
4	To dismantle front bumper, rhs front fender and rhs front door. To renew rhs front fender and rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	
5	To respray rhs front fender, rhs front door and rhs wing mirror cover.	\$ 2,600.00	\$ 700.00
6	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
7	To carry out diagnostic check.	S/N \$192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 6,812.00	\$ 1,172.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJC 9811 H

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER - RH	\$ 700.00	
2	FRONT FENDER ATTACHMENT PARTS	\$ 183.00	
3	FRONT FENDER CLOSING ELEMENT - RH	\$ 45.00	
4	FRONT FENDER BRACKET - RH	\$ 32.00	
5	FRONT FENDER DEFORMATION ELEMENT BRACKET - R	\$ 45.00	
6	FRONT FENDER BRACKET	\$ 29.00	
7	FRONT FENDER BRACE	\$ 107.00	
8	FRONT WHEEL HOUSING LINER - RH	\$ 220.00	
9	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 82.00	
10	FENDER LEDGE COVER - RH INNER	\$ 28.00	
11	FENDER LEDGE COVER - RH OUTER	\$ 21.00	
12	EXTERIOR MIRROR MOUNTING - RH	\$ 824.00	
13	MIRROR CAP - RH	\$ 220.00	
14	MIRROR GLASS - RH	\$ 1,553.00	
15	FRONT DOOR - RH	\$ 2,152.00	
16	FRONT DOOR OUTER SEAL - RH	NEC \$ 185.00	
17	BONDING AGENT	NEC \$ 45.00	
18	CLEANING SOLUTION	NEC \$ 65.00	
19	FRONT DOOR ATTACHMENT PARTS	\$ 488.00	
20	FRONT DOOR CATCH	\$ 96.00	
21	TYRE PRESURE DATA PLATE	\$ 35.00	
22	FRONT RIM - RH (By owner)	\$ 1,230.00	\$ 1,230.00
23	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		\$ 8,685.00	\$ 1,230.00
TOTAL LABOUR CHARGES		\$ 6,812.00	\$ 1,172.00
GRAND TOTAL		\$ 15,497.00	\$ 2,402.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19016902/Atd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-03-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2097C	Veh. Inspected	SJC 9811H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005875MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	25/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4 SEDAN	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WAUZZZF49GA111725	Colour	RED	
Odometer	49434	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/35 R19	GOODYEAR	6 mm	
L/H Front Tyre	245/35 R19	GOODYEAR	6 mm	
R/H Rear Tyre	245/35 R19	GOODYEAR	6 mm	
L/H Rear Tyre	245/35 R19	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/09/2019	Inspection Date	26/09/2019	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 9811H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER-RH (SN)	TO REPAIR SEE LABOUR	700.00	-
1	FRONT FENDER ATTACHMENT PARTS (SN)	NOT NECESSARY	183.00	-
1	FRONT FENDER CLOSING ELEMENT-RH (SN)	NOT NECESSARY	45.00	-
1	FRONT FENDER BRACKET-RH (SN)	NOT NECESSARY	32.00	-
1	FRONT FENDER DEFORMATION ELEMENT BRACKET-RH (SN)	NOT NECESSARY	45.00	-
1	FRONT FENDER BRACKET (SN)	NOT NECESSARY	29.00	-
1	FRONT FENDER BRACE (SN)	NOT NECESSARY	107.00	-
1	FRONT WHEEL HOUSING LINER-RH (SN)	NOT NECESSARY	220.00	-
1	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS (SN)	NOT NECESSARY	82.00	-
1	FENDER LEDGE COVER-RH INNER (SN)	NOT NECESSARY	28.00	-
1	FENDER LEDGE COVER-RH OUTER (SN)	NOT NECESSARY	21.00	-
1	EXTERIOR MIRROR MOUNTING-RH (SN)	NOT NECESSARY	824.00	-
1	MIRROR CAP-RH (SN)	NOT NECESSARY	220.00	-
1	MIRROR GLASS-RH (SN)	NOT NECESSARY	1,553.00	-
1	FRONT DOOR-RH (SN)	NOT NECESSARY	2,152.00	-
1	FRONT DOOR OUTER SEAL-RH (SN)	NOT NECESSARY	185.00	-
1	BONDING AGENT (SN)	NOT NECESSARY	45.00	-
1	CLEANING SOLUTION (SN)	NOT NECESSARY	65.00	-
1	FRONT DOOR ATTACHMENT PARTS (SN)	NOT NECESSARY	488.00	-
1	FRONT DOOR CATCH (SN)	NOT NECESSARY	96.00	-
1	TYRE PRESURE DATA PLATE (SN)	NOT NECESSARY	35.00	-
1	FRONT RIM-RH (SN)	CUT	1,230.00	1,230.00
1	SUNDRIES (SN)	NOT NECESSARY	300.00	-
			8,685.00	1,230.00
LABOUR				
	TO REMOVE CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	NOT NECESSARY	360.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE RHS FRONT DOOR PANEL TRIM.TO REMOVE AND RENEW RHS WING MIRROR ASSY.	NOT NECESSARY	300.00	-
	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES.	NOT NECESSARY	280.00	-
	TO DISMANTLE FRONT BUMPER,RHS FRONT FENDER AND RHS FRONT DOOR.TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR,RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	NOT NECESSARY	2,800.00	-
	TO RESPRAY RHS FRONT FENDER,RHS FRONT DOOR AND RHS WING MIRROR COVER.		2,600.00	700.00
	TO RENEW RHS FRONT RIM AD CARRY OUT WHEEL ALIGNMENT.		280.00	280.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			6,812.00	1,172.00
GRAND TOTAL			15,497.00	2,402.00
RECOMMENDED COST OF REPAIRS				2,402.00

Report Ref No. CS/FCI19016902/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.