

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 24/09/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SMJ5096J	MRH FCS650JT002435	
MODEL	: HONDA CIVIC 1.5A	khanchan	
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 22-Sep-19
		TIME	: 17:00HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Dehnd</i>	1	\$ 663.20	\$ 663.20
2	FRONT BUMPER SIDE RETAINER RH <i>2nd</i>	2	\$ 65.90	\$ 131.80
3	FRONT BUMPER REINFORCEMENT BAR <i>new</i>	1	\$ 360.00	\$ 360.00
4	FRONT BUMPER FOGLAMP COVER RH <i>Dehnd</i>	1	\$ 98.20	\$ 98.20
5	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 166.20	\$ 166.20
6	FRONT GRILLE BASE <i>cracked</i>	1	\$ 320.00	\$ 320.00
7	FRONT GRILLE LOGO <i>new</i>	1	\$ 80.00	\$ 80.00
8	FRONT GRILLE LOGO CHROME <i>cracked</i>	1	\$ 190.00	\$ 190.00
9	HID HEADLAMP RH <i>cracked</i>	1	\$ 1,250.30	\$ 1,250.30
10	HEADLAMP TOP GARNISH CHROME <i>new</i>	1	\$ 145.60	\$ 145.60
11	HEADLAMP LOWER BRACKET RH <i>new</i>	1	\$ 65.90	\$ 65.90
12	FRONT FENDER RH <i>Dented</i>	1	\$ 530.00	\$ 530.00
13	FRONT FENDER INNER COWLING RH <i>new torn</i>	1	\$ 120.00	\$ 120.00
14	FRONT FENDER SIGNAL LAMP RH <i>cracked</i>	1	\$ 90.00	\$ 90.00
15	FRONT WASHER TANK <i>Dehnd</i>	1	\$ 190.00	\$ 190.00
16	FRONT WASHER TANK MOTOR <i>cracked</i>	1	\$ 230.00	\$ 230.00
17	FRONT DOOR RH <i>Not New</i>	1	\$ 980.50	\$ 980.50

3322.4
2657.92

TOTAL PRICE	\$	5,611.70
LESS 20%	\$	1,122.34
SUB TOTAL PRICE	\$	4,489.36

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>item</i>	1	\$ 50.00	\$ 50.00
2	HEADLAMP CLIPS (SET) <i>item</i>	1	\$ 20.00	\$ 20.00
3	FRONT BUMPER CLIP (SET) <i>item</i>	1	\$ 20.00	\$ 20.00
4	FRONT FENDER INNER COWLING CLIP (SET) <i>item</i>	1	\$ 20.00	\$ 20.00
5	SUPPORT PANEL TOP COVER CLIPS(SET) <i>item</i>	1	\$ 20.00	\$ 20.00

40 TOTAL \$ 80.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,500.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,500.00	400	
3	TO CONDUCT WIRING CHECK	\$ 100.00	30	
4	TO REFOCUS HEADLAMP BEAM	\$ 250.00	X	

TOTAL 830 \$3,350.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	4,569.36
TOTAL LABOUR COST	:	\$	3,350.00
TOTAL REPAIR COST	:	\$	7,919.36

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM
NO OF DAYS

Adrian Lj
L/S 24/09/19.

04 Days.

total 3527.82

FAX : L/S: 2810

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: