

ASSIGNMENT

Surveyor:

ADRIAN

DOI: 24/09/2019

Date / Time: 24/09/2019

Registered in Merimen: 26/09/2019

Pre-assign / CCU / FTE



Insured Vehicle No.

SJR 288Z

Claim No.: 1027864025SG

Name of Insured

KELVIN CHEONG KAH WING

Policy No.:

Insured Tel No.

HP: +65-98772777

Make / Model:

VOLVO V40-T4 (A)

Excess Sec II :S\$

D.O.A: 22/09/2019 15:30

Place of Accident:

17A TELOK BLANGAH CRESCENT

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SMD 9600J



INSRS:

WSP: GREEN FOREST

Tel: AUTOMOBILE

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	16/2/2020
	After call ltr to OI:	
	Documentation Check List: Handler	Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Report Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	S\$ 5,000	(5 days) Reduction: 52 %
FINAL SETTLEMENT	Date/Time: 18/3/2020	Confirm with: CHFIS
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: NIL
Repair Cost:	S\$ 5,350	
Loss of Rental (LOR):	S\$ -	(- days) -
Loss of Use (LOU):	S\$ 420	(S 60 x 7 days)
Loss of Income (LOI):	S\$ -	(S - x - days)
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐		[Tick only one]
GIA/LTA Search	S\$ 7.45	
Medical:	S\$ -	
Disbursement:	S\$ -	(e.g. Tow/ Independent)
Legal Cost	S\$ -	
Total:	S\$ 5,777.45	Global Sum S\$: 5,700
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	S\$ 5,700	Name 1: GREEN FOREST AUTOMOBILE PTE LTD
Payee 2: (Strike if N.A.)	S\$ -	Name 2:
Payee 3: (Strike if N.A.)	S\$ -	Name 3:

1/902/ALC

SMD9600J

2018 Sept.

Honda Vezel Hybrid 1496
White
18462

R431248258

215/60R16.
215/60R16.

SS / EX / NOVA / GY / FS / LCA / MIC / CHTB / FR / SUM
TOYO / YOKO or

24/09/19.
Green Forest

Front o/s, u/c.

The UIC / Chassis frame / Body Structure / Wheel suspension

TP A16.

CLIS \$5,000 (Red \$ 5,454.20 / 52.1)

+ days + 1 Sunday + 1 PRS = 7 days

MV
PV
Nett

PRIS REPORT
PRIS REPORT

Days Off Road
Reserve No. of Tires

5-10
10-15
15-20
20-25
25-30

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

SYLLYS AUTO PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

04th OCT 2019

TPA 16
Khor Chan

Accident date: 22nd SEPTEMBER 2019

Estimated repair cost for vehicle no: SMD9600J HONDA VEZEL 1.5 '2018

S/n	Qty	Items	U/price	Amount
1	1	Front head lamp -RH <i>Cracked</i>		\$1,785.40 ✓
2	1	Front head lamp lower bracket-RH <i>Cracked</i>		\$112.10 ✓
3	1	Front bumper <i>Detained</i>		\$950.00 <i>880</i>
4	2	Front bumper side bracket <i>RH Dmg</i>	\$88.20	\$176.40 <i>45</i>
5	10	Front bumper clips <i>New</i>	\$5.00	\$50.00 <i>30</i>
6	1	Front bumper number plate <i>New</i>		\$50.00 <i>X</i>
7	1	Front bumper reinforcement <i>Bent</i>		\$484.00 <i>321</i>
8	1	Front bumper mud shield -RH <i>New</i>		\$116.00 <i>X</i>
9	1	Front bumper center lower garnish <i>New</i>		\$220.10 <i>X</i>
10	1	Front bumper center lower cover <i>New</i>		\$295.10 ✓
11	1	Front Bumper Fog lamp-RH <i>New</i>		\$255.00 <i>X</i>
12	1	Front bumper fog lamp cover-RH <i>Cracked</i>		\$135.00 ✓
13	1	Front Grille <i>New</i>		\$385.00 <i>X</i>
14	1	Front Grille emble logo <i>New</i>		\$56.00 <i>X</i>
15	10	Front Grille clips	\$5.00	\$50.00 <i>X</i>
16	1	Front water tank assy <i>Cracked</i>		\$288.00 <i>115</i>
17	1	Front fender-RH <i>Bent</i>		\$588.10 ✓
18	1	Front fender cowling-RH <i>Torn</i>		\$168.20 ✓
19	5	Front R/H fender cowling clips <i>New</i>	\$5.00	\$25.00 ✓
20	1	Front R/H fender signal lamp <i>New</i>		\$58.80 <i>X</i>
21	1	Front lower arm-RH <i>Bent</i>		\$285.00 ✓
22	1	Front knuckle arm-RH <i>Bent</i>		\$325.00 ✓
23	1	Front knuckle arm bearing-RH <i>2nd</i>		\$168.00 ✓
24	1	Front shock absorber-RH <i>Bent</i>		\$458.00 ✓
25	1	front Tyre-RH <i>New</i>		\$300.00 <i>X</i>
26	1	front rim -RH <i>New</i>		\$400.00 ✓

6135.9

Subtotal :- \$8,184.20

Labour charges

To remove & re-fix front undercarriage

4908.72

\$250.00 *220*

Wheel alignment (computer)

\$120.00 *80*

To Check Wiring System

LKK Auto Consultants hence notify
Tuff Kote repairer of the following:
• To resurvey before/after spray painting
• To resurvey damaged part(s) during resurvey
• Parts price are subject to confirmation
Towing charges
• That survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
Panel beating
• Supplementary item(s) must be resurveyed and
• subject to final approval from Insurance Company
Spray painting

\$80.00 *30*

\$120.00 *50*

\$100.00 *60*

\$800.00 *500*

\$800.00 *400*

total: 6248.72

4/5: 5K 05 days

Subtotal :- \$2,270.00

Total:- \$10,454.20

Acknowledged by Repairer

Signature:

Date:

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	359K

Vehicle Details

Vehicle No.:	SMD9600J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	LEB5948277
Chassis No.:	RU31248258
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$27,107.00
Original Registration Date:	13 Sep 2018
First Registration Date:	13 Sep 2018
Transfer Count:	1
Actual ARF Paid:	\$19,950.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Sep 2028
PARF Rebate Amount:	\$14,962.00

Intended COE Rebate Details

COE Expiry Date:	12 Sep 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,311.00
COE Rebate Amount:	\$25,848.00
Total Rebate Amount:	\$40,810.00

The information contained herein is correct as at 09 Oct 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

359K

Vehicle Details

Vehicle No.:

SMD9600J

Vehicle to be Exported:

Yes

Intended Deregistration Date:

09 Oct 2019

Vehicle Make:

HONDA

Vehicle Model:

VEZEL HYBRID 1.5X AUTO

Primary Colour:

White

Manufacturing Year:

2017

Engine No.:

LEB5948277

Chassis No.:

RU31248258

Maximum Power Output:

112.0 kW (150 bhp)

Open Market Value:

\$27,107.00

Original Registration Date:

13 Sep 2018

First Registration Date:

13 Sep 2018

Transfer Count:

1

Actual ARF Paid:

\$19,950.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

12 Sep 2028

PARF Rebate Amount:

\$14,962.00

Intended COE Rebate Details

COE Expiry Date:

12 Sep 2028

COE Category:

E - Open - all except motorcycle

COE Period(Years):

10

QP Paid:

\$32,311.00

COE Rebate Amount:

\$25,848.00

Total Rebate Amount:

\$40,810.00

The information contained herein is correct as at 09 Oct 2019

OK



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	CASH	DATE	Sep 24, 2019 3:27:40 PM
LICENSE NO.	SMD 9600 J		
MILEAGE	18465		
REFERENCE	CUSTOM	MODEL	HONDA VEZEL (RU3)

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-2.00	0.00	2.00			16.60				16.60		
PARTIAL TOE	-1.00	0.00	1.00		7.20		9.30		-0.70		17.40	
SET BACK	---	---	---			0°20"				-0°20"		
CAMBER	-1°30"	-0°30"	0°30"		-0°40"		0°06"	0°46"	-0°38"		0°08"	0°48"
CASTER	4°30"	5°30"	6°30"		4°46"		4°14"	0°32"	4°46"		4°14"	0°32"
KING-PIN	---	---	---		13°22"		12°30"	0°50"	13°22"		12°30"	0°50"
INCL ANGLE	---	---	---		12°42"		12°38"		12°42"		12°38"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			3.20				3.20		
PARTIAL TOE	---	---	---		2.60		0.60		2.60		0.60	
SET BACK	---	---	---			-0°02"				-0°02"		
CAMBER	---	---	---		-1°44"		-1°26"	0°16"	-1°44"		-1°26"	0°16"
THRUST ANGLE	-0°08"	0.00	0°08"			0°08"				0°08"		

Khanchna (LKK Auto)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Wednesday, 6 November 2019 9:06 AM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: RE: SJR288Z vs SMD9600J On 22/09/2019 | 1027864025SG-003

Dear Khanchna,

Investigation completed and revealed that there is no suspicious element.

Please proceed to handle the claim.

Thank you.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]
Sent: 05 November 2019 17:49
To: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: [EXTERNAL] RE: SJR288Z vs SMD9600J On 22/09/2019 | 1027864025SG-003

This message is from an external sender; be cautious with links and attachments.

Dear Mr. Bernard,

As requested in your e-mail below, we have uploaded the accident videos from third party via Merimen.

Thank you.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 8 October 2019 11:58 AM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Subject: FW: SJR288Z vs SMD9600J On 22/09/2019 | 1027864025SG-003

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Tuesday, 8 October, 2019 11:53 AM
To: Admin A <admin-a@lkkauto.com>
Subject: RE: SJR288Z vs SMD9600J On 22/09/2019 | 1027864025SG-003

Hi LKK,

In the meantime, please request for video from TP.

Thank you.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Ler, Bernard-JQ
Sent: 08 October 2019 11:51
To: Admin A <admin-a@lkkauto.com>
Subject: SJR288Z vs SMD9600J On 22/09/2019 | 1027864025SG-003

Hi LKK,

Please put on hold for the above case while the investigation is still on going.

We will update once the investigation is cleared.

Thank you.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.
Attn : Ler, Bernard-JQYour Ref : 1027864025SG
Our Ref : CC6/AIG19016907/AKA3
Date : 24 Feb 2020**"WITHOUT PREJUDICE"****ACCIDENT INVOLVING SJR288Z & SMD9600J ON 22/09/2019**

Refer to the above accident.

The accident occurred when Insured overtook TP that was travelling straight. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SJR288Z) and third party claimant (vehicle no. SMD9600J).

Summary of offer made to workshop Green Forest Automobile Pte Ltd is as follows :

	Claimed	Revised
Cost of Repairs (w/GST)	\$ 11,185.99	\$ 5,350.00
LOU/LOR (7 days x \$100)	\$ 700.00	\$ 420.00~700.00 (7 days x \$60 ~ \$100)
LTA Search Fee	\$ 7.45	\$ 7.45
TOTAL	\$ 11,893.44	\$ 5,777.45~6,057.45

Amount of claim at **Liability 100%** \$ 5,777.45~6,057.45

Enclose herewith the relevant supporting documents for your perusal.

**** 5 days recommendation for repair + 1 Sunday + 1 PRS = 7 days**

For your approval please.

Regards,
Khanchna Pothuraj
LKK Auto Consultants Pte Ltd

Print Received Message

This mail is associated with :

***SMD9600J (1027864025SG)**

[SJR288Z]

TP

SYLLYS AUTO PTE LTD

Sep 22 2019 3:00PM

[KELVIN CHEONG KAH WING]

Green Forest Automobile Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 18/03/2020 13:43 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5777.45) - SMD9600J - Claim Handler: Ler, Bernard-JQ

Approved:5777.45:Cost of Repair : \$5,350.00 Loss of Rental : \$420.00 7 days @ S\$ 60/day LTA/ GIA Search Fee :
\$7.45 Total : \$5,777.45

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 18 March 2020 3:33 PM
To: 'chan pick yuen'
Cc: Admin A
Subject: RE: SMD9600J GIA report *** LKK REF: CC6/AIG19016907/Aka3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement on a global sum for **\$5,700.00(all in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Tuesday, 5 November 2019 4:55 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Subject: Re: SMD9600J GIA report *** LKK REF: CC6/AIG19016907/Aka3

Dear Khanchna ,

Enclosed is the invoice ,GIA report , LOA , video what add to Ms Hsiao Tong & Ita fee

As request following :

1. RC \$ 5350(\$5000 + 7% GST - AS agreed)
2. loss of use \$700(\$100 -1600cc new car 2018 year under leasing company - 5 days recommend + 1 day waiting period + 1 day weekend -total 7 days)
3. Ita fee \$7.45

@ 100% (video submitted by whatadd Ms Hsiao Tong 05.11.19)

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Sep 2019 Edit Reg		24 Sep 2019 00:00 Edit Adj Rpt	S\$5,000.00 Edit Estimates	S\$5,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

KELVIN CHEONG KAH WING, ID: S7639992A

Main Claimant:

SYLLYS AUTO PTE LTD, Co. Reg. No.: 201634359K

Vehicle Reg. No.:

SMD9600J

Date of Loss:

22/09/2019 15:00 - :59
[12 Months and 9 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 1027864025SG

Policy/Cover Note No.:

(Comprehensive)

Vehicle Reg. No. (Insured):

SJR288Z

Policy No. (Claimant):

A29131133MCX

Excess:

Repairer:

Green Forest Automobile Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit, 415875 Kaki Bukit - Tel: 63846383

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]
BernardJiQian.Ler@aig.com

Claimant's Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/10/2019]

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

• AIG_SG_EXPRESS (18/03/2020): Alert - Adj Mandate Approved (S\$5777.45) - SMD9600J - Claim Handler: Ler, Bernar...

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMD9600J (1027864025SG)
[SJR288Z]
TP
SYLLYS AUTO PTE LTD
Sep 22 2019 3:00PM
[KELVIN CHEONG KAH WING]
Green Forest Automobile Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Video

1 per page

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

05/11/19 17:47

Video - Accident TP

1

Load MP4

2

05/11/19 17:47

Video - Accident TP

1

Load MP4

Letters/Correspondences

1 per page

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

(Draft)

Third Party Express Settlement - Payment Breakdown

1

Edit

Assessment Reports

1 per page

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

24/02/20 18:29

Adjuster Immediate Advice

1

Load HTM

Photos/Images

3 per page

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

01/11/19 08:59

General View

1

Load JPG

☒

2

01/11/19 08:59

General View

1

Load JPG

☒

3

01/11/19 08:59

General View

1

Load JPG

☒

4

01/11/19 08:59

General View

1

Load JPG

☒

5

01/11/19 08:59

General View

1

Load JPG

☒

6

01/11/19 08:59

General View

1

Load JPG

☒

7

01/11/19 08:59

General View

1

Load JPG

☒

8

01/11/19 08:59

General View

1

Load JPG

☒

9

01/11/19 08:59

General View

1

Load JPG

☒

10

01/11/19 08:59

General View

1

Load JPG

☒

11

01/11/19 08:59

General View

1

Load JPG

☒

12

01/11/19 08:59

General View

1

Load JPG

☒

13

01/11/19 08:59

General View

1

Load JPG

☒

14

01/11/19 08:59

General View

1

Load JPG

☒

15

01/11/19 08:59

General View

1

Load JPG

☒

16

01/11/19 08:59

General View

1

Load JPG

☒

17

01/11/19 08:59

General View

1

Load JPG

☒

18

01/11/19 08:59

General View

1

Load JPG

☒

19

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

20

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

21

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

22

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

23

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

24

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

25

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

26

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

27

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

28

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

29

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

30

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

31

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

32

01/11/19 08:59

Reinspection Photo

1

Load JPG

☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
34	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
35	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
36	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
37	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
38	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
39	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
40	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
41	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
42	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
43	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
44	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
45	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
46	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
47	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
48	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
49	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
50	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
51	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
52	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
53	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
54	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
55	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
56	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
57	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
58	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
59	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
60	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
61	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
62	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
63	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
64	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
65	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
66	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
67	01/11/19 08:59	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/19 10:58	TP GIA REPORT	 Load PDF	
2	02/10/19 10:17	WHEEL ALIGNMENT	 Load PDF	
3	12/02/20 08:51	LETTER TO OI	 Load PDF	
4	06/03/20 14:35	LTA SEARCH	 Load PDF	
5	06/03/20 17:37	Tax Invoice	 Load PDF	
6	01/04/20 10:18	AUTHORISATION TO ACT FORM	 Load PDF	
7	01/04/20 10:18	Release Voucher	 Load PDF	
8	01/04/20 10:18	LDD	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/09/19 12:46	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SJR288Z (Insd veh)	Model:	HONDA VEZEL 1.5 HYBRID
	SMD9600J (TP veh)		X (A)
Date of Accident:	22/09/2019		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No
Repair Estimate	:	\$	11,185.99
Final Repair Cost	:	\$	5,700.00
Loss of Use	:	\$	7.00 days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	5,700.00
Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Green Forest Automobile Pte Ltd	:	\$ 5,700.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

01 Apr
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016907/AKA3Q2

Date: 01/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SMD9600J

Insured Vehicle No : SJR288Z

Date of Loss: 22/09/2019

Nature of Claim: TP

Claim No: 1027864025SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD9600J

Make & Model: HONDA VEZEL, 1.5 HYBRID X (A)

Engine No: LEB5948277

Reg. Date: 13/09/2018 (Man. Year: 2017)

Chassis No: RU31248258

Colour: White

Odometer: 18462 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,184.20	4,908.72	3,275.48	40.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,340.00	930.00	40.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,454.20	6,248.72	4,205.48	40.23
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	10,454.20	5,000.00	5,454.20	52.17
+ GST 7.00/7.00% (S\$)	731.79	350.00	381.79	52.17
Nett Amount (S\$)	11,185.99	5,350.00	5,835.99	52.17
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,777.45		
Global Sum Settlement (S\$)		5,700.00		

INSPECTION

Date of Assignment: 24/09/2019

Date Inspected: 24/09/2019 Inspected At:

Green Forest Automobile Pte Ltd (Kaki Bukit)
8 Kaki Bukit Avenue 4, #05-25,,
Premier@Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEAD LAMP RH	Cracked	1,785.40 F	*1,785.40 FL
2	1		*FRONT HEAD LAMP LOWER BRACKET RH	Cracked	112.10 F	*112.10 FL
3	1		*FRONT BUMPER	Deformed	950.00 F	*880.00 FL
4	1		*FRONT BUMPER SIDE BRACKET	O/S Damaged	176.40 F	*45.00 FL
5	10		*FRONT BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
6	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	484.00 F	*321.00 FL
8	1		*FRONT BUMPER MUD SHIELD -RH	Not Necessary	116.00 F	*- FL
9	1		*FRONT BUMPER CENTER LOWER GARNISH	Not Necessary	220.10 F	*- FL
10	1		*FRONT BUMPER CENTER LOWER COVER	Cut	295.10 F	*295.10 FL
11	1		*FRONT BUMPER FOG LAMP -RH	Not Necessary	255.00 F	*- FL
12	1		*FRONT BUMPER FOG LAMP COVER-RH	Cracked	135.00 F	*135.00 FL
13	1		*FRONT GRILLE	Not Necessary	385.00 F	*- FL
14	1		*FRONT GRILLE EMBLE LOGO	Not Necessary	56.00 F	*- FL
15	10		*FRONT GRILLE CLIPS	Not Necessary	50.00 F	*- FL
16	1		*FRONT WATER TANK ASSY	Cracked	288.00 F	*115.00 FL
17	1		*FRONT FENDER -RH	Dented	588.10 F	*588.10 FL
18	1		*FRONT FENDER COWLING -RH	Torn	168.20 F	*168.20 FL
19	5		*FRONT R/H FENDER COWLING CLIPS	Necessary	25.00 F	*25.00 FL
20	1		*FRONT R/H FENDER SIGNAL LAMP	Not Necessary	58.80 F	*- FL
21	1		*FRONT LOWER ARM -RH	Bent	285.00 F	*285.00 FL
22	1		*FRONT KNUCKLE ARM -RH	Bent	325.00 F	*325.00 FL
23	1		*FRONT KNUCKLE ARM BEARING-RH	Damaged	168.00 F	*168.00 FL
24	1		*FRONT SHOCK ABSORBER -RH	Bent	458.00 F	*458.00 FL
25	1		*FRONT TYRE -RH	Not Necessary	300.00 F	*- FL
26	1		*FRONT RIM -RH	Cut	400.00 F	*400.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	8,184.20	6,135.90
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,227.18
Total Parts (S\$)	8,184.20	4,908.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RE-FIX FRONT UNDERCARRIAGE	New	250.00	220.00
2	WHEEL ALIGNMENT (COMPUTER)	New	120.00	80.00
3	TO CHECK WIRING SYSTEM	New	80.00	30.00
4	TUFF KOTE	New	120.00	50.00
5	TOWING CHARGES	New	100.00	60.00
6	PANEL BEATING	New	800.00	500.00
7	SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (S\$)			2,270.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >