

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1992090/AMK

Date: 02 Oct 2019

Policy No: DMCVSN1913011900

Veh Reg No: GBJ3531M

Make/Model: NISSAN NISSAN NV350
 PANEL VAN 5DR 2.5
 5AT

Chassis No: JN1MC2E26Z0031065

Engine No: YD25047507B

Reg. Date: 26/03/2019

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 15/09/2019

TP Veh Reg No: SKR4499T

Not Asstained
Running B4 paint
6 days

Estimate Repair Cost to Vehicle No :GBJ3531M

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 REAR BUMPER	600.50	1 PC	<i>B₁</i> 600.50	<i>✓</i>
2 REAR BUMPER CENTRE STEP PANEL	169.00	1 PC	<i>B₁</i> 169.00	<i>✓</i>
3 REAR BUMPER CLIP	4.40	6 PC	<i>mc</i> 26.40	<i>✓</i>
4 REAR TAILGATE	1,742.00	1 PC	<i>B₁</i> 1,742.00	<i>✓</i>
5 TAILGATE INNER LOCK	261.00	1 PC	<i>nd</i> 261.00	<i>✓</i>
6 TAILGATE INNER LOCK OUTER COVER	32.50	1 PC	<i>am</i> 32.50	<i>✓</i>
7 TAILGATE INNER RUBBER	127.50	1 PC	<i>am</i> 127.50	<i>✓</i>
8 TAILGATE LOGO	59.70	1 PC	<i>mc</i> 59.70	<i>✓</i>
9 TAILGATE EMBLEM 'NV350'	101.30	1 PC	<i>mc</i> 101.30	<i>✓</i>
10 REAR END PANEL (INNER)	411.80	1 PC	<i>B₁</i> 411.80	<i>✓</i>
11 REAR END PANEL INNER TOP MOULDING	65.30	1 PC	<i>nd</i> 65.30	<i>✓</i>
			3,597.00	
		Less 10%	359.70	3,237.30
Special Net				
12 REAR END PANEL (OUTER)	138.50	1 PC	<i>B₁</i> 138.50	<i>✓</i>
13 REVERSE SENSOR	200.00	1 SET	<i>Shan</i> 200.00	<i>✓</i>
14 STICKER 70KM/HR	10.00	1 PC	<i>mc</i> 10.00	<i>✓</i>
15 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	<i>mc</i> 40.00	<i>✓</i>
			388.50	388.50
Labour				
16 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	<i>✓</i>
17 REMOVE & REFIX REAR BUMPER, TAILGATE & ATTACHMENTS, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL (INNER & OUTER); KNOCKING & REPAIR REAR FLOORBOARD & REALIGN THE SAME	1,000.00	1 LA	1,000.00	<i>Foot</i>
18 PUTTY & RESPRAY REAR BUMPER, TAILGATE, REAR END PANEL (INNER & OUTER), REAR FLOORBOARD & ALL AFFECTED AREAS	800.00	1 LA	800.00	<i>Foot</i>
19 TO REWRITE ADVERTISEMENT	200.00	1 LA	<i>(B₁11)</i> 200.00	<i>7</i>
20 RUSTPROOFING	90.00	1 LA	90.00	<i>60L</i>
			2,210.00	2,210.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 15/09/2019
TP Veh Reg No: SKR4499T

Estimate No: ES1992090/AMK
Date: 02 Oct 2019
Policy No: DMCVSN1913011900
Veh Reg No: GBJ3531M
Make/Model: NISSAN NISSAN NV350
PANEL VAN 5DR 2.5
5AT
Chassis No: JN1MC2E26Z0031065
Engine No: YD25047507B
Reg. Date: 26/03/2019

Estimate Repair Cost to Vehicle No :GBJ3531M

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 5,835.80
			Add GST @ 7%	408.51
			Total Amount Payable	<u>S\$ 6,244.31</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE