

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1992183/AMK

Date: 30 Oct 2019

Policy No: DMPPHQ18-007769

Veh Reg No: SLH7231U

Make/Model: MITSUBISHI LANCER
EX 1.6 AT LED TAIL
LAMP

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 23/09/2019

TP Veh Reg No: SCR3624A

Chassis No: JMYSRCY1AGU005926

Engine No: 4A92CL7290

Reg. Date: 17/11/2016

Estimate Repair Cost to Vehicle No :SLH7231U

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR BUMPER	891.00	1 PC	891.00	—
2 REAR BUMPER CLIP	5.00	5 PC	25.00	—
			916.00	
		Less 10%	91.60	824.40
Special Net				
3 REVERSE SENSOR	200.00	1 SET	200.00	—
4 REAR NUMBER PLATE	35.00	1 PC	35.00	—
			235.00	235.00
Labour				
5 REMOVE & REFIX REAR BUMPER & ATTACHMENTS:KNOCKING & REPAIR REAR END PANEL & REALIGN THE SAME	350.00	1 LA	350.00	200
6 PUTTY & RESPRAY REAR BUMPER & ATTACHMENTS,REVERSE SENSORS & ALL AFFECTED AREAS	300.00	1 LA	300.00	250
			650.00	650.00
Total				S\$ 1,709.40
Add GST @ 7%				119.66
Total Amount Payable				S\$ 1,829.06

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn Li

AUTHORISED SIGNATURE
LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary survey must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: